

McHenry County



Illinois


**McHenry County - Townships**

Chemung  Township

0 1 2 4 6 8 Miles

0 5 10 Kilometers





McHenry County



Township Key

Chemung	Alden	Hebron	
Dunham	Hartland		
Marengo	Seneca		
Riley	Not Included in Survey		

### Hartland Township


T45N, R6E

0 0.5 1 2 Miles

0 0.5 1 2 Kilometers



MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 1



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-1-1 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 5805 McCawley Rd

Lat/Long: 42.409871, -88.472844

Primary Use: Ag /Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 9

List Observed Structures: a) residence b) outbuildings c) outbuildings  
d) demolished outbuildings - east side

Residence Detail

Style Foursquare

Wall materials vinyl and board

Roof materials asphalt

Foundation materials fieldstone

Other distinguishing features  
pyramid roof, dormer, enclosed front porch, wide eaves

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - metal pole building C -and D - metal silos E - shed F - small wooden coop G - gabled timber shed

H - concrete stave silo I - milkhouse also includes barn foundation

Number of photos taken for this property\*: 4

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-1-1: 5805 McCauley Road - Residence



HA-1-1: 5805 McCauley Road - Outbuildings



HA-1-1: 5805 McCauley Road - Outbuildings



HA-1-1: 5805 McCauley Road – Demolished Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-1-2 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 5219 McCauley Rd

Lat/Long: 42.420004, -88.475806

Primary Use: Residence / Ag

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 3

List Observed Structures: a) residence b) barn

Residence Detail

Style Side Gabled  
Wall materials vinyl  
Roof materials asphalt  
Foundation materials \_\_\_\_\_  
Other distinguishing features enclosed front porch

Any obvious Additions/Alterations \_\_\_\_\_

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - modern barn/garage

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style Gabled  
Wall materials board  
Roof materials asphalt  
Foundation materials \_\_\_\_\_  
Other distinguishing features attached shed addition



HA-1-2: 5219 McCauley Road - Residence



HA-1-2: 5219 McCauley Road - Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-1-3 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 14601-15015 Thayer Rd \*14617

Lat/Long: 42.413961, -88.483523

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 6

List Observed Structures: a) Residence b) Barn

Residence Detail

Style Upright and Wing

Wall materials board

Roof materials asphalt

Foundation materials

Other distinguishing features  
wing has door and modern window

Any obvious Additions/Alterations

Barn Detail

Style metal, modern

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small gabled shed C - windmill base D - large pole barn/machine shed E - small pole building

F - small gabled shed

Number of photos taken for this property\*: 3

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-1-3: 14601-15015 Thayer Road – Residence, Barn

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 2




Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-2-1 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 15817 Thayer Rd

Lat/Long: 42.414033, -88.506588

Primary Use: Residence

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 3

List Observed Structures: a) Residence b) shed C) barn

Residence Detail

Style Ranch

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small gabled shed C - small barn

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1974 assessor date



HA-2-1: 15817 Thayer Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-2-2 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 5615 Alden Rd

Lat/Long: 42.408245, -88.504833

Primary Use: Aj/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 6

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Foursquare

Wall materials board or vinyl

Roof materials asphalt

Foundation materials fieldstone

Other distinguishing features

rear extension, full front porch

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - gabled milk house D - gabled shed E - gabled shed F - concrete stave silo

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.



HA-2-2: 5615 Alden Road - Residence



HA-2-2: 5615 Alden Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-2-3 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 5083-5783 Alden Rd

Lat/Long: 42.403274, -88.801628

Primary Use: Residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: 2

List Observed Structures: A) Residence

Residence Detail

Style Front Gabled

Wall materials board

Roof materials asphalt

Foundation materials fieldstone

Other distinguishing features

enclosed front and rear porches

Any obvious Additions/Alterations

siding not original

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small gabled shed

shown as a school 1872

Number of photos taken for this property\*: (

\* Attach Photo log, additional notes and map of resource location.

circa 1886 assessor date



HA-2-3: 5083-5783 Alden Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-2-4 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 5402 Alden Rd

Lat/Long: 42.404429, -88.501459

Primary Use: Ag /Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 8

List Observed Structures: a) Residence b) outbuildings

Residence Detail

Style Foursquare

Wall materials vinyl

Roof materials asphalt

Foundation materials \_\_\_\_\_

Other distinguishing features

dormer - mostly obscured

Any obvious Additions/Alterations

Barn Detail

Style Gabled hay barn

Wall materials wood

Roof materials asphalt

Foundation materials \_\_\_\_\_

Other distinguishing features

extensions to side and milkhouse

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C and D - concrete stave silos E - garage F - gabled small barn G - grain silo H - metal silo

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.



HA-2-4: 402 Alden Road - Residence



HA-2-4: 5402 Alden Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-2-5 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: McGuire Rd

Lat/Long: 42.402377, -88.910931

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 3

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Bungalow

Wall materials aluminum

Roof materials asphalt

Foundation materials concrete

Other distinguishing features  
multi-pane windows

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete stave silo

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1940 assessor date

Barn Detail

Style Gabled

Wall materials wood

Roof materials

Foundation materials

Other distinguishing features



HA-2-5: McGuire Road - Outbuildings



HA-2-5: McGuire Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-2-6 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 15817 Green Rd

Lat/Long: 42.409548, -88.506832

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence - obstructed view

Residence Detail

Style Side Gabled/Colonial Revival

Wall materials

Roof materials asphalt

Foundation materials

Other distinguishing features  
obscured by trees

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1980 assessor date



HA-2-6: 15817 Green Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-2-7 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 16019 Green Rd

Lat/Long: 42.410039, -88.511035

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) Residence

Residence Detail

Style Front Gabled

Wall materials board

Roof materials asphalt

Foundation materials

Other distinguishing features  
dormers, extensions

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

view to outbuildings mostly obscured

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-2-7: 16019 Green Road – Residence

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 3





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-3-1 Surveyor Name: JD, KM

Current Property or Structure Name: Pathfinder Ranch

Address: 16209 Green Rd

Lat/Long: 42.410125, -88.512964

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 2

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Ranch/split level

Wall materials aluminum/stone facing

Roof materials asphalt

Foundation materials

Other distinguishing features

attached garage?

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1972 assessor date

Barn Detail

Style Modern pole building

Wall materials metal

Roof materials metal

Foundation materials

Other distinguishing features



HA-3-1: 16209 Green Road - Residence



HA-3-1: 16209 Green Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-3-2 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 16204 McGuire Rd

Lat/Long: 42.400041, -88.513167

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style Side Gabled

Wall materials vinyl

Roof materials asphalt

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

saltbox extension

Any obvious Additions/Alterations \_\_\_\_\_

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1872-1892

Barn Detail

Style \_\_\_\_\_

Wall materials \_\_\_\_\_

Roof materials \_\_\_\_\_

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_



HA-3-2: 16204 McGuire Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-3-3 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 16410 McGuire Rd

Lat/Long: 42.400453, -88.517480

Primary Use: Ag /Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 8

List Observed Structures: a) residence b) barn c) outbuildings (C-H)

Residence Detail

Style No style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail 2

Style metal + wood Main is a Gabled hay

Wall materials board barn

Roof materials asphalt

Foundation materials concrete

Other distinguishing features  
single story gabled addition front and rear

Any obvious Additions/Alterations

- possible modern additions + updates

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - garage D - large metal pole barn E - concrete silo F - gabled shed G - -coop

H - small machine shed/shelter

Number of photos taken for this property\*: 3

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-3-3: 16410 McGuire Road – Outbuildings, Barn



HA-3-3: 16410 McGuire Road – Outbuildings,  
Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-3-4 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 17020 McGuire Rd

Lat/Long: 42.400200, -88.530555

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 8

List Observed Structures: a) residence b) barn c) outbuildings

Residence Detail

Style Gabled El

Wall materials board

Roof materials metal

Foundation materials

Other distinguishing features

Barn Detail

Style gambrel

Wall materials wood

Roof materials asphalt

Foundation materials

Other distinguishing features

front and rear modern extensions

Any obvious Additions/Alterations

new windows/door/porch

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - garage D and E - concrete stave silos F - pole building G and H - metal silos

Number of photos taken for this property\*: 3

\* Attach Photo log, additional notes and map of resource location.




HA-3-4: 17020 McGuire Road – Outbuildings



HA-3-4: 17020 McGuire Road – Residence

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 4





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-4-1 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 17512 McGuire Rd

Lat/Long: 42.400434, -88.540050

Primary Use: Ag /Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 8

List Observed Structures: a) ~~barn~~ residence b) barn c) outbuildings

Residence Detail

Style Foursquare

Wall materials Brick

Roof materials asphalt

Foundation materials fieldstone

Other distinguishing features

full front porch, fieldstone, patterned brickwork

Any obvious Additions/Alterations

Barn Detail

Style gabled hay barn

Wall materials board

Roof materials

Foundation materials fieldstone

Other distinguishing features

attached milkhouse

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - small garage D - large garage/shed E - silo F - small barn G - gabled crib H - small barn/garage

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872-1892



HA-4-1: 17512 McGuire Road – Outbuildings



HA-4-1: 17512 McGuire Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-4-2 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: McGuire Rd

Lat/Long: 42.400343, -88.543408

Primary Use: Ag /Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 9

List Observed Structures: a) residence b) barns c) outbuildings

Residence Detail

Style Upright and Wing

Wall materials wood board

Roof materials asphalt

Foundation materials concrete

Other distinguishing features

simple porch supports

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete stave silo D and E - red metal pole buildings F - small gabled barn G - gabled crib  
H - pole building I - grain complex

Number of photos taken for this property\*: 3

\* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail 2

Style Gabled livestock barn

Wall materials wood

Roof materials metal

Foundation materials

Other distinguishing features



HA-4-2: McGuire Road - Outbuildings



HA-4-2: McGuire Road - Residence



HA-4-2: McGuire Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-4-3 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 17813 Lincoln Rd

Lat/Long: 42.40416, -88.545811

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 2

List Observed Structures: a) barn b) pole building C) res

Residence Detail

Style modern - No style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style Gabled hay barn

Wall materials wood

Roof materials asphalt

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

modern pole building and residence

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1941-1951 assessor date



HA-4-3: 17813 Lincoln Road – Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-4-4 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 17609 Lincoln Rd

Lat/Long: 42.410523, -88.541359

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) house

Residence Detail

Style Ranch

Wall materials board

Roof materials

Foundation materials

Other distinguishing features  
obscured

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.



HA-4-4: 17609 Lincoln Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-4-5 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 17806 Lincoln Rd

Lat/Long: 42.413552, -88.545290

Primary Use: Ag

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 5

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Ranch

Wall materials brick

Roof materials asphalt

Foundation materials

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - pyramid roof shed C - pole building D - metal silo E - shed

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1975 assessor date




HA-4-5: 17806 Lincoln Road – Residence



HA-4-5: 17806 Lincoln Road – Outbuildings

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 5





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-S-1 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 18417 Lincoln Rd

Lat/Long: 42.410751, -88.558232

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 6

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Gabled El

Wall materials vinyl or aluminum

Roof materials asphalt

Foundation materials concrete

Other distinguishing features

Raised basement

Any obvious Additions/Alterations

rear addition

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - pole building D - metal shed E and F - metal silos

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

no assessor date given - circa 1900

Barn Detail

Style Gabled livestock/hay

Wall materials wood

Roof materials

Foundation materials

Other distinguishing features



HA-5-1: 18417 Lincoln Road – Residence



HA-5-1: 18417 Lincoln Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-5-2 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 18620 Lincoln Rd

Lat/Long: 42.411527, -88.561708

Primary Use: Residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style Obscured

Wall materials

Roof materials

Foundation materials

Other distinguishing features

obscured

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1978-1980

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features



HA-5-2: 18620 Lincoln Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-5-3 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 19020 Lincoln Rd

Lat/Long: 42.41274, -88.569851

Primary Use: Ag

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style Foursquare

Wall materials board

Roof materials fishscale

Foundation materials

Other distinguishing features

enclosed front porch

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style

not visible from road

Wall materials

Roof materials

Foundation materials

Other distinguishing features

circa 1872-1892



HA-5-3: 19020 Lincoln Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-5-4 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 5507 Irish Ln

Lat/Long: 42.407193, -88.853517

Primary Use: Ag /Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 4

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Upright and Wing

Wall materials

Roof materials asphalt

Foundation materials

Other distinguishing features

behind a line of trees off road

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete stave silo D - timber machine shed

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style Gabled Hay barn

Wall materials wood

Roof materials cedar + asphalt?

Foundation materials

Other distinguishing features



HA-5-4: 5507 Irish Lane – Residence



HA-5-4: 5507 Irish Lane – Outbuildings

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 6





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-6-1 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 19102 McGuire Rd

Lat/Long: 42.400362, -88.569921

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 4

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Ranch

Wall materials siding/vinyl

Roof materials asphalt

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - shed C - barn complex E - long pole barn

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1941-1951 assessor date

Barn Detail

Style ~~XXXXXX~~  
Gambrel

Wall materials

Roof materials

Foundation materials

Other distinguishing features

appears to be a modern or modernized complex of buildings attached to barn



HA-6-1: 19102 McGuire Road - Residence



HA-6-1: 19102 McGuire Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-6-2 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 1982 McGuire Rd

Lat/Long: 42.401676, -88.584300

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 3

List Observed Structures: a) residence b) barn + outbuildings

Residence Detail

Style Upright and Wing (originally)

Wall materials

Roof materials asphalt

Foundation materials

Other distinguishing features

Barn Detail

Style Gambrel

Wall materials wood

Roof materials

Foundation materials concrete

Other distinguishing features

Any obvious Additions/Alterations

multiple additions

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - shed

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-6-2: 19882 McGuire Road - Residence



HA-6-2: 19882 McGuire Road - Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-6-3 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 19709 Shultz Rd

Lat/Long: 42.407101, -88.582985

Primary Use: Ag /Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 3

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Side gabled

Wall materials aluminum

Roof materials asphalt

Foundation materials

Other distinguishing features

obscured

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B and C - modern or remodeled outbuildings

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.



HA-6-3: 19709 Schultz Road – Residence, Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-6-4 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 5523 Shultz Rd

Lat/Long: 42.407525, -88.584667

Primary Use: Residence

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 2

List Observed Structures: a) residence b) garage

Residence Detail

Style Upright and Wing

Wall materials aluminum and board

Roof materials asphalt

Foundation materials

Other distinguishing features

spindle supports on front porch

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - early twentieth century gabled garage

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date



HA-6-4: 5523 Schultz Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-6-5 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 2000<sup>9</sup> McGuire Rd

Lat/Long: 42.407090, -88.587427

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 4

List Observed Structures: a) residence b) barn

Residence Detail

Style Upright and Wing

Wall materials vinyl

Roof materials asphalt

Foundation materials

Other distinguishing features

Barn Detail

Style Gabled

Wall materials wood

Roof materials

Foundation materials

Other distinguishing features  
Side opening

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - large gabled outbuilding D - small gabled outbuilding/garage

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-6-5: 2009 McGuire Road - Residence



HA-6-5: 2009 McGuire Road - Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-6-6 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 5602 Schultz Rd

Lat/Long: 42.407318, -88.879223

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 9

List Observed Structures: a) residence b) barn

Residence Detail

Style Cape Cod

Wall materials brick

Roof materials asphalt

Foundation materials

Other distinguishing features

gabled dormers with siding,  
front entry porch with gabled roof

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - garage C and D - small sheds

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style Gabled

Wall materials wood

Roof materials asphalt

Foundation materials

Other distinguishing features



HA-6-6: 5602 Schultz Road - Barn



HA-6-6: 5602 Schultz Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-6-7 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: Schultz Rd

Lat/Long: 42.409924, -88.578462

Primary Use: Ag

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 3

List Observed Structures: b) barn + outbuildings

Residence Detail

Style demolished

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style Gabled T-Plan

Wall materials wood

Roof materials asphalt

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

A - silo B - gable pole building C - gabled machine shed

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.



HA-6-7: Schultz Road – Barn, Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-6-8 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 5810 Schultz Rd

Lat/Long: 42.411326, -88.579642

Primary Use: Residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: 2

List Observed Structures: a) Residence b)garage

Residence Detail

Style Front Gabled

Wall materials

Roof materials asphalt

Foundation materials

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - garage

shown as a school in 1872

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1949 assessor date



HA-6-8: 5810 Schultz Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-6-9 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: Schultz Rd

Lat/Long: 42.414664, -88.579260

Primary Use: Ag

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 6

List Observed Structures: a) residence b) barn + outbuildings

Residence Detail

Style Cross Gabled

Wall materials wood

Roof materials asphalt

Foundation materials concrete block

Other distinguishing features

full front porch

Any obvious Additions/Alterations

rear extension

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C and D - metal silos EFG - gabled timber sheds

Barn Detail

Style Gabled long barn

Wall materials wood

Roof materials metal

Foundation materials

Other distinguishing features

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872




HA-6-9: Schultz Road - Outbuildings



HA-6-9: Schultz Road - Residence

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 7





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-7-1 Surveyor Name: JD, KM

Current Property or Structure Name: Bailey Crone Farm

Address: 19703 McGuire Rd

Lat/Long: 42.399848, -88.582076

Primary Use: Ag /Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 4

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Upright and Wing

Wall materials wood

Roof materials asphalt

Foundation materials

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

replaced windows

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled milkhouse with attached shed C and D - metal silos E - gabled shed

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-7-1: 19703 McGuire Road - Outbuildings



HA-7-1: 19703 McGuire Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-7-2 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 4106 Lindwall Rd

Lat/Long: Ag /Res

Primary Use: 42.385976, -88.579284

Is this a record of a single structure or group (give total number of structures):

Single:  Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) Residence

Residence Detail

Style Upright and Wing

Wall materials vertical board

Roof materials asphalt

Foundation materials

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

extra wing, reconfigured windows

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.



HA-7-2: 4106 Lindwall Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-7-3 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 4407 Lindwall Rd

Lat/Long: 42.385976, -88.579284

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) Residence

Residence Detail

Style Bungalow

Wall materials aluminum

Roof materials asphalt

Foundation materials

Other distinguishing features  
pyramid roof

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

shed roof dormer, metal lattice supports on front porch

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.



HA-7-3: 4407 Lindwall Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-7-4 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 19419 McGuire Rd

Lat/Long: 42.399647, -88.577352

Primary Use: Ag /Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 3

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style: ~~XXXXXX~~ modern /Upright and Wing

Wall materials vinyl

Roof materials asphalt

Foundation materials

Other distinguishing features

Barn Detail

Style Gabled

Wall materials aluminum or vinyl

Roof materials metal

Foundation materials

Other distinguishing features

remodeled

Any obvious Additions/Alterations

extensively remodeled

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - small gabled shed

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872




HA-7-4: 19419 McGuire Road - Residence



HA-7-4: 19419 McGuire Road - Outbuildings

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 8





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-8-1 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 4608 Countryside Ln

Lat/Long: 42.393253, -88.561914

Primary Use: Residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style Ranch possibly modern but 1961  
map shows structures at  
that location  
Wall materials  
Roof materials  
Foundation materials  
Other distinguishing features  
obscured

Barn Detail

Style  
Wall materials  
Roof materials  
Foundation materials  
Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1973 assessor date (shown on 1961 map)



HA-8-1: 4608 Countryside Lane – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-8-32 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 5017 countryside Ln

Lat/Long: 42.399403, -88.561354

Primary Use: Residence

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 2

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style No style

Wall materials

Roof materials asphalt

Foundation materials

Other distinguishing features

remodeled

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style Gambrel

Wall materials board

Roof materials asphalt

Foundation materials

Other distinguishing features

gable front addition



HA-8-2: 5017 Countryside Lane – Residence,  
Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-8-43 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 18919 McGuire Rd

Lat/Long: 42.398395, -88.567966

Primary Use: Residence / Ag

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 4

List Observed Structures: a) residence b) home

Residence Detail

Style Upright and Wing

Wall materials vinyl

Roof materials asphalt

Foundation materials

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - metal shed C - shelter/coop D - large outbuilding

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-8-3: 18919 McGuire Road - Residence



HA-8-3: 18919 McGuire Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-8-~~8~~<sup>4</sup> Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 1819 McGuire Rd

Lat/Long: 42.399395, -88.551996

Primary Use: Ag<sup>/Res</sup>

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 7

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Gabled El

Wall materials vinyl

Roof materials asphalt

Foundation materials

Other distinguishing features

bay window, front porch at El

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete silo D - gabled shed E - small gabled shed F - gabled outbuilding with metal roof  
G - flat roofed outbuilding

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872 date

Barn Detail

Style Gabled hay barn

Wall materials wood

Roof materials asphalt

Foundation materials

Other distinguishing features



HA-8-4: 18119 McGuire Road - Residence



HA-8-4: 18119 McGuire Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-8-185 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 4618 King Rd

Lat/Long: 42.393742, -88.554516

Primary Use: Ag /Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 7

List Observed Structures: a) Residence b) outbuildings

Residence Detail

Style Foursquare

Wall materials

Roof materials asphalt

Foundation materials

Other distinguishing features  
front porch with flat pyramid roof

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - gabled hay barn D - gabled crib building E - silo F - windmill G - small shed

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date

Barn Detail

Style Gambrel roof

Wall materials wood

Roof materials asphalt

Foundation materials

Other distinguishing features  
front single story wide gambrel addition



HA-8-5: 4618 King Road - Outbuildings



HA-8-5: 4618 King Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-8-~~76~~ Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 4502 King Rd

Lat/Long: 42.390897, -88.551140

Primary Use: AgRes

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 3?

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Upright and Wing

Wall materials

Roof materials

Foundation materials

Other distinguishing features

obscured/off road

Any obvious Additions/Alterations

Barn Detail

Style Gabled livestock barn

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

mix of old and new buildings - hard to see details and buildings because of location

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

location set back from road + obscured obscured by trees

circa 1872



HA-8-6: 4502 King Road – Residence, Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-8-87 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 4104 King Rd

Lat/Long: 42.387386, -88.553839

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 3

List Observed Structures: a) Residence b) outbuildings

Residence Detail

Style Cross Gabled  
Wall materials vinyl  
Roof materials asphalt  
Foundation materials \_\_\_\_\_  
Other distinguishing features \_\_\_\_\_

Barn Detail

Style Gambrel  
Wall materials \_\_\_\_\_  
Roof materials \_\_\_\_\_  
Foundation materials \_\_\_\_\_  
Other distinguishing features side garage door

Any obvious Additions/Alterations \_\_\_\_\_

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small shed

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-8-7: 4104 King Road - Residence



HA-8-7: 4104 King Road - Barn

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-8-98 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 18904 Streit Rd

Lat/Long: 42.386005, -88.565975

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 7

List Observed Structures: a) residence b) outbuildings

### Residence Detail

Style Ranch

Wall materials aluminum

Roof materials asphalt

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

### Barn Detail

Style \_\_\_\_\_

Wall materials \_\_\_\_\_

Roof materials \_\_\_\_\_

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

Any obvious Additions/Alterations

rear extension

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - metal silo C - garden shed D - metal and wood outbuilding E - small shed F - pole building G - concrete stave silo

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1941-1951 assessor date



HA-8-8: 18905 Streit Road - Outbuildings



HA-8-8: 18905 Streit Road - Residence

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 9





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-9-1 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 17513 Streit Rd

Lat/Long: 42.385869, -88.839807

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 4

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Gabled El

Wall materials vinyl

Roof materials asphalt

Foundation materials

Other distinguishing features

appears to have some decoration on front porch, but hidden by trees

Any obvious Additions/Alterations

Barn Detail

Style Gambrel Hay barn

Wall materials wood

Roof materials

Foundation materials

Other distinguishing features

"Circa 1918" on barn

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C and D - concrete silos

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-9-1: 17513 Streit Road - Residence



HA-9-1: 17513 Streit Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-9-2 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 17104 Streit Rd

Lat/Long: 42.386006, -88.530952

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 5

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Pancho

Wall materials wood and brick facing

Roof materials asphalt

Foundation materials concrete

Other distinguishing features

Barn Detail

Style Gabled livestock

Wall materials wood

Roof materials asphalt

Foundation materials concrete

Other distinguishing features

numerous extensions

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - gabled outbuilding D - low gabled outbuilding/pole barn E - concrete stave silo  
also includes a concrete foundation

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1961-1965



HA-9-2: 17104 Streit Road - Outbuildings



HA-9-2: 17104 Streit Road - Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-9-3 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 17201 McGuire Rd

Lat/Long: 42.399611, -88.533133

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 4

List Observed Structures: a) Residence b) outbuildings

### Residence Detail

Style Italianate

Wall materials aluminum or asbestos

Roof materials asphalt

Foundation materials \_\_\_\_\_

Other distinguishing features  
obscured

Any obvious Additions/Alterations \_\_\_\_\_

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - garage D - pole building

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872




HA-9-3: 17209 McGuire Road - Residence



HA-9-3: 17209 McGuire Road - Outbuildings

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 10





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-10-1 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 4815 Wilson Rd

Lat/Long: 42.396137, -88.515194

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 7

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Foursquare

Wall materials

Roof materials asphalt

Foundation materials

Other distinguishing features

too far back to determine details

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

CDE - concrete silos F - gambrel crib building G - machine shed

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style Gabled livestock

Wall materials

Roof materials

Foundation materials

Other distinguishing features

too far from road



HA-10-1: 4815 Wilson Road - Residence



HA-10-1: 4815 Wilson Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-10-2 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 16303 Streit Rd

Lat/Long: 42.388813, -88.515812

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style Front gabled

Wall materials aluminum

Roof materials asphalt

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

enclosed front porch, side extension, large chimney

Any obvious Additions/Alterations \_\_\_\_\_

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1900/1976 assessor date - both dates given

Barn Detail

Style \_\_\_\_\_

Wall materials \_\_\_\_\_

Roof materials \_\_\_\_\_

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_



HA-10-2: 16303 Streit Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-10-3 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 16330 Streit Rd

Lat/Long: 42.387571, -88.518500

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 11

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Gabled El

Wall materials vinyl

Roof materials asphalt

Foundation materials \_\_\_\_\_

Other distinguishing features  
reconfigured, new windows, new roofline

Any obvious Additions/Alterations \_\_\_\_\_

Barn Detail

Style \_\_\_\_\_

Wall materials \_\_\_\_\_

Roof materials \_\_\_\_\_

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - brick shelter D - concrete stave silo E pole building F and G - long wood barns H - round roof shed  
I - small gabled shed J - metal silo K - concrete stave silo  
also appears to have a long gambreled barn - obscured

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872-1892




HA-10-3: 16330 Streit Road - Outbuildings



HA-10-3: 16330 Streit Road - Residence

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 11





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-11-1 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 4706 Alden Rd

Lat/Long: 42.397132, -88.495562

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Foursquare

Wall materials vinyl

Roof materials asphalt

Foundation materials \_\_\_\_\_

Other distinguishing features  
enclosed porch, pyramid dormer

Any obvious Additions/Alterations \_\_\_\_\_

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

outbuildings include garage and numerous sheds, but too hard to see through trees

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.



HA-11-1: 4706 Alden Road - Residence



HA-11-1: 4706 Alden Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-11-2 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 4608 Alden Rd

Lat/Long: 42.393603, -88.492363

Primary Use: Ag /Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence b) shed

Residence Detail

Style ~~gabled~~ upright and wing

Wall materials aluminum

Roof materials asphalt

Foundation materials fieldstone

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small gabled shed/garage

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.




HA-11-2: 4608 Alden Road - Residence



HA-11-2: 4608 Alden Road - Shed

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 12





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/16/15 Survey Number: HA-12-1 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 4411 Alden Rd

Lat/Long: 42.389380, -88.490971

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 7

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style four-square

Wall materials aluminum

Roof materials asphalt

Foundation materials \_\_\_\_\_

Other distinguishing features

enclosed front porch

Any obvious Additions/Alterations \_\_\_\_\_

Barn Detail

Style Gabled hay

Wall materials board

Roof materials metal

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - garage D - pole building E - small barn F - shed G - large pole building

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-12-1: 4411 Alden Road - Residence



HA-12-1: 4411 Alden Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-12-2 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 4210 Alden Rd

Lat/Long: 42.386766, -88.487312

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 3

List Observed Structures: a) residence b) outbuilding c) silo

Residence Detail

Style Side gabled/I House

Wall materials board or vinyl

Roof materials asphalt

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

Barn Detail

Style \_\_\_\_\_

Wall materials \_\_\_\_\_

Roof materials \_\_\_\_\_

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

Any obvious Additions/Alterations

rear extension

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - wood outbuilding C - concrete stave silo

Number of photos taken for this property\*: 3

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-12-2: 4210 Alden Road - Residence



HA-12-2: 4210 Alden Road - Outbuilding



HA-12-2: 4210 Alden Road - Silo

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-12-43 Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 4503 McCauley Rd

Lat/Long: 42.390625, -88.477500

Primary Use: AggRes

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 5

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style four-square

Wall materials

Roof materials asphalt

Foundation materials

Other distinguishing features

wrap-around porch

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete stave silo D - shed E - shed/machine shed

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style Gabled mixed use barn

Wall materials wood

Roof materials asphalt

Foundation materials

Other distinguishing features

attached milkhouse



HA-12-3: 4503 McCauley Road - Residence



HA-12-3: 4503 McCauley Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/10/15 Survey Number: HA-<sup>12</sup>~~12~~-~~84~~ Surveyor Name: JD, KM

Current Property or Structure Name: \_\_\_\_\_

Address: 4906 McCauley Rd

Lat/Long: 42.397134, -88.475500

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 3?

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style view obstructed by trees

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - shed/garage C - pole building

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1987 assessor date, shown in 1872 township map




HA-12-4: 4906 McCauley Road - Residence



HA-12-4: 4906 McCauley Road - Outbuildings

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 13





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-13-1 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: ~~4401 4159A~~ Jankowski RA 14505

Lat/Long: 42.384875, -88.480400

Primary Use: Residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) Residence

Residence Detail

Style Queen Anne

Wall materials vinyl

Roof materials asphalt

Foundation materials

Other distinguishing features

wrap around porch

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features



HA-13-1: 14505 Jankowski Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-13-82 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 4009 McCauley Rd

Lat/Long: 42.384629, -88.484139

Primary Use: Ag<sup>/Res</sup>

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 3

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Upright and Wing

Wall materials vinyl

Roof materials asphalt

Foundation materials fieldstone

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - garage C - concrete silo

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.



HA-13-2: 4009 McCauley Road - Residence



HA-13-2: 4009 McCauley Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-13-43 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 3811 Alden Rd

Lat/Long: 42.381540, -88.484327

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style converted schoolhouse?

Wall materials wood

Roof materials asphalt

Foundation materials

Other distinguishing features

Front Gabled

Any obvious Additions/Alterations

new windows at some point

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

shown as a school in 1872

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-13-3: 3811 Alden Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-13-84 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: Alden Rd

Lat/Long: 42.380914, -88.486733

Primary Use: Ag /Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style  
Wall materials  
Roof materials  
Foundation materials  
Other distinguishing features

not visible  
from road

Barn Detail

Style  
Wall materials  
Roof materials  
Foundation materials  
Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1855 assessor date



HA-13-4: Alden Road – Residence, Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-13-165 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 3515 Alden Rd

Lat/Long: 42.377615, -88.482693

Primary Use: Residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: 2

List Observed Structures: a) residence b) garage

Residence Detail

Style Minimal Traditional

Wall materials vinyl

Roof materials asphalt

Foundation materials

Other distinguishing features

small entry porch

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - garage

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1952 assessor date



HA-13-5: 3515 Alden Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-13-10X6 Surveyor Name: JD, EM

Current Property or Structure Name: st. Patrick Church

Address: 15012 St. Patrick Rd

Lat/Long: 42.378335, -88.490275

Primary Use: Church

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) church

Residence Detail

Style Romanesque

Wall materials Brick

Roof materials

Foundation materials

Other distinguishing features

bell tower, rounded windows

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

no assessor date - 1913 corner stone, shown on 1872 township map

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features



HA-13-6: 15012 Saint Patrick Road– Church

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-13-~~117~~ Surveyor Name: JD, EM

Current Property or Structure Name: St. Patricks Cemetery

Address: St. Patrick Rd

Lat/Long: 42.378097, -88.490307

Primary Use: Cemetery

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: N/A

Residence Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

gate, headstones

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

no assessor date - maps show pre-1862



HA-13-7: Saint Patrick Road– Saint Patricks Cemetery

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-13-128 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 3419 West Rd

Lat/Long: 42.376106, -88.486906

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 14

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Side Gabled

Wall materials aluminum

Roof materials asphalt

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

Barn Detail

Style Gabled Hay Barn

Wall materials \_\_\_\_\_

Roof materials metal

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

Any obvious Additions/Alterations \_\_\_\_\_

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete silo D - gabled outbuilding E - pole building F - pole building G - pole building  
H - windmill base I - shed J - shed K - shed LMN - grain bins

Number of photos taken for this property\*: 3

\* Attach Photo log, additional notes and map of resource location.

circa 1872-1892



HA-13-8: 3419 West Road - Outbuildings



HA-13-8: 3419 West Road - Residence



HA-13-8: 3419 West Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-13-~~13~~9 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 3305 West Rd

Lat/Long: 42.374339, -88.488445

Primary Use: Residence

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 2

List Observed Structures: a) residence b) garage

Residence Detail

Style Cape Cod  
Wall materials vinyl  
Roof materials asphalt

Foundation materials \_\_\_\_\_  
Other distinguishing features \_\_\_\_\_

steep roof, gabled dormers, enclosed entry

Any obvious Additions/Alterations \_\_\_\_\_

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled garage

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1961 assessor date

Barn Detail

Style \_\_\_\_\_  
Wall materials \_\_\_\_\_  
Roof materials \_\_\_\_\_

Foundation materials \_\_\_\_\_  
Other distinguishing features \_\_\_\_\_



HA-13-9: 3305 West Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-13-~~10~~10 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 3215 West Rd

Lat/Long: 42.372356, -88.489119

Primary Use: AgRes

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 6

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Cross Gabled

Wall materials vinyl and fishscale

Roof materials asphalt

Foundation materials

Other distinguishing features  
large enclosed front porch

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - shed C - shed D - shed E and F - metal silos

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features



HA-13-10: 3215 West Road - Residence



HA-13-10: 3215 West Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-13-151 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 3121 West Rd

Lat/Long: 42.371215, -88.489608

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 5

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Front Gabled

Wall materials aluminum

Roof materials asphalt

Foundation materials

Other distinguishing features  
side extension

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete silo D - shed E - pole building

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style Gabled hay barn

Wall materials wood

Roof materials asphalt

Foundation materials

Other distinguishing features




HA-13-11: 3121 West Road - Residence



HA-13-11: 3121 West Road - Outbuildings

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 14





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-14-1 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 15318 St. Patrick Rd

Lat/Long: 42.380119, -88.496196

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 4

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Upright and Wing

Wall materials vinyl

Roof materials asphalt

Foundation materials

Other distinguishing features

front porch on wing

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled garage C - Quonset D - gabled outbuilding

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features



HA-14-1: 15318 Saint Patrick Road - Residence



HA-14-1: 15318 Saint Patrick Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-14-2 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: St. Patrick Rd

Lat/Long: 42.379926, -88.495552

Primary Use: Residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: 1) residence

Residence Detail

Style Ranch

Wall materials aluminum

Roof materials asphalt

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

small house, two wide front windows

Any obvious Additions/Alterations \_\_\_\_\_

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

property also includes modern shed and garage

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1959 assessor date



HA-14-2: Saint Patrick Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/18 Survey Number: HA-14-3 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 15711 St. Patrick Rd

Lat/Long: 42.381309, -88.505245

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a residence

Residence Detail

Style Ranch

Wall materials vinyl

Roof materials asphalt

Foundation materials

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.



HA-14-3: 15711 Saint Patrick Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-14-4 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: Murray Rd

Lat/Long: 42.374668, -88.500665

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 9

List Observed Structures: a) residence b) barn 1 c) barn 2  
d) outbuildings

Residence Detail

Style Greek Revival/Upright and Wing

Wall materials aluminum

Roof materials asphalt

Foundation materials

Other distinguishing features

wide cornice still evident

Any obvious Additions/Alterations

front

addition;

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - windmill D - timber machine shed E - brick or block Gambrel shed/barn F - drive thru crib

G - small shed H - metal silo I - shed

Number of photos taken for this property\*: 5

\* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style Gambrel

Wall materials wood

Roof materials asphalt + cedar

Foundation materials

Other distinguishing features

attached brick Gambrel milkhouse



HA-14-4: Murray Road - Residence



HA-14-4: Murray Road – Barn 1




HA-14-4: Murray Road – Barn 2



HA-14-4: Murray Road - Outbuildings

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 15



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom





**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



Township Location



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-15-1 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 16214 St. Patrick Rd

Lat/Long: 42.381587, -88.514545

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 9

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Upright and Wing

Wall materials wood/shingle

Roof materials asphalt

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

enclosed porch/addition

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete stave silo D - timber shed E - corncrib building F and G - grain bins

Hi and I - mod pole buildings

Number of photos taken for this property\*: 3

\* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style Gabled hay and livestock

Wall materials wood

Roof materials metal

Foundation materials concrete

Other distinguishing features

smaller rear gabled addition; attached milkhouse



HA-15-1: 16214 Saint Patrick Road - Outbuildings



HA-15-1: 16214 Saint Patrick Road – Residence,  
Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-15-2 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 16309 St. Patrick Rd

Lat/Long: 42.376365, -88.516192

Primary Use: ag

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 7

List Observed Structures: a) outbuildings

Residence Detail

Style farmstead located back

Wall materials from road

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style Gambrel

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B and C - concrete silos D - pole building E - pole building F and G - metal silos

difficult to evaluate because of distance

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-15-2: 16309 Saint Patrick Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-15-3 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: ~~111~~ 3741 Deep cut Rd

Lat/Long: 42.380765, -22.520889

Primary Use: Ag /Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 5

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style

view obstructed by trees

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style Gambrel

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - formed concrete (?) silo D - pole building E - grain bin

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-15-3: 3749 Deep Cut Road - Outbuildings



HA-15-3: 3749 Deep Cut Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-15-4 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 3420 Deep cut Rd

Lat/Long: 42.376073, -88.521398

Primary Use: ~~Ag~~ Res

Is this a record of a single structure or group (give total number of structures):

Single:  Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style Minimal Traditional

Wall materials aluminum

Roof materials asphalt

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

Barn Detail

Style \_\_\_\_\_

Wall materials \_\_\_\_\_

Roof materials \_\_\_\_\_

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

Any obvious Additions/Alterations

wide front windows - new?

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1952 assessor date



HA-15-4: 3420 Deep Cut Road – Residence

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 16



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-16-1 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 17415 Streit Rd

Lat/Long: 42.384108, -88.536917

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style Four-square

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style not visible

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - pole building

no other buildings visible

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-16-1: 17415 Streit Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-16-2 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 17601 Streit Rd

Lat/Long: 42.384906, -88.540847

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 2

List Observed Structures: a) residence b) garage

Residence Detail

Style Side gabled

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled garage

1998 assessor date indicates it is modern but may be more to it than it seems

Number of photos taken for this property\*: 1


\* Attach Photo log, additional notes and map of resource location.

circa 1872-1892



HA-16-2: 17601 Streit Road – Residence, Garage

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 17



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-17-1 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 3719 Paulson Rd

Lat/Long: 42.381263, -88.550639

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 4

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Upright and Wing

Wall materials aluminum

Roof materials asphalt

Foundation materials fieldstone

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - round roofed concrete block building C - concrete stave silo E - pole building

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date



HA-17-1: 3719 Paulson Road - Residence



HA-17-1: 3719 Paulson Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-17-2 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 3107 Paulson Rd

Lat/Long: 42.371925, -88.550568

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style

view obstructed by trees

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

at least two outbuildings and a residence

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872-1892




HA-17-2: 3107 Paulson Road - Outbuildings



HA-17-2: 3107 Paulson Road – Residence

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 18





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-18-1 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: ~~1913~~ Streit Rd

Lat/Long: 42.385299, -88.571546

Primary Use: Ag

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) silo

Residence Detail

Style demolished

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style demolished

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

concrete stave silo

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.



HA-18-1: Streit Road – Silo

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-18-2 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 19113 Streit Rd

Lat/Long: 42.384980, -88.576806

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 5

List Observed Structures: a) residence b) barn 1 c) outbuildings

Residence Detail

Style Foursquare

Wall materials aluminum

Roof materials asphalt

Foundation materials

Other distinguishing features  
small entry porch

Any obvious Additions/Alterations  
side extension

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete stave silo D - pole building E - gabled crib/small barn

Number of photos taken for this property\*: 3

\* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date

Barn Detail

Style Gabled hay barn

Wall materials wood

Roof materials

Foundation materials

Other distinguishing features  
small gabled addition



HA-18-2: 19113 Streit Road - Residence



HA-18-2: 19113 Streit Road - Outbuildings



HA-18-2: 19113 Streit Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-18-3 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 20001 Strait Rd

Lat/Long: 42.385333, -88.587328

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence b) outbuilding

Residence Detail

Style Ranch

Wall materials vinly

Roof materials asphalt

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1977 assessor date

Barn Detail

Style A-stylistic

Wall materials

Roof materials

Foundation materials

Other distinguishing features

tall slim gambrel center with shed roof extensions on either side



HA-18-3: 2001 Streit Road - Residence



HA-18-3: 2001 Streit Road – Outbuilding

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-18-4 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 20009 U.S. 14

Lat/Long: 42.382781, -88.588573

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style obscured

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1976 assessor date



HA-18-4: 2009 U.S. 14 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-18-5 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 20006 U.S. 14

Lat/Long: 42.383819 -88.587253

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style Ranch

Wall materials

Roof materials

Foundation materials

Other distinguishing features

obscured

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1960 assessor date

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features



HA-18-5: 2006 U.S. 14 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-18-6 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 19919 U.S. 14

Lat/Long: 42.382052, -88.587760

Primary Use: Residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: 2

List Observed Structures: a) Residence

Residence Detail

Style Minimal Traditional

Wall materials

Roof materials asphalt

Foundation materials

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1958 assessor date



HA-18-6: 19919 U.S. 14 – Residence, Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-18-7 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 19917 U.S. 14

Lat/Long: 42.381571, -88.887003

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: 2

List Observed Structures: a) residence

Residence Detail

Style Bungalow

Wall materials

Roof materials asphalt

Foundation materials

Other distinguishing features

obscured

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - wide gabled shed

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1956 assessor date

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features



HA-18-7: 19917 U.S. 14 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-18-8 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 19910 U.S. 14

Lat/Long: 42.382727, -88.586169

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style Contemporary

Wall materials

Roof materials

Foundation materials

Other distinguishing features

wide windows, wide chimney, wide roof

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1950 assessor date

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features



HA-18-8: 19910 U.S. 14 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-18-9 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: U.S. 14

Lat/Long: 42.381973, -88.584788

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: 1) residence

Residence Detail

Style Ranch

Wall materials

Roof materials asphalt

Foundation materials

Other distinguishing features

bay window (looks like mod addition)

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1970 assessor date

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features



HA-18-9: U.S. 14 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 12-12-15 Survey Number: HA-18-10 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: U.S. 14

Lat/Long: \_\_\_\_\_

Primary Use: Ag - demolished farmstead

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) outbuildings

Residence Detail

Style demolished

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

A - small timber shed/well house B - metal shed/pole building

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-18-10: U.S. 14 – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-18-11 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 20098 Lembocke Rd

Lat/Long: 42.371282, -88.588797

Primary Use: AggRes

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 6

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Gabled El

Wall materials vinyl

Roof materials asphalt

Foundation materials

Other distinguishing features

Barn Detail

Style Gambrel dairy

Wall materials wood

Roof materials metal

Foundation materials

Other distinguishing features  
multiple extensions

Any obvious Additions/Alterations

front porch closed off; new windows

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete stave silo D - machine shed E - quonset F - grain storage complex

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1913 assessor date




HA-18-11: 20098 Lembcke Road - Outbuildings



HA-18-11: 20098 Lembcke Road – Residence,  
Outbuildings

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 19





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-19-1 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: Lemboke Rd

Lat/Long: 42.370843, -88.584035

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 4

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Bungalow

Wall materials vinyl

Roof materials asphalt

Foundation materials

Other distinguishing features  
enclosed front porch

Any obvious Additions/Alterations

Barn Detail

Style

Wall materials wood

Roof materials

Foundation materials

Other distinguishing features  
includes an older gabled front end and a newer pole addition - more of a machine shed

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - modern rounded roof machine shed attached to older gambrel outbuilding

D - gabled shed/outbuilding

Number of photos taken for this property\*: 3

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-19-1: Lembcke Road - Residence



HA-19-1: Lembcke Road - Outbuildings



HA-19-1: Lembcke Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-19-2 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 19708 Bunker Hill Rd

Lat/Long: 42.357166, -88.584151

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style Ranch

Wall materials brick

Roof materials asphalt

Foundation materials

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1961-1965



HA-19-2: 19708 Bunker Hill Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-19-3 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 19314 Bunker Hill Rd

Lat/Long: 42.356926, -88.575128

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style Ranch

Wall materials vinyl/aluminum

Roof materials asphalt

Foundation materials concrete

Other distinguishing features

sunken garage

Any obvious Additions/Alterations

front wooden deck

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Barn Detail

Style

Wall materials

Roof materials

Foundation materials ~~concrete~~

Other distinguishing features

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1940 assessor date



HA-19-3: 19314 Bunker Hill Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-19-4 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 19318 Bunker Hill Rd

Lat/Long: 42.356974, -88.575782

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style Ranch

Wall materials vinyl or aluminum

Roof materials asphalt

Foundation materials

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

wooden front deck

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1968 assessor date



HA-19-4: 19318 Bunker Hill Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-19-5 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 19410 Bunker Hill Rd

Lat/Long: 42. 357144 , -88. 576962

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: 3

List Observed Structures: a) residence

Residence Detail

Style Ranch

Wall materials vinyl

Roof materials asphalt

Foundation materials concrete

Other distinguishing features \_\_\_\_\_

Barn Detail

Style \_\_\_\_\_

Wall materials \_\_\_\_\_

Roof materials \_\_\_\_\_

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

Any obvious Additions/Alterations \_\_\_\_\_

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - garage C - garden shed

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1966 assessor date



HA-19-5: 19410 Bunker Hill Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-~~10~~<sup>19</sup>-6 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 19420 Bunker Hill Rd

Lat/Long: 42.359085, -88.577644

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: 2

List Observed Structures: a) residence

Residence Detail

Style Ranch

Wall materials vinyl

Roof materials asphalt

Foundation materials concrete

Other distinguishing features \_\_\_\_\_

Barn Detail

Style \_\_\_\_\_

Wall materials \_\_\_\_\_

Roof materials \_\_\_\_\_

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

Any obvious Additions/Alterations \_\_\_\_\_

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - garage

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1971 assessor date



HA-19-6: 19420 Bunker Hill Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-19-7 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 19510 Bunker Hill Rd

Lat/Long: 42.357073, -88.578620

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style Ranch

Wall materials brick

Roof materials asphalt

Foundation materials concrete

Other distinguishing features

wide front porch

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1973 assessor date



HA-19-7: 19510 Bunker Hill Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-19-8 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 19518 Bunker Hill Rd

Lat/Long: 42.357073, -88.579328

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style Ranch

Wall materials brick and vinyl

Roof materials asphalt

Foundation materials concrete

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1972 assessor date



HA-19-8: 19518 Bunker Hill Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/12/15 Survey Number: HA-19-9 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 19606 Bunker Hill Rd

Lat/Long: 42.356950, -88.579822

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style Side gabled/Minimal Traditional

Wall materials aluminum/brick facing

Roof materials asphalt

Foundation materials

Other distinguishing features

3 sections

attached garage

Any obvious Additions/Alterations

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1


\* Attach Photo log, additional notes and map of resource location.

circa 1954 assessor date



HA-19-9: 19606 Bunker Hill Road – Residence

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 20





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-20-1 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 18814 U.S. 14

Lat/Long: 42-364870, -88.564544

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style view obstructed by trees  
Wall materials \_\_\_\_\_  
Roof materials \_\_\_\_\_  
Foundation materials \_\_\_\_\_  
Other distinguishing features \_\_\_\_\_

Barn Detail

Style \_\_\_\_\_  
Wall materials \_\_\_\_\_  
Roof materials \_\_\_\_\_  
Foundation materials \_\_\_\_\_  
Other distinguishing features \_\_\_\_\_

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

property appears to have at least two outbuildings and a residence

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.



HA-20-1: 18814 U.S. 14 – Residence, Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-20-~~2~~<sup>2</sup> Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 1000 RT 14

Lat/Long: 42.366180, -88.867017

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 2

List Observed Structures: a) residence b) garage

Residence Detail

Style obscured

Wall materials wood

Roof materials

Foundation materials

Other distinguishing features

obscured

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

garage is obscured by heavy tress

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-20-2: 19000 U.S. 14 – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-20-3 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 18918 Bunker Hill Rd

Lat/Long: 42.357671, -88.566794

Primary Use: Ag

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 4

List Observed Structures: a) residence b) residence 2 c) outbuildings

Residence Detail

x2 homes on property

Style Side Gabled

Wall materials wood or vinyl

Roof materials asphalt

Foundation materials

Other distinguishing features

older residence remodeled - hard to tell original form

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - modern? residence - may be a Ranch C - windmill D - pole barn - wood and metal

Number of photos taken for this property\*: 4

\* Attach Photo log, additional notes and map of resource location.

circa 1942/1945 assessor date, shown in 1872 township map



HA-20-3: 18918 Bunker Hill Road - Windmill



HA-20-3: 18918 Bunker Hill Road - Residence



HA-20-3: 18918 Bunker Hill Road - Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-20-4 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 2801 Paulson Rd

Lat/Long: 42.362991, -88.554593

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style located back from road  
Colonial Revival/ Side gabled

Wall materials

Roof materials asphalt

Foundation materials

Other distinguishing features

front entry porch

Any obvious Additions/Alterations

remodeled - addition/windows

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - shed D - concrete stave silo E - gabled outbuilding  
property obscured and far back

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features



HA-20-4: 2801 Paulson Road – Residence, Outbuildings

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 21



Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

0 125 250 500 Meters

0 375 750 1,500 Feet

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-21-1 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 2318 Paulson Rd

Lat/Long: 42.359906, -88.549323

Primary Use: Residence

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style ~~XXXXXXXXXXXXXXXXXXXX~~  
Painted Cape Cod ?  
Obscured

Wall materials

Roof materials

Foundation materials

Other distinguishing features

obscured by trees

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

also includes at least a garage

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1956 assessor date



HA-21-1: 2318 Paulson Road – Residence, Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-21-2 Surveyor Name: JD, CF

Current Property or Structure Name: D. central Farms

Address: 2224 Deep cut Rd

Lat/Long: 42.360043, -88.532340

Primary Use: Ag /Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 4

List Observed Structures: a) residence 1 b) residence 2 c) outbuildings

Residence Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

a) to be demolished  
b) sears catalog home - keeping

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

A - Minimal Traditional B - Cross Gabled, possible Sears home

C -connected pole barns D - garage

Number of photos taken for this property\*: 3

\* Attach Photo log, additional notes and map of resource location.



HA-21-2: 2224 Deep Cut Road – Residence 1



HA-21-2: 2224 Deep Cut Road – Residence 2



HA-21-2: 2224 Deep Cut Road - Outbuilding

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-21-3 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 2416 Deep cut Rd

Lat/Long: 42.361908, -88.531093

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence ~~b) out buildings~~

Residence Detail

Style older ranch

Wall materials aluminum

Roof materials asphalt

Foundation materials

Other distinguishing features  
front overhang

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1961-1965

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features



HA-21-3: 2416 Deep Cut Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-21-4 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 2515 Deep cut Rd

Lat/Long: 42.362845, -88.531278

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence ~~XXXXXXXXXXXX~~ b) outbuildings

Residence Detail

Style older ranch

Wall materials aluminum and brick

Roof materials asphalt

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

Barn Detail

Style \_\_\_\_\_

Wall materials \_\_\_\_\_

Roof materials \_\_\_\_\_

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

Any obvious Additions/Alterations

side addition

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1


\* Attach Photo log, additional notes and map of resource location.

circa 1961-1965



HA-21-4: 2515 Deep Cut Road – Residence

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 22



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-22-1 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 2718 Deep cut Rd

Lat/Long: 42.366159, -88.525206

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style possible remodeled older residence

Wall materials

Roof materials

Foundation materials

Other distinguishing features

obscured by fence but may be remodeled Side Gabled

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1987 assessor date

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features



HA-22-1: 2718 Deep Cut Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-22-2 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 2915 Deep cut Rd

Lat/Long: 42.368545, -88.526253

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 6

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Four square

Wall materials wood

Roof materials asphalt

Foundation materials concrete

Other distinguishing features

pyramid roof

shed roof dormer

Any obvious Additions/Alterations

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - machine shed D - coop E - shed/animal shelter E and F - shed

Number of photos taken for this property\*: 3

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-22-2: 2915 Deep Cut Road - Outbuildings



HA-22-2: 2915 Deep Cut Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-22-3 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 16702 Nelson Rd

Lat/Long: 42.363526, -88.524042

Primary Use: Ag

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 3

List Observed Structures: a) possible residence b) outbuildings

Residence Detail

Style possible converted barn Cape Cod

Wall materials wood siding

Roof materials metal

Foundation materials

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B and C - sheds

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 2009 assessor date, shown in 1872 township map



HA-22-3: 16702 Nelson Road - Residence



HA-22-3: 16702 Nelson Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-22-4 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 16410 Nelson Rd

Lat/Long: 42.363863, -88.517377

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 4

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Cross Gabled

Wall materials wood + vinyl

Roof materials fishscale

Foundation materials field stone

Other distinguishing features

multi-pane windows  
possibly a Queen Anne

Any obvious Additions/Alterations

wide eaves, porch, half-circle window in gable

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - small gabled shed D - gabled outbuilding with concrete foundation

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1892-1908

Barn Detail

Style modern/Gambrel

Wall materials

Roof materials

Foundation materials

Other distinguishing features

either brand new or completely remodeled



HA-22-4: 16410 Nelson Road - Residence



HA-22-4: 16410 Nelson Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-22-5 Surveyor Name: JD, CF

Current Property or Structure Name: McHenry county cemetery

Address: 16387 Nelson Rd

Lat/Long: 42.363446, -88.515902

Primary Use: Cemetery

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: \_\_\_\_\_

Residence Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

stone indicates circa 1864

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.



HA-22-5: 16387 Nelson Road – Cemetery

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-22-6 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 16210 Nelson Rd

Lat/Long: 42.363947, -88.513781

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 2

List Observed Structures: a) residence b) garage

Residence Detail

Style older ranch

Wall materials vinyl and brick

Roof materials asphalt

Foundation materials concrete

Other distinguishing features

attached garage

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - shed

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa1957 assessor date

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features



HA-22-6: 16210 Nelson Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-22-7 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 16212 Nelson Rd

Lat/Long: 42.368178, -88.515421

Primary Use: Ag Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 3

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Farmstead located back from road  
Gabled

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style Obscured

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete stave silo

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-22-7: 16212 Nelson Road – Residence, Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-22-8 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 2205 Hartland Rd

Lat/Long: 42.358319, -88.512416

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style cape cod

Wall materials

Roof materials asphalt

Foundation materials

Other distinguishing features

two gabled dormers, front entry porch  
attached garage with clipped gable roof  
Any obvious Additions/Alterations

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1940 assessor date



HA-22-8: 2205 Hartland Road – Residence

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 23





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number





Copyright 2013 Esri, DeLorme, NAVTEQ, Tom Tom



Township  
Location

**DETAIL:**

**HARTLAND TOWNSHIP  
SECTION 23 - NW 1/4**

0 20 40 80  
Meters

0 80 160 320  
Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-23-1 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 2120 Havland Rd

Lat/Long: 42.357677, -88.510640

Primary Use: Ag /Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 4

List Observed Structures: a) residence b) outbuildings c) outbuildings

Residence Detail

Style ~~XXXXXX~~ Front Gabled

Wall materials

Roof materials

Foundation materials fieldstone

Other distinguishing features  
enclosed porch on side

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - concrete silo C - pole barn D - pyramid roof garage

heavy trees on property obscure buildings

Number of photos taken for this property\*: 3

\* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style Gabled

Wall materials ~~XXXXXX~~ metal

Roof materials metal

Foundation materials

Other distinguishing features



HA-23-1: 2120 Hartland Road - Outbuildings



HA-23-1: 2120 Hartland Road - Residence



HA-23-1: 2120 Hartland Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-23-2 Surveyor Name: JD, EM

Current Property or Structure Name: \_\_\_\_\_

Address: 15918 Nelson Rd Unincorporated Hartland

Lat/Long: 42.363716, -88.508361

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style Front Gabled

Wall materials vinyl

Roof materials

Foundation materials

Other distinguishing features

two chimneys - 1 appears industrial

Any obvious Additions/Alterations

building is remodeled - includes sliding doors

side wing and upper addition accessed via concrete stairs

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date



HA-23-2: 15918 Nelson Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-23-3 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 15913 Nelson Rd , Unincorporated Hartland

Lat/Long: 42.363355, -88.508159

Primary Use: business / commercial

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) building

Residence Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

gabled concrete block industrial building/garage with metal roof

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

no assessor date



HA-23-3: 15913 Nelson Road – Building

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/18 Survey Number: HA-23-4 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 15912 Nelson Rd , Unincorporated Hartland

Lat/Long: 42.363603, -88.508111

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 2

List Observed Structures: a) residence b) garage

Residence Detail

Style Upright and Wing

Wall materials vinyl

Roof materials asphalt

Foundation materials

Other distinguishing features

gabled front entry

Any obvious Additions/Alterations

wing roof extended, new windows

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled garage

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date



HA-23-4: 15912 Nelson Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-23-5 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 15909 Nelson Rd , Unincorporated Hartland

Lat/Long: 42.363240, -88.507770

Primary Use: business / commercial

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) building

Residence Detail

Barn Detail

Style

Style

Wall materials concrete block

Wall materials

Roof materials

Roof materials

Foundation materials

Foundation materials

Other distinguishing features

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Front gabled commercial building - concrete block (or facing?) with some wood and an asphalt roof;  
concrete lintels  
L-shaped addition or extension

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

no assessor date



HA-23-5: 15909 Nelson Road – Building

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-23-6 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 15904 Nelson Rd , Unincorporated Hartland

Lat/Long: 42.363642 , -88.507526

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style partial boom-town ? commercial

Wall materials wood

Roof materials

Foundation materials fieldstone + concrete

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Front gabled commercial building with false/front -Boomtown extension. Wood and vinyl siding and asphalt roof.

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date



HA-23-6: 15904 Nelson Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-23-7 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 15912 Nelson Rd , Unincorporated Hartland

Lat/Long: 42.364025, -88.507188

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style Front Gabled

Wall materials aluminum

Roof materials asphalt

Foundation materials \_\_\_\_\_

Other distinguishing features

enclosed porch

Any obvious Additions/Alterations

wide dormer; front deck

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Barn Detail

Style \_\_\_\_\_

Wall materials \_\_\_\_\_

Roof materials \_\_\_\_\_

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.



HA-23-7: 15912 Nelson Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-23-8 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 15817 Nelson Rd , unincorporated Hartland

Lat/Long: 42.363315 , -88.507070

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: 2

List Observed Structures: a) residence

Residence Detail

Style Front Gabled

Wall materials aluminum

Roof materials asphalt

Foundation materials fieldstone

Other distinguishing features  
enclosed front porch

Any obvious Additions/Alterations

rear deck/railing

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B- garage

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1901 assessor date

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features



HA-23-8: 15817 Nelson Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-23-9 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 15816 Nelson Rd , Unincorporated Hartland

Lat/Long: 42.363678, -88.506904

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 2

List Observed Structures: a) residence b) shed

Residence Detail

Style Front Gabled

Wall materials vinyl

Roof materials asphalt

Foundation materials concrete

Other distinguishing features

enclosed front porch/entry

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

school?

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date



HA-23-9: 15816 Nelson Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-23-10 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: Goddard Rd , Unincorporated Hartland

Lat/Long: 42.364457 , -88.507982

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Barn Detail

Style duplex \* set for demolition style

Wall materials brick Wall materials

Roof materials asphalt Roof materials

Foundation materials Foundation materials

Other distinguishing features Other distinguishing features

built 1918? for Bowman Dairy Superintendent

Any obvious Additions/Alterations

Assistant superintendent

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Hipped roof; full front (split) porch with square support columns

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

no assessor date - circa 1918 as per caretaker



HA-23-10: Goddard Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-23-11 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 15915 Maxwell st, Unincorporated Hartland

Lat/Long: 42.364027, -88.508319

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: \_\_\_\_\_

Residence Detail

Style Side Gabled

Wall materials vinyl

Roof materials asphalt

Foundation materials concrete

Other distinguishing features

rear extension (single story); brick front stoop

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date



HA-23-11: 15915 Maxwell Street – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-23-<sup>12</sup>~~11~~ Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 15920 Nelson Rd, Unincorporated Hartland

Lat/Long: 42.364456, -88.508785

Primary Use: Commercial / Industry

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) Factory

Residence Detail

Style Factory  
Wall materials brick + metal  
Roof materials \_\_\_\_\_  
Foundation materials \_\_\_\_\_  
Other distinguishing features  
Constructed 1918 as Bowman Dairy  
Associated with HA-23-10  
Any obvious Additions/Alterations \_\_\_\_\_

Barn Detail

Style \_\_\_\_\_  
Wall materials \_\_\_\_\_  
Roof materials \_\_\_\_\_  
Foundation materials \_\_\_\_\_  
Other distinguishing features \_\_\_\_\_

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

main section of brick still intact - windows replaced and filled in but brick arches still visible; modern metal additions

Number of photos taken for this property\*: 3

\* Attach Photo log, additional notes and map of resource location.

no assessor date - circa 1918



HA-23-12: 15920 Nelson Road – Factory

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-23-13 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 15712 Nelson Rd

Lat/Long: 42.363942, -88.505320

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 2

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Foursquare

Wall materials wood

Roof materials asphalt

Foundation materials

Other distinguishing features

very plain

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - pyramid roof garage

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.



HA-23-13: 15712 Nelson Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-23-14 Surveyor Name: JD, CF

Current Property or Structure Name: Steeple View Farm

Address: 15210 Nelson Rd

Lat/Long: 42.363726, -88.494090

Primary Use: Ag

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 5

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Side Gabled

Wall materials vinyl

Roof materials asphalt

Foundation materials fieldstone

Other distinguishing features

Interesting mix of styles and components - includes elaborate front entrance and windows at second floor as well as large additions  
Any obvious Additions/Alterations see front entrance

Barn Detail

Style Gabled Livestock

Wall materials

Roof materials asphalt

Foundation materials

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C and D - concrete stave silos      D - small barn or coop

Number of photos taken for this property\*: 5

\* Attach Photo log, additional notes and map of resource location.



HA-23-14: 15210 Nelson Road - Outbuildings



HA-23-14: 15210 Nelson Road - Residence



HA-23-14: 15210 Nelson Road - Entrance

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 24





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-24-1 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 32225 Nelson Rd

Lat/Long: 42.361153, -88.485235

Primary Use: Ag

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) shed

Residence Detail

Style demolished

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style demolished

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

metal shed/coop/storage

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-24-1: 32225 Nelson Road – Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-24-2 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 2717 West Rd

Lat/Long: 42.365733, -88.485102

Primary Use: Ag /Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 2

List Observed Structures: a) residence

Residence Detail

Style Greek Revival

Wall materials board

Roof materials asphalt

Foundation materials fieldstone / concrete

Other distinguishing features

cornice returns and wide window hood on Gable end

Any obvious Additions/Alterations

enclosed front porch - early 20th C

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

also includes small modern shed

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features



HA-24-2: 2717 West Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-24-3 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 2809 West Rd

Lat/Long: 42.366748, -88.485976

Primary Use: Residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style Ranch

Wall materials

Roof materials asphalt

Foundation materials concrete

Other distinguishing features

wide chimney at rear

Any obvious Additions/Alterations

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1957 assessor date



HA-24-3: 2809 West Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-24-4 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 14505 Nelson Rd

Lat/Long: 42. 365457 , -88. 480198

Primary Use: Ag

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) silo

Residence Detail

Style demolished

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style demolished

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

concrete silo with domed roof

Number of photos taken for this property\*: 1


\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-24-4: 14505 Nelson Road – Silo


MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 25



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom




Township  
Location



**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-25-1 Surveyor Name: JD, CF

Current Property or Structure Name: Falcon Waste & Recycling

Address: 1258 North Rose Farm Rd

Lat/Long: 42.344518, -88.488403

Primary Use: Industrial / Commercial

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 4

List Observed Structures: a) smoke stack b) Quonset

Residence Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

A - concrete smokestack B - gabled garage C - concrete block quonset D - Quonset/hoop house with concrete base and plastic cover

Number of photos taken for this property\*: 3

\* Attach Photo log, additional notes and map of resource location.

circa 1961-1965



HA-25-1: 1258 North Rose Farm Road – Buildings,  
Quonset



HA-25-1: 1258 North Rose Farm Road – Smokestack,  
Buildings

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 26



Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet





Copyright 2013 Esri, DeLorme, NAVTEQ, Tom Tom



Township  
Location

**DETAIL:**

**HARTLAND TOWNSHIP  
SECTION 26 - SE 1/4**

0 30 60 120  
Meters

0 115 230 460  
Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-26-81 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 1505 Antuna Blvd

Lat/Long: 42.348005, -88.495385

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: residence

Residence Detail

Style Ranch

Wall materials aluminum

Roof materials asphalt

Foundation materials concrete

Other distinguishing features

flat pyramid roof; attached garage

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1961 assessor date



HA-26-1: 1505 Antuna Boulevard – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-26-92 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 1417 Antona Blvd

Lat/Long: 42.347418, -88.495366

Primary Use: Residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: Residence

Residence Detail

Style Ranch

Wall materials

Roof materials asphalt

Foundation materials

Other distinguishing features  
attached garage

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1962 assessor date

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features



HA-26-2: 1417 Antuna Boulevard – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-26-~~MX~~3 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 1501 Rose Farm Rd

Lat/Long: 42.347736, -88.492250

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: residence

\_\_\_\_\_

Residence Detail

Style Ranch

Wall materials vertical board and aluminum

Roof materials asphalt

Foundation materials

Other distinguishing features

very wide roof overhang; attached garage

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1960 assessor date



HA-26-3: 1501 Rose Farm Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-26-~~XX~~4 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 1413 Rose Farm Rd

Lat/Long: 42.347121, -88.492267

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: Residence

Residence Detail

Style Ranch

Wall materials

Roof materials asphalt

Foundation materials

Other distinguishing features

2 sections including attached garage

rooftop vent

Any obvious Additions/Alterations

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1957/1981 assessor date



HA-26-4: 1413 Rose Farm Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-26-185 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 1401 Rose Farm Rd

Lat/Long: 42.346325, -88.492291

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: residence

Residence Detail

Style Ranch

Wall materials aluminum

Roof materials asphalt

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

Barn Detail

Style \_\_\_\_\_

Wall materials \_\_\_\_\_

Roof materials \_\_\_\_\_

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

Any obvious Additions/Alterations \_\_\_\_\_

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1958 assessor date



HA-26-5: 1401 Rose Farm Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-26-196 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 1317 Rose Farm Rd

Lat/Long: 42.346035, -88.492315

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: residence

Residence Detail

Style Ranch

Wall materials aluminum

Roof materials asphalt

Foundation materials \_\_\_\_\_

Other distinguishing features  
attached garage

wide front chimney

Any obvious Additions/Alterations \_\_\_\_\_

Barn Detail

Style \_\_\_\_\_

Wall materials \_\_\_\_\_

Roof materials \_\_\_\_\_

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1961-1965



HA-26-6: 1317 Rose Farm Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-26-2017 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 1313 Rose Farm Rd

Lat/Long: 42.345720, -88.492309

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: residence

Residence Detail

Style Ranch

Wall materials vinyl

Roof materials asphalt

Foundation materials

Other distinguishing features

L - shaped  
wide front chimney

Any obvious Additions/Alterations

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1965 assessor date



HA-26-7: 1313 Rose Farm Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-26-~~218~~ Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 1309 Rose Farm Rd

Lat/Long: 42.345430, -88.492307

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: residence

Residence Detail

Style Ranch

Wall materials vinyl

Roof materials

Foundation materials

Other distinguishing features  
attached garage

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1953 assessor date

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features



HA-26-8: 1309 Rose Farm Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-26-~~22~~ Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 1103 Rose Farm Rd

Lat/Long: 42.342023, -88.492333

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: 2

List Observed Structures: residence

Residence Detail

Style Minimal Traditional

Wall materials

Roof materials asphalt

Foundation materials concrete

Other distinguishing features  
small gable over bay window

Any obvious Additions/Alterations  
front deck

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - -garage

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1957 assessor date

Barn Detail

Style

Wall materials

Roof materials


Foundation materials

Other distinguishing features



HA-26-9: 1103 Rose Farm Road – Residence

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 27



Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-27-1 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 1217 Hartland Rd

Lat/Long: 42.344942, -88.511708

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence b) garage

Residence Detail

Style cape cod Minimal Traditional

Wall materials aluminum

Roof materials asphalt

Foundation materials

Other distinguishing features

front center gable

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - garage

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1954 assessor date



HA-27-1: 1217 Hartland Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-22-2 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 1309 Hartland Rd

Lat/Long: 42.345824, -88.511645

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Greek Revival/T Plan

Wall materials wood

Roof materials asphalt

Foundation materials fieldstone

Other distinguishing features

Any obvious Additions/Alterations

owner claims the property is "237 years old"  
(obviously owner is wrong)

Barn Detail

Style Gabled

Wall materials wood

Roof materials

Foundation materials

Other distinguishing features  
may be L-Pan but obscured

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete stave soiklo D - dilapidated outbuilding/barn

Number of photos taken for this property\*: 4

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-27-2: 1309 Hartland Road - Outbuildings



HA-27-2: 1309 Hartland Road - Residence



HA-27-2: 1309 Hartland Road - Outbuilding

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-27-3 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 1907 Hartland Rd

Lat/Long: 42.353315, -88.511870

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 3

List Observed Structures: a) residence b) metal shed

Residence Detail

Style four-square

Wall materials aluminum

Roof materials

Foundation materials

Other distinguishing features

obscured by trees

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - shed C - garage

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style

Wall materials

Roof materials


Foundation materials

Other distinguishing features



HA-27-3: 1907 Hartland Road – Residence, Shed

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 28





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-28-1 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 17422 U.S. 14

Lat/Long: 42.345606, -88.540199

Primary Use: Ag /Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 8

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Ranch

Wall materials brick and vinyl

Roof materials asphalt

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

Barn Detail

Style \_\_\_\_\_

Wall materials \_\_\_\_\_

Roof materials \_\_\_\_\_

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

Any obvious Additions/Alterations \_\_\_\_\_

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - garage C and D - pole buildings E - grain elevator complex F GH - gabled sheds

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1967 assessor date



HA-28-1: 17422 U.S. 14 – Outbuildings



HA-28-1: 17422 U.S. 14 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-28-2 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 17421 U.S. 14

Lat/Long: 42.344508, -88.540124

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style Minimal Traditional/single story Cross gable

Wall materials board

Roof materials asphalt

Foundation materials

Other distinguishing features

front gable extension  
attachyed garage

Any obvious Additions/Alterations

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1961-1965



HA-28-2: 17421 U.S. 14 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-28-3 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 17817 U.S. 14

Lat/Long: 42.348343, -88.546263

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style Greek Revival

Wall materials brick

Roof materials asphalt

Foundation materials

Other distinguishing features

elaborate door surrounds and wide lintels over windows; multi-pane windows  
pronounced cornice; detail in gable - obscured

Any obvious Additions/Alterations

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-28-3: 17817 U.S. 14 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-28-4 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 1905 Deep cut Rd

Lat/Long: 42.355347, -88.542648

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 4

List Observed Structures: a) residence b) barn c) outbuilding

Residence Detail

Style Ranch  
Wall materials asbestos or aluminum  
Roof materials asphalt  
Foundation materials \_\_\_\_\_  
Other distinguishing features \_\_\_\_\_

Barn Detail

Style Round Roof livestock barn  
Wall materials \_\_\_\_\_  
Roof materials asphalt  
Foundation materials \_\_\_\_\_  
Other distinguishing features \_\_\_\_\_

Any obvious Additions/Alterations \_\_\_\_\_

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete silo D - timber and metal machine shed

Number of photos taken for this property\*: 3

\* Attach Photo log, additional notes and map of resource location.

circa 1961-1965



HA-28-4: 1905 Deep Cut Road – Residence, Silo,  
Outbuilding



HA-28-4: 1905 Deep Cut Road – Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/18 Survey Number: HA-28-5 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 17221 U.S. 14

Lat/Long: 42.342216, -88.535032

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 3

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Bungalow

Wall materials board ?

Roof materials asphalt

Foundation materials

Other distinguishing features  
gabled dormer and addition

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - machine shed/shop C - carport/shelter

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features



HA-28-5: 17221 U.S. 14 – Residence, Outbuildings

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 29



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



0 125 250 500 Meters

0 375 750 1,500 Feet

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-29-1 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 1202 Brookdale Rd

Lat/Long: 42.344188, -88.569436

Primary Use: Ag /Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 6

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Upright and Wing  
Wall materials vinyl and aluminum  
Roof materials asphalt  
Foundation materials \_\_\_\_\_  
Other distinguishing features \_\_\_\_\_

Barn Detail

Style \_\_\_\_\_  
Wall materials \_\_\_\_\_  
Roof materials \_\_\_\_\_  
Foundation materials \_\_\_\_\_  
Other distinguishing features \_\_\_\_\_

Any obvious Additions/Alterations Under renovation

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B and C - concrete silos D - shed roofed building E and F - sheds

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-29-1: 1202 Brookdale Road – Outbuildings



HA-29-1: 1202 Brookdale Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/25/15 Survey Number: HA-29-2 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 18804 Dunham Rd

Lat/Long: 42.342458, -88.564218

Primary Use: Ag /Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 3

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Cape Cod

Wall materials aluminum

Roof materials asphalt

Foundation materials concrete

Other distinguishing features  
gabled front porch

sidelights

Any obvious Additions/Alterations

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small shed C - pole building

Number of photos taken for this property\*: 1


\* Attach Photo log, additional notes and map of resource location.

circa 1872-1892



HA-29-2: 18804 Dunham Road – Residence

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 30





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-30-1 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 1919 Brookdale Rd

Lat/Long: 42.353506, -88.570194

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: 2

List Observed Structures: a) residence

Residence Detail

Style Front gabled  
Wall materials aluminum  
Roof materials asphalt  
Foundation materials \_\_\_\_\_  
Other distinguishing features modern picture window

Barn Detail

Style \_\_\_\_\_  
Wall materials \_\_\_\_\_  
Roof materials \_\_\_\_\_  
Foundation materials \_\_\_\_\_  
Other distinguishing features \_\_\_\_\_

Any obvious Additions/Alterations \_\_\_\_\_

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled single bay garage shown as a school in 1892

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1872-1892



HA-30-1: 1919 Brookdale Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-30-2 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 1219 Brookdale Rd

Lat/Long: 42.345331, -88.570923

Primary Use: Ag /Rea \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence b) barn

Residence Detail

Style Upright and Wing

Wall materials vinyl

Roof materials asphalt

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

Barn Detail

Style modern

Wall materials \_\_\_\_\_

Roof materials \_\_\_\_\_

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

Any obvious Additions/Alterations

addition to wing second story; front porch redone

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - modern outbuilding

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-30-2: 1219 Brookdale Road – Residence, Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-30-43 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 1414 Menage Rd

Lat/Long: 42.347933, -88.588352

Primary Use: Ag /Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 4

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style gabled ell

Wall materials

Roof materials asphalt

Foundation materials

Other distinguishing features

house has been remodeled and includes several new parts

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B and C - pole buildings D - concrete stave silo

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872-1892

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features



HA-30-3: 1414 Menge Road – Residence



HA-30-3: 1414 Menge Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-30-~~164~~ Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 19817 Bunker Hill Rd

Lat/Long: 42.356002, -88.584949

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single:  Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence b) silo

Residence Detail

Style gabled ell

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

attached garage

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - silo

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-30-4: 19817 Bunker Hill Road – Residence, Silo

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-30-75 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 19213 Bunker Hill Rd

Lat/Long: 42.356263, -88.572086

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style Ranch

Wall materials

Roof materials

Foundation materials

Other distinguishing features

small covered entry

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

circa 1965 assessor date

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features



HA-30-5: 19213 Bunker Hill Road – Residence

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 31





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 2/4/15 Survey Number: HA-31-1 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 19802 Bauman Rd

Lat/Long: 42.331589, -88.583673

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 9

List Observed Structures: a) residence b) barn c) outbuildings

Residence Detail

Style Ranch

Wall materials aluminum

Roof materials asphalt

Foundation materials concrete

Other distinguishing features

concrete steps to front door

Barn Detail

Style Gabled hay barn/English Three bay

Wall materials board

Roof materials

Foundation materials

Other distinguishing features

attached extensions/milkhouse

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - garden shed D - coop E - metal grain bin F - concrete stave silo G - timber shed H - pole building

I - machine shed

Number of photos taken for this property\*: 5

\* Attach Photo log, additional notes and map of resource location.

circa 1954 assessor date



HA-31-1: 19802 Bauman Road - Outbuildings



HA-31-1: 19802 Bauman Road – Barn, Silo



HA-31-1: 19802 Bauman Road - Outbuildings



HA-31-1: 19802 Bauman Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-31-2 Surveyor Name: JD, CE

Current Property or Structure Name: \_\_\_\_\_

Address: 19810 Banman Rd

Lat/Long: 42.331627, -88.584140

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style older ranch?

Wall materials vertical board

Roof materials asphalt

Foundation materials concrete

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1988 assessor date



HA-31-2: 19810 Bauman Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-31-3 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 802 Menge Rd

Lat/Long: 42.338128, -88.587859

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 5

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style gabled ell

Wall materials

Roof materials asphalt

Foundation materials

Other distinguishing features

Barn Detail

Style Gambrel

Wall materials wood

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

rebuilt wrap around porch

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - small Gambrel barn with shed addition D - concrete block and wood machine shed E - metal and wood building

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1941-1951 assessor date




HA-31-3: 802 Menge Road – Residence



HA-31-3: 802 Menge Road – Outbuildings


MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 32



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom




Township  
Location



**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-32-1 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 18803 Dunham Rd

Lat/Long: 42.341924, -88.564106

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 9

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Ranch

Wall materials brick

Roof materials asphalt

Foundation materials concrete

Other distinguishing features

L-shape; glass block window in garage; attached garage

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete silo D - small concrete silo F - round roof shed GHI - grain bins

Number of photos taken for this property\*: 3

\* Attach Photo log, additional notes and map of resource location.

circa 1967 assessor date, shown in 1872 township map

Barn Detail

Style Round roof

Wall materials

Roof materials asphalt

Foundation materials

Other distinguishing features

side entry?; attached milkhouse



HA-32-1: 18803 Dunham Road - Residence



HA-32-1: 18803 Dunham Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-32-2 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 709 McKinstry Rd

Lat/Long: 42.337533, -88.555970

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style side-gabled

Wall materials vinyl

Roof materials asphalt

Foundation materials possible brick?

Other distinguishing features

enclosed front porch with centered gable

Any obvious Additions/Alterations

possible I House with later porch

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

outbuildings out of view

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features



HA-32-2: 709 McKinstry Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-32-3 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 603 McKinstry Rd

Lat/Long: 42.335269, -88.555844

Primary Use: Ag /Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 12

List Observed Structures: a) residence #1 b) barn c) outbuildings  
d) outbuildings e) residence #2

Residence Detail

Style residence #1 - Greek revival

Wall materials board

Roof materials asphalt

Foundation materials limestone

Other distinguishing features

Italianate details including window hoods and triple ogee window in gable pilasters; centered gabled dormer on wing

Any obvious Additions/Alterations

Barn Detail

Style Gabled livestock

Wall materials metal ?

Roof materials asphalt

Foundation materials

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - round roof crib building D - gabled machine shed E - small shed FGH - concrete silos

I - small gabled barn J - pole building K - windmill base L - Residence 2, small single story side gabled

Number of photos taken for this property\*: 6

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-32-3: 603 McKinstry Road - Outbuildings



HA-32-3: 603 McKinstry Road – Residence 2



HA-32-3: 603 McKinstry Road - Barn



HA-32-3: 603 McKinstry Road – Residence 1



HA-32-3: 603 McKinstry Road - Outbuildings



HA-32-3: 603 McKinstry Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-32-4 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: McKinstry Rd

Lat/Long: 42.331477, -88.556242

Primary Use: Ag

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 5

List Observed Structures: a) outbuildings

Residence Detail

Style demolished?

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style Gabled hay barn

Wall materials

Roof materials metal

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - Gambrel roof crib C - metal shed D - small metal silo

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-32-4: McKinstry Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-32-5 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 108 McKinstry Rd

Lat/Long: 42.327098, -88.553858

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 7

List Observed Structures: a) residence b) barn c) outbuildings

Residence Detail

Style Ranch

Wall materials

Roof materials asphalt

Foundation materials

Other distinguishing features

wide covered front porch

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - long barn D - round roof crib E and F - concrete silos G - pole building

Number of photos taken for this property\*: 4

\* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style Gabled Hay barn

Wall materials wood + vinyl

Roof materials asphalt

Foundation materials

Other distinguishing features



HA-32-5: 108 McKinstry Road - Residence



HA-32-5: 108 McKinstry Road - Barn



HA-32-5: 108 McKinstry Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-32-6 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 612 Brookdale Rd

Lat/Long: 42.335427, -88.569118

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 10

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Gabled El

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style Gambrel

Wall materials

Roof materials asphalt

Foundation materials

Other distinguishing features

shed addition to one side

Any obvious Additions/Alterations

El addition?

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C and D - concrete silos E - shed F - garage G - shed H - pole building G and H - trailers

Number of photos taken for this property\*: 3

\* Attach Photo log, additional notes and map of resource location.

circa 1872-1892



HA-32-6: 612 Brookdale Road - Outbuildings




HA-32-6: 612 Brookdale Road - Residence



HA-32-6: 612 Brookdale Road - Outbuildings

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 33





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-33-1 Surveyor Name: JD, CF

Current Property or Structure Name: Old Rivers Inn

Address: 17112 U.S. 14

Lat/Long: 42.341797, -88.531778

Primary Use: Bar

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) road house

Residence Detail

Style road house  
Wall materials board and aluminum  
Roof materials \_\_\_\_\_  
Foundation materials \_\_\_\_\_  
Other distinguishing features \_\_\_\_\_

Barn Detail

Style \_\_\_\_\_  
Wall materials \_\_\_\_\_  
Roof materials \_\_\_\_\_  
Foundation materials \_\_\_\_\_  
Other distinguishing features \_\_\_\_\_

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

many additions /alterations to original structure

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1872-1892



HA-33-1: 17112 U.S. 14 – Road House Bar

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-33-2 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 917 Dimmel Rd

Lat/Long: 42.340887, -88.531182

Primary Use: Ag

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 3

List Observed Structures: a) residence b) outbuilding

Residence Detail

Style gabled ex Greek Revival

Wall materials board

Roof materials asphalt

Foundation materials

Other distinguishing features  
enclosed front porch

Any obvious Additions/Alterations

shed roof dormer with ribbon windows

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - pole barn C - concrete silo

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features



HA-33-2: 917 Dimmel Road – Residence, Outbuilding

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-33-3 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 407 Dimmel Rd

Lat/Long: 42.333924, -88.531152

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style gabled ell  
Wall materials \_\_\_\_\_  
Roof materials asphalt  
Foundation materials limestone  
Other distinguishing features  
dentils across front porch and gable

Barn Detail

Style \_\_\_\_\_  
Wall materials \_\_\_\_\_  
Roof materials \_\_\_\_\_  
Foundation materials \_\_\_\_\_  
Other distinguishing features \_\_\_\_\_

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - shed

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-33-3: 407 Dimmel Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-33-4 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 213 Dimmel Rd

Lat/Long: 42.330816, -88.531196

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 5

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Bungalow

Wall materials aluminum/vinyl

Roof materials asphalt

Foundation materials concrete

Other distinguishing features

gabled dormer

Any obvious Additions/Alterations  
extensions to rear

Black tile outbuildings

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - small shed D - windmill base E - machine shed

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872-1892

Barn Detail

Style Gabled

Wall materials bloxk

Roof materials

Foundation materials

Other distinguishing features

gable end garage door




HA-33-4: 213 Dimmel Road - Residence



HA-33-4: 213 Dimmel Road - Outbuildings

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 34





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-34-1 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 802 Dimmel Rd

Lat/Long: 42.338105, -88.530357

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 8

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Greek Revival/Gabled El

Wall materials vinyl

Roof materials asphalt

Foundation materials fieldstone

Other distinguishing features

Barn Detail

Style Gabled with side extensions

Wall materials board

Roof materials metal

Foundation materials concrete

Other distinguishing features

Any obvious Additions/Alterations

rear extension

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C and D - concrete silos E - Gabled barn with extension F - garage G - shed H - large modern pole building

Number of photos taken for this property\*: 3

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-34-1: 802 Dimmel Road - Outbuildings



HA-34-1: 802 Dimmel Road - Outbuildings



HA-34-1: 802 Dimmel Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-34-2 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 16915 U.S. 14

Lat/Long: 42.340388, -88.528327

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 3

List Observed Structures: a) residence #1 b) residence #2  
c) residence #3

Residence Detail

Style Ranch

Wall materials

Roof materials asphalt

Foundation materials

Other distinguishing features

L-shaped

Any obvious Additions/Alterations

Barn Detail

Style Gambrel

Wall materials

Roof materials

Foundation materials

Other distinguishing features

used as a garage

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - square building with square entry way and windows on either side - could be commercial

Number of photos taken for this property\*: 2 \* photo #5 missing

\* Attach Photo log, additional notes and map of resource location.

circa 1958



HA-34-2: 16915 U.S 14 – Residence 1



HA-34-2: 16915 U.S 14 – Residence 3, Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-34-3 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 16806 U.S. 14

Lat/Long: 42.340696, -88.524968

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 4

List Observed Structures: a) residence b) barn

Residence Detail

Style gabled ell  
Wall materials aluminum  
Roof materials asphalt  
Foundation materials fieldstone  
Other distinguishing features

Barn Detail

Style Gabled Raised barn  
Wall materials asbestos  
Roof materials asphalt  
Foundation materials fieldstone  
Other distinguishing features

Any obvious Additions/Alterations

shutters; front porch

posts replaced

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete stave silo D - garage

Number of photos taken for this property\*: 3

\* Attach Photo log, additional notes and map of resource location.

circa 1850 assessor date



HA-34-3: 16806 U.S 14 - Outbuildings



HA-34-3: 16806 U.S 14 - Residence



HA-34-3: 16806 U.S 14 – Outbuildings, Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-34-4 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 1670Z U.S. 14

Lat/Long: 42.340995, -88.523069

Primary Use: Residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) Residence

Residence Detail

Style view obstructed by trees

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1974 assessor date



HA-34-4: 16702 U.S 14 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-34-5 Surveyor Name: JD, CF

Current Property or Structure Name: Oney's Tree Farm

Address: 16608 U.S. 14

Lat/Long: 42.340486, -88.521873

Primary Use: residence, commercial

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 4

List Observed Structures: a) residence b) barn

Residence Detail

Style gabled ell Gothic

Wall materials board

Roof materials asphalt

Foundation materials fieldstone

Other distinguishing features

lattice trusses in gable ends

bay window

Any obvious Additions/Alterations

Barn Detail

Style Gambrel raised barn

Wall materials wood

Roof materials metal

Foundation materials fieldstone

Other distinguishing features

steeply pitched dormers

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - garage C - pole building

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1840 assessor date



HA-34-5: 16608 U.S 14 – Residence



HA-34-5: 16608 U.S 14 – Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-34-6 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 16220 U.S. 14

Lat/Long: 42.339477, -88.515895

Primary Use: Ag

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 3

List Observed Structures: a) residence #1 b) residence #2

Residence Detail

Style Side gabled

Wall materials

Roof materials asphalt

Foundation materials fieldstone

Other distinguishing features

simple 1 1/2 story

possibly Hall and Parlor  
Any obvious Additions/Alterations

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - Res 2, Cross gabled 2 story w/ aluminum siding and asphalt roof - possibly attached garage

C - shed/garage

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-34-6: 16220 U.S 14 – Residence 1



HA-34-6: 16220 U.S 14 – Residence 2

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-34-7 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 415 Hughes Rd

Lat/Long: 42.333273, -88.511769

Primary Use: Ag /Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 3

List Observed Structures: a) residence # 1 b) residence #2

Residence Detail

Style Queen Anne

Wall materials aluminum

Roof materials asphalt

Foundation materials fieldstone

Other distinguishing features  
cross gable dormers

enclosed front porch  
Any obvious Additions/Alterations

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - Res 2, Bungalow w/ cross gabled dormers, enclosed front porch

C - garage

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1900/1936 assessor date, shown in 1872 township map




HA-34-7: 415 Hughes Road – Residence 1



HA-34-7: 415 Hughes Road – Residence 2

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 35




Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-35-1 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 206 Hughes Rd

Lat/Long: 42.329478, -88.510965

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 5

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style Queen Anne

Wall materials

Roof materials asphalt

Foundation materials fieldstone

Other distinguishing features

wrap around porch

Any obvious Additions/Alterations

attached garage

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - grain elevator complex D - large machine shed E - small garage/machine shed

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style Gabled hay barn

Wall materials vinyl

Roof materials

Foundation materials

Other distinguishing features

modern addition



HA-35-1: 206 Hughes Road – Residence, Outbuildings



HA-35-1: 206 Hughes Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-35-2 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 415 Hughes Rd

Lat/Long: 42.333270, -88.811127

Primary Use: Ag

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 10

List Observed Structures: a) barn

Residence Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style Gambrel Raised barn

Wall materials wood

Roof materials metal

Foundation materials fieldstone

Other distinguishing features

L-Plan

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Associated with HA-34-7

B - Harvestore silo C and D - concrete silos E-H - metal grain bins I - pole building J - gabled shed

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-35-2: 415 Hughes Road – Outbuildings



HA-35-2: 415 Hughes Road – Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-35-3 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 15914 U.S. 14

Lat/Long: 42.338380, -88.509010

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 6

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style modern No style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style Gambrel hay barn

Wall materials wood

Roof materials asphalt

Foundation materials concrete

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - small shed D - shed E - concrete silo F - metal barn

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1930/2001 assessor date, shown in 1872 township map



HA-35-3: 15914 U.S 14 – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-35-4 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 15910 U.S. 14

Lat/Long: 42.339246, -88.508452

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: 2

List Observed Structures: a) residence

Residence Detail

Style Front Gabled

Wall materials board

Roof materials asphalt

Foundation materials concrete

Other distinguishing features \_\_\_\_\_

Barn Detail

Style \_\_\_\_\_

Wall materials \_\_\_\_\_

Roof materials \_\_\_\_\_

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

Any obvious Additions/Alterations \_\_\_\_\_

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - garage shown as a school in 1872

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-35-4: 15910 U.S 14 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-35-5 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 15815 U.S. 14

Lat/Long: 42.338572, -88.506963

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence b) dug-out garage

Residence Detail

Style Gabled

Wall materials asbestos

Roof materials \_\_\_\_\_

Foundation materials \_\_\_\_\_

Other distinguishing features \_\_\_\_\_

May be front or side Gabled - hard to tell from right of way

Any obvious Additions/Alterations \_\_\_\_\_

modern windows

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - underground garage

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-35-5: 15815 U.S. 14 – Residence



HA-35-5: 15815 U.S. 14 – Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-35-6 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 15706 U.S. 14

Lat/Long: 42.340548, -88.504717

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: 3

List Observed Structures: a) residence

Residence Detail

Style Gabled El

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations  
enclosed front porch; windows

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - shed C - garage

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-35-6: 15706 U.S 14 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-35-7 Surveyor Name: JO, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 15357 U.S. 14

Lat/Long: 42.338087, -88.497526

Primary Use: ~~Ag~~ Res

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: 2

List Observed Structures: a) Residence

Residence Detail

Style four-square

Wall materials vinyl

Roof materials

Foundation materials

Other distinguishing features

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Any obvious Additions/Alterations

new windows

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - garage

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-35-7: 15357 U.S 14 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-35-8 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 1521a U.S. 14

Lat/Long: 42.338025, -88.496295

Primary Use: Residence Ag<sup>/Res</sup>

Is this a record of a single structure or group (give total number of structures):

Single:  Group:  Number Structures in Group: 2

List Observed Structures: a) residence b) outbuildings

Residence Detail

Style colonial revival  
Wall materials  
Roof materials asphalt  
Foundation materials  
Other distinguishing features  
gabled entry porch; decorative door trim

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - garage

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1946 assessor date

Barn Detail

Style  
Wall materials  
Roof materials  
Foundation materials  
Other distinguishing features



HA-35-8: 15219 U.S 14 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-35-~~10X9~~ Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 511 Rose Farm Rd

Lat/Long: 42.333457, -88.493052

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 2

List Observed Structures: a) residence b) garage

Residence Detail

Style Minimal Traditional

Wall materials

Roof materials asphalt

Foundation materials

Other distinguishing features

attached garage

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - large garage

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1945 assessor date

Barn Detail

Style

Wall materials

Roof materials


Foundation materials

Other distinguishing features



HA-35-9: 511 Rose Farm Road – Residence, Garage

MCHENRY COUNTY  
HARTLAND TOWNSHIP  
SECTION 36





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- HA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-36-21 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 14513 Washington St

Lat/Long: 42.336140, -88.480201

Primary Use: Ag

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 2

List Observed Structures: a) residence b) barn

Residence Detail

Style Side Gabled ?

Wall materials variable

Roof materials

Foundation materials fieldstone

Other distinguishing features  
lots of remodeling

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

property somewhat obscured

C - shed

Number of photos taken for this property\*: 2

\* Attach Photo log, additional notes and map of resource location.

circa1872



HA-36-1: 14513 Washington Street – Residence



HA-36-1: 14513 Washington Street – Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15 Survey Number: HA-36-82 Surveyor Name: JD, CF

Current Property or Structure Name: \_\_\_\_\_

Address: 14419 Washington St.

Lat/Long: 42.335492, -88.478833

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single:  Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: a) residence

Residence Detail

Style Foursquare

Wall materials aluminum

Roof materials

Foundation materials fieldstone

Other distinguishing features

full front porch

Any obvious Additions/Alterations

modern iron porch supports

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Barn Detail

Style

Wall materials

Roof materials

Foundation materials

Other distinguishing features

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1872



HA-36-2: 14419 Washington Street – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/18 Survey Number: HA-36-43 Surveyor Name: JD, CF

Current Property or Structure Name: Mrs Organic Farm

Address: 14101 Washington St.

Lat/Long: 42.331734, -88.472693

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: 2

List Observed Structures: a) residence b) outbuilding

Residence Detail

Style Gabled  
Wall materials asbestos  
Roof materials \_\_\_\_\_  
Foundation materials \_\_\_\_\_  
Other distinguishing features  
fron porch addition/enclosed

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - garage

Number of photos taken for this property\*: 1

\* Attach Photo log, additional notes and map of resource location.

circa 1934 assessor date

Barn Detail

Style \_\_\_\_\_  
Wall materials \_\_\_\_\_  
Roof materials \_\_\_\_\_  
Foundation materials \_\_\_\_\_  
Other distinguishing features \_\_\_\_\_



HA-36-3: 14101 Washington Street – Residence,  
Outbuilding