

McHenry County



Illinois


McHenry County - Townships

Chemung Township

0 1 2 4 6 8 Miles

0 5 10 Kilometers





McHenry County



Illinois

Township Key

Chemung	Alden	Hebron	
Dunham	Hartland		
Marengo	Seneca		
Riley	Not Included in Survey		

Hebron Township

T46N, R7E

0 0.5 1 2 Miles

0 0.5 1 2 Kilometers



MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 1



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15 Survey Number: HE-1-1 Surveyor Name: J Davis

Current Property or Structure Name: _____

Address: 8404 Burgett Road

Lat/Long: 42.486967/-88.361108

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 9

List Observed Structures: (A) Res 1 (B) Res 2 (C) Barn (D) Barn (E and F) silos (G) barn (H) pole barn (I) garage

Residence Detail (Residence 1)

Barn Detail

Style: Gabled EI

Style: Wide Gabled

Wall materials: aluminum

Wall materials: metal and wood

Roof materials: asphalt

Roof materials: metal

Foundation materials: fieldstone

Foundation materials:

Other distinguishing features
two front entries (duplex?)
multiple rooflines/levels
rear expansion

Other distinguishing features
Side pent roof

Any obvious Additions/Alterations
some new windows

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - Res 2 - Ranch w/stone facing and vinyl siding D - metal gabled Dairy Barn

E and F- concrete stave silos G - Gabled Hay barn w/ metal siding H - mod pole bldg I - garage

Number of photos taken for this property*: 6

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870

Ranch C. 1970



HE-1-1: 8404 Burgett Road – Barns, Silos



HE-1-1: 8404 Burgett Road – Barn, Pole Barn




HE-1-1: 8404 Burgett Road – Residence 1



HE-1-1: 8404 Burgett Road – Residence 2

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 2





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15 Survey Number: HE-2-1 Surveyor Name: J

Davis Current Property or Structure Name: _____

Address: 9802 Burgett Road

Lat/Long: 42.487059/-88.387926

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 10

List Observed Structures: (A) Res (B) Barn (C) Barn (D) shed (E and F) silos (G) grain silo

(H-J) sheds

Residence Detail

Style: Gabled EI

Wall materials: aluminum

Roof materials: asphalt

Foundation materials:

Other distinguishing features

gabled dormer

no streetside entrance

Any obvious Additions/Alterations

Barn Detail

Style: Gambrel Roof

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features

multi-pane windows

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C- EI shaped Gabled barn/shop D - timber gabled shed E and F - concrete stave silos G - metal grain silo

H-J - gabled sheds

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870



HE-2-1: 9802 Burgett Road – Barns, Sheds, Silos



HE-2-1: 9802 Burgett Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15 Survey Number: HE-2-2 Surveyor Name: J Davis

Current Property or Structure Name: _____

Address: 10012 Burgett Road

Lat/Long: 42.486944/-88.393054

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 4

List Observed Structures: (A)Res (B-D) sheds

Residence Detail

Style: Gabled

Wall materials: vinyl and vertical board

Roof materials: asphalt

Foundation materials:

Other distinguishing features
octagon window

Any obvious Additions/Alterations
one story addition/front porch

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B-D - gabled metal sheds/pole buildings

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870 with modern outbuildings

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-2-2: 10012 Burgett Road – Residence



HE-2-2: 10012 Burgett Road – Sheds

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 3



Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15 Survey Number: HE-3-1 Surveyor Name: J Davis

Current Property or Structure Name: Button Farm

Address: 10309 Button Road

Lat/Long: 42.489228/-88.398326

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 7

List Observed Structures: (A)Res (B) Barn (C) machine shed (D) silo

(E) shed (F) garage (G) metal silo

Residence Detail

Style: Gabled

Wall materials: vinyl

Roof materials: metal

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations
extension off side/4 season space
large wooden deck

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - gabled metal barn/machine shed D - concrete stave silo E - small gabled shed F - gabled garage

G - metal grain bin

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870

Barn Detail

Style: Gabled Hay barn

Wall materials: board

Roof materials: metal

Foundation materials: concrete
block

Other distinguishing features
attached long gabled section



HE-3-1: 10309 Button Road – Residence



HE-3-1: 10309 Button Road – Barn, Shed, Silos

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15 Survey Number: HE-3-2 Surveyor Name: J Davis

Current Property or Structure Name: _____

Address: 10712 Button Road

Lat/Long: 42.490800/-88.405932

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A)Res (B) Quonset

Residence Detail

Style: Gabled

Wall materials: board (cedar?)

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - Quonset hut

Number of photos taken for this property*: 2


* Attach Photo log, additional notes and map of resource location.

C. 1860-1870



HE-3-2: 10712 Button Road – Residence

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 4



Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15_____ Survey Number: HE-4-1

Surveyor Name: J. Davis, E. Maher

Current Property or Structure Name: _____

Address: No address State Line Road _____

Lat/Long: 42.493945/-88.425881 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) shed _____

Residence Detail

Style: Trailer

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features: all metal/vinyl

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): B - timber shed

Circa mid 20th century

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



HE-4-1: State Line Road – Residence, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15_____ Survey Number: HE-4-2 Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 11913 State Line Road _____

Lat/Long: 42.494013/-88.429648 _____

Primary Use: Resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) barn; (C) concrete silo; (D) shed with vertical wood siding and metal roof _____

Residence Detail

Style: Two-story Side Gabled

Wall materials: vertical wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style: Gabled roof dairy

Wall materials: vertical wood board

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: shed extension

Any obvious Additions/Alterations: residence has one-story addition

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa L. 19th century

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

A residence and farmstead are shown in this location on the 1872 plat.



HE-4-2: 11913 State Line Road – Residence, Shed, Barn, Silo

MCHENRY COUNTY
 HEBRON TOWNSHIP
 SECTION 5





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
 Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15_____ Survey Number: HE-5-1 Surveyor Name: J. Davis, E. Maier

Current Property or Structure Name: _____

Address: 13017 State Line Road _____

Lat/Long: 42.494506/-88.451963 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: Group: X Number Structures in Group: nine

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) shed/garage with peaked metal roof; (E) small lean-to shed with metal roof; (F-G) two metal storage bins; (H) 2nd garage with fieldstone foundation; (I) small garage next to barn

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style: Gambrel-roof Dairy

Wall materials: vertical wood

Roof materials: asphalt over shake

Foundation materials: concrete

Other distinguishing features: large ramp; attached milk house

Any obvious Additions/Alterations: additions on both sides of residence include attached 2-car garage

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa L.19th century

Number of photos taken for this property*: three_____

* Attach Photo log, additional notes and map of resource location.

A residence and farmstead are shown in this location on the 1872 plat.



HE-5-1: 13017 State Line Road – Barn, Silo, Sheds, Bins



HE-5-1: 13017 State Line Road – 2nd Garage



HE-5-1: 13017 State Line Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15_____ Survey Number: HE-5-2

Surveyor Name: J. Davis, E. Maher

Current Property or Structure Name: _____

Address: 12705 State Line Road _____

Lat/Long: 42.494544/-88.445883 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) garage with asphalt roof, vinyl siding _____

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete block across front

Other distinguishing features: updated

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa L.19th century

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

A residence and farmstead are shown near this location on the 1872 plat.



HE-5-2: 12705 State Line Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15_____ Survey Number: HE-5-3

Surveyor Name: J. Davis, E. Maher

Current Property or Structure Name: _____

Address: 12703 State Line Road _____

Lat/Long: 42.494531/-88.444748 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: two _____

List Observed Structures: (A) residence #1; (B) residence #2 _____

Residence Detail

Style: One-story Side Gabled

Wall materials: asbestos shingle

Roof materials: asphalt

Foundation materials: concrete covered/poss. fieldstone

Other distinguishing features: peaked entrance roof

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials: Other

distinguishing features:

Any obvious Additions/Alterations: extensive additions to Residence #2, an Upright and Wing

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa L.19th – E.20th century

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

A residence is shown near this location on the 1908 plat.



HE-5-3: 12703 State Line Road – Residence



HE-5-3: 12703 State Line Road – Residence 2

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15_____ Survey Number: HE-5-4

Surveyor Name: J. Davis, E. Maher

Current Property or Structure Name: _____

Address: 12317 State Line Road _____

Lat/Long: 42.494497/-88.436789 _____

Primary Use: Resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: three _____

List Observed Structures: (A) residence #1; (B) garage; (C) pole barn; (D) demolished barn _____

Residence Detail

Style: Bungalow

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: front roof dormer

Barn Detail

Style: Demolished

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: addition to west side

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa L.19th – E.20th century

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

A residence is shown near this location on the 1872 plat. Residence is likely ca. 1920s



HE-5-4: 12317 State Line Road – Garage




HE-5-4: 12317 State Line Road – Pole Barn,
Demolished Barn



HE-5-4: 12317 State Line Road – Residence

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 6



Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15_____ Survey Number: HE-6-1

Surveyor Name: J. Davis, E. Maher

Current Property or Structure Name: _____

Address: 11415 Hillside Road _____

Lat/Long: 42.491818/-88.462577 _____

Primary Use: Resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) metal pole barn _____

Residence Detail

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style: Dairy

Wall materials: metal

Roof materials: metal

Foundation materials: concrete

Other distinguishing features: extensions

Any obvious Additions/Alterations: additions on both ends of barn, all metal clad

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa L.19th – E.20th century

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

A residence and farmstead are shown just west of this location in 1872, residence shown in this location on the 1892 plat. Current residence is 20th c.



HE-6-1: 11415 Hillside Road – Residence, Barn



HE-6-1: 11415 Hillside Road – Silo, Pole Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15_____ Survey Number: HE-6-2

Surveyor Name: J. Davis, E. Maher

Current Property or Structure Name: _____

Address: 14028 Hillside Road _____

Lat/Long: 42.487535/-88.469695 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) garage _____

Residence Detail

Style: Ranch

Wall materials: wood and vinyl

Roof materials: metal

Foundation materials: concrete

Other distinguishing features: obscured

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: screened-in front porch

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa Mid.20th century


Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



HE-6-2: 14028 Hillside Road – Residence, Garage

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 7





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15_____ Survey Number: HE-7-1

Surveyor Name: J. Davis, E. Maher

Current Property or Structure Name: Linn-Hebron Cemetery_____

Address: West side of Hillside Road_____

Lat/Long: 42.485986/-88.462653_____

Primary Use: burial ground_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) cemetery entrance_____

Residence Detail

Style

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

established 1847

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.



HE-7-1: West Side of Hillside Road – Cemetery

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15_____ Survey Number: HE-7-2 Surveyor Name: J. Davis, E. Maier

Current Property or Structure Name: _____

Address: 13811 Nichols Road _____

Lat/Long: 42.482910/-88.465530 _____

Primary Use: Resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) concrete stave silo; (E) metal garage;
(F) three metal storage bins _____

Residence Detail

Style: Queen Anne

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete block visible

Other distinguishing features: enclosed wrap-around porch;
Diagonal corner window.

Barn Detail

Style: round roof dairy

Wall materials: unknown

Roof materials: metal

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa L. 19th century

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

Residence and farmstead shown in this location on the 1872 plat.



HE-7-2: 13811 Nichols Road – Barn, Silos, Bins, Garage



HE-7-2: 13811 Nichols Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15_____ Survey Number: HE-7-3 Surveyor Name: J. Davis, E. MaHer

Current Property or Structure Name: _____

Address: 13620 Nichols Road _____

Lat/Long: 42.482910/-88.465530 _____

Primary Use: Resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) smaller wood-sided barn/garage with gambrel roof; (C) larger dairy barn; (D) concrete silo #1; (E) concrete silo #2; (F) 2nd smaller wood sided barn with gambrel roof

Residence Detail

Style: Gabled EI

Wall materials: asbestos shingle

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features: fish-scale shingles below front bay

Barn Detail

Style: rambling dairy

Wall materials: vertical wood board

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: ramp

Any obvious Additions/Alterations: residence front porch has concrete block foundation

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): concrete silos are squat, look older. Barn to SE is wood board sided, gambrel roof, loft doors, concrete foundation

Circa L. 19th century

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

Residence and farmstead shown near this location on the 1872 plat.



HE-7-3: 13620 Nichols Road – Residence



HE-7-3: 13620 Nichols Road – Garage, Dairy Barns, Silos

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15_____ Survey Number: HE-7-4

Surveyor Name: J. Davis, E. Maher

Current Property or Structure Name: _____

Address: 13022 Hebron Road _____

Lat/Long: 42.480008/-88.462317 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) garage _____

Residence Detail

Style: Gabled E1

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features:

Any obvious Additions/Alterations: residence front porch has concrete block foundation

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa early to middle 20th

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

No structures shown here 1872-1908 plats.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

unknown

Other distinguishing features:



HE-7-4: 13022 Hebron Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15_____ Survey Number: HE-7-5 Surveyor Name: J. Davis, E. Maier

Current Property or Structure Name: _____

Address: 13202 Hebron Road _____

Lat/Long: 42.479636/-88.454434 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) garage; (C) small shed #1; (D) small shed #2; (E) vinyl clad shed/garage;

(F) pole type metal hay barn _____

Residence Detail

Style: Gabled EI originally

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: pole barn

Wall materials: metal

Roof materials: metal

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: residence has multiple additions

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa L.19th century

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

Residence shown in this location on 1892 plat.



HE-7-5: 13202 Hebron Road – Residence



HE-7-5: 13202 Hebron Road – Garage, Sheds, Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15_____ Survey Number: HE-7-6 Surveyor Name: J. Davis, E. Maier

Current Property or Structure Name: Nichols Centennial Farm _____

Address: 14001 Hebron Road _____

Lat/Long: 42.479119/-88.470089 _____

Primary Use: Resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: six _____

List Observed Structures: (A) residence #1; (B) residence #2; (C) grain elevator complex*; (D) large white/tan metal pole barn; (E) red metal pole barn

Residence #1 Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: poss. Greek Revival elements

Residence #2 Detail

Style: Two-story Cube/Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features: roof dormer

Any obvious Additions/Alterations: residence #2 has one-story addition to east

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): * elevator complex includes metal Quonsett hut, four metal silos and elevator structure, four metal storage bins.

Circa L.19th century

Number of photos taken for this property*: five _____

* Attach Photo log, additional notes and map of resource location.

Residence shown near this location on 1892 plat.




HE-7-6: 14001 Hebron Road – Complex, Pole Barns



HE-7-6: 14001 Hebron Road – Residence



HE-7-6: 14001 Hebron Road – Residence 2



HE-7-6: 14001 Hebron Road – Sign

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15_____ Survey Number: HE-7-7 Surveyor Name: J. Davis, E. MaHer

Current Property or Structure Name: _____

Address: 10517 Johnson Road _____

Lat/Long: 42.479017/-88.462365 _____

Primary Use: Resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: seven _____

List Observed Structures: (A) residence #1; (B) residence #2; (C) barn; (D) wood-side shed/garage; (E) metal pole barn equipment shed; (F) concrete stave silo #1; (G) concrete stave silo #2

Residence #1 Detail

Style: Two-story Cube

Wall materials: wood clapboard

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: corner pediments

Any obvious Additions/Alterations: residence #1 has one-story addition to east

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): barn is peaked roofed and metal clad

Circa: L.19th century

Number of photos taken for this property*: Three _____

* Attach Photo log, additional notes and map of resource location.

Residence shown near this location on 1892 plat.

Residence #2 Detail

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:



HE-7-7: 10517 Johnson Road – Residence 2,
Barns, Silos



HE-7-7: 10517 Johnson Road - Residence



HE-7-7: 10517 Johnson Road – Silos, Barn, Sheds

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15_____ Survey Number: HE-7-8 Surveyor Name: J. Davis, E. MaHer

Current Property or Structure Name: _____

Address: No address Johnson Road _____

Lat/Long: 42.477608/-88.460761 _____

Primary Use: agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: three _____

List Observed Structures: (A) metal silo; (B) low concrete block shed with peaked roof; (C) low concrete block shed with round roof

Residence #1 Detail

Residence #2 Detail

Style:

Style:

Wall materials:

Wall materials:

Roof materials:

Roof materials:

Foundation materials:

Foundation materials:

Other distinguishing features:

Other distinguishing features:

Any obvious Additions/Alterations: Abandoned farmstead, outbuildings only

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Circa L.19th century

Number of photos taken for this property*: One _____

* Attach Photo log, additional notes and map of resource location.

Residence shown near this location on 1892 plat.



HE-7-8: Johnson Road – Silo, Sheds

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15_____ Survey Number: HE-7-9 Surveyor Name: J. Davis, E. Maier

Current Property or Structure Name: _____

Address: 10206 Johnson Road _____

Lat/Long: 42.473495/-88.461405 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) large pole barn; (C) concrete silo; (D) larger concrete stave silo; (E)

Quonset shed with concrete block walls, metal roof; (F) small wooden shed with asphalt roof

Residence Detail

Style: Italianate

Wall materials: vinyl/wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: screened front entry structure

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Circa L.19th century

Number of photos taken for this property*: One _____

* Attach Photo log, additional notes and map of resource location.

Residence shown near this location on 1872 plat.



HE-7-9: 10206 Johnson Road – Bins, Silos




HE-7-9: 10206 Johnson Road – Residence



HE-7-9: 10206 Johnson Road – Pole Barn, Shed,
Quonset

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 8





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15_____ Survey Number: HE-8-1

Surveyor Name: J. Davis, E. Maher

Current Property or Structure Name: _____

Address: 13811 Hebron Road _____

Lat/Long: 42.482910/-88.465530 _____

Primary Use: Resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: thirteen _____

List Observed Structures: (A) residence #1; (B) residence #2; (C) barn*; (D) tallest concrete silo with zig-zag pattern; (E) concrete stave silo with zig-zag pattern; (F) shortest concrete silo; (G) concrete stave silo to east; (H) pole barn animal shed; (I) low wooden animal barn; (J) metal clad equipment barn/shed; (K) garage #1; (L) garage #2, both vinyl clad with asphalt roofs; (M) newer grey metal pole barn

Residence #1 Detail

Style: One story Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features:

Residence #2 Detail

Style: Upright and Wing originally

Wall materials: vinyl and brick

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features: see below

Any obvious Additions/Alterations: residence #2: Wing portion replaced with two-story brick addition

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): *Barn is peak-roofed, vinyl siding, asphalt roof.

Circa E.20th century

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

Residential structure shown near this location on the 1908 plat.



HE-8-1: 13811 Hebron Road – Barns, Silos, Pole Barn



HE-8-1: 13811 Hebron Road – Residence, Garage



HE-8-1: 13811 Hebron Road – Residence 2, Barn, Pole Barn, Garage 2

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15_____ Survey Number: HE-8-2

Surveyor Name: J. Davis, E. Maher

Current Property or Structure Name: _____

Address: 12648 Hebron Road _____

Lat/Long: 42.476702/-88.443827 _____

Primary Use: Resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three _____

List Observed Structures: (A) residence #1; (B) residence #2; (C) metal pole barn

Residence #1Detail

Style: Ranch (modern)

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Residence #2 Detail

Style: Two-story Front Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: see below

Any obvious Additions/Alterations: residence #2 is possible Upright and Wing but the Wing is now a 2-car garage

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa E.20th century

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

A structure is shown here on the 1908 plat.



HE-8-2: 12648 Hebron Road – Barn



HE-8-2: 12648 Hebron Road – Residence



HE-8-2: 12648 Hebron Road – Residence 2

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15_____ Survey Number: HE-8-3 Surveyor Name: J. Davis, E. Maher _____

Current Property or Structure Name: _____

Address: 12607 Hebron Road _____

Lat/Long: 42.475578/-88.443261 _____

Primary Use: Resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) barn/shed; (C) concrete block garage; (D) low wood-sided shed _____

Residence Detail

Style: Two-story Bungalow

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: see below

Barn Detail

Style: small Gambrel Roofed

Wall materials: vertical wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: two windows, hay loft, two barn doors

Any obvious Additions/Alterations: residence has large front roof gable, and prominent fieldstone columns on front porch

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa E.20th century

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

No structures shown here on 1872-1908 platst.



HE-8-3: 12607 Hebron Road – Shed, Garage



HE-8-3: 12607 Hebron Road – Residence



HE-8-3: 12607 Hebron Road – Residence 2

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15_____ Survey Number: HE-8-4

Surveyor Name: J. Davis, E. Maher

Current Property or Structure Name: _____

Address: 12607 Hebron Road _____

Lat/Long: 42.475578/-88.443261 _____

Primary Use: Resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) barn/garage _____

Residence Detail

Style: Neo-Dutch Colonial

Wall materials: brick

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: residence has large front roof gable, and prominent fieldstone columns on front porch

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa Mid-Late 20th century

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

No structures shown here on 1872-1908 plats.

Barn Detail

Style: small Gambrel Roofed

Wall materials: vertical wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: three front bays. Converted/re-modeled - may be contemporary with residence but hard to tell



HE-8-4: 12607 Hebron Road – Residence



HE-8-4: 12607 Hebron Road – Barn/Garage



MCHENRY COUNTY
 HEBRON TOWNSHIP
 SECTION 9



Township
 Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15_____ Survey Number: HE-9-1

Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 10511 Freeman Road _____

Lat/Long: 42.478701/-88.432379 _____

Primary Use: Resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: two _____

List Observed Structures: (A) garage; (B) barn/shed _____

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Barn Detail

Style: Banked

Wall materials: clapboard

Roof materials: metal/asphalt

Foundation materials: concrete block

Other distinguishing features:

Any obvious Additions/Alterations: barn/shed is built into a steep bank and is mostly composed of concrete block foundation.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): vertical wood-sided garage on upper part of embankment.

Circa early-mid 20th century

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

No structures shown in this location 1872-1908



HE-9-1: 10511 Freeman Road – Garage, Barn/Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: HE-9-2 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 11508 Rt. 173_____

Lat/Long: 42.472331/-88.422895_____

Primary Use: Residential_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) barn/shed (Quonset is on next property) _____

Residence Detail

Style: 2-story Side-Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): B - low shed w/ wood board siding

Circa L. 19th century

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Residence first shown on 1892 plat.



HE-9-2: 11508 Illinois Route 173 – Residence



HE-9-2: 11508 Illinois Route 173 – Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: HE-9-3 _____ Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 11506 Rt. 173 _____

Lat/Long: 42.472410/-88.422723 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) metal Quonset hut/shed _____

Residence Detail

Style: 2-story Cube

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): B - metal Quonset

Circa L. 19th century

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Residence shown in this location on 1892 plat.



HE-9-3: 11506 Illinois Route 173 – Quonset



HE-9-3: 11506 Illinois Route 173 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: HE-9-4 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: Vaughan & Bushnell Manufacturing Company_____

Address: 11414 Rt. 173_____

Lat/Long: 42.472730/-88.419713_____

Primary Use: Industrial_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) one-story brick industrial/office building with Neo-Colonial elements_____

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Circa Mid-20th century

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.



HE-9-4: 11414 Illinois Route 173 – Industrial/Office Building

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: HE-9-5 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 11302 Seaman Road _____

Lat/Long: 42.479833/-88.416694 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: seven _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) Quonset-shaped barn/shed; (E) pole barn; (F) wood-sided animal shed with asphalt roof; (G) pole barn-type open-sided animal shed

Residence Detail

Style: American Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete-covered

Other distinguishing features

Barn Detail

Style: Gambrel roof dairy

Wall materials: vertical wood board

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: attached milk-house

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa Late 19th century

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

A residence and farmstead are shown in this location on the 1872 plat.



HE-9-5: 11302 Seaman Road – Barns, Silo, Quonset



HE-9-5: 11302 Seaman Road - Residence



HE-9-5: 11302 Seaman Road – Barn, Shed, Pole Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15_____ Survey Number: HE-9-6

Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 11080 Maple Avenue (RT. 173)_____

Lat/Long: 42.472973/-88.415787_____

Primary Use: agriculture_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) barn; (B) concrete stave silo_____

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Barn Detail

Style: Gambrel roof

Wall materials: vertical wood board

Roof materials: asphalt/shake shingle

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations: attached milk-house (concrete) connects barn and silo

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Circa early-mid 20th century

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.

A residence and farmstead are shown here in 1872. These structures probably E-Mid 20th c.



HE-9-6: 11080 Maple Avenue – Barn, Silo

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 10





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15 Survey Number: HE-10-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: Sherwood Nursery

Address: 10826 Seaman Road

Lat/Long: 42.481614/-88.408624

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 6

List Observed Structures: (A) Res (B) Barn (C) pole building (D) shed (E) carriage house (F) shed

Residence Detail

Style: Upright and Wing

Wall materials: wood

Roof materials: asphalt

Foundation materials:

Other distinguishing features
obscured by trees
bay window and attached enclosed porch

Any obvious Additions/Alterations

Barn Detail

Style: Gabled Hay Barn

Wall materials: horizontal and
vertical boards

Roof materials: fishscale

Foundation materials: concrete

Other distinguishing features
attached extended gable
attached gabled
shed/milkhouse (?)

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - modern metal pole building D - small timber shed E - folly or carriage house (2 story cornice decoration) E - metal shed

Number of photos taken for this property*: 4

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870



HE-10-1: 10826 Seaman Road - Residence



HE-10-1: 10826 Seaman Road – Barn, Pole Building



HE-10-1: 10826 Seaman Road – Shed, Carriage House, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15 Survey Number: HE-10-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 10502 Seaman Road

Lat/Long: 42.483403/-88.402222

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 3

List Observed Structures: (A) Res (B) garage (C) barn

Residence Detail

Style: Ranch

Wall materials: brick

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

Barn Detail

Style: Gambrel Hay Barn

Wall materials: boards

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - Side gabled small barn/garage with board siding

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

C. 1960



HE-10-2: 10502 Seaman Road – Barn



HE-10-2: 10502 Seaman Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15 Survey Number: HE-10-3 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 10310 Seaman Road

Lat/Long: 42.483297/-88.399017

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 3

List Observed Structures: (A) Res (B) barn (C) shed/coop (D) shed (E) machine shed

Residence Detail

Style: Pyramid roof

Wall materials: aluminum

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features
central chimney
Colonial Revival style door trim
enclosed porch/side extension

Barn Detail

Style: Gambrel Hay Barn

Wall materials: boards and
concrete block

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features
two garage doors on front

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - shed/coop D - small gabled shed/outhouse E - gabled machine shed

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1900



HE-10-3: 10310 Seaman Road – Residence, Barn



HE-10-3: 10310 Seaman Road - Sheds



HE-10-3: 10310 Seaman Road – Machine Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15 Survey Number: HE-10-4 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 10818 Route 173

Lat/Long: 42.472790/-88.408958

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) shed

Residence Detail

Style: Gabled

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features
obscured - too far from road

Any obvious Additions/Alterations

Barn Detail

Style: Gambrel Hay Barn

Wall materials: boards and
concrete block

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small shed

aerial suggests presence of barn - not visible

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870



HE-10-4: 10818 Illinois Route 173 – Shed



HE-10-4: 10818 Illinois Route 173 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15 Survey Number: HE-10-5 Surveyor Name: M Prchal/C

Flynn Current Property or Structure Name: _____

Address: Route 173 _____

Lat/Long: 42.472798/-88.406998 _____

Primary Use: Res/Ag _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: 4 _____

List Observed Structures: (A) Res (B) barn (C) silo (D) garage _____

Residence Detail

Style: Upright and Wing

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations
shutters

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete silo D - pyramid roof garage

may be other sheds but not visible - property has heavy tree cover

Number of photos taken for this property*: 4 _____

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870



HE-10-5: Illinois Route 173 – Barn, Silo



HE-10-5: Illinois Route 173 - Barn



HE-10-5: Illinois Route 173 - Garage



HE-10-5: Illinois Route 173 - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15 Survey Number: HE-10-6 Surveyor Name: M Prchal/C

Flynn Current Property or Structure Name: _____

Address: 10708 Route 173 _____

Lat/Long: 42.472511/-88.405994 _____

Primary Use: Res _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: 2 _____

List Observed Structures: (A) Res (B) pole building _____

Residence Detail

Style: Upright and Wing/Gabled El

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations
concrete stoop

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - metal pole building

Number of photos taken for this property*: 1 _____

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-10-6: 10708 Illinois Route 173 – Residence, Pole Building

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15 Survey Number: HE-10-7 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 10507 Route 173

Lat/Long: 42.472512/-88.402437

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 3

List Observed Structures: (A) Res (B)shed/garage (C) outbuilding

Residence Detail

Style: Pyramid roof

Wall materials: aluminum and brick

Roof materials: asphalt

Foundation materials:

Other distinguishing features
flat roof peak

Any obvious Additions/Alterations
enclosed brick front porch
rear extension

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - pyramid roof (?) garage C - gabled outbuilding/coop

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1900

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-10-7: 10507 Illinois Route 173 – Outbuilding



HE-10-7: 10507 Illinois Route 173 – Residence



HE-10-7: 10507 Illinois Route 173 – Shed/Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15 Survey Number: HE-10-8 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: Route 173

Lat/Long: 42.472408/-88.395240

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 8

List Observed Structures: (A) Res (B)garage (C) small barn (D) silo (E) silo (F) shed (G) shed

(H and I) metal grain bins

Residence Detail

Style: Pyramid roof

Wall materials: board

Roof materials: asphalt

Foundation materials: concrete (visible)

Other distinguishing features

full front porch with spindle supports

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - 3 bay pyramid roof garage C - small gabled barn/shed D - concrete stave silo E - formed concrete silo

F - small gabled shed G - metal and wood shed H and I - metal grain bins

Number of photos taken for this property*: 5

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870



HE-10-8: Illinois Route 173 – Garage, Shed



HE-10-8: Illinois Route 173 – Residence, Bins



HE-10-8: Illinois Route 173 – Silos, Sheds



HE-10-8: Illinois Route 173 – Barn, Shed

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 11





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15 Survey Number: HE-11-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9316 Lange Road

Lat/Long: 42.472653/-88.379814

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 7

List Observed Structures: (A) Res (B) garage (C) barn (D) silo (E) shed (F) shed (G) metal shed

Residence Detail

Style: Gabled EI

Wall materials:

Roof materials: asphalt

Foundation materials:

Other distinguishing features
spindle porch supports

Barn Detail

Style: Gambrel Livestock Barn

Wall materials: board

Roof materials: metal

Foundation materials: concrete

Other distinguishing features
9-pane windows
attached milkhouse

Any obvious Additions/Alterations
side attached garage

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled barn/garage D - silo E - gabled shed F - gabled shed G - modern metal shed

Number of photos taken for this property*: 5

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870



HE-11-1: 9316 Lange Road - Shed



HE-11-1: 9316 Lange Road - Outbuildings



HE-11-1: 9316 Lange Road – Residence with Garage



HE-11-1: 9316 Lange Road – Barn, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15 Survey Number: HE-11-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9114 Route 173

Lat/Long: 42.472654/-88.375995

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 4

List Observed Structures: (A) Res (B) shed (C) shed (D) silo

Residence Detail

Style: Gabled EI

Wall materials: vinyl/aluminum

Roof materials: asphalt

Foundation materials:

Other distinguishing features
enclosed front porch

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small barn/gabled shed C - small shed D - formed concrete silo

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870



HE-11-2: 9114 Illinois Route 173 – Silo, Shed



HE-11-2: 9114 Illinois Route 173 – Residence, Sheds

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15 Survey Number: HE-11-3 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: Route 173 _____

Lat/Long: 42.472398/-88.374828 _____

Primary Use: Res (formerly a school house) _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2 _____

List Observed Structures: (A) Res (B) garage _____

Residence Detail

Style: Italiante front gabled single story

Wall materials: board

Roof materials: asphalt

Foundation materials: brick

Other distinguishing features
eave brackets

Any obvious Additions/Alterations
front addition

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - metal garage

identified as a school in 1872-1965 (Stones School)

Number of photos taken for this property*: 2 _____

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-11-3: Illinois Route 173 – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15 Survey Number: HE-11-4 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: Lange Road _____

Lat/Long: 42.482692/-88.377669 _____

Primary Use: Res/Ag _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: _____

List Observed Structures: obscured and far off road _____

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property*: 1 _____

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870



HE-11-4: Lange Road – Buildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/16/15 Survey Number: HE-11-4 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9905 Burgett Road

Lat/Long: 42.486386/-88.390281

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 9

List Observed Structures: (A) Res (B) shed (C) pole building (D) pole building (E and F) silos

(GHI) metal grain bins

Residence Detail

Style: Upright and Wing/Greek Revival

Wall materials: aluminum

Roof materials: asphalt

Foundation materials:

Other distinguishing features
frieze band window

Any obvious Additions/Alterations

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small timber shed C - large pole barn D - small pole barn/garage E and F - concrete silos

GHI - metal grain bins

Number of photos taken for this property*: 4

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870



HE-11-5: 9905 Burgett Road - Outbuildings




HE-11-5: 9905 Burgett Road - Residence



HE-11-5: 9905 Burgett Road – Silos, Bins

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 12



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-12-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 8803 Burgett Road

Lat/Long: 42.486354/-88.369217

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 8

List Observed Structures: (A) Res (B) metal outbuilding (C) shed (D) barn (E-H) pole buildings

(I) grain silo

Residence Detail

Style: Pyramid roof

Wall materials: board

Roof materials: fishscale

Foundation materials: fieldstone

Other distinguishing features

cross dormers

central chimney

front entry porch with spindle supports

Any obvious Additions/Alterations

Barn Detail

Style: Gambrel hay barn

Wall materials: board

Roof materials: metal

Foundation materials: concrete

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - metal outbuilding/shed C - shed E-H - modern pole buildings I - metal grain silo

Number of photos taken for this property*: 5

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870



HE-12-1: 8803 Burgett Road – Residence



HE-12-1: 8803 Burgett Road – Shed, Barn, Pole Buildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-12-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: Burgett Road

Lat/Long: 42.486384/-88.364009

Primary Use: Res/ Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 7

List Observed Structures: (A) Res (B) shed (C) shed (D) silo (E and F) grain bins (G) metal silo complex

Residence Detail

Style: Trailer home

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - timber gabled sheds C - larger timber gabled shed D - concrete silo E and F - metal grain bins

G - metal silo complex

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

C. 1920 sheds

mostly modern

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-12-2: Burgett Road – Residence, Sheds, Silo Complex,
Silo, Bins

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-12-3 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 8710 Route 173

Lat/Long: 42.472500/-88.366755

Primary Use: Res/ Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 7

List Observed Structures: (A) Res (B) barn (C) silo (D) silo (E) shed (F) windmill (G) shed

Residence Detail

Style: Gabled EI

Wall materials: aluminum

Roof materials: asphalt

Foundation materials: stone

Other distinguishing features
double windows in gabled end

Any obvious Additions/Alterations

Barn Detail

Style: Gabled

Wall materials: board

Roof materials:

Foundation materials:

Other distinguishing features
far from road/obscured

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C and D - concrete silos w/ domed concrete tops E - gabled shed F - windmill base G - gabled shed

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870



HE-12-3: 8710 Illinois Route 173 – Residence



HE-12-3: 8710 Illinois Route 173 – Barn, Silos, Sheds, Windmill

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-12-4 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: Route 173

Lat/Long: 42.472482/-88.363191

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: stone

Other distinguishing features
double windows in gabled end

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled one bay garage

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-12-4: Illinois Route 173 – Residence, Garage

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 13





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-13-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 8201 Route 173

Lat/Long: 42.471757/-88.356285

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 7

List Observed Structures: (A) Res (B) barn (C) silo (D) silo (E) garage (F) machine shed (G) shed

Residence Detail

Style: Greek Revival (with wing)

Wall materials: asbestos

Roof materials: asphalt

Foundation materials:

Other distinguishing features
cornice returns

Any obvious Additions/Alterations
front porch removed/stoop added

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete silo D - Harvestore silo E - gabled 2 bay garage F - machine shed/shop G - gabled timber shed

Number of photos taken for this property*: 4

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870



HE-13-1: 8201 Illinois Route 173 - Residence



HE-13-1: 8201 Illinois Route 173 – Barn, Silos, Garage, Shed



HE-13-1: 8201 Illinois Route 173 - Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-13-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 8519 Route 173

Lat/Long: 42.471599/-88.363946

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 8

List Observed Structures: (A) Res (B) barn (C) silo (D) greenhouses (E) machine shed (F) garden shed

(G) garage (H) shop

Residence Detail

Style: Side Gabled/Colonial Revival

Wall materials:

Roof materials: asphalt

Foundation materials:

Other distinguishing features
front entry porch

Any obvious Additions/Alterations

Barn Detail

Style: Gambrel hay
barn/foundation barn

Wall materials: board

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - formed concrete silo (D) plastic greenhouses (E) gabled one bay machine shed (F) small garden shed

G - two bay garage H - pole building/shop

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870



HE-13-2: 8519 Illinois Route 173 – Barn, Silo, Sheds, Greenhouses



HE-13-2: 8519 Illinois Route 173 - Residence



HE-13-2: 8519 Illinois Route 173 - Shop

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-13-3 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 8705 Route 173

Lat/Long: 42.471859/-88.366039

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 9

List Observed Structures: (A) Res (B) pole building (C) barn (D-F) silos (G) pole building (H) machine shed (I) pole building

Residence Detail

Style: Prairie Foursquare

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features

pyramid dormers

enclosed front porch with Prairie multi-pane windows (3/2)

vertical wood lattice at porch base

concrete steps

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - pole building D-F - concrete silos G - pole building H - small open machine shed I - pole building

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1900



HE-13-3: 8705 Illinois Route 173 – Residence



HE-13-3: 8705 Illinois Route 173 – Barn



HE-13-3: 8705 Illinois Route 173 – Silos, Pole Buildings, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-13-4 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 8907 Route 173

Lat/Long: 42.471794/-88.370353

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 3

List Observed Structures: (A) Res (B)garage (C) grain complex

Residence Detail

Style: Ranch

Wall materials: brick and siding

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - garage C - timber drive through crib with metal silos

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

C. 1965

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-13-4: 8907 Illinois Route 173 – Residence, Garage,
Grain Complex

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-13-5 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 8508 Norgard Road

Lat/Long: 42.461739/-88.363465

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 8

List Observed Structures: (A) Res (B) machine shed (C) small barn (D) large barn (E and F) silos

(G) shed (H) pole building

Residence Detail

Style: Prairie Foursquare

Wall materials: brick

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

pyramid dormers

enclosed front porch

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - pole building/machine shed C - small Gambrel barn E and F - concrete silos G - shed

H - pole building

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

C. 1860/1910



HE-13-5: 8508 Norgard Road – Residence, Shed



HE-13-5: 8508 Norgard Road – Barns, Silos

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-13-6 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 8205 Norgard Road

Lat/Long: 42.461099/-88.357470

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 3

List Observed Structures: (A) Res (B) silo (C) milkhouse

Residence Detail

Style: Upright and Wing

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - formed concrete sillo C - milkhouse

owner informed us that barn came down in a tornado

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870



HE-13-6: 8205 Norgard Road – Residence



HE-13-6: 8205 Norgard Road – Silo, Milk House

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 14





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-14-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: Greenwood Road

Lat/Long: 42.460699/-88.375146

Primary Use: Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 4

List Observed Structures: (A) barn (B) silo (C) pole building (D) shed

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - concrete stave silo C - pole building D - gabled shed/small barn

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

C. mid 20th century

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features
Mostly demolished



HE-14-1: Greenwood Road – Barn, Silo, Pole Building, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-14-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9704 Okeson Road

Lat/Long: 42.458118/-88.390483

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 6

List Observed Structures: (A) res (B) garage (CDE) pole buildings (F) grain silo complex

Residence Detail

Style: Pyramid roof

Wall materials: aluminum

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

arched/eyebrow porch roof

side addition

rear porch/entry

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Mostly demolished

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - pyramid roof garage CDE - modern pole buildings F - grain silo complex

Number of photos taken for this property*: 4

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870 (shows up on 1872 map)



HE-14-2: 9704 Okeson Road – Residence, Garage, Pole Building



HE-14-2: 9704 Okeson Road – Pole Buildings, Grain Silo Complex

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-14-3 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: Route 173

Lat/Long: 42.471849/-88.378359

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 6

List Observed Structures: (A) Res (B) barn (C) metal silo (D) small shed (E) shed (F) pole building

Residence Detail

Style: Victorian Gabled EI

Wall materials: aluminum

Roof materials: asphalt

Foundation materials: limestone

Other distinguishing features
spindle porch supports and railing
eave/window brackets
decorative window trim
box bay windows

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - metal grain silo D - small shed E - timber shed/crib F - pole building

Number of photos taken for this property*: 4

* Attach Photo log, additional notes and map of resource location.

C. 1880



HE-14-3: Illinois Route 173 – Barn



HE-14-3: Illinois Route 173 – Silo, Sheds, Pole Building



HE-14-3: Illinois Route 173 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-14-4 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: Von Bergen Farm

Address: 9717 Route 173

Lat/Long: 42.471748/-88.388071

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 8

List Observed Structures: (A) Res (B) trailer (C) pole building (D) pole building

(E) shop/grain elevator/silos (F) block building (G) pole building (H) modern res

Residence Detail

Style: Gabled EI

Wall materials: aluminum

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - modern trailer C - pole building D - pole building E - pole building with connected silos and elevator

F - concrete block outbuilding with staggered roof G - pole building H - modern residence

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870

block building C. 1940



HE-14-4: Von Bergen Farm – Trailer, Pole Buildings, Shop, Grain Elevator, Silos



HE-14-4: Von Bergen Farm – Residence



HE-14-4: Von Bergen Farm – Block Building, Pole Building

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 15



Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-15-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 10417 Route 173

Lat/Long: 42.471952/-88.401072

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 4

List Observed Structures: (A) Res (B) garage (C) barn (D) shed

Residence Detail

Style: Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features
spindle supports on front porch

Any obvious Additions/Alterations
new front porch railings

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled garage D - garden shed

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

C. mid to late nineteenth century

Barn Detail

Style: obscured

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-15-1: 10417 Illinois Route 173 – Garage, Barn



HE-15-1: 10417 Illinois Route 173 – Residence, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-15-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 10419 Route 173

Lat/Long: 42.471942/-88.401639

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 3

List Observed Structures: (A) Res (B) garage (C) shed

Residence Detail

Style: Queen Anne/Pyramid

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features
eave/roofline decorative band
wrap-around porch
pyramid roof with flat peak

Any obvious Additions/Alterations

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - pyramid roof 2 bay garage with central entry C - shed/old barn ramp

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1910



HE-15-2: 10419 Illinois Route 173 – Garage



HE-15-2: 10419 Illinois Route 173 – Residence



HE-15-2: 10419 Illinois Route 173 – Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-15-3 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 10212 Route 173

Lat/Long: 42.472007/-88.405228

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 10

List Observed Structures: (A) Res (B) garage (C) crib/barn (D) pole building (E) pole building/barn

(F) pole building (GHIJ) metal grain bins

Residence Detail

Style: Pyramid roof

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

Any obvious Additions/Alterations

new windows

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - pyramid roof garage C - corn crib or small barn board w/metal roof D - pole building

E - pole building/gabled outbuilding F - pole building G-J - metal grain bins

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1910-1920



HE-15-3: 10212 Illinois Route 173 – Residence



HE-15-3: 10212 Illinois Route 173 – Garage, Barn,
Pole Building



HE-15-3: 10212 Illinois Route 173 – Pole
Buildings, Bins

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-15-4 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9508 Kenman Road

Lat/Long: 42.464076/-88.412727

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) silo

Residence Detail

Style: Pyramid roof

Wall materials: vinyl

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations
new windows

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - formed concrete silo

property also includes a fieldstone partial barn foundation

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-15-4: 9508 Kenman Road – Residence




HE-15-4: 9508 Kenman Road – Silo



HE-15-4: 9508 Kenman Road – Foundation

MCHENRY COUNTY
 HEBRON TOWNSHIP
 SECTION 16





Township
 Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number

Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-16-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 11505 Price Road

Lat/Long: 42.464793/-88.422107

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage

Residence Detail

Style: Vernacular Italianate/Greek Revival

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features

eave brackets

multi-pane windows

multiple roof lines, main pyramid roof with later wing

cornice decoration

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small gabled barn or carriage house

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-16-1: 11505 Price Road – Garage



HE-16-1: 11505 Price Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-16-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 11311 Route 173

Lat/Long: 42.471877/-88.418325

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 3

List Observed Structures: (A) Res (B) barn (C) silo

Residence Detail

Style: Gabled EI

Wall materials: board

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features
elaborate window surrounds
lattice in gables
corner window

Barn Detail

Style: Gabled hay Barn

Wall materials: board

Roof materials:

Foundation materials:

Other distinguishing features
front shed extension with
fishcale roofing

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete stave silo

aerial and real estate listing indicate second residence and pole barn at rear of property - obscured

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870



HE-16-2: 11311 Illinois Route 173 – Residence



HE-16-2: 11311 Illinois Route 173 – Barn, Silo

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-16-3 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 11407 Route 173/Maple Avenue

Lat/Long: 42.472066/-88.419570

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: X Group: _____ Number Structures in Group: _____

List Observed Structures: Res

Residence Detail

Style: Pyramid/Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

attached garage

enclosed front porch w/ picture window

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

may be barn to rear but not visible

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

C. 1900-1920



HE-16-3: 11407 Illinois Route 173 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-16-4 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 11409 Route 173/Maple Avenue

Lat/Long: 42.472007/-88.419900

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: Group: _____ Number Structures in Group: _____

List Observed Structures: Res

Residence Detail

Style: Ranch

Wall materials: aluminum and stone facing

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

enclosed front porch w/ picture window

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

C. 1950



HE-16-4: 11409 Illinois Route 173 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-16-5 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 11411 Route 173/Maple Avenue

Lat/Long: 42.472008/-88.420242

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: Group: _____ Number Structures in Group: _____

List Observed Structures: Res

Residence Detail

Style: Ranch

Wall materials: aluminum and stone facing

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

C. 1950



HE-16-5: 11411 Illinois Route 173 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-16-6 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 10005 Green Street

Lat/Long: 42.471100/-88.420852

Primary Use: Garage

Is this a record of a single structure or group (give total number of structures):

Single: Group: _____ Number Structures in Group: _____

List Observed Structures: Commercial Garage

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Round roofed concrete block garage

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

C. 1950



HE-16-6: 10005 Green Street – Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-16-7 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9308 Route 47

Lat/Long: 42.461321/-88.432568

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 6

List Observed Structures: (A) Res (B) garage (C) shed (D) shed (E) shed (F) shed

Residence Detail

Style: Upright and Wing

Wall materials: aluminum

Roof materials: asphalt

Foundation materials:

Other distinguishing features
enclosed gabled front porch

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - cross gabled garage C - small gabled shed/coop D - small gabled garden shed

E - gabled shed F - gabled shed

Number of photos taken for this property*: 4

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870



HE-16-7: 9308 Route 47 – Garage, Sheds



HE-16-7: 9308 Route 47 – Residence



HE-16-7: 9308 Route 47 – Sheds

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 17




Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-17-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 12414 Route 173

Lat/Long: 42.465230/-88.441232

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 5

List Observed Structures: (A) Res (B) shed (C) barn (D) shed (E) shed

Residence Detail

Style: Gabled EI

Wall materials: asbestos or asphalt

Roof materials: asphalt

Foundation materials:

Other distinguishing features

wide trim at cornice

elaborate window trim

Any obvious Additions/Alterations

fully enclosed front porch w/ door

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small gabled shed/garage C - small gabled shed D - small gabled barn/shed

Number of photos taken for this property*: 5

* Attach Photo log, additional notes and map of resource location.

C. 1850-1870

Barn Detail

Style: Gothic livestock

Wall materials: board

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

two rooftop vents



HE-17-1: 12414 Illinois Route 173 - Residence



HE-17-1: 12414 Illinois Route 173 – Shed, Barn



HE-17-1: 12414 Illinois Route 173 - Sheds

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-17-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 12716 Route 173

Lat/Long: 42.465248/-88.444887

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 5

List Observed Structures: (A) Res (B) garage (C) shed (D) windmill base (E) silo

Residence Detail

Style: Upright and Wing

Wall materials: aluminum

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - garage (obscured) C - small shed D - windmill base E - concrete silo, no roof

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-17-12: 12716 Illinois Route 173 – Shed,
Windmill



HE-17-12: 12716 Illinois Route 173 - Residence



HE-17-12: 12716 Illinois Route 173 - Silo

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-17-3 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 12808 Route 173

Lat/Long: 42.465115/-88.448244

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 3

List Observed Structures: (A) Res (B) garage (C) shed

Residence Detail

Style: Upright and Wing

Wall materials: aluminum

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

Any obvious Additions/Alterations

wing has been modified/porch enclosed

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small gabled garage (timber) C - shed/carport

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-17-3: 12808 Illinois Route 173 – Garage, Shed



HE-17-3: 12808 Illinois Route 173 – Residence

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 18





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-18-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 13218 Route 173

Lat/Long: 42.465090/-88.456476

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 5

List Observed Structures: (A) Res (B) barn (C) barn (D) silo (E) coop

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features

Any obvious Additions/Alterations

Bay window

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - gabled small barn D - Harvestore grain silo E - coop/shed

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870

Barn Detail

Style: Gabled livestock

Wall materials:

Roof materials: metal

Foundation materials: concrete

Other distinguishing features
attached pyramid roof
milkhouse



HE-18-1: 13218 Illinois Route 173 – Barns, Silo, Coop



HE-18-1: 13218 Illinois Route 173 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-18-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 13303 Route 173

Lat/Long: 42.464460/-88.457148

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage

Residence Detail

Style: Upright and Wing

Wall materials: board

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features
Cornice returns on gable end

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small gabled shed/garage

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

C. 1850-1860

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-18-2: 13303 Illinois Route 173 – Residence



HE-18-2: 13303 Illinois Route 173 – Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-18-3 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: Route 173

Lat/Long: 42.464976/-88.457480

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 3

List Observed Structures: (A) Res (B) garage _____ (C) garage/commercial building

Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete block/concrete

Other distinguishing features

Any obvious Additions/Alterations

additions/change to roofline - now centered gabled

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - 2 bay gabled garage C - semi-pyramid roofed building with garages and commercial front, includes modern doors/windows as well as multi-pane older windows

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870 (outbuilding C. 1920-1940)

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-18-3: Illinois Route 173 – Residence, Garage



HE-18-3: Illinois Route 173 – Commercial Building/Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-18-4 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9608 Johnson Road

Lat/Long: 42.465531/-88.458323

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage

Residence Detail

Style: Ranch

Wall materials: aluminum

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - large metal garage/machine shed

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

C. 1960

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-18-4: 9608 Johnson Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-18-5 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9804 Johnson Road

Lat/Long: 42.468082/-88.460282

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage

Residence Detail

Style: Neo-Cape Cod

Wall materials: vinyl and stone facing

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled garage

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

C. 1960

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-18-5: 9804 Johnson Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-18-6 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9806 Johnson Road

Lat/Long: 42.468344/-88.460365

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage

Residence Detail

Style: Ranch

Wall materials: aluminum and wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled garage

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

C. 1960

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-18-6: 9806 Johnson Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-18-7 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9809 Johnson Road

Lat/Long: 42.468711/-88.461795

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage/machine shed

Residence Detail

Style: Gabled

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features
obscured

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - large gabled garage/machine shed/pole building

Likely Lyons School (school house)

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

C. 1850-1860

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-18-7: 9809 Johnson Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-18-8 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9911 Johnson Road

Lat/Long: 42.470172/-88.463205

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 7

List Observed Structures: (A) Res (B) pole building (C) quonset (D) barn (E) silo (F) silo (G) barn

Residence Detail

Style: Ranch

Wall materials:

Roof materials: metal

Foundation materials:

Other distinguishing features
too far from road

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - pole building/garage C - quonset E and F - silos G - small Gambrel barn

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

C. 1940

Barn Detail

Style: Round Roof

Wall materials:

Roof materials: metal

Foundation materials:

Other distinguishing features



HE-18-8: 9911 Johnson Road – Pole Building, Quonset, Barns, Silos



HE-18-8: 9911 Johnson Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/6/15 Survey Number: HE-18-9 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 14004 Route 173

Lat/Long: 42.462999/-88.470087

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: _____

List Observed Structures: (A) Res plus modern pole buildings

Residence Detail

Style: Upright and Wing

Wall materials: board

Roof materials:

Foundation materials:

Other distinguishing features

square posts on porch
multipane/French doors

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

several modern pole buildings

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-18-9: 14004 Illinois Route 173 – Residence



HE-18-9: 14004 Illinois Route 173 – Pole Buildings

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 19



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15_____ Survey Number: HE-19-1 Surveyor Name: M. Prchal, C.Flynn_____

Address: 8117 Johnson Road_____

Lat/Long: 42.444286/-88.453477_____

Primary Use: Residential /Ag_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: five_____

List Observed Structures: (A) residence; (B) small A-Frame shed; (C) barn; (D) concrete stave silo; (E) pole barn_____

Residence Detail

Style: Gabled E1

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features:

Barn Detail

Style: Peaked roof

Wall materials: vertical wood board

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: in 2 parts

Any obvious Additions/Alterations: Side gabled wing expanded

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa L.19th century

Number of photos taken for this property*: six_____

* Attach Photo log, additional notes and map of resource location.

A residence and farmstead are shown in this location on the 1872 plat.



HE-19-1: 8117 Johnson Road - Residence



HE-19-1: 8117 Johnson Road - Shed




HE-19-1: 8117 Johnson Road – Barn, Silo



HE-19-1: 8117 Johnson Road – Pole Barn

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 20





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15_____ Survey Number: HE-20-1

Surveyor Name: M. Prchal, C. Flynn_____

Address: 9005 Johnson Road_____

Lat/Long: 42.455649/-88.452782_____

Primary Use: Agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) concrete shed with vinyl roof. Demolished farmstead_____

Residence Detail

Style: no residence

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

unknown date

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.

No structures shown here 1872-1908.



HE-20-1: 9005 Johnson Road – Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15_____ Survey Number: HE-20-2

Surveyor Name: M. Prchal, C.Flynn_____

Address: 8914 Johnson Road_____

Lat/Long: 42.454993/-88.451012_____

Primary Use:Resid/Agri_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: six_____

List Observed Structures: (A) residence; (B) wood-sided shed; (C)barn; (D) concrete silo; (E) wood-sided milk house; (F) small lean-to shed

Residence Detail

Style: Queen Anne

Wall materials: clapboard

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: front bay windows

Barn Detail

Style: Gambrel roof dairy

Wall materials: vertical wood boards

Roof materials: metal

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: concrete silo and milk house attached to barn

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa L. 19th C.

Number of photos taken for this property*: four_____

* Attach Photo log, additional notes and map of resource location.

Structure shown in this location on the 1892 plat.



HE-20-2: 8914 Johnson Road – Barn, Silo, Shed



HE-20-2: 8914 Johnson Road – Milk House, Shed



HE-20-2: 8914 Johnson Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15_____ Survey Number: HE-20-3

Surveyor Name: M. Prchal, C.Flynn

Address: 1218 O/Brien Road_____

Lat/Long: 42.443527/-88.446276_____

Primary Use:Resid/Agri_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: five_____

List Observed Structures: (A) residence; (B) pole barn #1; (C) very small metal shed; (D) pole barn/garage #2; (E) pole barn/garage #3

Residence Detail

Style: Cross-Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: wrap around front porch

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa L. 19th C.

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.

Residence and farmstead shown in this location on the 1872 plat.



HE-20-3: 1218 O'Brien Road – Residence, Pole Barns



HE-20-3: 1218 O'Brien Road – Shed, Pole Barn

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 21





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15_____ Survey Number: HE-21-1 Surveyor Name: M. Prchal, C.Flynn _____

Address: 9016 Rt. 47_____

Lat/Long: 42.456709/-88.432520_____

Primary Use: Resid/Agri_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: four_____

List Observed Structures: (A) residence; (B) shed/garage; (C) low metal pole barn; (D) pole barn/garage

Residence Detail

Style: Gabled EI

Wall materials: clapboard, wood trim

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: front porch

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials: Other

distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa L. 19th C.

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

Residence and farmstead shown in this location on the 1872 plat.



HE-21-1: 9016 Route 47 – Residence, Shed, Pole Barn



HE-21-1: 9016 Route 47 – Pole Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15_____ Survey Number: HE-21-2

Surveyor Name: M. Prchal, C.Flynn_____

Address: 11902 Vanderkarr Road_____

Lat/Long: 42.443516/-88.429920_____

Primary Use: Resid/Agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) low metal animal shed; (E) small wood-sided coop; (F) wood-sided garage with metal roof

Residence Detail

Style: Foursquare/obscured

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: front porch and steps

Barn Detail

Style: Gambrel Roof

Wall materials: vertical wood boards

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features: Red

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa L. 19th C.

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

Residence and farmstead shown in this location on the 1872 plat.



HE-21-2: 11902 Vanderkarr Road – Residence,
Shed



HE-21-2: 11902 Vanderkarr Road – Shed, Garage



HE-21-2: 11902 Vanderkarr Road – Barn, Silo,
Coop

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15_____ Survey Number: HE-21-3 Surveyor Name: M. Prchal, C.Flynn_____

Address: 8915 Kenman Road_____

Lat/Long: 42.455871/-88.415012_____

Primary Use: Resid/Agri_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: five_____

List Observed Structures: (A) residence; (B) garage; (C) pole barn; (D) very small shed; (E) small shed obscured

Residence Detail

Style: obscured

Wall materials: vinyl or wood

Roof materials: asphalt

Foundation materials: some fieldstone visible

Other distinguishing features: wrap-around porch and steps

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: all structures set back and obscured

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa early - middle 20th C.

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.

No structures shown in this location 1872-1908.



HE-21-3: 8915 Kenman Road – Residence, Garage, Pole
Barn, Sheds

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 22



Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15_____ Survey Number: HE-22-1

Surveyor Name: M. Prchal, C.Flynn_____

Address: 10603 Okeson Road_____

Lat/Long: 42.456937/-88.404804_____

Primary Use: resid/Agri_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: four_____

List Observed Structures: (A) wood-sided garage with metal roof; (B) small wooden shed with metal roof; (C) pole barn; (D) pole barn. Modern residence not photographed

Residence Detail

Barn Detail

Style:

Style:

Wall materials:

Wall materials:

Roof materials:

Roof materials:

Foundation materials:

Foundation materials:

Other distinguishing features:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

unknown date

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.

Residence shown here close to road in 1872, gone by 1908.



HE-22-1: 10603 Okeson Road – Garage, Shed, Pole Barns

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15_____ Survey Number: HE-22-2

Surveyor Name: M. Prchal, C.Flynn_____

Address: 9812 Stewart Road_____

Lat/Long: 42.456078/-88.396595_____

Primary Use: residential_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence with attached garage_____

Residence Detail

Style: Gabled El

Wall materials: brick or cut stone

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: attached garage

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa Early-Mid. 20th C.

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.

No structures shown here 1872-1908.



HE-22-2: 9812 Stewart Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15_____ Survey Number: HE-22-3

Surveyor Name: M. Prchal, C.Flynn_____

Address: 8915 Kenman Road_____

Lat/Long: 42.455871/-88.415012_____

Primary Use: Resid/Agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) barn; (C) garage

Residence Detail

Style: Side Gabled

Wall materials: clapboard

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Gambrel roof dairy

Wall materials: vertical wood board

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: carved horse figure on front

Any obvious Additions/Alterations: Residence Ell wing projects to west, connects to large 2-story addition. Barn has large earth ramp.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa E. 20th C.

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

No structures shown in this location 1872-1908.



HE-22-3: 8915 Kenman Road - Residence



HE-22-3: 8915 Kenman Road - Garage



HE-22-3: 8915 Kenman Road - Barn

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 23





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15_____ Survey Number: HE-23-1

Surveyor Name: M. Prchal, C.Flynn_____

Address: 9715 Okeson Road_____

Lat/Long: 42.457320/-88.391966_____

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: four_____

List Observed Structures: (A) residence; (B) pole barn; (C) concrete silo #1; (D) concrete silo #2_____

Residence Detail

Style: Obscured

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa late 19th C.

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.

A residential structure shown in this location on the 1872 plat.



HE-23-1: 9715 Okeson Road – Residence, Pole Barn



HE-23-1: 9715 Okeson Road – Silos

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15_____ Survey Number: HE-23-2

Surveyor Name: M. Prchal, C.Flynn_____

Address: 9713 Okeson Road_____

Lat/Long: 42.457547/-88.391429_____

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: three_____

List Observed Structures: (A) residence; (B) wood-sided garage; (C) wood-sided shed_____

Residence Detail

Style: Gabled EI? Obscured

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa L. 19th – E.20th C.

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.

A residential structure shown near this location on the 1872 plat.



HE-23-2: 9713 Okeson Road – Residence



HE-23-2: 9713 Okeson Road – Garage, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15_____ Survey Number: HE-23-3

Surveyor Name: M. Prchal, C.Flynn_____

Address: 9617 Okeson Road; Misty Moo Farm_____

Lat/Long: 42.457487/-88.386745_____

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: seven _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) wood-sided shed/garage; (E) Pole barn #1; (F) Pole barn #2; (G) Pole barn #3

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features: enclosed front porch

Barn Detail

Style: Gabled roof dairy

Wall materials: vertical wood boards

Roof materials: metal

Foundation materials: concrete

Other distinguishing features: attached milk house

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa L. 19th C.

Number of photos taken for this property*: three_____

* Attach Photo log, additional notes and map of resource location.

A residence and farmstead are shown in this location on the 1872 plat.



HE-23-3: 9617 Okeson Road – Silo, Pole Barns, Silo



HE-23-3: 9617 Okeson Road – Shed, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15_____ Survey Number: HE-23-4 Surveyor Name: M. Prchal, C.Flynn_____

Address: 8909 Greenwood Road_____

Lat/Long: 42.455322/-88.375361_____

Primary Use: resid/Agri_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: two_____

List Observed Structures: (A) trailer home residence; (B) wood-sided shed/garage in process of demolition_____

Residence Detail

Style: trailer home

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

unknown date

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.

A cheese factory is shown in this location on the 1872 plat.



HE-23-4: 8909 Greenwood Road – Residence, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15_____ Survey Number: HE-23-5

Surveyor Name: M. Prchal, C.Flynn_____

Address: 8341 Greenwood Road_____

Lat/Long: 42.450271/-88.376390_____

Primary Use: resid/Agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: three _____

List Observed Structures: (A) Barn (obscured); (B) shed (obscured); (C) garage_____

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Barn Detail

Style: Gambrel roof?

Wall materials:

Roof materials:

Foundation materials: fieldstone

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa early 20th C.

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.

A residence is shown in this location on the 1908 plat.



HE-23-5: 8341 Greenwood Road – Barn, Shed, Garage

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 24



Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15 Survey Number: HE-24-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9007 Greenwood Road

Lat/Long: 42.457179/-88.373966

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 7

List Observed Structures: (A) Res (B) Barn (C) silo (D) shed (EFG) silos

Residence Detail

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete silo D - gabled shed/small barn E - metal grain bin F - concrete silo G - Harvestore silo

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1950



HE-24-1: 9007 Greenwood Road – Barn, Silo



HE-24-1: 9007 Greenwood Road – Residence



HE-24-1: 9007 Greenwood Road – Shed, Silos

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15 Survey Number: HE-24-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: Regnier Road _____

Lat/Long: 42.446342/-88.361238 _____

Primary Use: Res _____

Is this a record of a single structure or group (give total number of structures):

Single: Group: _____ Number Structures in Group: _____

List Observed Structures: Res _____

Residence Detail

Style: Gabled

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

far back from road so details are not visible

Number of photos taken for this property*: 1 _____

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870

Barn Detail

Style:

Wall materials:

Roof materials:


Foundation materials:

Other distinguishing features



HE-24-2: Regnier Road – Residence

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 25





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15 Survey Number: HE-25-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: Regnier Road

Lat/Long: 42.443119/-88.361301

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 5

List Observed Structures: (A) Res (B) Res2 (C) barn (D) silo (E) pole building

Residence Detail

Style: Single story Upright and Wing

Wall materials: vertical and horizontal board

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features

Any obvious Additions/Alterations
doors replaced

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - modern residence D - concrete silo E - modern pole building

owner would not allow photos of residences or other buildings

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

C. 1900

Barn Detail

Style: Gambrel roof Dairy barn

Wall materials: board

Roof materials: asphalt and
shake

Foundation materials: concrete

Other distinguishing features



HE-25-1: Regnier Road – Barn, Silo

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15 Survey Number: HE-25-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 7614 Greenwood Road

Lat/Long: 42.437001/-88.374213

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 3

List Observed Structures: (A) Res (B) barn (C) silo

Residence Detail

Style: No style

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations
replaces original farmhouse, or original has been drastically changed

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - formed concrete silo

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

C. 1900/Res late 20th century

Barn Detail

Style: Gambrel roof Dairy barn

Wall materials: board

Roof materials: metal

Foundation materials:

Other distinguishing features



HE-25-2: 7614 Greenwood Road – Barn, Silo



HE-25-2: 7614 Greenwood Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15 Survey Number: HE-25-3 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: Tryon Grove Farm

Address: 8914 Tryon Grove Road

Lat/Long: 42.429761/-88.371789

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 5

List Observed Structures: (A) Res (B) barn (C) silo (D) shed (E) shed

Residence Detail

Style: Cross Gabled

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features
obscured by dense trees

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete stave silo D - small gabled shed E - small gabled shed

may be 2 more outbuildings at rear but not visible from front of property

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870

Barn Detail

Style: Gambrel roof barn

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features
wood roof top vents



HE-25-3: 8914 Tryon Grove Road – Residence



HE-25-3: 8914 Tryon Grove Road – Barn, Silo, Sheds

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15 Survey Number: HE-25-4 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 8901 Tryon Grove Road

Lat/Long: 42.429030/-88.370701

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 3

List Observed Structures: (A) Res (B) garage (C) shed/pole barn

Residence Detail

Style: Gabled

Wall materials: aluminum

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled 2 bay garage C - modern pole barn

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

C. 1950-1960

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-25-4: 8901 Tryon Grove Road – Residence, Garage,
Pole Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15 Survey Number: HE-25-5 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 8702 Tryon Grove Road

Lat/Long: 42.429030/-88.370701

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 9

List Observed Structures: (A) Res (B) pole building (C) pole building (D) shed (E) barn (F and G) silos

(H) shed/coop (I) windmill

Residence Detail

Style: obscured

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - metal pole building C - metal and wood pole building D - shed F and G - concrete silos

H - shed/coop I - windmill base

may be more buildings to rear but obscured

Number of photos taken for this property*: 4

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870

Barn Detail

Style: Gabled Livestock

Wall materials: board

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features
rooftop vents
sets of multi-pane windows



HE-25-5: 8702 Tryon Grove Road – Pole Buildings



HE-25-5: 8702 Tryon Grove Road – Residence, Shed



HE-25-5: 8702 Tryon Grove Road – Barn, Silos, Shed, Windmill

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15 Survey Number: HE-25-6 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 8214 Tryon Grove Road

Lat/Long: 42.434052/-88.358079

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 9

List Observed Structures: (A) Res (B) shed (C) barn (D) silo

Residence Detail

Style: Gabled

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features
obscured

Any obvious Additions/Alterations

Barn Detail

Style: Gabled Hay Barn

Wall materials: board

Roof materials: fishscale

Foundation materials:

Other distinguishing features
attached office

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small gabled barn/shed with metal roof D - concrete stave silo

may be more buildings to rear but obscured

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870



HE-25-6: 8214 Tryon Grove Road – Shed



HE-25-6: 8214 Tryon Grove Road – Residence



HE-25-6: 8214 Tryon Grove Road – Barn, Silo

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15 Survey Number: HE-25-7 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: Green Earth Farm

Address: 8308 Barnard Mill Road

Lat/Long: 42.429117/-88.358579

Primary Use: Res/Ag/Commercial

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 9

List Observed Structures: (A) Res (B) shed (C) barn (D) silo

Residence Detail

Style: Obscured

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features
obscured

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

far from road and obscured by trees - includes 2 silos and a windmill

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

C. 1910

Barn Detail

Style: Gabled Hay Barn

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features



HE-25-7: 8308 Barnard Mill Road – Silos, Barn

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 26





Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number

Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15 Survey Number: HE-26-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 7213 Greenwood Road

Lat/Long: 42.430979/-88.374921

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 8

List Observed Structures: (A) Res (B) garage (C) shed (D) barn (E) silo (F) pole building (G) shed (H) shed

Residence Detail

Style: Front Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials:

Other distinguishing features sidelights around door
most distinguishing elements gone

Any obvious Additions/Alterations
concrete front steps

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - Gabled garage C - gabled shed/coop E - formed concrete silo F - pole building G - small gabled shed

H - gabled shed to rear of barn

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1880

Barn Detail

Style: Gabled livestock barn

Wall materials: board

Roof materials: fishscale

Foundation materials: concrete

Other distinguishing features



HE-26-1: 7213 Greenwood Road – Residence, Garage




HE-26-1: 7213 Greenwood Road – Shed, Pole Building



HE-26-1: 7213 Greenwood Road – Barn, Silo, Sheds

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 27





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15 Survey Number: HE-27-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: Stewart Cemetery (South Hebron Cemetery)

Address: Van Der Karr Road

Lat/Long: 42.429008/-88.394159

Primary Use: Cemetery

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: headstones

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property*: 6

* Attach Photo log, additional notes and map of resource location.

C. mid nineteenth century-present

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-27-1: Van Der Karr Road – Cemetery

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15 Survey Number: HE-27-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 7415 Stewart Road

Lat/Long: 42.434778/-88.397592

Primary Use: Res/Ag (vineyard)

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 7

List Observed Structures: (A) Res (B) garage (C) barn (D) shed (E and F) silos (G) windmill

Residence Detail

Style: Bungalow

Wall materials: board

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gambrel garage/barn D - gabled shelter/machine shed E and F - concrete stave silos with round roofs G - windmill base

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1960

Barn Detail

Style: Round Roof Livestock barn

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features
rooftop vents
attached round roof milkhouse



HE-27-2: 7415 Stewart Road - Residence



HE-27-2: 7415 Stewart Road - Garage



HE-27-2: 7415 Stewart Road – Barn, Shed, Silos,
Windmill

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15 Survey Number: HE-27-3 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: Stewart Road

Lat/Long: 42.434834/-88.396935

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 10

List Observed Structures: (A) Res (B) pole building (C) barn (D-F) silos (G) crib (H) metal silo

(I) shed (J) shed

Residence Detail

Style: Cross Gabled

Wall materials: aluminum

Roof materials: asphalt

Foundation materials:

Other distinguishing features

spindle porch supports

pyramid roof front porch

Any obvious Additions/Alterations

new windows

Barn Detail

Style: Gabled Livestock/Raised

Wall materials: board

Roof materials: shake

Foundation materials:
concrete/concrete block

Other distinguishing features

multi-pane windows

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - metal pole building w/attached garage D - concrete stave silo E and F - formed concrete silo

G - timber crib building with shake shingles H - metal grain silo I - timber shed/small barn with multiple J - small shed doors and shake shingles

Number of photos taken for this property*: 8

* Attach Photo log, additional notes and map of resource location.

C. 1880-1890

eligible, especially outbuildings



HE-27-3: Stewart Road – Barn, Silos, Crib, Shed



HE-27-3: Stewart Road – Sheds, Silos



HE-27-3: Stewart Road – Pole Building



HE-27-3: Stewart Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15 Survey Number: HE-27-4 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: Van Der Karr Road

Lat/Long: 42.429349/-88.401247

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 10

List Observed Structures: (A) Res (B) small shed (C) pole barn (D) pole barn (E) shed

(F) garage (G-I) silos (J) shed

Residence Detail

Style: Italianate

Wall materials: limestone brick

Roof materials: asphalt

Foundation materials: rough cut limestone

Other distinguishing features

rounded windows and door

sidelights at door

wide eaves

pyramid roof

defined band between 1st and 2nd story

Any obvious Additions/Alterations

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small gabled limestone shed C and D - large modern metal pole barns

E - small gabled shed F - pyramid roof garage G-I - concrete silos J -small gabled shed

according to 1872 map could be location of cheese factory

Number of photos taken for this property*: 5

* Attach Photo log, additional notes and map of resource location.

C. 1850-1860

residence and small stone building eligible



HE-27-4: Van Der Karr Road – Residence, Shed



HE-27-4: Van Der Karr Road – Pole Barns, Sheds, Silos,
Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15 Survey Number: HE-27-5 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 10714 Van Der Karr Road

Lat/Long: 42.429451/-88.406333

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage

Residence Detail

Style: Upright and Wing

Wall materials: board

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features
spindle porch supports
bay window w/decorative supports

Any obvious Additions/Alterations

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled garage

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

C. 1870



HE-27-5: 10714 Van Der Karr Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15 Survey Number: HE-27-6 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 11004 Van Der Karr Road

Lat/Long: 42.430846/-88.411733

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 5

List Observed Structures: (A) Res (B) barn (C) barn (D) silo (E) barn

Residence Detail

Style: Centered Gabled - obscured

Wall materials:

Roof materials: asphalt

Foundation materials:

Other distinguishing features

some Queen Anne style decorative trim and recessed window corner

Any obvious Additions/Alterations

Barn Detail

Style: Gabled Hay Barn/Raised

Wall materials: board

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

concrete block square "garage"
spaces/extensions on either side
roof collapsing

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - two story shed roof barn D - concrete block silo with decorative banding

E - wood and concrete **round storage barn**

Number of photos taken for this property*: 4

*Attach Photo log, additional notes and map of resource location.

C. 1890



HE-27-6: 11004 Van Der Karr Road – Barn



HE-27-6: 11004 Van Der Karr Road – Residence



HE-27-6: 11004 Van Der Karr Road – Barn, Silo



HE-27-6: 11004 Van Der Karr Road – Quonset

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 28



Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15 Survey Number: HE-28-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 11108 Van Der Karr Road

Lat/Long: 42.431936/-88.413860

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage

Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

new windows

deck

attached garage

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - garage

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

C. 1900



HE-28-1: 11108 Van Der Karr Road – Garage



HE-28-1: 11108 Van Der Karr Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15 Survey Number: HE-28-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 11101 Van Der Karr Road

Lat/Long: 42.433206/-88.416556

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 4

List Observed Structures: (A) Res (B) shed (C) shed (D) barn

Residence Detail

Style: Greek Revival

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features

wide trim at cornice
transom and sidelights at front door
round columns supporting front entry porch
decorative window crowns
false columns at corners of building
gabled emphasized with wide trim/pediment
rear extension and cellar door

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - modern machine shed C - fieldstone shed/outbuilding with wooden door and gable roof

Number of photos taken for this property*: 3

Attach Photo log, additional notes and map of resource location.

* C. 1850-1860

Barn Detail

Style: Gambrel Livestock Barn

Wall materials: wood

Roof materials: asphalt

Foundation materials:

Other distinguishing features



HE-28-2: 11101 Van Der Karr Road - Barn



HE-28-2: 11101 Van Der Karr Road - Sheds



HE-28-2: 11101 Van Der Karr Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15 Survey Number: HE-28-3 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 11401 Van Der Karr Road

Lat/Long: 42.436688/-88.419542

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 5

List Observed Structures: (A) Res (B) barn (C) garage (D) pole building (E) shed

Residence Detail

Style: Greek Revival/Upright and Wing

Wall materials: aluminum and vinyl/wood

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

side addition

windows reconfigured

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - modern garage D - pole building E - shed

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870

Barn Detail

Style: Gambrel Livestock
Barn/Raised

Wall materials: wood

Roof materials: metal

Foundation materials: concrete

Other distinguishing features
multi-pane windows




HE-28-3: 11401 Van Der Karr Road – Residence



HE-28-3: 11401 Van Der Karr Road – Barn, Garage, Pole Building, Shed

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 29



Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15 Survey Number: HE-29-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: Van Der Karr Road

Lat/Long: 42.442891/-88.433586

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: X Group: _____ Number Structures in Group: _____

List Observed Structures: Res

Residence Detail

Style: Gabled EI

Wall materials: aluminum

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features
double second story window on gable

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-29-1: Van Der Karr Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15 Survey Number: HE-29-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 12615 O'Brien Road

Lat/Long: 42.443020/-88.444524

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 7

List Observed Structures: (A) Res (B) garage (C) barn (D-F) silos (G) pole building

Residence Detail

Style: Gabled EI

Wall materials: aluminum

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features

2/2 windows

small second story window on wing

Barn Detail

Style: Gabled

Wall materials: board

Roof materials: metal

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gambrel garage/shop D and E - concrete stave silos F - formed concrete silo G - pole building

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1860-1910



HE-29-2: 12615 O'Brien Road – Silos, Barn



HE-29-2: 12615 O'Brien Road - Garage



HE-29-2: 12615 O'Brien Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15 Survey Number: HE-29-3 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 12617 O'Brien Road

Lat/Long: 42.442768/-88.445060

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 3

List Observed Structures: (A) Res (B) pole building (C) grain bin

Residence Detail

Style: T-Plan/Italianate

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features
bay window
decorative window crowns
lattice work on front and rear porches

Any obvious Additions/Alterations
attached garage

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - pole building/garage

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1860-1910

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-29-3: 12617 O'Brien Road – Pole Building



HE-29-3: 12617 O'Brien Road – Residence, Bin

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/7/15 Survey Number: HE-29-4 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 12915 O'Brien Road

Lat/Long: 42.442918/-88.449802

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 10

List Observed Structures: (A) Res (B) Res 2 (C) shed (D) shed (E) pole building (F) crib (G) barn

(H) silo (I) silo (J) quonset

Residence Detail

Style: Greek Revival

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features

cornice returns

false columns

rectangular windows

odd arrangement of facade suggests may be earlier house within

current structure

multiple doors

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - Ranch C.1970 C - shed/garage associated with B D - shed E - pole building F - drive-in crib

H and I - concrete stave silos J - metal quonset

Barn Detail

Style: L Plan Gabled

Wall materials: board

Roof materials: metal

Foundation materials:

Other distinguishing features

single story gabled extension w/

pent roof at front gable end

Number of photos taken for this property*: 6

* Attach Photo log, additional notes and map of resource location.

C. 1850-1860



HE-29-4: 12915 O'Brien Road – Residence 2



HE-29-4: 12915 O'Brien Road – Shed



HE-29-4: 12915 O'Brien Road – Shed, Pole Building, Crib




HE-29-4: 12915 O'Brien Road – Residence



HE-29-4: 12915 O'Brien Road – Barn, Silos, Quonset

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 30



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/13/15 Survey Number: HE-30-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 7120 Johnson Road

Lat/Long: 42.430532/-88.462696

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 6

List Observed Structures: (A) Res (B) garage (C) garage (D) barn (E) milkhouse (F) silo

Residence Detail

Style: obscured

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gambrel garage C- concrete block garage

E - timber milkhouse with concrete foundation and metal roof

F - concrete stave silo with rounded roof

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1870

Res and garage on east side of road, barn and other outbuildings on west side

Barn Detail

Style: Banked barn

Wall materials: board

Roof materials: metal

Foundation materials: concrete
block

Other distinguishing features



HE-30-1: 7120 Johnson Road – Garage



HE-30-1: 7120 Johnson Road – Barn, Milk House, Silo



HE-30-1: 7120 Johnson Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/13/15 Survey Number: HE-30-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 7108 Johnson Road

Lat/Long: 42.429867/-88.463586

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) shed

Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials:

Other distinguishing features
enclosed pyramid roof front entry

Any obvious Additions/Alterations
rear deck

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small garden shed

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-30-2: 7108 Johnson Road – Residence, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/13/15 Survey Number: HE-30-3 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 7304 Johnson Road

Lat/Long: 42.432005/-88.462194

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 12

List Observed Structures: (A) Res (B) coop/shelter (C) pole building (D) shed (E) barn (F) barn/crib
(G) machine shed (H and I) silos (J KL) grain bins

Residence Detail

Style: Upright and Wing

Wall materials: aluminum

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Barn Detail

Style: Gabled

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features
low profile

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - shed roofed coop or shelter C - pole building D - small gabled shed F - crib building

G - machine shed H and I - concrete silos J-L - metal grain bins

Number of photos taken for this property*: 4

* Attach Photo log, additional notes and map of resource location.



HE-30-3: 7304 Johnson Road – Outbuildings




HE-30-3: 7304 Johnson Road – Outbuildings



HE-30-3: 7304 Johnson Road – Residence

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 31





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/13/15 Survey Number: HE-31-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 7012 Johnson Road

Lat/Long: 42.427424/-88.464372

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 5

List Observed Structures: (A) Res (B) garage (C) shed (D) shed (E) silo

Residence Detail

Style: Gabled EI

Wall materials:

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations
new windows/door

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - pyramid roof garage C - gabled foundation shed w/board siding D - gambrel concrete foundation shed/small barn with board siding and dormer E - concrete stave silo

Number of photos taken for this property*: 4

* Attach Photo log, additional notes and map of resource location.

C. 1880-1890



HE-31-1: 7012 Johnson Road - Silo



HE-31-1: 7012 Johnson Road - Sheds



HE-31-1: 7012 Johnson Road - Garage



HE-31-1: 7012 Johnson Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/13/15 Survey Number: HE-31-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 6201 Johnson Road

Lat/Long: 42.415423/-88.470463

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: _____

List Observed Structures: Residence and multiple modern buildings

Residence Detail

Style: Pyramid Roof

Wall materials:

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations
front deck

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

all other buildings on property are part of a modern grain operation

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870



HE-31-2: 6201 Johnson Road – Residence



HE-31-2: 6201 Johnson Road – Modern Buildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/13/15 Survey Number: HE-31-3 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 13302 Thayer Road

Lat/Long: 42.415248/-88.456778

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 6

List Observed Structures: (A) Res (B) Barn (C) silo (D) pole building/machine shed (E) windmill (F) shed

Residence Detail

Style: Ranch

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features
too far from road to see detail

Any obvious Additions/Alterations

Barn Detail

Style: Saltbox barn

Wall materials: board

Roof materials: metal

Foundation materials: fieldstone

Other distinguishing features
side extension

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete stave silo D - pole building/shelter/machine shed E - windmill base F - small shed

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870 (appears on map) - probably only barn exists from this period



HE-31-3: 13302 Thayer Road – Barn, Silo, Sheds



HE-31-3: 13302 Thayer Road – Residence, Windmill

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/13/15 Survey Number: HE-31-4 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 13106 Thayer Road

Lat/Long: 42.414608/-88.452849

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 9

List Observed Structures: (A) Res (B) Barn (C) silo (D) silo (E) pole building (F) shed (G) shed (H) shelter (I) shed

Residence Detail

Style: Modern Split Level

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Barn Detail

Style: Gambrel

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features
obscured

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C and D - concrete silos E - pole building F, G, and I - sheds/outbuildings H - metal machine shed/shelter

Number of photos taken for this property*: 4

* Attach Photo log, additional notes and map of resource location.

C. 1900 - property appears on 1908 map but it's hard to determine which if any buildings remain from that period



HE-31-4: 13106 Thayer Road – Sheds, Shelter



HE-31-4: 13106 Thayer Road – Residence, Silo, Barn



HE-31-4: 13106 Thayer Road – Silos, Pole Building

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 32




Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/13/15 Survey Number: HE-32-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 6119 Route 47

Lat/Long: 42.415730/-88.438768

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 3

List Observed Structures: (A) Res (B) barn (C) silo

Residence Detail

Style: Gabled El

Wall materials:

Roof materials: asphalt

Foundation materials:

Other distinguishing features
bay window, but mostly obscured

Barn Detail

Style: Gambrel roof

Wall materials:

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete stave silo

any other buildings on property not visible

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870



HE-32-1: 6119 Route 47 – Residence



HE-32-1: 6119 Route 47 – Silo, Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/13/15 Survey Number: HE-32-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 6505 Route 47

Lat/Long: 42.420045/-88.438472

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 14

List Observed Structures: (A) Res (B) garage (C) pole building (D) grain bin (E) shed (F) small barn (G) machine shed (H) large barn (I and J) silos (K and L) grain bins (M) Res 2 (N) garage 2

Residence Detail

Style: Gabled EI (originally)

Wall materials: vinyl

Roof materials: asphalt

Foundation materials:

Other distinguishing features

looks like originally a Gabled EI, but then another gabled end was added. Other distinguishing features one side has a more steeply pitched gable, the other has a lower profile. Both sides have bay windows, but the south side (which may be original) has a double second floor window, while the north side has two separate windows. The first floor porch connects pretty seamlessly to both sides, and there is a centered gabled dormer/door on the second floor wing. The second gable was probably a fairly early addition.

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - garage (behind Res) C - pole building D - metal grain bin E - gabled shed

F - small gambrel barn with rough block foundation G - pole building/machine shed

I and J - concrete stave silos K and L - metal grain bins M - second Res (Upright and Wing with enclosed porch/vinyl siding/asphalt roof) N - second garge (2 bay gabled)

Number of photos taken for this property*: 6

* Attach Photo log, additional notes and map of resource location.

C. 1860-1870



HE-32-2: 6505 Route 47 - Residence



HE-32-2: 6505 Route 47 – Barns, Shed



HE-32-2: 6505 Route 47 - Silos



HE-32-2: 6505 Route 47 – Residence 2, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/13/15 Survey Number: HE-32-3 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 7004 Route 47

Lat/Long: 42.427072/-88.437465

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 14

List Observed Structures: (A) Res (B) pole building (C) pole building (D) silo (E) grain silo complex

(F) Barn (G-I) silos

Residence Detail

Style: Ranch

Wall materials: brick/stone facing

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features
wide low roof

Any obvious Additions/Alterations

Barn Detail

Style: Gambrel roof

Wall materials: board

Roof materials: metal

Foundation materials: concrete

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - pole building/machine shed C - pole building D - concrete stave silo E - metal grain silo/complex

G - I - concrete silos

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1940-1965 (barn and silos may be older/res C. 1960)



HE-32-3: 7004 Route 47 – Residence, Pole Building




HE-32-3: 7004 Route 47 – Pole Building, Silo, Silo Complex



HE-32-3: 7004 Route 47 – Barn, Silos

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 33



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/13/15 Survey Number: HE-33-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 11718 Thayer Road

Lat/Long: 42.430532/-88.462696

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 4

List Observed Structures: (A) Res (B) pole building (C) shed (D) grain silo (E) shed

Residence Detail

Style: Gabled EI

Wall materials: board

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features
covered entry porch
ornate window and door hoods

Any obvious Additions/Alterations
shutters

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - pole building C - block shed w/ gable roof D - grain silo complex E - small shed

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1880-1890

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



HE-33-1: 11718 Thayer Road – Pole Building, Shed, Silo



HE-33-1: 11718 Thayer Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/13/15 Survey Number: HE-33-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 6811 Kenman Road

Lat/Long: 42.426067/-88.414056

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 3

List Observed Structures: (A) Res (B) pole building (C) shed

Residence Detail

Style: Gabled EI

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features
obscured

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - pole building C - small shed

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

C. 1900

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features




HE-33-2: 6811 Kenman Road – Residence, Pole Building



HE-33-2: 6811 Kenman Road – Shed

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 34



Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location





Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/13/15 Survey Number: HE-34-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 10714 Van Der Karr Road

Lat/Long: 42.428568/-88.406869

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) barn (B) silo

Residence Detail

Style: modern

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Barn Detail

Style: Gabled Hay barn

Wall materials: board

Roof materials: metal

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - concrete silo

other buildings on property are modern

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

C. 1920 - barn



HE-34-1: 10714 Van Der Karr Road – Barn, Silo



HE-34-1: 10714 Van Der Karr Road – Modern Building

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/13/15 Survey Number: HE-34-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 10419 Van Der Karr Road

Lat/Long: 42.428451/-88.401393

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 5

List Observed Structures: (A) Res (B) garage/pole building (C) barn (D) shed (E) shed (F) silo

Residence Detail

Style: Gabled EI

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features

ornate window hoods

wide cornices

square porch supports

Barn Detail

Style: Gabled Hay barn

Wall materials: board

Roof materials: metal

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - garage/pole building D and E - smaller gabled shed F - brick silo, partially demolished

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1850-1860

Residence may be eligible



HE-34-2: 10419 Van Der Karr Road - Silo



HE-34-2: 10419 Van Der Karr Road – Pole Building, Barn, Sheds



HE-34-2: 10419 Van Der Karr Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/13/15 Survey Number: HE-34-3 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 10316 Thayer Road

Lat/Long: 42.414961/-88.398613

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 3

List Observed Structures: (A) Res (B) garage/pole building (C) barn

Residence Detail

Style: Minimal Traditional

Wall materials:

Roof materials: asphalt

Foundation materials:

Other distinguishing features
too far from road/obscured

Any obvious Additions/Alterations

Barn Detail

Style: Gabled

Wall materials: shingles

Roof materials: asphalt

Foundation materials:

Other distinguishing features
gabled dormers

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - garage/pole building

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1960



HE-34-3: 10316 Thayer Road – Residence, Garage/Pole Building



HE-34-3: 10316 Thayer Road – Barn

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 35





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/13/15 Survey Number: HE-35-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 6500 Miller Road

Lat/Long: 42.418783/-88.393932

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: _____

List Observed Structures: (A) Res (B) barn (C) silo

Residence Detail

Style: Neo-Colonial

Wall materials: aluminum

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Barn Detail

Style: Gambrel

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features
obscured

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete silo Other buildings also present

property heavily secured- fencing, trees, security cameras, making it difficult to document

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

C. 1960



HE-35-1: 6500 Miller Road – Barn, Silo



HE-35-1: 6500 Miller Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/13/15 Survey Number: HE-35-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9703 Van De Karr Road

Lat/Long: 42.424752/-88.386665

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 6

List Observed Structures: (A) Res (B) pole barn (C) pole barn (D-F) grain bins

Residence Detail

Style: Ranch

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features
too far from road

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B and C - metal pole barns D-F - metal grain silos

property heavily secured- fencing, trees, security cameras, making it difficult to document

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

C. 1960-1965



HE-35-2: 9703 Van De Karr Road – Bins



HE-35-2: 9703 Van De Karr Road – Residence, Pole Barns

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/13/15 Survey Number: HE-35-3 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 6142 Greenwood Road

Lat/Long: 42.420451/-88.376748

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 6

List Observed Structures: (A) Res (B) garage (C) small barn (D) shed (E) shed (F) barn

Residence Detail

Style: Gabled EI

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Barn Detail

Style: Gabled Hay Barn

Wall materials: asbestos

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - garage C - small gambrel barn D - garden shed E - small shed

property heavily secured- fencing, trees, security cameras, making it difficult to document

Number of photos taken for this property*: 4

* Attach Photo log, additional notes and map of resource location.

C. 1900



HE-35-3: 6142 Greenwood Road – Barn, Sheds



HE-35-3: 6142 Greenwood Road - Barn



HE-35-3: 6142 Greenwood Road – Residence,
Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/13/15 Survey Number: HE-35-4 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 6109 Greenwood Road

Lat/Long: 42.415003/-88.380248

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage

Residence Detail

Style: Gabled EI

Wall materials: aluminum

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations
shutters

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled garage

property heavily secured- fencing, trees, security cameras, making it difficult to document

Number of photos taken for this property*: 2


* Attach Photo log, additional notes and map of resource location.

C. 1860-1870



HE-35-4: 6109 Greenwood Road – Residence

MCHENRY COUNTY
HEBRON TOWNSHIP
SECTION 36



Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- HE-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/13/15 Survey Number: HE-36-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 7016 Greenwood Road

Lat/Long: 42.428532/-88.374353

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 4

List Observed Structures: (A) Res (B) garage (C) shed (D) shed

Residence Detail

Style: Gabled

Wall materials: aluminum

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations
roofline extended with flat roof

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled garage C and D - shed

maps suggest this is Tryons Grove School

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

C. 1850-1870



HE-36-1: 7016 Greenwood Road – Residence, Garage,
Sheds

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 5/13/15 Survey Number: HE-36-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 8303 Barnard Mills Road

Lat/Long: 42.427165/-88.359307

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 8

List Observed Structures: (A) Res (B) garage (C) shed (D) shed (E) barn (F) silo (G) shed
(H) pole building

Residence Detail

Style: Gabled EI

Wall materials: board

Roof materials: asphalt/metal

Foundation materials:

Other distinguishing features
bay/box window
front porch

Barn Detail

Style: Gabled T Plan

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features
transom window over front
door

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - garage C and D - outbuildings/sheds F - formed concrete silo G - shed H - pole building

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

C. 1850-1870



HE-36-2: 8303 Barnard Mills Road – Shed, Pole Building



HE-36-2: 8303 Barnard Mills Road – Shed, Barn, Silo



HE-36-2: 8303 Barnard Mills Road – Residence, Garage, Shed