

McHenry County




Illinois

Township Key


Chemung	Alden	Hebron	
Dunham	Hartland		
Marengo	Seneca		
Riley		Not Included in Survey	

Seneca Township

T44N, R6E



MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 1



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-1-1_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 14212 Kishwaukee Valley Road _____

Lat/Long: 42.316817/-88.475901 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) barn; (C) garage; (D) wire corn bin; (E) small wood-sided shed; (F) metal pole barn

Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: large stone chimney

Barn Detail

Style: Gambrel roof

Wall materials: vertical wood boards

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: shed roof,
milk house attached

Any obvious Additions/Alterations: front porch enclosed.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-1-1: 14212 Kishwaukee Valley Road - Outbuildings



SE-1-1: 14212 Kishwaukee Valley Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-1-2_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 14305 Kishwaukee Valley Road _____

Lat/Long: 42.316958/-88.477049 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete block under porch

Other distinguishing features: large stone chimney

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: front porch enclosed. House faces east

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965-1978 assessor date

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-1-2: 14305 Kishwaukee Valley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-1-3_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: Kiawassa_____

Address: 14604 Kishwaukee Valley Road_____

Lat/Long: 42.316893/-88.483033_____

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group:_____

List Observed Structures: (A) residence; (B-D) three vinyl/wood-sided outbuildings

Residence Detail

Style: Cape Cod

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965-1978 assessor date

Number of photos taken for this property*:two_____

* Attach Photo log, additional notes and map of resource location.



SE-1-3: 14604 Kishwaukee Valley Road - Outbuildings



SE-1-3: 14604 Kishwaukee Valley Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-1-4_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 701 Rose Farm Road _____

Lat/Long: 42.318347/-88.491702 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) small wood-sided shed; (C) small wood-sided garage with barn doors

Residence Detail

Style: Greek Revival

Wall materials: wood clapboard

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*:two _____

* Attach Photo log, additional notes and map of resource location.



SE-1-4: 708 Rose Farm Road - Residence



SE-1-4: 708 Rose Farm Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-1-5_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name:_____

Address: 204 Rose Farm Road_____

Lat/Long: 42.325934/-88.491515_____

Primary Use: residence_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Cape Cod

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: attached three-bay garage

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965-1978 assessor date

Number of photos taken for this property*:one _____

* Attach Photo log, additional notes and map of resource location.



SE-1-5: 204 Rose Farm Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-1-6_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 114 Rose Farm Road _____

Lat/Long: 42.326428/-88.491485 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence; (B) barn; (C) small tool shed with cupola; (D) metal pole barn; (E) small raised wood-sided shed

Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Gabled Roof, Center bay

Wall materials: wood/vinyl

Roof materials: obscured

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1939 assessor date

Number of photos taken for this property*:two _____

* Attach Photo log, additional notes and map of resource location.



SE-1-6: 114 Rose Farm Road - Residence



SE-1-6: 114 Rose Farm Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-1-7_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 14715 Kishwaukee Valley Road _____

Lat/Long: 42.316221/-88.484914 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Obscured

Wall materials: wood/vinyl

Roof materials: obscured

Foundation materials:

Other distinguishing features: may be side

gabled

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965 assessor date

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-1-7: 14715 Kishwaukee Valley Road – Cabin

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-1-8_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 14515 Kishwaukee Valley Road _____

Lat/Long: 42.315911/-88.482232 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Ranch

Wall materials: wood/vinyl

Roof materials: obscured

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965 assessor date

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-1-8: 14515 Kishwaukee Valley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-1-9_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 14513 Kishwaukee Valley Road _____

Lat/Long: 42.315927/-88.481902 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Cape Cod

Wall materials: wood/vinyl

Roof materials: obscured

Foundation materials: concrete

Other distinguishing features: attached garage

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965 assessor date

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-1-9: 14513 Kishwaukee Valley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-1-10_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: Rindal Transitional Home_____

Address: 14411 Kishwaukee Valley Road_____

Lat/Long: 42.314957/-88.479833_____

Primary Use: residence/institution_____

Is this a record of a single structure or group (give total number of structures):

Single: X_____ Group:_____ Number Structures in Group:_____

List Observed Structures: (A) residence building

Residence Detail

Barn Detail

Style: No style

Style:

Wall materials: brick

Wall materials:

Roof materials: obscured

Roof materials:

Foundation materials: concrete

Foundation materials:

Other distinguishing features:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965 assessor date

Number of photos taken for this property*:one_____

* Attach Photo log, additional notes and map of resource location.



SE-1-10: 14411 Kishwaukee Valley Road – Building

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-1-11_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 14315 Kishwaukee Valley Road _____

Lat/Long: 42.316133/-88.478123 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Cape Cod

Wall materials: vinyl/wood

Roof materials: obscured

Foundation materials: concrete

Other distinguishing features: attached garage

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: front roof dormer, front porch enclosed

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965 assessor date

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-1-11: 14315 Kishwaukee Valley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-1-12_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 815 Alpine Lane _____

Lat/Long: 42.316123/-88.477482 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: obscured

Wall materials: vinyl/wood

Roof materials: obscured

Foundation materials: obscured

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1939 assessor date

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-1-12: 815 Alpine Lane – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-1-13_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 14207 Kishwaukee Valley Road _____

Lat/Long: 42.315869/-88.476726 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Ranch

Wall materials: wood

Roof materials: obscured

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965 assessor date

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-1-13: 14207 Kishwaukee Valley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-1-14_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 1101 Alpine Lane _____

Lat/Long: 42.312714/-88.478227 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Ranch

Wall materials: wood

Roof materials: obscured

Foundation materials: concrete

Other distinguishing features: attached garage below grade

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1939 assessor date

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-1-14: 1101 Alpine Lane – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-1-15_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name:_____

Address: 1104 Alpine Lane_____

Lat/Long: 42.312505/-88.476564_____

Primary Use: residence_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: No style

Wall materials: unknown Roof

materials: obscured

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1939 assessor date

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.



SE-1-15: 1104 Alpine Lane – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-1-16_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 14115 Kishwaukee Valley Road _____

Lat/Long: 42.313806/-88.475553 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: _____

List Observed Structures: (A) residence; (B-) obscured out-buildings

Residence Detail

Style: Side Gabled

Wall materials: unknown

Roof materials: obscured

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1939 assessor date


Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-1-16: 14115 Kishwaukee Valley Road – Residence

MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 2




Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-2-1_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: Hughes Road _____

Lat/Long: 42.317881/-88.510698 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) metal pole barn

Residence Detail

Style: Modern

Wall materials: brick

Roof materials: snow-covered

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Gambrel roof

Wall materials: vinyl

Roof materials: metal

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Property Group Date Range: Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-2-1: Hughes Road - Residence



SE-2-1: Hughes Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-2-2_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 308 Hughes Road _____

Lat/Long: 42.323423/-88.509257 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) metal pole barn

Residence Detail

Style: Modern Ranch

Wall materials: brick

Roof materials: snow-covered

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Gambrel roof

Wall materials: vinyl

Roof materials: metal

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Property Group Date Range: Circa 1872

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-2-2: 308 Hughes Road – Residence, Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-2-3_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 910 Hobe Road _____

Lat/Long: 42.314119/-88.507061 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) barn; (C-D) concrete stave silos; (E) small gambrel roof barn/garage; (F) metal pole barn metal pole barn

Residence Detail

Style: Modern

Wall materials: brick

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Barrel roof/ peak roof

Wall materials: vinyl/wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: two styles/phases connected. Office attached

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Property Group Date Range: Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-2-3: 910 Hobe Road - Outbuildings



SE-2-3: 910 Hobe Road – Barn, Silos

MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 3



Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

0 125 250 500 Meters

0 375 750 1,500 Feet

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-3-1_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 311 Hughes Road _____

Lat/Long: 42.323430/-88.511648 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) garage; (C-D) concrete stave silos; (E) metal grain bin

Residence Detail

Style: Italianate

Wall materials: wood/vinyl

Roof materials: asphalt

Foundation materials: unknown/covered

Other distinguishing features: screened-in rear porch

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.



SE-3-1: 311 Hughes Road - Residence



SE-3-1: 311 Hughes Road - Garage



SE-3-1: 311 Hughes Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-3-2_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 605 Hughes Road _____

Lat/Long: 42.319615/-88.511814 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown/covered

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1960

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-3-2: 605 Hughes Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-3-3_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 402 Dimmel Road _____

Lat/Long: 42.323621/-88.530155 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) barn; (C) garage

Residence Detail

Style: No Style

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: limestone

Other distinguishing features:

Barn Detail

Style: one-story peaked roof

Wall materials: vertical wood boards

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.




SE-3-3: 402 Dimmel Road - Outbuildings



SE-3-3: 402 Dimmel Road – Residence

MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 4



Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location




Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-4-1_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 209 Dimmel Road _____

Lat/Long: 42.323621/-88.530155 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) barn; (C) garage; (D) small vinyl-clad shed; (E) metal pole barn

Residence Detail

Style: No Style

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features: enclosed front

porch - remodeled Gabled EI

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872-1892

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gambrel roof

Wall materials: vinyl

Roof materials: metal

Foundation materials: unknown

Other distinguishing features:



SE-4-1: 209 Dimmel Road - Outbuildings



SE-4-1: 209 Dimmel Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-4-2_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 17808 Kishwaukee Valley Road _____

Lat/Long: 42.316213/-88.549603 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: attached garage

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965-1970

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-4-2: 17808 Kishwaukee Valley Road – Residence

MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 5





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/4/15_____ Survey Number: SE-5-1_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 515 McKinstry Road _____

Lat/Long: 42.316213/-88.549603 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence; (B) residence; (C) barn; (D) shed; (E) shed (F-H) silos

Residence Detail (Res 1)

Barn Detail

Style: Minimal Traditional

Style: Gambrel roof

Wall materials: vinyl

Wall materials:

Roof materials: asphalt

Roof materials:

Foundation materials: concrete

Foundation materials:

Other distinguishing features: attached garage

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. B - Upright and Wing residence D and E - gabled sheds F-H - concrete silos

Circa 1872-1892

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.



SE-5-1: 515 McKinstry Road - Outbuildings



SE-5-1: 515 McKinstry Road – Residence 1



SE-5-1: 515 McKinstry Road – Residence 2



SE-5-1: 515 McKinstry Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-5-2_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 18104 Kishwaukee Valley Road _____

Lat/Long: 42.313300/-88.550253 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence;

Residence Detail

Style: Ranch

Wall materials: brick/vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: attached garage

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1960-1965

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-5-2: 18104 Kishwaukee Valley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-5-3_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 18110 Kishwaukee Valley Road _____

Lat/Long: 42.314442/-88.552795 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) garage

Residence Detail

Style: Ranch

Wall materials: /stonebrick

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965-1970

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-5-3: 18110 Kishwaukee Valley Road – Residence,
Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-5-4_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 18316 Kishwaukee Valley Road _____

Lat/Long: 42.313917/-88.555628 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) garage; (C) pole barn

Residence Detail

Style: one-story Gabled El

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872-1892

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-5-4: 18316 Kishwaukee Valley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-5-5_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: Moctezuma Stables_____

Address: 18520 Kishwaukee Valley Road_____

Lat/Long: 42.313215/-88.559410_____

Primary Use: resid/equestrian_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: six_____

List Observed Structures: (A) residence; (B) barn; (C) garage; (D) small shed; (E) metal pole barn stables ; (F) metal pole barn

Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features:

Barn Detail

Style: Gambrel roof dairy

Wall materials: vertical wood boards

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: shed attached

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Coirca 1870-1890

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.



SE-5-5: 18520 Kishwaukee Valley Road - Outbuildings



SE-5-5: 18520 Kishwaukee Valley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-5-6_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 18905 Kishwaukee Valley Road _____

Lat/Long: 42.313261/-88.565700 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Cape Cod

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1930-1940


Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-5-6: 18905 Kishwaukee Valley Road – Residence

MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 6





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-6-1_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 19110 Kishwaukee Valley Road _____

Lat/Long: 42.313446/-88.570411 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Ranch

Wall materials: brick

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

cCirca 1965

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-6-1: 19110 Kishwaukee Valley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-6-2_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 19516 Kishwaukee Valley Road _____

Lat/Long: 42.313145/-88.578360 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) barn; (C) garage

Residence Detail

Style: Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: wrap-around porch with stone support

Barn Detail

Style: Gambrel roof

Wall materials: vertical wood boards

Roof materials: metal

Foundation materials: concrete

Other distinguishing features: two metal cupolas/vents

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1910-1920

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-6-2: 19516 Kishwaukee Valley Road - Barn



SE-6-2: 19516 Kishwaukee Valley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-6-3_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 19712 Kishwaukee Valley Road _____

Lat/Long: 42.313943/-88.581880 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Ranch

Wall materials: stone/brick

Roof materials: asphalt Foundation

materials:

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965-1978

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-6-3: 19712 Kishwaukee Valley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-6-4_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 1008 Menge Road _____

Lat/Long: 42.313971/-88.587976 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) barn; (C-D) concrete stave silos; (E) garage

Residence Detail

Style: Upright and Wing

Wall materials: vinyl/brick

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: new wing added to W side

Barn Detail

Style: Gabled roof

Wall materials: vertical wood

Roof materials: metal

Foundation materials: concrete

Other distinguishing features: large shed attachment, small shed attachment

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1850-1870

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.



SE-6-4: 1008 Menge Road - Outbuildings



SE-6-4: 1008 Menge Road – Residence



SE-6-4: 1008 Menge Road – Barn, Silo

MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 7





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-7-1_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name:_____

Address: 19309 Collins Road_____

Lat/Long: 42.299284/-88.537975_____

Primary Use: residence_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) vertical wood-sided shed/barn

Residence Detail

Barn Detail

Style:

Style: Gabled roof

Wall materials:

Wall materials: vertical wood

Roof materials:

Roof materials: asphalt

Foundation materials:

Foundation materials: unknown

Other distinguishing features:

Other distinguishing features:

Any obvious Additions/Alterations: Remains of a demolished farmstead

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.



SE-7-1: 19309 Collins Road – Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-7-2_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 19514 Collins Road _____

Lat/Long: 42.298712/-88.578457 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: Remains of a demolished farmstead

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-7-2: 19514 Collins Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-7-3_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name:_____

Address: 19806 Collins Road_____

Lat/Long: 42.298708/-88.582931_____

Primary Use: resid/agri: abandoned_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: two_____

List Observed Structures: (A) stone structure, poss. small residence or an outbuilding; (B) metal shed

Residence Detail

Barn Detail

Style: demolished

Style:

Wall materials:

Wall materials:

Roof materials:

Roof materials:

Foundation materials:

Foundation materials:

Other distinguishing features:

Other distinguishing features:

Any obvious Additions/Alterations: Remains of a demolished farmstead

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.



SE-7-3: 19806 Collins Road – Stone Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-7-4_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 1512 Deer Pass Road _____

Lat/Long: 42.306228/-88.588470 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) garage

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: brick

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-7-4: 1512 Deerpass Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-7-5_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 19319 Kishwaukee Valley Road _____

Lat/Long: 42.312457/-88.757184 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo

Residence Detail

Style: No style

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Peaked roof

Wall materials: vertical wood

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features: newer siding

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Property Group Date Range: circa 1872

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.



SE-7-5: 19319 Kishwaukee Valley Road - Outbuildings



SE-7-5: 19319 Kishwaukee Valley Road – Residence

MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 8





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-8-1_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 1215 Sullivan Road _____

Lat/Long: 42.310504/-88.862214 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) barn; (C) garage; (D) large barn-like structure may be a modern residence or agri/industrial building (asphalt, vinyl, concrete)

Residence Detail

Style: Minimal Traditional

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style: Peaked roof

Wall materials: unknown

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1930

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.



SE-8-1: 1215 Sullivan Road - Outbuildings



SE-8-1: 1215 Sullivan Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-8-2_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 1516 Sullivan Road _____

Lat/Long: 42.306106/-88.559231 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) barn; (C) small wood-sided shed with metal roof; (D) garage

Residence Detail

Style: Minimal Traditional

Wall materials: wood/vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style: Gabled roof

Wall materials: wood

Roof materials: asphalt/wood

Foundation materials: unknown

Other distinguishing features: poss. two sections, mostly collapsed

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1920-1930

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.



SE-8-2: 1516 Sullivan Road - Residence



SE-8-2: 1516 Sullivan Road – Shed



SE-8-2: 1516 Sullivan Road – Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-8-3_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 1702 Sullivan Road _____

Lat/Long: 42.304572/-88.559970 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) barn; (C) long wood-sided machine shed/garage with metal roof; (D-E) concrete stave silos; (F) tall metal-frame windmill

Residence Detail Style:

Style: Pyramid Roof

Wall materials: wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style: Round roofed, T-shaped

Wall materials: vertical wood

Roof materials: shake shingle

Foundation materials: unknown

Other distinguishing features: in two joining sections, metal cupolas/vents

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.



SE-8-3: 1702 Sullivan Road - Residence



SE-8-3: 1702 Sullivan Road – Barn



SE-8-3: 1702 Sullivan Road – Outbuilding

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-8-4_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name:_____

Address: 18302 Collins Road_____

Lat/Long: 42.298726/-88.553449_____

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: four_____

List Observed Structures: (A) residence; (B) barn; (C) wood-sided equipment barn; (D) small concrete block shed

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gabled roof, L-shaped

Wall materials: vertical wood

Roof materials: metal

Foundation materials: unknown

Other distinguishing features:



SE-8-4: 18302 Collins Road - Residence



SE-8-4: 18302 Collins Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-8-5_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 18302 Collins Road _____

Lat/Long: 42.298726/-88.553449 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) barn; (C) concrete block milk house; (D) concrete stave silo

Residence Detail

Style: Foursquare

Wall materials: vertical wood/brick

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Gambrel roofed, banked

Wall materials: vertical wood

Roof materials: metal

Foundation materials: fieldstone

Other distinguishing features:

Any obvious Additions/Alterations: two brick-clad wings added to sides

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872-1892

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-8-5: 18802 Collins Road - Barn



SE-8-5: 18802 Collins Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-8-6_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: Jane's Farm_____

Address: 18316 Collins Road_____

Lat/Long: 42.312597/-88.554916_____

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) barn; (C) wood-sided small barn or stables; (D) small tool shed; (E) metal pole barn; (F) concrete stave silo

Residence Detail

Style: Colonial Revival

Wall materials: vinyl/alum

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Gambrel roofed, dairy

Wall materials: vertical wood

Roof materials: metal

Foundation materials: fieldstone

Other distinguishing features:

Any obvious Additions/Alterations: additions to E and W

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1900

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.




SE-8-6: 18316 Kishwaukee Valley Road - Outbuildings



SE-8-6: 18316 Kishwaukee Valley Road – Residence

MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 9



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location





Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-9-1_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 1303 Vermont Road _____

Lat/Long: 42.310109/-88.545351 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: seven _____

List Observed Structures: (A) residence; (B) barn #1; (C) barn #2; (D) wood sided low equipment shed/garage; (E-F) concrete stave silos; (G) metal pole barn

Residence Detail

Style: Upright and Wing

Wall materials: asbestos shingle

Roof materials: asphalt

Foundation materials: concrete over stone

Other distinguishing features:

Barn Detail

Style: (A) Gambrel roofed, dairy

Wall materials: vertical wood

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: attached milk house

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. Barn #2 is Barrel roofed with large dormer/cupola

Circa 1850-1860

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-9-1: 1303 Vermont Road - Outbuildings



SE-9-1: 1303 Vermont Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-9-2_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 1525 Vermont Road _____

Lat/Long: 42.306299/-88.541158 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) garage

Residence Detail

Style: Front Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Gambrel roofed, dairy

Wall materials: vertical wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: newer siding,
metal cupola/vent

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.



SE-9-2: 1525 Vermont Road - Outbuildings



SE-9-2: 1525 Vermont Road – Barn



SE-9-2: 1525 Vermont Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-9-3_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 2005 Vermont Road _____

Lat/Long: 42.299583/-88.538025 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) barn; (C) low long coop/shed; (D) garage; (E) poss. 5th building, obscured

Residence Detail

Style: Foursquare

Wall materials: vinyl/brick

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: front entrance and porch remodeled

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: one-story addition to north

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872-1892

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-9-3: 2005 Vermont Road - Outbuildings



SE-9-3: 2005 Vermont Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-9-4_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 1920 Vermont Road _____

Lat/Long: 42.300186/-88.537088 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) barn

Residence Detail

Style: Minimal Traditional

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style: modern Gambrel roofed

Wall materials: vinyl/metal

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: modern

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1940-1950

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-9-4: 1920 Vermont Road – Residence, Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/5/15_____ Survey Number: SE-9-5_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 1210 Vermont Road _____

Lat/Long: 42.310871/-88.544749 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) barn; (C) wood-sided garage; (D) concrete stave silo; (E) shed or poss. 2nd residence to rear

Residence Detail

Style: Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: enclosed front porch

Barn Detail

Style: Gabled roof

Wall materials: vinyl/wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-9-5: 1210 Vermont Road – Residence



SE-9-5: 1210 Vermont Road – Outbuildings

MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 10





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-10-1_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name:_____

Address: 1317 Hobe Road_____

Lat/Long: 42.303746/-88.511705_____

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: extended

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1960-1965

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.



SE-10-1: 1713 Hobe Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-10-2_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 1913 Hobe Road _____

Lat/Long: 42.300554/-88.512452 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) garage; (C) concrete stave silo

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

Barn Detail

Style: demolished

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-10-2: 1913 Hobe Road – Residence



SE-10-2: 1913 Hobe Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-10-3_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 16410 Collins Road _____

Lat/Long: 42.298819/-88.518555 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) wood-sided garage/shed; E)

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete over fieldstone

Other distinguishing features: front porch

Barn Detail

Style: Gambrel roofed

Wall materials: vertical wood

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: attached milk house

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-10-3: 16410 Collins Road – Outbuildings



SE-10-3: 16410 Collins Road – Residence

MCHENRY COUNTY
 SENECA TOWNSHIP
 SECTION 11





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
 Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-11-1_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 1712 Hobe Road _____

Lat/Long: 42.303921/-88.510752 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: nine _____

List Observed Structures: (A) residence; (B) barn; (C) concrete silo; (D) vertical wood-sided garage/shed/barn; E) metal grain bin; (F) metal pole barn; (G-I) metal pole barns/sheds

Residence Detail

Style: Itaianate

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: house faces east.

Barn Detail

Style: Gabled roof, side gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: attached milk house

Any obvious Additions/Alterations: one-story addition at NE corner

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1850-1860

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-11-1: 1712 Hobe Road - Residence



SE-11-1: 1712 Hobe Road – Barn



SE-11-1: 1712 Hobe Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-11-2_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 1608 Rose Farm Road _____

Lat/Long: 42.305710/-88.494295 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: seven _____

List Observed Structures: (A) residence; (B) barn; (C) concrete silo; (D) metal pole barn/garage; (E) garage; (F) metal pole barn/garage with shed extension; (G) metal pole barn/shed

Residence Detail

Style: Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features:

Barn Detail

Style: Gambrel roof

Wall materials: vertical wood

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: attached milk house

Any obvious Additions/Alterations: front porch supported by timbers

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1900

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.



SE-11-2: 1608 Rose Farm Road - Outbuildings



SE-11-2: 1608 Rose Farm Road – Outbuildings



SE-11-2: 1608 Rose Farm Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-11-3_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 1813 Rose Farm Road _____

Lat/Long: 42.302531/-88.494592 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: seven _____

List Observed Structures: (A) residence; (B) barn; (C-D) concrete stave silos; (E) concrete block shed with metal upper; (F) larger concrete block peaked-roof barn with block glass windows; (G) small wooden shed with split roof lines

Residence Detail

Style: Pyramid Roof

Wall materials: asbestos shingle/other

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: brick wall at entrance

Barn Detail

Style: Gabled roof

Wall materials: vertical wood

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features: siding and roof partly missing

Any obvious Additions/Alterations: front porch enclosed with brick siding, block glass windows

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.



SE-11-3: 1813 Rose Farm Road – Residence



SE-11-3: 1608 Rose Farm Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-11-4_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 3541 Rose Farm Road _____

Lat/Long: 42298557/-88.496590 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Minimal Traditional

Wall materials: brick/vinyl/wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: single roof dormer

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: residence incorporates garage with barn doors.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1920-1940

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-11-4: 3541 Rose Farm Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-11-5_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 15402 South Street _____

Lat/Long: 42.298563/-88.497513 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) two-bay garage

Residence Detail

Style: Ranch

Wall materials: brick

Roof materials: asphalt

Foundation materials: brick covered

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1955-1965

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-11-5: 15402 South Street – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-11-6_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 15122 South Street _____

Lat/Long: 42.298576/-88.498461 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) barn #1; (C) barn #2; (D) wood-sided crib; (E) pole barn to rear

Residence Detail

Style: Cross Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: diagonal window

Barn Detail

Style: Gabled roof dairy

Wall materials: vertical wood/asbestos shingles

Roof materials: asphalt

Foundation materials: unknown/covered

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. Barn #2 is wood and vinyl covered with shed extension

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-11-6: 15412 South Street – Outbuildings



SE-11-6: 15412 South Street – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-11-7_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: Pioneer Cemetery_____

Address: South Street_____

Lat/Long: 42.298387/-88.501159_____

Primary Use: cemetery_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: none

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Barn Detail

Style:

Wall materials

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.



SE-11-7: South Street – Pioneer Cemetery

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-11-8_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 15620 South Street _____

Lat/Long: 42.298579/-88.503331 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) garage; (C) small wood-sided shed; (D) small two-story vertical wood-sided shed/barn, mostly dismantled

Residence Detail

Barn Detail

Style: Ranch

Style:

Wall materials:

Wall materials

Roof materials:

Roof materials:

Foundation materials:

Foundation materials:

Other distinguishing features:

Other distinguishing features:

Any obvious Additions/Alterations: original residence demolished

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1960-1965

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.



SE-11-8: 15620 South Street – Residence, Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-11-9_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 15620 South Street _____

Lat/Long: 42.298579/-88.503331 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) metal clad garage; (C) metal shed

Residence Detail

Style: Queen Anne

Wall materials: vinyl/alum

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features: leaded glass windows, shutters

Barn Detail

Style:

Wall materials

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: no front steps

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872


Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-11-9: 15906 South Street – Residence, Outbuildings

MCHENRY COUNTY
 SENECA TOWNSHIP
 SECTION 12





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
 Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-12-1_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name:_____

Address: 14818 South Street_____

Lat/Long: 42.298229/-88.847396_____

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: two_____

List Observed Structures: (A) residence; (B) tool shed

Residence Detail

Style: Ranch

Wall materials: vinyl/alum

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965

Number of photos taken for this property*:one_____

* Attach Photo log, additional notes and map of resource location.



SE-12-1: 14818 South Street – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-12-2_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 14906 South Street _____

Lat/Long: 42.298225/-88.888326 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) garage

Residence Detail

Style: Minimal Traditional

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1950-1960

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-12-2: 14906 South Street – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-12-3_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 14914 South Street _____

Lat/Long: 42.298209/-88.498064 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Minimal Traditional

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: attached garage

Barn Detail

Style:

Wall materials

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1960

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-12-3: 14914 South Street – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-12-4_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: Long Meadow Farm_____

Address: 15016 South Street_____

Lat/Long: 42.298544/-88.490826_____

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group:_____

List Observed Structures: (A) residence #1; (B) barn; (C) residence #2: Raised Ranch or Split Level

Residence Detail

Barn Detail

Style: Split Level

Style: Gabled roof/unknown

Wall materials: vinyl

Wall materials: wood

Roof materials: asphalt

Roof materials: unknown

Foundation materials: unknown

Foundation materials: unknown

Other distinguishing features:

Other distinguishing features:

Any obvious Additions/Alterations: enclosed front porch

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965

Number of photos taken for this property*: three_____

* Attach Photo log, additional notes and map of resource location.



SE-12-4: 15016 South Street – Residence 1, Outbuilding



SE-12-4: 15016 South Street – Residence 2

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-12-5_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 14510 South Street _____

Lat/Long: 42.298608/-88.481031 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) small tool shed

Residence Detail

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: banked, garage below grade

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-12-5: 14510 South Street – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-12-6_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 14516 South Street _____

Lat/Long: 42.298552/-88.481420 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Cape Cod

Wall materials: asbestos shingle

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1940-1960

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-12-6: 14516 South Street – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-12-7_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 14604 South Street _____

Lat/Long: 42.298524/-88.481755 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Front Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: remodeled

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872-1892


Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-12-7: 14604 South Street – Residence

MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 13





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-13-1_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 14606 South Street _____

Lat/Long: 42.297995/-88.482254 _____

Primary Use: resid/agri abandoned farmstead _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) Vinyl-covered shed with fieldstone foundation; (B) shed #2 obscured

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Property shows up on maps by circa 1872

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-13-1: 14606 South Street – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-13-2_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 15003 South Street _____

Lat/Long: 42.297518/-88.490124 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: four _____

List Observed Structures: (A) residence #1; (B) residence #2; (C) barn; (D) concrete silo

Residence Detail

Style: Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. Residence #2 is two-story No style residence

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gabled Roof

Wall materials: vertical wood boards

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features:



SE-13-2: 15003 South Street – Residence 1



SE-13-2: 15003 South Street – Residence 2,
Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-13-3_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 14407 Davis Road _____

Lat/Long: 42.298046/-88.478552 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: four _____

List Observed Structures: (A) residence #1; (B) garage; (C) small residence and garage

Residence Detail

Style: Greek Revival

Wall materials: wood/vinyl?

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: large addition to west

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: Two-story addition to west in keeping with style

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1850-1860

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-13-3: 14407 Davis Road – Residence



SE-13-3: 14407 Davis Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-13-4_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 14407 Davis Road _____

Lat/Long: 42.298046/-88.478552 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) barn; (C) concrete silo; (D) wood-sided outhouse/tool shed

Residence Detail

Style: No style

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Saltbox

Wall materials:

Roof materials: asphalt

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: poss. originally a Gabled EI, expanded. Addition to E includes attached garage

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-13-4: 14019 Davis Road – Residence, Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-13-5_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 2719 Stieg Road _____

Lat/Long: 42.288801/-88.477612 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) barn

Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features:

Barn Detail

Style: One-story Gabled roof

Wall materials: wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: 3 bays

Any obvious Additions/Alterations: One-story addition to north

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-13-5: 2719 Stieg Road – Residence



SE-13-5: 2719 Stieg Road – Outbuilding

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-13-6_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 3004 Stieg Road _____

Lat/Long: 42.285678/-88.476647 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) barn; (C) barn #2; (D) garage

Residence Detail

Style: Cross Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Gabled roof

Wall materials: vertical wood

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: obscured

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. Barn #2 is wood-sided, metal roof.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-13-6: 3004 Stieg Road – Outbuildings



SE-13-6: 3004 Stieg Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-13-7_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 2222 Stieg Road _____

Lat/Long: 42.295348/-88.476725 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence #1; (B) residence #2; (C) barn (obscured); (D,E) metal pole barns/garage; (F) concrete stave silo

Residence Detail

Style: Gabled El/Greek Revival

Wall materials: wood

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features: some new windows

Barn Detail

Style: obscured

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features: obscured

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. Residence #2 is a clapboard sided two-story Cross Gabled with asphalt roof.

Circa 1850-1860

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.




SE-13-7: 2222 Stieg Road – Outbuildings



SE-13-7: 2222 Stieg Road – Residence

MCHENRY COUNTY
 SENECA TOWNSHIP
 SECTION 14





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
 Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-14-1_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 2916 Franklinville Road _____

Lat/Long: 42.286233/-88.501690 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) barn; (C) small shed; (D) Gambrel roof barn with metal roof and siding; (E) metal pole barn; (F) small structure, obscured.

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: metal

Foundation materials: fieldstone

Other distinguishing features:

Barn Detail

Style: Gambrel roof

Wall materials: asbestos

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: obscured

Any obvious Additions/Alterations: brick-sided additions to N and S ends

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-14-1: 2916 Franklinville Road – Residence



SE-14-1: 2916 Franklinville Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-14-2_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 2712 Franklinville Road _____

Lat/Long: 42.289047/-88.510633 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) small barn/shed; (B) metal grain bin

Residence Detail

Style: demolished

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Barn Detail

Style: Gabled hay barn

Wall materials: wood

Roof materials: asphalt

Foundation materials: poss limestone

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Property Group Date Range: circa 1872

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-14-2: 2712 Franklinville Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-14-3_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 15601 South Street _____

Lat/Long: 42.298050/-88.802696 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) barn; (C) shed/garage

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style: Gabled roof

Wall materials: vertical wood

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features: high foundation, shed addition to south

Any obvious Additions/Alterations: two one-story additions to south

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-14-3: 15601 South Street – Residence, Shed



SE-14-3: 15601 South Street – Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-14-4_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 15601 South Street _____

Lat/Long: 42.298001/-88.501263 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) garage

Residence Detail

Style: Front Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-14-4: 15601 South Street – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-14-5_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 15019 South Street _____

Lat/Long: 42.297216/-88.491414 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: five _____

List Observed Structures: (A) residence #1; (B) residence #2; (C) barn; (D) concrete stave silo; (E) wood-sided shed

Residence Detail

Style: (A) Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. (B) residence #2 is small Ranch

Circa 1960

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gabled roof

Wall materials: vertical wood or vinyl

Roof materials: metal

Foundation materials: unknown

Other distinguishing features:



SE-14-5: 15019 South Street - Outbuildings



SE-14-5: 15019 South Street – Residence 1



SE-14-5: 15019 South Street – Residence 2

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-14-6_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: South Street _____

Lat/Long: 42.297922/-88.509318 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: four _____

List Observed Structures: (A) residence (obscured); (B) modern barn; (C) milk house/shed; (D) yellow wood-sided shed

Residence Detail

Style: Obscured

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Barn Detail

Style: Gambrel roof

Wall materials: wood/vinyl/stucco

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872 according to maps but likely later


Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-14-6: South Street – Outbuildings

MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 15




Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-15-1_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 2605 Franklinville Road _____

Lat/Long: 42.297872/-88.511533 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) concrete silo

Residence Detail

Style: Side Gabled

Wall materials: wood clapboard

Roof materials: asphalt

Foundation materials: limestone blocks

Other distinguishing features: wrap-around porch with columns

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: additions to rear

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-15-1: 2605 Franklinville Road – Residence



SE-15-1: 2605 Franklinville Road – Silos

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-15-2_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 2719 Franklinville Road _____

Lat/Long: 42.288510/-88.511483 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: eight _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) wood-sided crib with green roof; (E) shed with white metal roof; (F) wood-sided white shed/crib with shed extension; (G) small white unoccupied residence with metal roof; (H) metal-frame wind-mill.

Residence Detail

Style: I House

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: limestone blocks

Other distinguishing features: enclosed front porch

Barn Detail

Style: Gabled roof

Wall materials: vertical wood board

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: hex sign

Any obvious Additions/Alterations: additions to rear

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.



SE-15-2: 2719 Franklinville Road - Outbuildings



SE-15-2: 2719 Franklinville Road –
Outbuildings, Barn



SE-15-2: 2719 Franklinville Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-15-3_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 16714 Secor Road _____

Lat/Long: 42.284258/-88.523643 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) garage

Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: enclosed front porch

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-15-3: 16714 Secor Road – Residence



SE-15-3: 16714 Secor Road – Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-15-4_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 17000 Secor Road _____

Lat/Long: 42.284715/-88.528324 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Round roofed barn Wall

materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: multiple additions

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1920

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-15-4: 17000 Secor Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-15-5_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 16410 Collins Road _____

Lat/Long: 42.298111/-88.519197 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: four _____

List Observed Structures: (A) residence #1; (B) residence #2; (C) barn; (D) garage

Residence Detail

Style: No style

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: multiple peaks/gables

Barn Detail

Style: Gambrel roof

Wall materials: vinyl

Roof materials: metal

Foundation materials: concrete

Other distinguishing features: attached milk house

Any obvious Additions/Alterations: poss. originally a Cape

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. (B) residence #2 is small one-story Side Gabled.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-15-5: 16410 Collins Road – Residence 2



SE-15-5: 16410 Collins Road – Residence 1



SE-15-5: 16410 Collins Road – Barn

MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 16





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-16-1_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 17709 Collins Road _____

Lat/Long: 42.298232/-88.519400 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: nine _____

List Observed Structures: (A) residence; (B) barn; (C) wood-sided crib/barn with cupola; (D) detached milk house, concrete found.; (E) concrete stave silo; (F) garage; (G) smaller Gambrel roofed barn/garage; (H) low white shed/kennel; (I) metal pole barn

Residence Detail

Style: No style

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: multiple peaks/gables

Barn Detail

Style: Gambrel roof

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations: multiple additions - Cross Gabled or Gabled E1 originally facing N

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.



SE-16-1: 17709 Collins Road - Outbuildings



SE-16-1: 17709 Collins Road – Residence



SE-16-1: 17709 Collins Road – Barn,
Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-16-2_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 2401 Vermont Road _____

Lat/Long: 42.296190/-88.538391 _____

Primary Use: Ag _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: three _____

List Observed Structures: (A) concrete stave silo; (B) open metal pole barn/shed; (C) small lean-to shed

Residence Detail

Style: no residence

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-16-2: 2401 Vermont Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-16-3_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 2411 Vermont Road _____

Lat/Long: 42.294026/-88.539234 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: eight _____

List Observed Structures: (A) residence #1; (B) residence #2; (C) residence #3; (D) barn; (E) crib/garage; (F) cantilever-roofed shed; (G) silo; (H) metal grain bins

Residence Detail

Style: Colonial Revival

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: hipped roof; awnings

Barn Detail

Style: Gambrel roof

Wall materials: vertical wood boards

Roof materials: wood shake shingles

Foundation materials: concrete

Other distinguishing features: attached milk house

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. (B) res. #2 is a one-story Side Gabled. Res. #3 is a converted barn with side roof dormers.

circa 1872

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.



SE-16-3: 2411 Vermont Road – Residence 1,
Residence 2



SE-16-3: 2411 Vermont Road – Outbuildings



SE-16-3: 2411 Vermont Road – Residence 3

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-16-4_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 2701 Vermont Road _____

Lat/Long: 42.290239/-88.540121 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: seven _____

List Observed Structures: (A) residence #1; (B) barn; (C) concrete stave silo; (D) low, long Barrel roofed wood-sided barn; (E) metal pole barn; (F,G) metal grain bins

Residence Detail

Style: Colonial Revival

Wall materials: vinyl/wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Gabled roof,

Wall materials: vertical wood boards Roof

materials: wood shake shingles

Foundation materials: concrete

Other distinguishing features: metal cupolas/vents - T or L-shaped building

Any obvious Additions/Alterations: additions to N and S ends, attached garage

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1920

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.



SE-16-4: 2701 Vermont Road – Outbuildings



SE-16-4: 2701 Vermont Road – Residence



SE-16-4: 2701 Vermont Road – Barn,
Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-16-5_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 2805 Vermont Road _____

Lat/Long: 42.288213/-88.540689 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: eight _____

List Observed Structures: (A) residence; (B) three-bay pole barn garage; (C) large low pole barn; (D) peaked roof wood-sided barn/shed; (E) open animal shed; (F) dog house; (G,H) two vertical wood-sided sheds/barns

Residence Detail

Style: No style

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: rambling, attached garage

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-16-5: 2805 Vermont Road – Outbuildings



SE-16-5: 2805 Vermont Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-16-6_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 2903 Vermont Road _____

Lat/Long: 42.286159/-88.541357 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) barn; (C) milk house; (D) Quonsett barn/garage; (E) wire corn bin

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features: attached garage

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gambrel roof

Wall materials: vertical wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: hex sign

L or T-shaped




SE-16-6: 2903 Vermont Road – Outbuildings



SE-16-6: 2903 Vermont Road – Residence

MCHENRY COUNTY
 SENECA TOWNSHIP
 SECTION 17





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
 Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-17-1_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 18616 Mill Stream Road _____

Lat/Long: 42.284290/-88.561053 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Barn Detail

Style: No style

Style:

Wall materials: vinyl/brick

Wall materials:

Roof materials: asphalt

Roof materials:

Foundation materials: unknown-brick covered

Foundation materials:

Other distinguishing features: remodel job

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1939

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-17-1: 18616 Millstream Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-17-2_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 18702 Mill Stream Road _____

Lat/Long: 42.285456/-88.561702 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) metal pole barn; (C) smaller pole barn/shed; (D) small lean-to shed

Residence detail:

Style: No style

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: obscured

Barn Detail

Style: pole barn

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965-1978

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-17-2: 18702 Millstream Road – Residence,
Outbuilding



SE-17-2: 18702 Millstream Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-17-3_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 3004 Standish Road _____

Lat/Long: 42.285246/-88.569014 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) metal pole barn; (E) metal grain bin; (F) brick sided garage

Residence detail:

Style: Gabled EI

Wall materials: brick

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features: semi-circle attic windows

Barn Detail

Style: Gambrel roof, banked

Wall materials: vertical wood

board Roof materials: metal

Foundation materials: large fieldstones

Other distinguishing features: attached fieldstone milk house

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872-1892

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.



SE-17-3: 3004 Standish Road – Outbuildings



SE-17-3: 3004 Standish Road - Barn



SE-17-3: 3004 Standish Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-17-4_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: David Allen Acres_____

Address: 2812 Standish Road_____

Lat/Long: 42.287873/-88.569035_____

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X_____ Number Structures in Group: six_____

List Observed Structures: (A) residence; (B) barn; (C) three-bay vinyl-covered garage

Residence detail:

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features: enclosed front porch

Barn Detail

Style: Round roofed

Wall materials: concrete block

Roof materials: metal

Foundation materials: concrete

Other distinguishing features: projecting roof peak to S

Any obvious Additions/Alterations: addition to N side

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872-1892

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.



SE-17-4: 2812 Standish Road – Residence



SE-17-4: 2812 Standish Road - Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-17-5_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 2518 Bockman Road _____

Lat/Long: 42.291627/-88.563971 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence detail:

Style: Neo-Colonial

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: attached three-bay garage

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-17-5: 2518 Bockman Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-17-6_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name:_____

Address: 2512 Bockman Road_____

Lat/Long: 42.291982/-88.564226_____

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: five_____

List Observed Structures: (A) residence; (B) Gambrel roofed garage; (C) concrete stave silo; (D) concrete block barn foundation; (E) open wood-sided crib/shed

Residence detail:

Barn Detail

Style: No style

Style: demolished

Wall materials: vinyl

Wall materials:

Roof materials: asphalt

Roof materials:

Foundation materials: concrete block/fieldstone

Foundation materials:

Other distinguishing features:

Other distinguishing features

Any obvious Additions/Alterations: wing section upper addition

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: three_____

* Attach Photo log, additional notes and map of resource location.



SE-17-6: 2512 Bockman Road – Residence



SE-17-6: 2512 Bockman Road - Garage



SE-17-6: 2512 Bockman Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-17-7_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 2210 Bockman Road _____

Lat/Long: 42.296376/-88.564009 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) vinyl covered garage

Residence detail:

Style: Minimal Traditional

Wall materials: brick?/vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1930-1940

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-17-7: 2210 Bockman Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-17-8_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 2303 Bockman Road _____

Lat/Long: 42.296932/-88.565226 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) barn; (C) metal pole barn/garage; (D) metal frame windmill

Residence detail:

Style: No style

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: limestone, concrete

Other distinguishing features: three front gables

May have been Upright and Wing originally

Any obvious Additions/Alterations: poss. additions to N side including new front entry. S end may be original Upright and Wing

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-17-8: 2303 Bockman Road – Residence,
Outbuildings



SE-17-8: 2303 Bockman Road - Barn

MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 18




Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-18-1_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 19908 Bockman Road _____

Lat/Long: 42.291500/-88.585619 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) small wood-sided unknown outbuilding

Residence detail:

Style: Upright and Wing

Wall materials: wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: decorative shingles, bay windows

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1850-1870

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-18-1: 19908 Bockman Road – Residence,
Outbuilding

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-18-2_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 19602 Bockman Road _____

Lat/Long: 42.291500/-88.585619 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) large pole barn; (C) concrete stave silo; (D) wood-sided open shed with metal roof

Residence detail:

Style: unknown modern

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone under porch

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-18-2: 19602 Bockman Road – Residence,
Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-18-3_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 19216 Bockman Road _____

Lat/Long: 42.294465/-88.572261 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: four _____

List Observed Structures: (A) residence; (B,C) metal pole barn; (D) small shed

Residence detail:

Style: No style

Wall materials: vinyl/brick

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-18-3: 19216 Bockman Road – Outbuildings



SE-18-3: 19216 Bockman Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/25/15_____ Survey Number: SE-18-4_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 19211 Bockman Road _____

Lat/Long: 42.290474/-88.571973 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) metal pole barn; (C) small shed

Residence detail:

Style: Side Gabled

Wall materials: wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: large attached garage

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1900

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-18-4: 19211 Bockman Road – Outbuildings



SE-18-4: 19211 Bockman Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-18-5_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: Benny's Farm_____

Address: 2819 Standish Road_____

Lat/Long: 42.286925/-88.569798_____

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: three_____

List Observed Structures: (A) residence; (B) barn; (C) wood-shingle sided shed

Residence detail:

Style: Gabled EI

Wall materials: wood shingles

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: peak trim

Barn Detail

Style: peaked roof

Wall materials: wood

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: 1920 over barn doors

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1900

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.



SE-18-5: 2819 Standish Road – Residence



SE-18-5: 2819 Standish Road – Barn, Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-18-6_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: Thunder Grove Orchard

Address: 3042 Deerpass Road_____

Lat/Long: 42.284653/-88.588227_____

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: three_____

List Observed Structures: (A) residence; (B) gambrel roof garage; (C) small pole barn type garage

Residence detail:

Barn Detail

Style: Gabled EI

Style:

Wall materials: vinyl

Wall materials:

Roof materials: asphalt

Roof materials:

Foundation materials: unknown

Foundation materials:

Other distinguishing features:

Other distinguishing features:

Any obvious Additions/Alterations: enclosed porch and side areas on ground floor

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1900

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.



SE-18-6: 3042 Deerpass Road – Residence, Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-18-7_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 2904 Deerpass Road _____

Lat/Long: 42.287065/-88.587681 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) garage

Residence detail:

Style: Ranch

Wall materials: brick

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-18-7: 2904 Deerpass Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-18-8_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 2720 Deerpass Road _____

Lat/Long: 42.288792/-88.587941 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B-D) obscured horse sheds/outbuildings

Residence detail:

Style: Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1910-1920

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-18-8: 2720 Deerpass Road – Residence



SE-18-8: 2720 Deerpass Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-18-9_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 20015 Bockman Road _____

Lat/Long: 42.2900551/-88.588353 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) garage; (C) metal pole barn

Residence detail:

Style: No style

Wall materials: wood/vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: modern residence

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-18-9: 20015 Bockman Road – Residence, Garage,
Barn

MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 19





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-19-1_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 19208 Bockman Road _____

Lat/Long: 42.271487/-88.571686 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stove silo; (D) wood-sided barn/garage on concrete;

Residence detail:

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features:

Barn Detail

Style: Round roof

Wall materials: vertical wood

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-19-1: 19208 River Road – Barn, Outbuilding



SE-19-1: 19208 River Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-19-2_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 19308 Bockman Road _____

Lat/Long: 42.272345/-88.573477 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) fieldstone and concrete barn foundation; (E) fieldstone milk house; (F) small residence/apartment behind house.

Residence detail:

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete over fieldstone

Other distinguishing features:

Barn Detail

Style: Gabled roof

Wall materials: vertical wood

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features:

Any obvious Additions/Alterations: original barn demolished

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1900-1910

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-19-2: 19308 River Road – Outbuildings



SE-19-2: 19308 River Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-19-3_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 19404 River Road _____

Lat/Long: 42.272863/-88.575348 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) pole barn

Residence detail:

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete block?

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-19-3: 19404 River Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-19-4_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 19502 River Road _____

Lat/Long: 42.273200/-88.576897 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: nine _____

List Observed Structures: (A) residence; (B) pole barn; (C) metal grain bin; (D) garage; (E) concrete stave silo; (F-I) metal-clad pole barn type sheds

Residence detail:

Style: Minimal Traditional

Wall materials: brick

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:
Prominent front gable, awnings

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1930-1940

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-19-4: 19502 River Road – Residence



SE-19-4: 19502 River Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-19-5_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 19515 River Road _____

Lat/Long: 42.273200/-88.576897 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) wood-sided shed/garage

Residence detail:

Style: Greek Revival/Upright and Wing

Wall materials: vinyl/alum.

Roof materials: asphalt

Foundation materials: poss. brick

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-19-5: 19515 River Road – Residence, Outbuilding

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-19-6_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 19707 River Road _____

Lat/Long: 42.273422/-88.580641 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: eight _____

List Observed Structures: (A) residence; (B) metal pole barn; (C) low, wooden shed; (D,E) two vinyl sided peak roofed barns with metal roofs; (F) small equipment shed; (G) wood-shed lean-to shed; (H) concrete stave silo

Residence detail:

Style: Front Gabled

Wall materials: asbestos shingles

Roof materials: asphalt

Foundation materials: poss. brick

Other distinguishing features: front porch enclosed

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gabled roof

Wall materials: vinyl

Roof materials: metal

Foundation materials: unknown

Other distinguishing features:



SE-19-6: 19707 River Road – Residence



SE-19-6: 19707 River Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-19-7_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 19801 River Road _____

Lat/Long: 42.274431/-88.583592 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three

List Observed Structures: (A) residence; (B) metal pole barn; (C) pole barn garage

Residence detail:

Style: Gabled EI

Wall materials: wood

Roof materials: asphalt

Foundation materials: concrete over fieldstone

Other distinguishing features: front porch enclosed

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1892-1908

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-19-7: 19810 River Road – Residence, Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-19-8_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 3204 Deerpass Road _____

Lat/Long: 42.282578/-88.588573 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) vinyl-clad garage

Residence detail:

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: front entrance

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872-189i2

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-19-8: 3204 Deerpass Road – Residence, Garage

MCHENRY COUNTY
 SENECA TOWNSHIP
 SECTION 20





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
 Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-20-1_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 19002 River Road _____

Lat/Long: 42.270187/-88.568267 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) pole barn garage; (C) small tool shed

Residence detail:

Style: Neo-Colonial

Wall materials: wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-20-1: 19002 River Road - Residence



SE-20-1: 19002 River Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-20-2_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 3904 Standish Road _____

Lat/Long: 42.272243/-88.568997 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) garage; (C) concrete stave silo; (D) metal pole barn

Residence detail:

Style: Obscured

Wall materials: wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. Original barn demolished

Circa 1939

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-20-2: 3904 Standish Road – Residence, Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-20-3_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 3418 Standish Road _____

Lat/Long: 42.278418/-88.569116 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) barn

Residence detail:

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Gabled roof

Wall materials: wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: shed extension

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872-1892

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-20-3: 3418 Standish Road – Residence, Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-20-4_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 3206Standish Road_____

Lat/Long: 42.282290/-88.568776_____

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) pole barn; (C) garage

Residence detail:

Style: poss. Obscured

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1939

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-20-4: 3206 Standish Road – Residence, Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-20-5_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 19007 Millstream Road _____

Lat/Long: 42.283803/-88.568126 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) pole barn; (C) garage

Residence detail:

Style: obscured

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872-1892

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-20-5: 19007 Millstream Road – Barn



SE-20-5: 19007 Millstream Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-20-6_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 18705 Millstream Road _____

Lat/Long: 42.283557/-88.562692 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) wood-sided pole barn; (C) wood-sided small shed; (D) concrete stave silo

Residence detail:

Style: Ranch

Wall materials: wood

Roof materials: asphalt

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials: Other

distinguishing features:



SE-20-6: 18705 Millstream Road – Residence,
Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-20-7_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 3213 Millstream Road _____

Lat/Long: 42.281626/-88.560176 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) metal pole barn; (C) metal pole barn garage

Residence detail:

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: enclosed front porch on concrete

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1900-1910

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-20-7: 3213 Millstream Road – Residence



SE-20-7: 3213 Millstream Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-20-8_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 3913 Millstream Road _____

Lat/Long: 42.271617/-88.560775 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) three-bay garage

Residence detail:

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872-1892

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-20-8: 3913 Millstream Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-20-9_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 18411 Garden Valley Road _____

Lat/Long: 42.273026/-88.557026 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) metal pole barn; (C) garage; (D) poss. out-house; (E,F) two small sheds

Residence detail:

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

Any obvious Additions/Alterations: additions to upright and rear of wing

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1900

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-20-9: 18411 Garden Valley Road – Residence



SE-20-9: 18411 Garden Valley Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-20-10_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: Cherry Lane Farm_____

Address: 18311 Garden Valley Road_____

Lat/Long: 42.272976/-88.555135_____

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: three_____

List Observed Structures: (A) residence; (B) small barn; (C) small shed

Residence detail:

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872-1892

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gabled roof

Wall materials: wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:



SE-20-10: 18311 Garden Valley Road – Residence



SE-20-10: 18311 Garden Valley Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-20-11_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 18116 Garden Valley Road _____

Lat/Long: 42.273435/-88.551586 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence detail:

Style: No style

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: limestone blocks

Other distinguishing features: mansard roof

Any obvious Additions/Alterations: addition to rear, expanded 2nd floor

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872-1892

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-20-11: 18116 Garden Valley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-20-12_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 18302 Garden Valley Road _____

Lat/Long: 42.273648/-88.554017 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) barn; (C) large pole barn

Residence detail:

Style: No style

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: remodeled

Upright and Wing

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1900

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gabled roof

Wall materials: vertical wood board

Roof materials: asphalt

Foundation materials: poss. fieldstone

Other distinguishing features: T or L-shaped



SE-20-12: 18302 Garden Valley Road -
Outbuildings



SE-20-12: 18302 Garden Valley Road -
Residence



SE-20-12: 18302 Garden Valley Road - Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-20-13_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name:_____

Address: 18518 Garden Valley Road_____

Lat/Long: 42.293497/-88.59499_____

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: three_____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo

Residence detail:

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872-1892

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gabled Roof

Wall materials: vertical wood board

Roof materials: metal

Foundation materials: concrete

Other distinguishing features:




SE-20-13: 18518 Garden Valley Road – Residence



SE-20-13: 18518 Garden Valley Road – Outbuildings

MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 21





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-21-1_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 17804 Garden Valley Road _____

Lat/Long: 42.273602/-88.544982

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) barn; (C) garage; (D) small shed

Residence detail:

Style: No style

Wall materials: vinyl

Roof materials: asphalt Foundation

materials: unknown Other

distinguishing features:

Any obvious Additions/Alterations: remodeled

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gambrel roof

Wall materials: vinyl/metal

Roof materials: metal

Foundation materials: concrete

Other distinguishing features: all white



SE-21-1: 17804 Garden Valley Road - Residence



SE-21-1: 17804 Garden Valley Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-21-2_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 3602 Vermont Road _____

Lat/Long: 42.276632/-88.544083

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) pole barn

Residence detail:

Style: Ranch

Wall materials: wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: includes garage

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965-1978

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-21-2: 3602 Vermont Road – Residence, Outbuilding

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-21-3_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 3320 Vermont Road _____

Lat/Long: 42.279779/-88.542168

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) pole barn

Residence detail:

Style: Ranch

Wall materials: wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: includes garage

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965-1978

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-21-3: 3320 Vermont Road – Residence, Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-21-4_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 3104 Vermont Road _____

Lat/Long: 42.283894/-88.541224

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) garage

Residence detail:

Style: Front Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: decorative concrete block

Other distinguishing features: converted schoolhouse

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials: Roof

materials:

Foundation materials:

Other distinguishing features:



SE-21-4: 3104 Vermont Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-21-5_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 3501 Vermont Road _____

Lat/Long: 42.277779/-88.544235

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: nine _____

List Observed Structures: (A) residence #1; (B) residence #2; (C) barn; (D) concrete stove silo; (E) grain elevator/storage complex; (F) large metal pole barn; (G) large Gambrel roof metal barn; (H) smaller gambrel roof dairy barn or stables; (I) garage

Residence detail:

Style: (A) Greek Revival/Upright and Wing

Wall materials: vinyl/wood

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. (B) residence #2 is a Ranch/Split Level

Circa 1872

Number of photos taken for this property*: five _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gambrel roof

Wall materials: vinyl/wood

Roof materials: metal

Foundation materials: concrete

Other distinguishing features: L-shaped



SE-21-5: 3501 Vermont Road - Outbuildings



SE-21-5: 3501 Vermont Road – Residence 2



SE-21-5: 3501 Vermont Road - Barn



SE-21-5: 3501 Vermont Road – Residence 1



SE-21-5: 3501 Vermont Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-21-6_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 17819 Garden Valley Road _____

Lat/Long: 42.272893/-88.546002

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three _____

List Observed Structures: (A) residence; (B,C) two long , low wood-sided sheds with asphalt roofs

Residence detail:

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: attached garage

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-21-6: 17819 Garden Valley Road – Residence,
Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-21-7_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 17401 Garden Valley Road _____

Lat/Long: 42.272917/-88.537877

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) garage; (C) barn; (D) metal pole barn; (E) small wood-sided crib/shed; (F) silo

Residence detail:

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Gabled roof

Wall materials: vertical wood boards

Roof materials: metal

Foundation materials: fieldstone

Other distinguishing features: low shed attachments

Any obvious Additions/Alterations: house is either Upright and Wing with one wing addition, or Front Gabled with two wing additions.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-21-7: 17401 Garden Valley Road – Residence,
Garage



SE-21-7: 17401 Garden Valley Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-21-8_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 17208 Garden Valley Road _____

Lat/Long: 42.272982/-88.533160

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence detail:

Barn Detail

Style: Cape Cod

Style:

Wall materials: vinyl

Wall materials:

Roof materials: asphalt

Roof materials:

Foundation materials: concrete block

Foundation materials:

Other distinguishing features: roof dormers

Other distinguishing features:

Any obvious Additions/Alterations: additions to south and east, including a poss. separate residence to south

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-21-8: 17208 Garden Valley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-21-9_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 17220 Garden Valley Road _____

Lat/Long: 42.273506/-88.535074

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence detail:

Style: Minimal Traditional

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: attached garage may include a small apartment

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1940

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-21-9: 17220 Garden Valley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: SE-21-10_____ Surveyor Name: J. Davis, E. Maher_____

Current Property or Structure Name: _____

Address: 17510 Garden Valley Road _____

Lat/Long: 42.273547/-88.539511

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stove silo; (D) metal-clad barn/shed; (E) metal clad barn/shed

Residence detail:

Style: Side Gabled Wall

materials: vinyl

Roof materials: asphalt

Foundation materials: limestone

Other distinguishing features: enclosed front porch

Barn Detail

Style: Gabled roof dairy

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: high concrete

Other distinguishing features: metal roof cupolas/vents. High foundation

Any obvious Additions/Alterations: additions to south

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-21-10: 17510 Garden Valley Road – Outbuildings



SE-21-10: 17510 Garden Valley Road - Residence

MCHENRY COUNTY
 SENECA TOWNSHIP
 SECTION 22





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
 Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-22-1_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 16607 Secor Road _____

Lat/Long: 42.283748/-88.521697

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) barn; (C) garage

Residence detail:

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features:

Any obvious Additions/Alterations: additions to west

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gabled roof

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: built in two perpendicular sections



SE-22-1: 16607 Secor Road - Outbuildings



SE-22-1: 16607 Secor Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-22-2_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 3417 Franklinville Road _____

Lat/Long: 42.278622/-88.811540

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence detail:

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-22-2: 3417 Franklinville Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-22-3_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 3817 Franklinville Road _____

Lat/Long: 42.277111/-88.511427

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence detail:

Style: Minimal Traditional

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations: attached garage

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1939

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-22-3: 3517 Franklinville Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-22-4_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name:_____

Address: 16108 Garden Valley Road_____

Lat/Long: 42.276896/-88.511875

Primary Use: residence_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence detail:

Style: No style

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone, concrete east end

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: east end prob. addition - poss. remodeled Italianate

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1900

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.



SE-22-4: 16108 Garden Valley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-22-5_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 16110 Garden Valley Road _____

Lat/Long: 42.277105/-88.512457

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence detail:

Style: Ranch

Wall materials: wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: rustic look

Any obvious Additions/Alterations: poss. a converted outbuilding

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1950-1960

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-22-5: 16110 Garden Valley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-22-6_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 16420 Garden Valley Road _____

Lat/Long: 42.277194/-88.518977

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: _____

List Observed Structures: (A) residence #1; (B) residence #2; (C) barn; (D) metal pole barn; (E) grain elevator storage complex; (F) screened gazebo

Residence detail:

Style: (A) Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: enclosed front porch

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. (B) residence #2 obscured.

Circa 1910-1920

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gabled roof

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:



SE-22-6: 16420 Garden Valley Road – Residence 1



SE-22-6: 16420 Garden Valley Road – Residence 2



SE-22-6: 16420 Garden Valley Road -
Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-22-7_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 16706 Garden Valley Road _____

Lat/Long: 42.273459/-88.523264

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) unknown wood-sided structure, obscured; (E) garage; (F) small vinyl-sided shed

Residence detail:

Style: Neo-eclectic poss

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: remodeled Gabled EI

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. (B) residence #2 obscured.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gambrel roof

Wall materials: vinyl

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features:



SE-22-7: 16706 Garden Valley Road - Outbuildings



SE-22-7: 16706 Garden Valley Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-22-8_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 16301 Garden Valley Road _____

Lat/Long: 42.276373/-88.516157

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence detail:

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-22-8: 16301 Garden Valley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-22-9_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 16205 Garden Valley Road _____

Lat/Long: 42.276446/-88.514890

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence detail:

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-22-9: 16205 Garden Valley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-22-10_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 16113 Garden Valley Road _____

Lat/Long: 42.276454/-88.513614

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: one _____

List Observed Structures: (A) residence

Residence detail:

Style: Cape Cod

Wall materials: wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: center-front chimney

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-22-10: 16113 Garden Valley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-22-11_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: Seneca Town Hall "Perkins Hall" 1885

Address: 4073 Franklinville Road_____

Lat/Long: 42.276518/-88.511299

Primary Use: civic_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: three _____

List Observed Structures: (A) Town Hall; (B) 2nd building/office; (B) small tool shed

Town Hall detail:

Barn Detail

Style: Front Gabled

Style:

Wall materials: vinyl

Wall materials:

Roof materials: asphalt

Roof materials:

Foundation materials: fieldstone

Foundation materials:

Other distinguishing features:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. 2nd building poss. former residence, now an office etc.

Circa 1885

Number of photos taken for this property*: five_____

* Attach Photo log, additional notes and map of resource location.



SE-22-11: 4073 Franklinville Road – Building 2



SE-22-11: 4073 Franklinville Road – Town Hall



SE-22-11: 4073 Franklinville Road - Sign



SE-22-11: 4073 Franklinville Road - Plaque

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-22-12_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 3607 Franklinville Road _____

Lat/Long: 42.276327/-88.511242

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: one _____

List Observed Structures: (A) residence

Residence detail:

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: brick and fieldstone

Other distinguishing features:

Any obvious Additions/Alterations: two-story addition to rear (west)

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1900

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-22-12: 3607 Franklinville Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-22-13_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 3711 Franklinville Road _____

Lat/Long: 42.274015/-88.512016

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: one _____

List Observed Structures: (A) residence; (B) barn

Residence detail:

Style: Cross Gabled

Wall materials: vinyl and wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: long, covered front porch

Barn Detail

Style: Gambrel roof

Wall materials: wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: not old

Any obvious Additions/Alterations: one-story additions to N and S ends

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-22-13: 3711 Franklinville Road - Residence



SE-22-13: 3711 Franklinville Road - Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-22-14_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 3807 Franklinville Road _____

Lat/Long: 42.273316/-88.511434

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence #1; (B) residence #2

Residence detail:

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. (B) residence #2 is a simple one story, asphalt, vinyl, on concrete

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



SE-22-14: 3807 Franklinville Road - Residence 1



SE-22-14: 3807 Franklinville Road – Residence 2

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-22-15_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 3813 Franklinville Road _____

Lat/Long: 42.227816/-88.511391

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) barn; (C) small wood-sided shed; (D) small animal barn with shed attachment; (E) small lean-to shed

Residence detail:

Style: Gabled EI

Wall materials: wood-clapboard

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: front porch roof removed

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



SE-22-15: 3813 Franklinville Road - Residence



SE-22-15: 3813 Franklinville Road – Outbuildings

MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 23




Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-23-1_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: Franklinville Settlers Cemetery establ. 1839_____

Address: 3708 Franklinville Road_____

Lat/Long: 42.274827/-88.501850

Primary Use: cemetery_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group:_____ Number Structures in Group:_____

List Observed Structures: N/A

Residence detail:

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1839

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



SE-23-1: 3708 Franklinville Road – Cemetery

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-23-2_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 3417 Franklinville Road, associated with residence across the road, SE-22-2, with same address _____

Lat/Long: 42.278702/-88.510663

Primary Use: agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: nine _____

List Observed Structures: (A) Gambrel roof barn; (B) metal-clad peaked roof barn; (C,D) two concrete stave silos; (E) Gambrel roofed garage; (F) outhouse; (G) metal-clad milk house?; (H) metal-clad lean-to shed; (I) metal pole barn

Residence detail:

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gambrel roof

Wall materials: metal/vinyl

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: metal roof cupola/vent



SE-23-2: 3417 Franklinville Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-23-3_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 3210 Franklinville Road _____

Lat/Long: 42.281951/-88.510729

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) barn; (C) garage

Residence detail:

Style: T Plan

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete visible

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gambrel roof, Gabled roof

Wall materials: metal/vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: T or L-shaped: one part Gambrel, other part gabled



SE-23-3: 3210 Franklinville Road - Residence



SE-23-3: 3210 Franklinville Road – Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-23-4_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name:_____

Address: 15610 Perkins Road_____

Lat/Long: 42.277102/-88.503653

Primary Use: residence_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: Number Structures in Group: two_____

List Observed Structures: (A) residence; (B) garage

Residence detail:

Style: Neo-eclctic

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete visible

Other distinguishing features: two dormers, bay windows

Any obvious Additions/Alterations: may be remodeled older structure

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Circa 1872

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.



SE-23-4: 15610 Perkins Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-23-5_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 15514 Perkins Road _____

Lat/Long: 42.277125/-88.500783

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence detail:

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete visible

Other distinguishing features:

Any obvious Additions/Alterations: long side-gabled addition

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1950-1960

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-23-5: 15514 Perkins Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-23-6_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 15320 Perkins Road _____

Lat/Long: 42.276947/-88.496921

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) barn; (C) concrete silo; (D) metal-clad pole barn; (E) smaller metal-clad shed

Residence detail:

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete visible

Other distinguishing features:

Barn Detail

Style: Gambrel roof

Wall materials: vertical wood boards

Roof materials: asphalt over shake

Foundation materials: concrete visible

Other distinguishing features: one metal roof cupola/vent

Any obvious Additions/Alterations: long side-gabled addition

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1960

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-23-6: 15320 Perkins Road – Barn, Outbuildings



SE-23-6: 15320 Perkins Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-23-7_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 15219 Perkins Road _____

Lat/Long: 42.275909/-88.495006

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) garage; (C) metal pole barn to right

Residence detail:

Style: Ranch

Wall materials: brick

Roof materials: asphalt

Foundation materials: concrete visible

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-23-7: 15219 Perkins Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-23-8_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 15113 Perkins Road _____

Lat/Long: 42.276344/-88.492396

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: ten _____

List Observed Structures: (A) residence #1; (B) residence #2; (C) barn; (D) concrete stave silo; (E) smaller wood-sided shed or crib near road; (F) small vertical wood-side shed; (G) small tool shed; (H) peaked roof shed; (I) metal pole barn; (J) low shed/garage behind Resid. #2

Residence detail:

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

Any obvious Additions/Alterations: additions to rear of resid.#1

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. (B) resid. #2 is octagonal, asphalt, vertical wood, unknown.

Circa 1872

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gabled roof with shed extension

Wall materials: vertical wood boards

Roof materials: asphalt

Foundation materials: cc over fieldstone

Other distinguishing features:



SE-23-8: 15113 Perkins Road – Residence 2



SE-23-8: 15113 Perkins Road – Residence 1



SE-23-8: 15113 Perkins Road - Outbuildings



SE-23-8: 15113 Perkins Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-23-9_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 3819 Gee Road _____

Lat/Long: 42.272377/-88.492140

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) garage

Residence detail:

Style: No style

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: roof dormer added

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872


Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-23-9: 3819 Gee Road – Residence, Garage

MCHENRY COUNTY
 SENECA TOWNSHIP
 SECTION 24





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
 Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-24-1_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 3720 Gee Road _____

Lat/Long: 42.272899/-88.491385

Primary Use: agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) wood-sided crib with metal roof and pier blocks foundation

Residence detail:

Barn Detail

Style:

Style:

Wall materials:

Wall materials:

Roof materials:

Roof materials:

Foundation materials:

Foundation materials:

Other distinguishing features:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1920

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-24-1: 3720 Gee Road – Crib

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-24-2_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 15004 Perkins Road _____

Lat/Long: 42.276915/-88.490575

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: eight _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (E) concrete silo; (F) metal frame windmill; (G) milk house on concrete; (H) shed-shaped metal pole barn

Residence detail:

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone and brick

Other distinguishing features:

Barn Detail

Style: Gabled roof

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: additions to east

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1910

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-24-2: 15004 Perkins Road – Residence



SE-24-2: 15004 Perkins Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-24-3_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 14917 Perkins Road _____

Lat/Long: 42.276432/-88.489759

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) barn; (C) peaked, metal-roofed shed on stone foundation; (D) stone smoke house, whitewashed; (E) metal Quonsett shed; (F) small red shed behind smoke house

Residence detail:

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone and brick

Other distinguishing features: front porch

Barn Detail

Style: Gambrel roof

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-24-3: 14917 Perkins Road – Outbuildings



SE-24-3: 14917 Perkins Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-24-4_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name:_____

Address: 14912 Perkins Road_____

Lat/Long: 42.2764941/88.489290

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence detail:

Barn Detail

Style: Ranch

Style:

Wall materials: vinyl

Wall materials:

Roof materials: asphalt

Roof materials:

Foundation materials: concrete

Foundation materials:

Other distinguishing features:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.



SE-24-4: 14912 Perkins Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-24-5_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: Seneca Ridge Farm – Centennial farm_____

Address: 14804 Perkins Road_____

Lat/Long: 42.276906/88.486206

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: Number Structures in Group: six_____

List Observed Structures: (A) residence; (B) barn; (C) concrete silo; (D) concrete stave silo; (E) wood-clad garage; (F) wood-clad small shed

Residence detail:

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

Barn Detail

Style: Gabled roof

Wall materials: vertical wood

Roof materials: metal

Foundation materials: cc over fieldstone

Other distinguishing features: red and green

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: three_____

* Attach Photo log, additional notes and map of resource location.



SE-24-5: 14804 Perkins Road - Outbuildings



SE-24-5: 14804 Perkins Road - Residence



SE-24-5: 14804 Perkins Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-24-6_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 14709 Perkins Road _____

Lat/Long: 42.276400/88.484693

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: seven _____

List Observed Structures: (A) residence; (B) barn; (C) concrete silo; (D,E) two concrete sided low sheds/barns; (F,G) two metal-roofed structures SW of residence, obscured

Residence detail:

Style: Pyramid Roof

Wall materials: wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style: large Gambrel roof, obscured

Wall materials: vertical wood

Roof materials: metal

Foundation materials: cc over fieldstone

Other distinguishing features: red and green

Any obvious Additions/Alterations: residence has one-story extension to south with asphalt roof. Wood siding, and a covered porch with turned spindle supports-Could be original structure.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-24-6: 14709 Perkins Road – Outbuildings



SE-24-6: 14709 Perkins Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-24-7_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: Mohawk Farm_____

Address: 14408 Perkins Road_____

Lat/Long: 42.277005/88.478637

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: Number Structures in Group: six_____

List Observed Structures: (A) residence; (B) pole barn; (C) vinyl-clad shed with metal roof; (D) low, shed-shaped metal barn/shed

Residence detail:

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.


Circa 1960

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.



SE-24-7: 14408 Perkins Road – Residence



SE-24-7: 14408 Perkins Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-24-8_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: Mohawk Farm_____

Address: 14318 Perkins Road_____

Lat/Long: 42.276985/88.477379

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single: X_____ Group:_____ Number Structures in Group:_____

List Observed Structures: (A) residence

Residence detail:

Style:Front Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.



SE-24-8: 14318 Perkins Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-24-9_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 14311 Perkins Road _____

Lat/Long: 42.275741/88.476896

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: three _____

List Observed Structures: (A) residence; (B,C) two metal pole barns

Residence detail:

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1960-1965

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-24-9: 14311 Perkins Road – Residence, Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-24-10_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 14118 Perkins Road _____

Lat/Long: 42.277255/88.473857

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) unknown blue structure-possible 2nd residence; (C) barn; (D) brown concrete block milk house; (E) tan, vinyl-clad possible 3rd residence

Residence detail:

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Gabled roof

Wall materials: vertical wood

Roof materials: asphalt

Foundation materials: cc over fieldstone

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-24-10: 14118 Perkins Road – Outbuildings



SE-24-10: 14118 Perkins Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-24-11_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 4017 Sunnyside Road _____

Lat/Long: 42.20950/88.472508

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) barn

Residence detail:

Style: Gabled EI

Wall materials: newer vertical wood

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

Barn Detail

Style: Gambrel roof, banked

Wall materials: newer vertical wood

Roof materials: metal

Foundation materials: concrete

Other distinguishing features: attached milk house

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-24-11: 4017 Sunnyside Road – Residence



SE-24-11: 4017 Sunnyside Road – Barn

MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 25





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-25-1_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 4203 Sunnyside Road _____

Lat/Long: 42.267565/88.472402

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) pole barn; (C) concrete stave silo; (D) wood-sided shed with metal roof; (E) metal pole barn/garage

Residence detail:

Style: No style

Wall materials: newer vertical wood and vinyl

Roof materials: asphalt

Foundation materials: concrete under extension

Other distinguishing features:

Barn Detail

Style:

Wall materials: Roof

materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: addition to south

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-25-1: 4203 Sunnyside Road – Residence



SE-25-1: 4203 Sunnyside Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-25-2_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 4513 Sunnyside Road _____

Lat/Long: 42.262916/88.472661

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) barn

Residence detail:

Style: Ranch

Wall materials: brick/vinyl

Roof materials: poss. wood shake shingles

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style: Gambrel roofed, obscured

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features: two venting roof cupolas. Roof poss. shake shingle

Any obvious Additions/Alterations: addition to south

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-25-2: 4513 Sunnyside Road – Residence



SE-25-2: 4513 Sunnyside Road – Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-25-3_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: Sunnyside Road _____

Lat/Long: 42.261179/88.472027

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: No structures observed. Elaborate metal gates, fence, and posts. Gates contain federal/government medallions and a medallion embossed with the date "1913".

Residence detail:

Barn Detail

Style:

Style:

Wall materials:

Wall materials:

Roof materials:

Roof materials:

Foundation materials:

Foundation materials:

Other distinguishing features:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1913

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-25-3: Sunnyside Road – Gate

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-25-4_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: “Lumberjacks”

Address: 5013 Sunnyside Road_____

Lat/Long: 42.255389/88.472354

Primary Use: resid/agri/commercial_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) garage; (E) peaked-roof, wood sided small barn or shed, banked

Residence detail:

Style: Cross Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: whitewashed

fieldstone Other distinguishing features:

Barn Detail

Style: Gambrel roof

Wall materials: vertical wood boards

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

Any obvious Additions/Alterations: brick-sided one-story addition over concrete in NW corner

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1900

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.



SE-25-4: 5013 Sunnyside Road – Outbuildings



SE-25-4: 5013 Sunnyside Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-25-5_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 4402 Gee Road _____

Lat/Long: 42.265863/88.490860

Primary Use: resid/agri/commercial _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) metal frame windmill

Residence detail:

Style: Foursquare

Wall materials: vinyl Roof

materials: asphalt

Foundation materials: unknown

Other distinguishing features: Hipped roof

Barn Detail

Style: Gabled roof

Wall materials: vertical wood boards

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: attached milk house

Any obvious Additions/Alterations: wrap around porch. Addition to N side

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872


Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-25-5: 4402 Gee Road – Residence, Outbuildings

MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 26





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-26-1_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 4409 Gee Road _____

Lat/Long: 42.264581/88.492090

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) pole barn; (C) garage (D) silo, obscured

Residence detail:

Style: Minimal Traditional

Wall materials: vinyl/wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Gabled roof

Wall materials: metal

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: attached milk house

Any obvious Additions/Alterations: center recessed covered porch with two columns

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1930-1940

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.



SE-26-1: 4409 Gee Road - Outbuilding



SE-26-1: 4409 Gee Road - Residence



SE-26-1: 4409 Gee Road – Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-26-2_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 4811 Gee Road _____

Lat/Long: 42.258445/88.491953

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) metal-clad shed/barn; (C) fieldstone smoke house with wood upper and roof; garage (D) concrete stove silo; (E) barn foundation rubble

Residence detail:

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials: Roof

materials: Foundation

materials:

Other distinguishing features:

Any obvious Additions/Alterations: addition to north side? Attached garage

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1900-1910

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.



SE-26-2: 4811 Gee Road - Outbuildings



SE-26-2: 4811 Gee Road – Smokehouse



SE-26-2: 4811 Gee Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-26-3_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 16018 IL Rt. 176 _____

Lat/Long: 42.255443/88.501629

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) barn/shed; (C) large metal pole barn; (D) Quonsett structure NE of house

Residence detail:

Style: Ranch

Wall materials: vinyl and brick

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style: Gabled roof

Wall materials: vertical wood

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: long shed-like extension to East

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1960-1965

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-26-3: 16018 Illinois Route 176 – Barn



SE-26-3: 16018 Illinois Route 176 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-26-4_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 4204 Franklinville Road _____

Lat/Long: 42.267928/88.501641

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) modern metal-clad outbuilding/barn behind residence

Residence detail:

Style: Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: full-width front

porch; some Free Classic Details

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:


Foundation materials:

Other distinguishing features:



SE-26-4: 4204 Franklinville Road – Residence

MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 27





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-27-1_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 16104 Kunde Road _____

Lat/Long: 42.266190/88.511343

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) barn; (C) concrete block milk house; (D) garage; (E) vinyl clad lean-to shed with metal roof; (F) small tool shed or outhouse; (G) small peaked roof shed

Residence detail:

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

Barn Detail

Style: Gabled roof

Wall materials: vertical wood boards

Roof materials: metal

Foundation materials: fieldstone

Other distinguishing features: owner says interior beams all hand-hewn

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.



SE-27-1: 16104 Kunde Road - Outbuildings



SE-27-1: 16104 Kunde Road – Residence



SE-27-1: 16104 Kunde Road – Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-27-2_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 16504 Kunde Road _____

Lat/Long: 42.266190/88.519287

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) poss. 2nd residence or outbuilding

Residence detail:

Style: Side Gabled

Wall materials: vinyl/wood

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: front porch

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: one-story extension to north

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-27-2: 16504 Kunde Road – Residence, Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-27-3_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 16504 Kunde Road _____

Lat/Long: 42.266190/88.519287

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) wood-sided barn/garage, asphalt roof, on concrete

Residence detail:

Style: modern Split Level

Wall materials: vinyl/brick

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: one-story extension to north

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965-1978

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-27-3: 16419 Kunde Road – Outbuildings



SE-27-3: 16419 Kunde Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-27-4_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: “The Kundes”_____

Address: 16616 Kunde Road_____

Lat/Long: 42.265131/88.525837

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) wood-sided barn/crib; (C) low, wood-sided coop or animal shed; (D,E) two metal pole barns

Residence detail:

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: porch rests on piers

Barn Detail

Style: Gabled roof

Wall materials: wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: addition to north

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-27-4: 16616 Kunde Road – Residence



SE-27-4: 16616 Kunde Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-27-5_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 16779 Kunde Road _____

Lat/Long: 42.264581/88.524627

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence detail:

Style: Gabled EI

Wall materials: vinyl/wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: two-story addition to east

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872-1892

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-27-5: 16779 Kunde Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-27-6_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 4601 Franklinville Road _____

Lat/Long: 42.262263/88.511501

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence detail:

Style: Ranch

Wall materials: vinyl/wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-27-6: 4601 Franklinville Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-27-7_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: The Mink Barn – Furs by Bill Talidis

Address: 4609 Franklinville Road_____

Lat/Long: 42.261664/88.511394

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: seven _____

List Observed Structures: (A) residence; (B) barn; (C) small shed; (D-F) low mink barns; (G) 2nd residence

Residence detail:

Style: Gabled El

Wall materials: vinyl/wood

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features:

Barn Detail

Style: Gambrel roof

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: "The Mink Barn"

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. (G) 2nd residence is a Ranch

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-27-7: 4609 Franklinville Road – Outbuildings



SE-27-7: 4609 Franklinville Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-27-8_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 4901 Franklinville Road _____

Lat/Long: 42.257876/88.511583

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) barn; (C) vinyl-sided shed/garage; (D) smaller vinyl sided shed

Residence detail:

Style: Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features: some

Free Classicl details

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gabled roof

Wall materials: vinyl

Roof materials: metal

Foundation materials: high concrete

Other distinguishing features: L or T-shaped




SE-27-8: 4901 Franklinville Road – Outbuildings



SE-27-8: 4901 Franklinville Road – Residence

MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 28





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-28-1_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 17118 Kunde Road _____

Lat/Long: 42.265201/88.532108

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) barn; (C) vertical wood-sided barn/shed; (D) low wood-sided crib with garage attached

Residence detail:

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features: Eave returns

Barn Detail

Style: Gabled roof

Wall materials: wood

Roof materials: metal

Foundation materials: concrete visible

Other distinguishing features: two sets of small windows - T-shaped

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.



SE-28-1: 17118 Kunde Road – Outbuildings



SE-28-1: 17118 Kunde Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-28-2_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 17408 Kunde Road _____

Lat/Long: 42.264903/88.537148

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) three-bay garage; (C) barn

Residence detail:

Style: Greek Revival

Wall materials: wood

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features: double Italianate eave brackets,

Front entrance porch with support columns.

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1850-1860

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gabled roof

Wall materials: wood

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: date over garage-type door: 1854



SE-28-2: 17408 Kunde Road – Outbuildings



SE-28-2: 17408 Kunde Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-28-3_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 17706 Kunde Road _____

Lat/Long: 42.264261/88.542846

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) concrete stave silo

Residence detail:

Style: Ranch

Wall materials: vinyl/wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1960-1965

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-28-3: 17706 Kunde Road – Residence, Silo

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-28-4_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 17814 Kunde Road _____

Lat/Long: 42.269221/88.544354

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) small shed; (C,D) two concrete silos

Residence detail:

Style: Neo Victorian

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: Residence may be remodeled or replaces original

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-28-4: 17814 Kunde Road – Outbuildings



SE-28-4: 17814 Kunde Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-28-5_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: Christy Dairy Farm

Address: 17916 Kunde Road_____

Lat/Long: 42.263515/88.547521

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) barn (C,D) two concrete stave silos; (E) small metal shed

Residence detail:

Style: Queen Anne

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone and brick

Other distinguishing features: decks added

Barn Detail

Style: Gabled T Plan

Wall materials: wood

Roof materials: metal

Foundation materials: high fieldstone

Other distinguishing features: attached milk house. Two shed attachments.

Any obvious Additions/Alterations: hipped roof addition

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: three_____

* Attach Photo log, additional notes and map of resource location.



SE-28-5: 17916 Kunde Road - Outbuildings



SE-28-5: 17916 Kunde Road – Outbuildings



SE-28-5: 17916 Kunde Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-28-6_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 18004 Kunde Road _____

Lat/Long: 42.263394/88.548205

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence detail:

Style: Minimal Traditional

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1940-1950

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-28-6: 18004 Kunde Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-28-7_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 18010 Kunde Road _____

Lat/Long: 42.255493/88.548990

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence detail:

Style: Obscured

Wall materials: wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1939


Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-28-7: 18010 Illinois Route 176 – Residence

MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 29




Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-29-1_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 18313 IL 176_____

Lat/Long: 42.255453/88.555223

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) garage

Residence detail:

Style: Cape Cod

Wall materials: wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.



SE-29-1: 18313 Illinois Route 176 – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-29-2_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 18408 IL 176_____

Lat/Long: 42.255326/88.557144

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: six _____

List Observed Structures: (A) residence; (B-F) collection of metal sheds and storage bins

Residence detail:

Style: Minimal Traditional

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1939

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.



SE-29-2: 18408 Illinois Route 176 – Outbuildings



SE-29-2: 18408 Illinois Route 176 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-29-3_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 18516 IL 176_____

Lat/Long: 42.255297/88.559394

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) barn; (C) small shed or pump house; (D) plastic-covered greenhouse

Residence detail:

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-29-3: 18516 Illinois Route 176 – Outbuildings, Barn



SE-29-3: 18516 Illinois Route 176 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-29-4_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 4308 Millstream Road _____

Lat/Long: 42.265498/88.557204

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) small shed; (C) unfinished garage; (D) vinyl/wood-sided 2nd garage

Residence detail:

Style: Upright and Wing

Wall materials: unknown

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-29-4: 4308 Millstream Road – Residence, Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-29-5_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 18716 River Road _____

Lat/Long: 42.267631/88.562878

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) metal pole barn; (C) out house

Residence detail:

Style: Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features:

Barn Detail

Style:

Wall materials: Roof

materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: Gabled additon

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-29-5: 18716 River Road – Residence



SE-29-5: 18716 River Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-29-6_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 18604 River Road _____

Lat/Long: 42.255429/88.560254

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence detail:

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-29-6: 18604 Illinois Route 176 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-29-7_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 18610 IL 176_____

Lat/Long: 42.255421/88.560706

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence detail:

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.



SE-29-7: 18610 Illinois Route 176 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-29-8_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 18614 IL 176_____

Lat/Long: 42.255410/88.561260

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence detail:

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.



SE-29-8: 18614 Illinois Route 176 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-29-9_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 18704 IL 176_____

Lat/Long: 42.255473/88.562071

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) barn; (C,D) two small sheds; (E) barn/garage with green asphalt roof, obscured

Residence detail:

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: Greek Revival cornice
returns

Any obvious Additions/Alterations: addition to west

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: T-shape Gambrel and Gabled roofed

Wall materials: vertical wood

Roof materials: Gambrel-asphalt/shake,
peaked-metal

Foundation materials: unknown

Other distinguishing features: two parts
combined



SE-29-9: 18704 Illinois Route 176 – Outbuildings



SE-29-9: 18704 Illinois Route 176 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-29-10_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 18720 IL 176_____

Lat/Long: 42.255485/88.563486

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) pole barn

Residence detail:

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: additonal wing

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1900


Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.



SE-29-10: 18720 Illinois Route 176 – Residence

MCHENRY COUNTY
 SENECA TOWNSHIP
 SECTION 30





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
 Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-30-1_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 19212 IL 176_____

Lat/Long: 42.255446/88.572472

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) garage; (C) low, long wood-sided barn; (D) wood-sided crib; (E) wood-sided equipment shed with concrete foundation

Residence detail:

Style: Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: addition to north side

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-30-1: 19212 Illinois Route 176 - Outbuildings



SE-30-1: 19212 Illinois Route 176 - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-30-2_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 19516 IL 176_____

Lat/Long: 42.255450/88.578931

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) collapsing wood-sided shed/garage

Residence detail:

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: addition to north side

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-30-2: 19516 Illinois Route 176 - Residence



SE-30-2: 19516 Illinois Route 176 - Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-30-3_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 4804 Deerpass Road _____

Lat/Long: 42.259207/88.588363

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: eight _____

List Observed Structures: (A) residence; (B-D) metal pole barns; (E) Gambrel roof barn; (F) wood-sided milk house with wood shingle roof; (G) elevator/grain storage bins complex; (H) garage

Residence detail:

Barn Detail

Style: Foursquare

Style: Gambrel roof

Wall materials: vinyl

Wall materials: metal

Roof materials: asphalt

Roof materials: metal

Foundation materials: concrete

Foundation materials: unknown

Other distinguishing features:

Other distinguishing features:

Any obvious Additions/Alterations: addition to east side

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.



SE-30-3: 4804 Deerpass Road - Outbuildings



SE-30-3: 4804 Deerpass Road - Residence



SE-30-3: 4804 Deerpass Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/1/15_____ Survey Number: SE-30-4_____ Surveyor Name: J. Davis, C. Flynn_____

Current Property or Structure Name: _____

Address: 4206 Deerpass Road _____

Lat/Long: 42.267103/88.55647

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence detail:

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: obscured by foliage and distance

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-30-4: 4206 Deerpass Road – Residence

MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 31





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/3/15_____ Survey Number: SE-31-1_____ Surveyor Name: J. Davis_____

Current Property or Structure Name: _____

Address: 19319 IL 176_____

Lat/Long: 42.254716/88.580294

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) barn; (C) corn crib; (D) concrete stave silo; (E) small octagonal or round shed with cupola at peak; (F) small shed, obscured

Residence detail:

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

Barn Detail

Style: Round roofed

Wall materials: vertical wood board

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-31-1: 19319 Illinois Route 176—Residence,
Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/3/15_____ Survey Number: SE-31-2_____ Surveyor Name: J. Davis_____

Current Property or Structure Name: _____

Address: 19319 IL 176_____

Lat/Long: 42.254716/88.580294

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) barn; (C) corn crib; (D) concrete stave silo; (E) small octagonal or round shed with cupola at peak; (F) small shed, obscured

Residence detail:

Style: Front Gabled

Wall materials: vinyl/alum

Roof materials: asphalt

Foundation materials: concrete under front porch

Other distinguishing features:

Barn Detail

Style: L-shaped Gabled roof

Wall materials: vertical wood board

Roof materials: unknown

Foundation materials: field/limestone

Other distinguishing features: attached milk house

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.




SE-31-2: 19211 Illinois Route 176 - Residence



SE-31-2: 19211 Illinois Route 176 - Outbuildings

MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 32





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/3/15_____ Survey Number: SE-32-1_____ Surveyor Name: J. Davis_____

Current Property or Structure Name: _____

Address: 18603 IL 176_____

Lat/Long: 42.254823/88.560368

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: seven _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) concrete silo; (E) tiny crumbling wood-sided shed on concrete; (F) wood-sided red barn/shed; (G) wood-sided barn/shed with shed extension

Residence detail:

Style: Cross Gabled

Wall materials: wood-clapboard

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features: fish scale shingle work,
Decorative barge boards at peaks

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gabled roof

Wall materials: vertical wood board

Roof materials: metal

Foundation materials: unknown

Other distinguishing features:



SE-32-1: 18603 Illinois Route 176 - Residence



SE-32-1: 18603 Illinois Route 176 -
Outbuildings



SE-32-1: 18603 Illinois Route 176 - Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/3/15_____ Survey Number: SE-32-2_____ Surveyor Name: J. Davis_____

Current Property or Structure Name: _____

Address: 5141 Dunham Road _____

Lat/Long: 42.249865/88.559213

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) barn; (C) low, long shed, obscured; (D) peaked roof shed, obscured

Residence detail:

Style: Greek Revival/Upright and Wing

Wall materials: wood

Roof materials: asbestos and asphalt shingle

Foundation materials: fieldstone

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1850-1870

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gabled roof

Wall materials: wood

Roof materials: metal

Foundation materials: unknown

Other distinguishing features:



SE-32-2: 5414 Dunham Road - Residence



SE-32-2: 5414 Dunham Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/3/15_____ Survey Number: SE-32-3_____ Surveyor Name: J. Davis_____

Current Property or Structure Name: _____

Address: 5613 Dunham Road _____

Lat/Long: 42.246973/88.559273

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: four _____

List Observed Structures: (A) residence #1; (B) residence #2; (C) barn; (D) metal pole barn

Residence detail:

Style: Side Gabled

Wall materials: wood

Roof materials: asphalt

Foundation materials: concrete over fieldstone

Other distinguishing features:

Any obvious Additions/Alterations: addition to north

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. (B) residence #2 is a Raised Ranch

Circa 1872

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gambrel roof

Wall materials: vertical wood

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features:



SE-32-3: 5613 Dunham Road - Outbuildings



SE-32-3: 5613 Dunham Road – Residence 1



SE-32-3: 5613 Dunham Road – Residence 2

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/3/15_____ Survey Number: SE-32-4_____ Surveyor Name: J. Davis_____

Current Property or Structure Name: _____

Address: 5619 Dunham Road _____

Lat/Long: 42.246549/88.560502

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) barn; (C) concrete silo; (D) possible 2nd residence with red wood-siding, asphalt roof

Residence detail:

Style: Minimal Traditional

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete visible

Other distinguishing features:

Barn Detail

Style: lean-to shed/barn

Wall materials: vertical wood

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features: not original barn

Any obvious Additions/Alterations: addition to south. Two-story addition to rear (W)

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1930-1940

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-32-4: 5619 Dunham Road – Barn, Silo



SE-32-4: 5619 Dunham Road – Residence, Outbuilding

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/3/15_____ Survey Number: SE-32-5_____ Surveyor Name: J. Davis_____

Current Property or Structure Name: _____

Address: 5817 Dunham Road _____

Lat/Long: 42.243822/88.560426

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) garage; (C) small shed

Residence detail:

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: painted concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:


Foundation materials:

Other distinguishing features:



SE-32-5: 5817 Dunham Road – Residence, Outbuildings

MCHENRY COUNTY
 SENECA TOWNSHIP
 SECTION 33



Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/3/15_____ Survey Number: SE-33-1_____ Surveyor Name: J. Davis_____

Current Property or Structure Name: _____

Address: 17515 IL 176_____

Lat/Long: 42.254915/88.539806

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence detail:

Style: Upright and Wing/Greek Revival

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete visible

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-33-1: 17515 Illinois Route 176 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/3/15_____ Survey Number: SE-33-2_____ Surveyor Name: J. Davis_____

Current Property or Structure Name: _____

Address: 6012 Union Road _____

Lat/Long: 42.241273/88.539893

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) wood sided crib/garage

Residence detail:

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: gabled dormer on wing, new porch supports

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gambrel roofed

Wall materials: vertical wood board

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:



SE-33-2: 6012 Union Road - Residence



SE-33-2: 6012 Union Road – Barn, Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/3/15_____ Survey Number: SE-33-3_____ Surveyor Name: J. Davis_____

Current Property or Structure Name: _____

Address: 18020 Ocock Road _____

Lat/Long: 42.241017/88.549218

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) garage; (C) six-sided structure with peaked roof; (D-F) metal grain bins

Residence detail:

Style: Front Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete under enclosed front porch

Other distinguishing features:

Any obvious Additions/Alterations: front enclosed, door faces east to porch. One-story addition to rear

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



SE-33-3: 18020 Ocock Road – Outbuildings



SE-33-3: 18020 Ocock Road – Residence



SE-33-3: 18020 Ocock Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/3/15_____ Survey Number: SE-33-4_____ Surveyor Name: J. Davis_____

Current Property or Structure Name: _____

Address: 17214 Highbridge Road _____

Lat/Long: 42.240973/88.533820

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) barn; (C) dilapidated wood-sided shed or milk house with shake shingle roof and fieldstone foundation; (D) metal frame windmill; (E) wood-sided coop on concrete; (F) vinyl sided garage

Residence detail:

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gambrel roof

Wall materials: vertical wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:



SE-33-4: 17214 Highbridge Road – Residence



SE-33-4: 17214 Highbridge Road – Outbuildings



SE-33-4: 17214 Highbridge Road - Barn

MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 34



Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location


No Resources in Key Area

0 125 250 500 Meters

0 375 750 1,500 Feet



MCHENRY COUNTY
SENECA TOWNSHIP
SECTION 35





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/3/15_____ Survey Number: SE-35-1_____ Surveyor Name: J. Davis_____

Current Property or Structure Name: _____

Address: 15913 Pleasant Valley Road _____

Lat/Long: 42.247454/88.508413

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: seven _____

List Observed Structures: (A) residence; (B) barn; (C-E) metal-clad pole barns; (F) vinyl-clad poss. 2nd residence or office structure; wood-sided coop on concrete; (G) vinyl sided garage

Residence detail:

Style: Cape Cod

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1940

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: Gabled roof

Wall materials: concrete block

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: poss. wood upper siding



SE-35-1: 15913 Pleasant Valley Road - Outbuildings



SE-35-1: 15913 Pleasant Valley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/3/15_____ Survey Number: SE-35-2_____ Surveyor Name: J. Davis_____

Current Property or Structure Name: _____

Address: 15916 Pleasant Valley Road _____

Lat/Long: 42.248227/88.508420

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: one photo'd _____

List Observed Structures: (A) residence; (B) modern outbuildings not photographed

Residence detail:

Style: Gabled El /Greek Revival

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: Greek Revival cornice returns

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



SE-35-2: 15916 Pleasant Valley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/3/15_____ Survey Number: SE-35-3_____ Surveyor Name: J. Davis_____

Current Property or Structure Name: _____

Address: 15618 Pleasant Valley Road _____

Lat/Long: 42.248178/88.502800

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence detail:

Style: Minimal Traditional

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features: enclosed side porch

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1930-1940

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-35-3: 15618 Pleasant Valley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/3/15_____ Survey Number: SE-35-4_____ Surveyor Name: J. Davis_____

Current Property or Structure Name: _____

Address: 15609 Pleasant Valley Road _____

Lat/Long: 42.247603/88.501997

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) barn; (C) garage; (D) small shed

Residence detail:

Style: Minimal Traditional

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: hipped roof

Barn Detail

Style: T-shaped Gabled roof

Wall materials: vertical wood board

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: attached wood-sided milk house.

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1930-1950

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.



SE-35-4: 15609 Pleasant Valley Road - Residence



SE-35-4: 15609 Pleasant Valley Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/3/15_____ Survey Number: SE-35-5_____ Surveyor Name: J. Davis_____

Current Property or Structure Name: Kinsail Farm

Address: 15106 Pleasant Valley Road_____

Lat/Long: 42.25110/88.491823

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) barn #1; (C) barn #2; (D) concrete stave silo

Residence detail:

Style: Foursquare

Wall materials: wood shingle upper, vinyl lower

Roof materials: asphalt

Foundation materials: concrete clad

Other distinguishing features: front porch, dormer

Barn Detail

Style: Gabled roof

Wall materials: vertical wood board

Roof materials: asphalt?

Foundation materials: unknown

Other distinguishing features: attached wood-sided milk house on concrete.

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. (B) barn #2 asphalt roof, vertical wood siding. Has Kinsail Farm sign on front

Circa 1900

Number of photos taken for this property*: three_____

* Attach Photo log, additional notes and map of resource location.



SE-35-5: 15106 Pleasant Valley Road - Residence



SE-35-5: 15106 Pleasant Valley Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/3/15_____ Survey Number: SE-35-6_____ Surveyor Name: J. Davis_____

Current Property or Structure Name: _____

Address: 5598 McCue Road _____

Lat/Long: 42.240686/88.500817

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) barn; (C) stone milk house; (D) new garage

Residence detail:

Style: Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: front porch, dormer

Barn Detail

Style: Hipped roof

Wall materials: vertical wood board

Roof materials: asphalt or concrete tile

Foundation materials: high fieldstone

Other distinguishing features: different

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.



SE-35-6: 5598 McCue Road – Barn




SE-35-6: 5598 McCue Road – Residence



SE-35-6: 5598 McCue Road - Outbuildings

MCHENRY COUNTY
 SENECA TOWNSHIP
 SECTION 36





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
 Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- SE-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/3/15_____ Survey Number: SE-36-1_____ Surveyor Name: J. Davis_____

Current Property or Structure Name: _____

Address: 5105 Timberline Road _____

Lat/Long: 42.254423/88.481349

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence detail:

Style: Split Level

Wall materials: vinyl and brick

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: attached two-bay garage

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: one-story addition to north

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1965

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-36-1: 5105 Timberline Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/3/15_____ Survey Number: SE-36-2_____ Surveyor Name: J. Davis_____

Current Property or Structure Name: _____

Address: Pleasant Valley Road _____

Lat/Long: 42.247420/88.474196

Primary Use: resid/agri: abandoned _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) fieldstone utility shed; (B) concrete stave silo

Residence detail: no residence

Barn Detail: no barn

Style:

Style:

Wall materials:

Wall materials:

Roof materials:

Roof materials:

Foundation materials:

Foundation materials:

Other distinguishing features:

Other distinguishing features:

Any obvious Additions/Alterations: one-story addition to north

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-36-2: Pleasant Valley Road – Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/3/15_____ Survey Number: SE-36-3_____ Surveyor Name: J. Davis_____

Current Property or Structure Name: _____

Address: 14705 Pleasant Valley Road _____

Lat/Long: 42.250535/88.483757

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence detail:

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: prominent roof dormers

Barn Detail:

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: one-story addition to east

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872-1892

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.



SE-36-3: 14705 Pleasant Valley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/3/15_____ Survey Number: SE-36-4_____ Surveyor Name: J. Davis_____

Current Property or Structure Name: _____

Address: 4501 Pleasant Valley Road _____

Lat/Long: 42.250373/88.488238

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) barn; (C) concrete silo; (D) metal pole barn; (E) low, long animal, poss. pig barn; (F) group of five Haverstore metal silos

Residence detail:

Style: Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: painted concrete

Other distinguishing features:

Barn Detail:

Style: Gambrel roof

Wall materials: vertical wood board

Roof materials: metal

Foundation materials: fieldstone

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.



SE-36-4: 4501 Pleasant Valley Road -
Outbuildings



SE-36-4: 4501 Pleasant Valley Road -
Outbuildings



SE-36-4: 4501 Pleasant Valley Road – Residence