

Previous Site	Pin Number	Pin Suffix	Structure Type	Vernacular Form	Architectural Style	Circa	Condition	Integrity	Foundation	Walls	Roof	Porch	Alterations	History	Roll	Photo.	Pin Prefix
1358	1701400001		1 House	Upright and Wing	N / A	1860-1890	Fair	Poor	Limestone	Asbestos	Asphalt	Enclosed and en	Siding, windows, porches changed	This property is now owned by MCCD and most of the buildings are in the process of being taken down.	3h	16	17
1358	1701400001		2 House	Cottage	Bungalow	1900-1930	Good	Good	Poured Concrete	Clapboard	Asphalt	Enclosed		Second house on property	3H	15	17
1358	1701400001		3 Shed	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt		New siding added and garage doors changed	Possible older barn that was converted to a garage/shed, but is greatly altered	3h	13	17
1358	1701400001		4 Shed	Side Gabled	N / A		Fair	Fair		Vertical Wood	Asphalt			Machine shed	3h	12	17
1358	1701400001		5 Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3h	14	17
1204	1702100013		1 House	Upright and Wing	N / A	1880-1920	Good	Good		Aluminum Siding	Asphalt	Enclosed	Windows, siding, porches changed, chimney added	Very little historic integrity left	3f	11	17
1204	1702100013		2 Barn	Transverse Frame	N / A	1880-1920	Good	Fair		Vertical Wood	Tin (Flat)			Includes concrete staved silo and metal pole barn with a quonset style side addition	3f	9	17
1204	1702100013		3 Shed	Front Gabled	N / A		Fair	Fair		Vertical Wood	Asphalt		Semi-circle gable window added	Older building converted into garage with extra tall door attached to other tin buildings	3f	10	17
1204	1702100013		4 Barn	Dairy Gambrel	N / A		Good	Fair		Aluminum Siding	Asphalt		Converted to garage with living area above	Very altered	3f	7	17
1204	1702100013		5 Garage	Side Gabled	N / A		Good	Good		Aluminum Siding	Asphalt			2-car; has same semi-circle gable window as other buildings	3f	8	17
1207	1702200002		1 House	Four-over-four	N / A	1900-1930	Good	Fair	Poured Concrete	Aluminum Siding	Asphalt	Removed	Porch removed, siding added, but windows are original 4-over-1	Has original dormer; Note that site has very high knolls (original glacial landform deposits differing from kames) to the north and across road	3e	22	17
1207	1702200002		2 Barn	Dairy Gambrel	N / A	1900-1930	Poor	Good		Vertical Wood	Asphalt			Includes concrete staved silo	3e	24	17
1207	1702200002		3 Shed	Side Gabled	N / A		Fair	Good		Vertical Wood	Asphalt			Machine shed	3e	23	17
1209	1702300002		1 House	I-house	N / A	1860-1880	Poor	Poor	Field Stone	Asbestos	Asphalt	Removed	Windows of different sizes and shapes added, porches changed, dormers may have been added	Looks abandoned and/or very run-down	3e	35	17
1209	1702300002		2 Barn	Dairy Gambrel	N / A		Very Poor	Fair		Vertical Wood	Wood Shingles			Abandoned; very huge	3e	37	17
1209	1702300002		3 Milkhouse	Side Gabled	N / A		Very Poor	Fair		Field Stone	Wood Shingles			Windows, doors and roof are all rotten wood	3e	34	17
1209	1702300002		4 Garage	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt				3e	36	17
1211	1702400014		1 Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			On site of former school from 1872 Platbook; this property still owned by a school district now	3g	11	17
1211	1702400014		2 Barn	Commercial	N / A		Good	Good		Cement Block	Asphalt			2 commercial structures (commercial garage and office building)	3g	10	17
1208	1702400017		1 House	Upright and Wing	N / A	1880-1920	Poor	Poor		Aluminum Siding	Asphalt	Removed	Porch changed, windows, siding, too; addition to rear	Very large hog farm operation; house integrity mostly gone; possibly in process of being sold to MCCD	3e	31	17
1208	1702400017		2 House	Ranch	Raised Ranch	1950-present	Good	Good		Tin (Flat)	Asphalt			Hired hand's house	3e	32	17
1208	1702400017		3 Shed	Slant-roofed	N / A		Poor	Poor		Tin (Flat)	Tin (Flat)		Completely covered	Unclear original purpose	3e	29	17
1208	1702400017		4 Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3e	33	17
1208	1702400017		5 Barn	Metal Pole Barn	N / A		Poor	Good		Tin (Flat)	Tin (Flat)				3e	30	17
1208	1702400017		6 Corn Crib	Side Gabled	N / A		Fair	Good		Tin (Perforated)	Tin (Flat)			Includes round grain bin and other small connected sheds for the feed/grainery operation	3e	28	17
1208	1702400017		7 Silo	Steel	N / A		Good	Good		Steel	Steel			2 "A.O. Smith Harvestore" silos including several grain/feed hoppers	3e	27	17
1208	1702400017		8 Hog House	Metal Pole Barn	N / A		Fair	Good	Brick	Tin (Flat)	Tin (Flat)			Large scale hog storage	3e	25	17
1208	1702400017		9 Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Includes feed hoppers	3e	26	17
1065	1703100001		1 House	Upright and Wing	Greek Revival	1850-1860	Very Poor	Fair	Field Stone	Clapboard	Asphalt	Open		This house has been abandoned for years and is now lived in by raccoons. Original windows are still intact underneath plywood.	3f	17	17
1065	1703100001		2 Corn Crib	Slant-roofed	N / A		Poor	Fair		Horizontal Slats	Wood Shingles		Shed addition to rear	Starting to fall down	3f	19	17
1065	1703100001		3 Chicken Coop	Uneven Gable	N / A		Poor	Fair		Vertical Wood	Asphalt			Falling down; windows are gone or broke	3f	18	17
1065	1703100001		4 Shed	Quonset	N / A		Poor	Good		Beveled Clapboard	Tin (Flat)				3f	20	17
1066	1703100007		1 House	I-house	N / A	1860-1890	Fair	Poor		Aluminum Siding	Asphalt	Removed	Large back wing added around the turn-of-the-century	This site is an old farmstead that is the local feedstore for the area farmers and horse stables	3f	27	17
1066	1703100007		2 Barn	Dairy Gambrel	N / A		Poor	Fair		Tin (Flat)	Wood Shingles		Siding altered appearance by covering windows and doors	Roof is in much need of repair	3f	21	17
1066	1703100007		3 Milkhouse	Front Gabled	N / A		Fair	Good		Aluminum Siding	Asphalt		Converted to office for feed business	Detached	3f	26	17
1066	1703100007		4 Garage	Front Gabled	N / A		Good	Good		Aluminum Siding	Asphalt			Attached	3f	24	17
1066	1703100007		5 Shed	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Includes grain hoppers and 2 large round grain bins	3f	23	17
1066	1703100007		6 Corn Crib	Transverse Aisle	N / A		Fair	Poor		Tin (Flat)	Asphalt			Corn crib has had sides coated with tin	3f	22	17
1066	1703100007		7 Grain Bin	Round	N / A		Good	Good		Tin (Corrugated)	Tin (Flat)			2 round bins, 2 hoppers and 1 metal pole building	3f	25	17
1203	1703200001		1 House	Four-over-four	N / A	1880-1920	Good	Fair	Field Stone	Clapboard	Asphalt	Open	Rear wing added and side bay changed/added	Appears to be a replacement house just after the turn-of-the-century	3f	16	17
1203	1703200001		2 Barn	Three-bay Threshing	N / A	1860-1880	Poor	Fair		Vertical Wood	Asphalt			Main door has been changed; note row of windows above door	3f	15	17
1203	1703200001		3 Corn Crib	Transverse Aisle	N / A		Poor	Good		Vertical Slats	Wood Shingles			One of few vertical slat corn cribs, however in very poor condition	3f	14	17
1203	1703200001		4 Milkhouse	Side Gabled	N / A		Fair	Good		Vertical Wood	Tin (Flat)			Detached	3f	13	17
1203	1703200001		5 Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3f	12	17
1067	1703300009		1 House	Upright and Wing	N / A	1860-1890	Good	Good		Vinyl Siding	Asphalt	Enclosed	The usual modernizations: siding, windows, doors	Original inset porch was enclosed	3f	31	17
1067	1703300009		2 Barn	Composite	N / A		Fair	Good		Vertical Wood	Asphalt			2 gambrels wing built as one composite barn	3f	29	17
1067	1703300009		3 Garage	Front Gabled	N / A		Fair	Fair		Beveled Clapboard	Asphalt				3f	28	17
1067	1703300009		4 Chicken Coop	Slant-roofed	N / A		Fair	Good		Beveled Clapboard	Rolled Asphalt				3f	30	17
1359	1703300011		1 Depot	Side Gabled	N / A	1860-1890	Excellent (R)	Excellent		Vertical Wood	Asphalt	Inset	Chimney was added long ago; windows and siding were changed	Original Railroad station depot on site of the Illinois Railway museum. Interior is still also all original and still has the feel of history.	3f	37	17
1359	1703300011		2 Shed	Pyramidal	N / A		Good	Good		Clapboard	Asphalt			Switching station building for railroad; rectangular 2-story structure with hipped roof	3f	36	17
1359	1703300011		3 Shed	Slant-roofed	N / A		Good	Good		Clapboard	Asphalt				3f	35	17
1068	1704400016		1 House	Upright and Wing	Greek Revival	1850-1870	Fair	Fair		Vertical Wood	Asphalt	Inset		Although there were major changes to the siding and windows, at least this house was taken care of. The roof had been falling-in and at least the cornice returns were saved.	3f	32	17
1068	1704400016		2 Barn	Transverse Frame	N / A		Good	Good		Vertical Wood	Tin (Flat)			Includes concrete staved silo	3f	34	17
1068	1704400016		3 Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Tin (Flat)			Has wide opening every 6 slats	3f	33	17
1774	1705100004		1 House	Upright and Wing	N / A		Poor	Poor		Aluminum Siding	Asphalt	Removed	Rear addition; windows, doors and siding changed	Abandoned	3v	30	17
1774	1705100004		2 Barn	Upright and Wing	N / A		Fair	Fair		Aluminum Siding	Asphalt			Includes concrete staved silo with metal dome roof	3v	33	17
1774	1705100004		3 Pumphouse	Pyramidal	N / A		Poor	Poor		Aluminum Siding	Asphalt			Pumphouse/milkhouse combination	3v	34	17
1774	1705100004		4 Shed	Slant-roofed	N / A		Poor	Fair		Aluminum Siding	Asphalt				3v	32	17
1774	1705100004		5 Shed	Slant-roofed	N / A		Poor	Fair		Cement Block	Asphalt				3v	31	17
1775	1705100005		1 House	Side Gabled	Classic Revival	1900-1930	Good	Good		Aluminum Siding	Asphalt		Side porch enclosed, but may have been built that way		3v	28	17

1775	1705100005	2	Garage	Side Gabled	N / A		Good	Good		Aluminum Siding	Asphalt					3-car; has semi-circle gable window to match house	3v	29	17	
1773	1705100009	1	House	Upright and Wing	N / A	1880-1920	Good	Good		Aluminum Siding	Asphalt	Removed	Modernized					3v	37	17
1773	1705100009	2	Barn	Transverse Frame	N / A		Good	Good		Vertical Wood	Asphalt					Has side wing that may have been original barn or this could have been built as a composite barn; also includes concrete staved silo with a metal dome roof	3v	35	17	
1773	1705100009	3	Corn Crib	Transverse Aisle	N / A		Good	Good		Vertical Wood	Asphalt		Converted into a shed			Also includes a side gabled machine shed	3v	36	17	
1773	1705100009	4	Chicken Coop	Uneven Gable	N / A		Fair	Good		Beveled Clapboard	Asphalt					Includes a livestock shelter and a pole barn	3w	1	17	
1076	1705200001	1	House	Upright and Wing	N / A	1880-1920	Poor	Poor		Aluminum Siding	Asphalt	Inset	New windows; already was much changed					3s	10	17
1076	1705200001	2	Garage	Pyramidal	N / A		Good	Good		Aluminum Siding	Asphalt					Double door	3s	11	17	
1076.5	1705200006	1	House	Upright and Wing	N / A	1860-1880	Good	Good	Field Stone	Clapboard	Asphalt	none	New windows			Unusually large side-wing; also with side wing being as tall as the upright and as large there is currently no porch area, but it may have been removed	3z	13	17	
1076.5	1705200006	2	Barn	Transverse Frame	N / A	1880-1920	Good	Poor		Vertical Wood	Asphalt		Has large shed addition to front of barn				3z	16	17	
1076.5	1705200006	3	Pumphouse	Front Gabled	N / A		Poor	Fair		Beveled Clapboard	Wood Shingles					Also includes slant-roofed chicken coop	3z	17	17	
1076.5	1705200006	4	Garage	Front Gabled	N / A		Poor	Good		Tin (Corrugated)	Tin (Corrugated)					1-Car	3z	14	17	
1076.5	1705200006	5	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)						3z	15	17	
1075	1705200009	1	House	Upright and Wing	N / A	1860-1890	Good	Good	Limestone	Clapboard	Asphalt	Shortened				Still has original 2-over-2 windows and wood storm windows	3s	14	17	
1075	1705200009	2	Garage	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt					Includes also an older wood-sided pole barn	3S	12	17	
1075	1705200009	3	Shed	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt					Includes also an older wood-sided pole barn	3s	12	17	
1075	1705200009	4	Shed	Side Gabled	N / A		Fair	Good		Vertical Wood	Asphalt					Machine shed	3s	13	17	
1074	1705300019	1	House	Cottage	Cape Cod	1900-1930	Good	Good		Vinyl Siding	Asphalt	Open	Totally redone			Original house barely recognizable	3x	22	17	
1074	1705300019	2	House	Cottage	Ranch	1950-present	Good	Good		Vinyl Siding	Asphalt	none				Secondary house	3x	15	17	
1074	1705300019	3	Barn	Transverse Frame	N / A		Good	Good		Vertical Wood	Asphalt		Has major shed addition to the side			Extremely small with an offset aisle	3x	17	17	
1074	1705300019	4	Barn	Transverse Frame	N / A	1900-1930	Good	Good		Vertical Wood	Asphalt					Includes poured concrete silo with metal dome roof and attached milkhouse	3x	20	17	
1074	1705300019	5	Pumphouse	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt						3x	18	17	
1074	1705300019	6	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)						3x	19	17	
1074	1705300019	7	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)						3x	21	17	
1772	1706100024	1	House	Side Gabled	Greek Revival	1850-1870	Excellent (R)	Excellent	Field Stone	Clapboard	Asphalt	Open	New windows, but this house is relatively unchanged from its original look with the grand full-façade columned porch and formal door surround.			Note that the upper railing is original. This is a Nat'l Reg. house and an 1872 Platbook house. It is known as the Orson Rogers house and the Seward house. It has a twin on site 1771.	3v	15	17	
1772	1706100024	2	Shed	Side Gabled	N / A		Good	Good		Glass	Glass					Poolhouse	3v	14	17	
1771.5	1706200001	1	House	Ranch	N / A	1900-1930	Good	Good		Clapboard	Asphalt	Inset				This house is older than it appears. Note the inset porch and the long windows	3v	22	17	
1771.5	1706200001	2	Barn	Gothic Arched	N / A		Fair	Poor		Tin (Flat)	Tin (Flat)		Inappropriate striped roof			Includes a detached milkhouse and a concrete staved silo	3v	21	17	
1771.5	1706200001	3	Shed	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)						3v	23	17	
1771	1706300007	1	House	Side Gabled	Greek Revival	1850-1860	Excellent (R)	Excellent	Field Stone	Clapboard	Asphalt	Open	Very little changes over the years			This is a twin house to site 1772; notice the full façade front porch; also, railing above porch is original as shown in the 1872 Platbook view	3v	16	17	
1771	1706300007	2	School	Side Gabled	Greek Revival	1850-1860	Excellent (R)	Good		Clapboard	Asphalt		Some windows changed; converted into a garage			Note the original cupolas and massive pilasters; this was a former school with style	3v	18	17	
1771	1706300007	3	Barn	Three-bay Threshing	N / A	1850-1870	Good	Good		Vertical Wood	Asphalt					This is a very old barn that was enlarged; also includes 2 concrete staved silos with metal dome roofs and 2 round metal grain bins	3v	20	17	
1771	1706300007	4	Shed	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt					Machine shed	3v	19	17	
1771	1706300007	5	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)						3v	17	17	
1770	1706400001	1	House	Four-over-four	Foursquare	1910-1940	Good	Good	Molded Block	Clapboard	Asphalt	Open	Lattice added to porch railing			Converted to a business site	3v	24	17	
1770	1706400001	2	Barn	Dairy Gambrel	N / A		Good	Poor		Tin (Flat)	Tin (Flat)		Covered in tin			Includes concrete staved silo with no roof	3v	25	17	
1769	1706400002	1	House	Cottage	N / A	1900-1930	Good	Fair		Aluminum Siding	Asphalt					Note front brackets on entry	3w	5	17	
1769	1706400002	2	Barn	Transverse Frame	N / A		Good	Poor		Tin (Flat)	Asphalt		Layout changed when sided				3w	2	17	
1769	1706400002	3	Chicken Coop	Front Gabled	N / A		Fair	Fair		Tin (Flat)	Tin (Flat)		Windows covered				3w	4	17	
1769	1706400002	4	Outhouse	Slant-roofed	N / A		Good	Good		Vertical Wood	Asphalt					Very narrow; also includes storage shed and livestock shelter	3w	3	17	
1767	1707200015	1	House	Side Gabled	N / A	1850-1870	Good	Good		Aluminum Siding	Asphalt	Front entry	Has back shed addition; side wing appears to be original			Much older house than it appears; note the original 6-over-6 windows; possibly owned by MCCD	3v	13	17	
1767	1707200015	2	Barn	Transverse Frame	N / A	1880-1920	Good	Good		Tin (Flat)	Asphalt		Has large shed addition to the side				3v	10	17	
1767	1707200015	3	Barn	Gothic Arched	N / A		Good	Good	Cement Block	Vertical Wood	Asphalt					Has central dormer	3v	11	17	
1767	1707200015	4	Milkhouse	Side Gabled	N / A		Fair	Good		Field Stone	Asphalt						3v	12	17	
1768.5	1707200018	1	House	Cottage	Dutch Revival	1910-1940	Good	Good		Brick	Asphalt	Open				Notice clipped gable	3v	26	17	
1768.5	1707200018	2	Barn	Dairy Gambrel	N / A		Good	Good		Clapboard	Asphalt		Has shed additions to rear and side			Also includes a very small side-gabled corn crib/shed	3v	27	17	
1730	1707300003	1	House	Upright and Wing	N / A	1880-1920	Poor	Poor		Aluminum Siding	Asphalt	Enclosed and en	Windows of different sizes, chimney, porch enlarged to the front are among the many changes			Not much apparent of the original house	3u	20	17	
1730	1707300003	2	Garage	Front Gabled	N / A		Good	Good		Aluminum Siding	Asphalt					Double door	3u	21	17	
1730	1707300003	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)					Partially open sides	3u	18	17	
1730	1707300003	4	Chicken Coop	Uneven Gable	N / A		Very Poor	Poor		Tin (Flat)	Tin (Flat)					Part of roof is missing	3u	19	17	
1728	1707300004	1	House	Side Gabled	N / A	1880-1920	Good	Good		Vinyl Siding	Asphalt	Open				Possibly older, but just redone and modernized	3v	5	17	
1728	1707300004	2	Barn	Transverse Frame	N / A	1880-1920	Good	Fair		Tin (Flat)	Tin (Flat)		Huge front wing was added			Includes the original, back barn, a gabled milkhouse and a concrete staved silo with a metal dome roof	3t	37	17	
1728	1707300004	3	Barn	Transverse Frame	N / A		Good	Good		Vertical Wood	Tin (Flat)					Small barn, possibly for horses or other livestock	3u	3	17	
1728	1707300004	4	Garage	Front Gabled	N / A		Good	Good		Vertical Wood	Tin (Flat)						3u	2	17	
1728	1707300004	5	Garage	Front Gabled	N / A		Good	Good		Molded Block	Asphalt		Has been added onto to make it deeper				3u	1	17	
1728	1707300004	6	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)						3u	4	17	
1727	1707300008	1	House	Upright and Wing	N / A	1860-1890	Good	Fair		Vinyl Siding	Asphalt	Enclosed	Chimney added, plus windows ,siding and doors changed				3u	8	17	
1727	1707300008	2	Garage	Front Gabled	N / A		Good	Good		Molded Block	Asphalt						3u	6	17	
1727	1707300008	3	Shed	Front Gabled	N / A		Fair	Fair		Tin (Flat)	Asphalt						3u	7	17	
1729	1707300017	1	House	Cottage	Bungalow	1910-1940	Good	Good		Aluminum Siding	Asphalt	Enclosed	New siding and porch enclosed			This is actually a two-part house the back section (in the next view) is much older and was the cheese factory. The front was added/redone just after the turn-of-the-century.	3u	16	17	
1729	1707300017	2	House		N / A								Shed addition to the side and new front section			Second view to show the former cheese factory/back section of this house.	3u	15	17	
1729	1707300017	3	Garage	Front Gabled	N / A		Good	Good		Clapboard	Asphalt					2-Car	3u	14	17	
1729	1707300017	4	Barn	Transverse Frame	N / A	1900-1930	Good	Fair		Tin (Flat)	Tin (Flat)		Shed addition				3u	13	17	

1729	1707300017	5	Silo	Concrete Staved	N / A			Good	Good		Concrete Staved	Metal Dome				3 Silos	3u	12	17
1729	1707300017	6	Barn	Metal Pole Barn	N / A			Good	Good		Tin (Flat)	Tin (Flat)					3u	11	17
1729	1707300017	7	Barn	Metal Pole Barn	N / A			Good	Good		Tin (Flat)	Tin (Flat)					3u	17	17
1729	1707300017	8	Corn Crib	Round	N / A			Good	Good		Wire Mesh	Tin (Flat)					3u	10	17
1731	1707400001	1	House	Cross Gabled	Queen Anne	1890-1910		Good	Excellent		Clapboard	Asphalt	Open	Only minor changes	Note porches and bays and gable ornamentation; this may be a second house on this site	3u	31	17	
1731	1707400001	2	Barn	Three-bay Threshing	N / A	1860-1890		Good	Excellent		Vertical Wood	Asphalt			Possibly older than house	3u	27	17	
1731	1707400001	3	Barn	Gothic Arched	N / A	1910-1940		Good	Good		Vertical Wood	Wood Shingles			Includes a concrete staved silo without roof	3u	33	17	
1731	1707400001	4	Chicken Coop	Side Gabled	N / A	1900-1930		Good	Good		Molded Block	Asphalt			Still being used as a chicken coop	3u	28	17	
1731	1707400001	5	Garage	Front Gabled	N / A	1900-1930		Good	Good		Molded Block	Asphalt			Notice the original period swing garage doors	3u	29	17	
1731	1707400001	6	Outhouse	Side Gabled	N / A			Good	Excellent		Clapboard	Asphalt			Notice the door is from the original house (2-over2 vertical panels)	3u	30	17	
1731	1707400001	7	Hog House	Side Gabled	N / A			Good	Good	Poured Concrete	Clapboard	Asphalt				3u	32	17	
1731	1707400001	8	Corn Crib	Transverse Aisle	N / A			Good	Good		Tin (Perforated)	Asphalt			Unusual style where the aisle runs perpendicular to the gable instead parallel. Also the center open area is extra wide to also be used as a machine shed.	3u	23	17	
1731	1707400001	9	Corn Crib	Transverse Aisle	N / A			Good	Good		Tin (Perforated)	Asphalt			Again this is a combination corncrib/machine shed	3u	24	17	
1731	1707400001	10	Pumphouse	Front Gabled	N / A			Poor	Good		Clapboard	Wood Shingles				3u	26	17	
1733	1707400005	1	House	Upright and Wing	N / A	1860-1890		Fair	Fair		Aluminum Siding	Asphalt	Enclosed	Both porches enclosed; windows changed; other details removed		3v	1	17	
1733	1707400005	2	Barn	Three-bay Threshing	N / A	1860-1890		Good	Good		Tin (Flat)	Asphalt		Two shed additions		3u	34	17	
1733	1707400005	3	Garage	Side Gabled	N / A			Good	Good		Cement Block	Asphalt		Shed addition made out of tin	3-car, 2-story	3u	38	17	
1733	1707400005	4	Corn Crib	Transverse Aisle	N / A			Good	Good		Tin (Perforated)	Tin (Flat)				3u	37	17	
1733	1707400005	5	Barn	Metal Pole Barn	N / A			Good	Good		Tin (Flat)	Tin (Flat)			2 Metal pole barns	3u	36	17	
1733	1707400005	6	Milkhouse	Pyramidal	N / A			Good	Good		Vertical Wood	Asphalt			Detached	3u	35	17	
1731.5	1707400021	1	House	Upright and Wing	N / A	1860-1890		Fair	Fair		Aluminum Siding	Asphalt	Enclosed	Used to have an inset porch; siding and window changes have greatly altered the appearance	Not much historic integrity left	3t	35	17	
1731.5	1707400021	2	Shed	Slant-roofed	N / A			Fair	Fair		Vertical Wood	Asphalt			2 Slant-roofed sheds together	3t	33	17	
1731.5	1707400021	3	Hog House	Broken Eave	N / A			Fair	Fair		Vertical Wood	Tin (Flat)			Roof sagging	3t	32	17	
1731.5	1707400021	4	Shed	Front Gabled	N / A			Good	Good		Wood Staved	Tin (Flat)			A series of 3 sheds including a metal pole barn and a curved-roof shed, also.	3t	34	17	
1731.5	1707400021	5	Chicken Coop	Broken Eave	N / A			Good	Good		Beveled Clapboard	Tin (Flat)				3t	36	17	
1765	1708100013	1	House	Upright and Wing	N / A	1860-1890		Fair	Good		Aluminum Siding	Asphalt	Enclosed	Windows, siding, chimney and porches all changed	Not much historic integrity left in this one, unless the inside is unaltered	3w	13	17	
1765	1708100013	2	Barn	Dairy Gambrel	N / A			Good	Good		Vertical Wood	Asphalt			In good shape except for vent	3w	11	17	
1765	1708100013	3	Shed	Gambrel	N / A			Good	Good		Beveled Clapboard	Asphalt			Possibly hog house or for other livestock	3w	14	17	
1765	1708100013	4	Shed	Front Gabled	N / A			Good	Good		Beveled Clapboard	Asphalt				3w	12	17	
1764	1708100014	1	House	Front Gabled	N / A	1900-1930		Good	Good	Molded Block	Aluminum Siding	Asphalt	Removed	New siding, windows, etc.	Undetermined prior usage or form	3w	16	17	
1764	1708100014	2	Barn	Metal Pole Barn	N / A			Good	Good		Tin (Flat)	Tin (Flat)				3w	15	17	
1763	1708100020	1	House	Upright and Wing	N / A	1860-1880		Very Poor	Poor		Aluminum Siding	Asphalt	Removed		Looks abandoned; note 2-over-2 windows	3v	8	17	
1763	1708100020	2	Shed	Front Gabled	N / A			Falling down	Fair		Beveled Clapboard	Wood Shingles			Note old door period to the house	3v	9	17	
1763	1708100020	3	Barn	Metal Pole Barn	N / A			Fair	Fair		Tin (Flat)	Tin (Flat)				3v	7	17	
1768	1708100021	1	House	Upright and Wing	N / A			Fair	Fair		Stone facing	Asphalt		Windows and siding changed		3w	7	17	
1768	1708100021	2	Barn	Dairy Gambrel	N / A			Good	Good		Vertical Wood	Asphalt			Includes Dairy Gambrel barn, pyramidal garage, milkhouse, small gabled garage and another shed in the back	3w	8	17	
1073.5	1708100028	1	House	Ranch	Ranch	1950-present		Good	Good		Vinyl Siding	Asphalt	none		Replacement house	3x	11	17	
1073.5	1708100028	2	Barn	Three-bay Threshing	N / A	1860-1890		Fair	Fair		Tin (Flat)	Asphalt			This includes both the older barn that has had siding put on it and the newer Dairy Gambrel barn that was added on behind it. Also included is the 2 concrete staved silos with metal dome roofs	3x	12	17	
1073.5	1708100028	3	Milkhouse	Side Gabled	N / A			Good	Excellent		Molded Block	Asphalt			Complete with vent!	3x	6	17	
1073.5	1708100028	4	Corn Crib	Gambrel	N / A			Good	Fair		Aluminum Siding	Tin (Flat)		This corn crib was converted into storage by placing siding over the slats	Hardly recognizable as a corn crib, now looks like a small barn. However, the large cross-vent that is only partially visible in this photo is the defining feature.	3x	9	17	
1073.5	1708100028	5	Barn	Metal Pole Barn	N / A			Good	Good		Tin (Flat)	Tin (Flat)				3x	10	17	
1073.5	1708100028	6	Barn	Metal Pole Barn	N / A			Good	Good		Tin (Flat)	Tin (Flat)				3x	7	17	
1073.5	1708100028	7	Barn	Metal Pole Barn	N / A			Good	Good		Tin (Flat)	Tin (Flat)				3x	8	17	
1073	1708200003	1	House	Upright and Wing	Greek Revival	1860-1890		Good	Fair		Aluminum Siding	Asphalt	Modified	Modernized: siding, windows, porch, chimney all changed	At least the cornice returns remain as a symbol of this houses older roots	3x	14	17	
1073	1708200003	2	Barn	Metal Pole Barn	N / A			Good	Good		Tin (Flat)	Tin (Flat)				3x	13	17	
1734	1708300001	1	House	Upright and Wing	N / A	1860-1890		Good	Fair		Vinyl Siding	Asphalt	Enclosed	Major: the lower side wing rebuilt into a massive wing larger than the original upright	Due to the massing, roof pitch, bay and fenestration pattern, the rebuild of the side wing could be of the 1880 - 1910 era, so has become part of the historic fabric of this farmstead.			17	
1734	1708300001	2	Barn	Three-bay Threshing	N / A	1860-1890		Fair	Good		Vertical Wood	Asphalt			Older than it initially appears, but due to its small stature may have a layout more conducive to a carriage barn	3v	5	17	
1734	1708300001	3	Shed	Side Gabled	N / A			Good	Good		Beveled Clapboard	Asphalt			Livestock or machine shed	3v	4	17	
1734	1708300001	4	Garage	Front Gabled	N / A			Good	Good		Vinyl Siding	Asphalt				3v	3	17	
1734	1708300001	5	Pumphouse	Side Gabled	N / A			Good	Good		Beveled Clapboard	Asphalt				3v	2	17	
1762	1708300005	1	House	Upright and Wing	N / A	1860-1890		Fair	Fair		Vinyl Siding	Asphalt	Enclosed	Windows, siding and porch all changed	Side wing is taller than upright; includes front-gabled shed in background	3w	18	17	
1762	1708300005	2	Shed	Front Gabled	N / A	1860-1880		Good	Good		Clapboard	Asphalt		Shed addition on rear	Note 2-over-2 window is clue that this is older than it appears; may have had prior function as summer kitchen	3w	20	17	
1761	1708300006	1	Garage	Front Gabled	N / A			Very Poor	Good		Aluminum Siding	Asphalt			House burned down in 1995; all that's left is this garage	3z	19	17	
1760	1708300008	1	vacant		N / A										Gone			17	
1759	1708300009	1	House	Upright and Wing	N / A	1860-1880		Good	Good		Vinyl Siding	Asphalt	Removed	Siding, porch, windows, doors	Very modernized and remuddled	3w	21	17	
1759	1708300009	2	Barn	Three-bay Threshing	N / A			Fair	Fair		Vertical Wood	Asphalt				3w	22	17	
1759	1708300009	3	Milkhouse	Side Gabled	N / A			Good	Good		Vertical Wood	Asphalt			Detached	3w	23	17	
1757	1708300010	1	House	Side Gabled	N / A	1880-1920		Good	Fair		Clapboard	Asphalt	Enclosed			3w	25	17	
1757	1708300010	2	Barn	Transverse Frame	N / A	1880-1920		Good	Good		Vertical Wood	Asphalt		Main door changed	Includes front-gabled shed	3w	24	17	
1732	1708300012	1	House	Front Gabled	N / A	1880-1920		Good	Fair		Vertical Wood	Asphalt		Windows, door, siding changed	Former school	3t	31	17	

1732	1708300012	2	Garage	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt				With shed back added	3t	30	17	
1756.5	1708300013	1	Cemetery		N / A		Good	Good							"Coral Cemetery"	3w	26	17	
1735	1708300014	1	House	Upright and Wing	N / A	1850-1870	Fair	Fair	Field Stone	Asbestos	Asphalt	Open	Windows changed and some other minor changes with siding change	Note: previous survey had their photo mislabeled as 1758. This is a cross-roads house for the former Coral village. Note the shed side wing with a store front façade. This could have been a combination shopkeeper's store and residence.	3t	27	17		
1735	1708300014	2	Barn	Composite	N / A	1860-1890	Good	Good		Vertical Wood	Asphalt			Small composite barn that may have been just the Three-bay Threshing barn with a small Transverse Frame barn added onto it. There is also a slant-roofed milkhouse attached to the older Three-bay barn.	3t	26	17		
1735	1708300014	3	Garage	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt					3t	28	17	
1735	1708300014	4	Shed	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt						3t	29	17
1756	1708400004	1	House	Upright and Wing	N / A	1860-1890	Good	Good		Asbestos	Asphalt	Open	Front bay window added and some other windows changed	Note upper 2-over-2 windows		3w	33	17	
1756	1708400004	2	Barn	Three-bay Threshing	N / A	1860-1890	Poor	Poor		Vertical Wood	Asphalt		Additions on both ends	This is an older Three-bay Threshing barn that was added onto both ends and converted into a Transverse Frame barn.		3w	32	17	
1756	1708400004	3	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome					3w	34	17	
1756	1708400004	4	Milkhouse	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Either added onto or built as a composite T-plan structure		3w	31	17	
1756	1708400004	5	Chicken Coop	Slant-roofed	N / A		Fair	Good		Vertical Wood	Asphalt					3w	30	17	
1756	1708400004	6	Corn Crib	Transverse Aisle	N / A		Good	Good		Vertical Slats	Wood Shingles			This is a very unique corn crib, since it is the only one located with vertical slats.		3w	28	17	
1756	1708400004	7	Shed	Front Gabled	N / A		Fair	Good		Beveled Clapboard	Asphalt			Shed with another attached slant-roofed shed		3w	27	17	
1756	1708400004	8	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)					3w	29	17	
1226	1709100006	1	House	Four-over-four	Italianate	1860-1880	Good	Fair	Field Stone	Aluminum Siding	Asphalt	Modified	Widow's walk or cresting removed; addition to side; modern picture windows added; porch modified	This is a "Central Hall Double Pile" vernacular house with Italianate influences. It is a classic "cube-and-side-wing" massing plan. However, if both were not built at the same time, further investigation would be needed to determine which came first.	3i	28	17		
1226	1709100006	2	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome			Also includes a poured concrete with no roof		3i	26	17	
1226	1709100006	3	Garage	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Sliding door		3i	29	17	
1226	1709100006	4	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)					3i	25	17	
1226	1709100006	5	Pumphouse	Front Gabled	N / A		Good	Good		Aluminum Siding	Asphalt					3i	24	17	
1226	1709100006	6	Garage	Side Gabled	N / A		Good	Good		Aluminum Siding	Asphalt				3-car	3i	27	17	
1068.5	1709200005	1	House	Front Gabled	N / A		Good	Fair		Vinyl Siding	Asphalt	Enclosed		Former school		3j	13	17	
1068.5	1709200005	2	Garage	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt					3j	12	17	
1070	1709200006	1	House	Four-over-four	Foursquare	1910-1940	Good	Good		Aluminum Siding	Asphalt	Enclosed		True Foursquare, the newer version of the four-over-four style house		3j	7	17	
1070	1709200006	2	Garage	Side Gabled	N / A		Good	Good		Aluminum Siding	Asphalt				2-car	3j	1	17	
1070	1709200006	3	Barn	Transverse Frame	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt					3j	3	17	
1070	1709200006	4	Shed	Front Gabled	N / A		Good	Good		Aluminum Siding	Asphalt					3j	2	17	
1070	1709200006	5	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)					3j	4	17	
1070	1709200006	6	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)					3j	6	17	
1070	1709200006	7	Grain Bin	Round	N / A		Good	Good		Tin (Corrugated)	Tin (Flat)					3j	5	17	
1069	1709200007	1	House	Upright and Wing	N / A	1880-1920	Good	Good	Molded Block	Aluminum Siding	Asphalt	Enclosed	Windows, siding and porch changes	Side wing is actually a little taller than upright portion		3j	11	17	
1069	1709200007	2	Barn	Dairy Gambrel	N / A		Good	Poor		Tin (Flat)	Asphalt			Either gambrel portion was added onto three-bay portion or the opposite.		3j	10	17	
1069	1709200007	3	Milkhouse	Front Gabled	N / A		Good	Good		Aluminum Siding	Asphalt					3j	8	17	
1069	1709200007	4	Garage	Front Gabled	N / A		Good	Good		Aluminum Siding	Asphalt				2-car	3j	9	17	
1068.3	1709200010	1	House	Side Gabled	N / A	1900-1930	Good	Good		Aluminum Siding	Asphalt			This house is a newer house added onto the original small house (see next photo).		3r	14	17	
1068.3	1709200010	2	House		N / A									Second view to show old original section of the house (Note 6-over-6 windows).		3r	11	17	
1068.3	1709200010	3	Barn	Gothic Arched	N / A	1910-1940	Very Poor	Poor		Clapboard	Asphalt					3r	13	17	
1068.3	1709200010	4	Silo	Poured Concrete	N / A		Good	Good		Poured Concrete	Concrete Conical					3r	12	17	
1068.3	1709200010	5	Shed		N / A		Good	Good		Vertical Wood	Asphalt			This shed is period to the original house. Inside inspection revealed lots of square nails.		3r	8	17	
1068.3	1709200010	6	Shed	Front Gabled	N / A		Fair	Good		Tin (Corrugated)	Tin (Flat)			Unusual roof form with a flared up edge		3r	9	17	
1068.3	1709200010	7	Shed	Side Gabled	N / A		Good	Good		Vertical Wood	Tin (Corrugated)			Machine shed		3r	10	17	
1227	1709300002	1	House	Upright and Wing	N / A	1860-1890	Good	Fair		Aluminum Siding	Asphalt	Open		Great collection of farm buildings on this original owner family farm (Froeling family); barn plaqued by historical society; still an active dairy farm		3i	23	17	
1227	1709300002	2	Barn	Dairy Gambrel	N / A	1910	Good	Good		Tin (Flat)	Asphalt			Plaqued by the McHenry County Historical Society		3i	16	17	
1227	1709300002	3	Milkhouse	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Attached		3i	15	17	
1227	1709300002	4	Silo	Poured Concrete	N / A		Good	Good		Poured Concrete	Metal Dome					3i	17	17	
1227	1709300002	5	Chicken Coop	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Also has slant-sided coop attached		3i	22	17	
1227	1709300002	6	Pumphouse	Front Gabled	N / A		Good	Good		Aluminum Siding	Asphalt					3i	14	17	
1227	1709300002	7	Shed	Pyramidal	N / A		Good	Good		Beveled Clapboard	Asphalt					3i	13	17	
1227	1709300002	8	Outhouse	Slant-roofed	N / A		Good	Good		Beveled Clapboard	Asphalt					3i	8	17	
1227	1709300002	9	Outhouse	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Unusual to have not one, but two outhouses on the premises. One was the newer, better version.		3i	9	17	
1227	1709300002	10	Shed	Slant-roofed	N / A		Good	Good		Vertical Wood	Asphalt					3i	10	17	
1227	1709300002	11	Chicken Coop	Slant-roofed	N / A		Good	Good		Beveled Clapboard	Asphalt					3i	12	17	
1227	1709300002	12	Shed	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Grainery		3i	10	17	
1227	1709300002	13	Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Asphalt					3i	11	17	
1227	1709300002	14	Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Asphalt			Very unique structure: combination corn crib and hog house; the ear corn used for feed for the hogs was certainly handy this way.		3i	20	17	
1227	1709300002	15	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)					3i	21	17	

1227	1709300002	16	Shed	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Machine shed	3i	18	17
1227	1709300002	17	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3i	19	17
1071	1709300004	1	House	Ranch	N / A	1950-present	Good	Good		Vinyl Siding	Asphalt			Replacement house	3i	34	17
1071	1709300004	2	Barn	Dairy Gambrel	N / A	1900-1930	Good	Good		Vertical Wood	Asphalt				3i	35	17
1071	1709300004	3	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome			Flat staved instead of the usual ribbed ones	3i	36	17
1071	1709300004	4	Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Asphalt			Combination crib with one bay slatted and one bay solid that is now used for storage	3i	30	17
1071	1709300004	5	Shed	Front Gabled	N / A		Good	Good		Tin (Flat)	Asphalt			Combination of two sheds	3i	31	17
1071	1709300004	6	Shed	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Livestock shed; notice fold-down doors for airflow	3i	33	17
1071	1709300004	7	Shed	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Machine shed	3i	32	17
1072	1709300005	1	House	Upright and Wing	Queen Anne	1890-1910	Good	Fair		Vinyl Siding	Asphalt	Open	New siding, new windows and trim details removed	This one burned after the photo was taken. However, although it was gutted, the shell was intact so with new insides and windows, it has been rebuilt.	3i	7	17
1072	1709300005	2	Shed	Front Gabled	N / A		Very Poor	Good		Vertical Wood	Asphalt			Older storage shed	3i	5	17
1072	1709300005	3	Silo	Poured Concrete	N / A		Good	Good		Poured Concrete	Metal Dome				3i	4	17
1072	1709300005	4	Smokehouse	Front Gabled	N / A		Good	Good		Molded Block	Asphalt				3i	3	17
1072	1709300005	5	Corn Crib	Transverse Aisle	N / A		Very Poor	Good		Horizontal Slats	Asphalt			Has slight slant to sides, but it is unclear if it is intentionally slant-sided or has just developed a slant due to its poor condition	3i	2	17
1072	1709300005	6	Garage	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Double door	3i	6	17
1223.5	1710100004	1	House	Ranch	N / A	1950-present	Good	Good		Aluminum Siding	Asphalt	none		Replacement house	3k	1	17
1223.5	1710100004	2	Shed	Side Gabled	N / A		Good	Good		Aluminum Siding	Asphalt				3j	36	17
1223.5	1710100004	3	Barn	Three-bay Threshing	N / A	1860-1890	Good	Good		Vertical Wood	Asphalt		New foundation	Has attached slant-roofed milkhouse	3j	37	17
1223.5	1710100004	4	Shed	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Livestock shed	3j	35	17
1223.5	1710100004	5	Shed	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Livestock shelter; open on one side	3j	34	17
1223.5	1710100004	6	Corn Crib	Slant-roofed	N / A		Good	Good		Horizontal Slats	Asphalt			Long, narrow, single bay crib; this one is in relatively good shape as these do not last long once out of use	3j	32	17
1223.5	1710100004	7	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3j	33	17
1224	1710100009	1	House	Upright and Wing	N / A	1850-1870	Good	Poor		Vinyl Siding	Asphalt	Enclosed	Cornice returns removed; large addition put on back and windows, doors, siding changed.	Although this house was drastically changed, the windows had already been changed prior to this round of changes plus it had been sided in asbestos. So, at least the old house has been reworked rather than demolished.	3j	19	17
1224	1710100009	2	Barn	Three-bay Threshing	N / A	1850-1870	Good	Good		Vertical Wood	Asphalt		New garage door and entry door put in	Original barn doors flanked by 6-light windows is still there	3j	18	17
1224	1710100009	3	Milkhouse	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Detached	3j	17	17
1224	1710100009	4	Chicken Coop	Side Gabled	N / A		Fair	Fair		Tin (Flat)	Asphalt			Also includes gambrel storage shed	3j	16	17
1806	1710200001	1	House	Upright and Wing	Greek Revival	1860-1880	Fair	Good		Clapboard	Asphalt	Enclosed		Sits back on opposite side of RR tracks; previous survey had this site and 1359 mixed up	3g	3	17
1806	1710200001	2	Garage	Front Gabled	N / A		Fair	Good		Vertical Wood	Tin (Flat)				3g	1	17
1806	1710200001	3	Shed	Front Gabled	N / A		Poor	Good		Beveled Clapboard	Tin (Flat)				3g	2	17
1806	1710200001	4	Chicken Coop	Slant-roofed	N / A		Falling down	Good		Beveled Clapboard	Wood Shingles			Also includes a small slant-roofed shed	3g	4	17
1223	1710200004	1	House	Upright and Wing	N / A	1860-1890	Good	Good		Clapboard	Asphalt			This is one of the few dual uprights (connected by the side wing) in the county; note 2-over-2 windows in both uprights;	3j	31	17
1223	1710200004	2	Barn	Metal Pole Barn	N / A		Poor	Poor		Tin (Flat)	Tin (Flat)			This is the old barn with a new top	3j	30	17
1223	1710200004	3	Garage	Side Gabled	N / A		Good	Good		Vinyl Siding	Asphalt			2-car	3j	26	17
1223	1710200004	4	Shed	Side Gabled	N / A		Poor	Poor		Asbestos	Tin (Corrugated)			Machine shed	3j	29	17
1223	1710200004	5	Shed	Slant-roofed	N / A		Poor	Poor		Tin (Flat)	Tin (Flat)			Livestock shed on back of machine shed	3j	28	17
1223	1710200004	6	Chicken Coop	Slant-roofed	N / A		Good	Good		Beveled Clapboard	Asphalt				3j	20	17
1223	1710200004	7	Outhouse	Slant-roofed	N / A		Good	Good		Beveled Clapboard	Asphalt			Common form of outhouse down in Coral Township	3j	21	17
1223	1710200004	8	Outhouse		N / A									Second view to show interior layout; note that this form of outhouse is a "one-holer" on an angle from the far corner	3j	23	17
1223	1710200004	9	Pumphouse	Side Gabled	N / A		Good	Good		Asbestos	Tin (Corrugated)				3j	27	17
1223	1710200004	10	Hog House	Front Gabled	N / A		Poor	Good		Cement Block	Tin (Corrugated)				3j	24	17
1223	1710200004	11	Shed	Quonset	N / A		Poor	Good		Beveled Clapboard	Tin (Corrugated)				3j	25	17
1223	1710200004	12	Grain Bin	Round	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Older style with ribs on sides rather than using corrugated tin as with newer bins	3j	22	17
1225	1710300001	1	House	Upright and Wing	N / A		Fair	Fair		Aluminum Siding	Asphalt	Enclosed	Siding, chimney, windows, porch: all changed	Note 6-light frieze window	3j	15	17
1225	1710300001	2	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3j	14	17
1222	1710300002	1	House	Upright and Wing	N / A		Good	Fair		Clapboard	Asphalt	Open	This house has undergone several transitions as detailed below the least of which are the new windows	This house started out as an I-house (note central section, then the front wing was added (but long ago). The next transition is the huge rear addition which is even taller than the central section. Lastly an enclosed back porch was added.	3k	7	17
1222	1710300002	2	Barn	Three-bay Threshing	N / A	1860-1880	Good	Good	Field Stone	Vertical Wood	Asphalt		Large upper cross-section may have been added when back sections put on	This also includes a large Dairy Gambrel barn that was added onto the back of the older barn	3k	5	17
1222	1710300002	3	Milkhouse	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Includes also a side gabled shed behind milkhouse, a metal pole barn and a concrete staved silo with a metal dome roof	3k	4	17
1222	1710300002	4	Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Asphalt			2-Bay with only one slatted, the other for shelled corn, oats or other grain, also include a slant-roofed livestock shed	3k	6	17
1222	1710300002	5	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3k	3	17
1222	1710300002	6	Pumphouse	Front Gabled	N / A		Good	Good		Clapboard	Asphalt				3k	2	17
1220	1710400004	1	House	Cottage	N / A		Good	Good		Vinyl Siding	Asphalt			1 and 1/2 storey square house with four dormers and both an open porch and an enclosed porch; rental house for landscape business	3k	11	17
1220	1710400004	2	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3k	12	17
1221	1710400006	1	House	Upright and Wing	N / A	1860-1890	Good	Good		Aluminum Siding	Asphalt	Enclosed	New windows, siding, etc.	Note that both the upright portion and the side wing portion are the same height	3k	10	17
1221	1710400006	2	Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Tin (Flat)			Both bays are slatted	3k	8	17

1221	1710400006	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Old barn has been replaced with this	3k	9	17
1210	1711200008	1	House	Side Gabled	N / A	1860-1890	Fair	Poor		Vinyl Siding	Asphalt	Redone	Totally redone; very modernized	Map point was wrong; it is on the other side of site 1212 across from former school	3g	9	17
1212	1711200009	1	House	Upright and Wing	N / A	1860-1890	Good	Good	Field Stone	Clapboard	Wood Shingles	Enclosed	Windows have been changed and the inset porch enclosed	Some alterations, but this house still has good historic integrity	3g	7	17
1212	1711200009	2	Barn	Transverse Frame	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			Also includes a poured concrete silo with no roof and an attached front gabled milkhouse with asbestos siding and a tin roof	3g	5	17
1212	1711200009	3	Barn	Gothic Arched	N / A		Good	Good		Vertical Wood	Asphalt			Also includes large cement block, tin roofed shed	3g	8	17
1212	1711200009	4	Shed	Front Gabled	N / A		Good	Good		Vertical Wood	Wood Shingles			2 Sheds: one front gabled and taller, the other side gabled and used as a livestock shed	3g	6	17
1219	1711300003	1	House	Cottage	Cape Cod		Fair	Good		Aluminum Siding	Asphalt			Includes attached 2-car side gabled garage	3i	1	17
1219	1711300003	2	Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Tin (Flat)			Large corn crib that was doubled in size	3h	36	17
1219	1711300003	3	Chicken Coop	Side Gabled	N / A		Good	Good		Vertical Wood	Tin (Flat)			Also include 2 other large livestock sheds	3h	37	17
1214	1711400001	1	House	Four-over-four	Foursquare	1910-1940	Good	Good	Molded Block	Clapboard	Asphalt	Open		Note that big, old barn picture in previous survey is gone	3g	16	17
1214	1711400001	2	Chicken Coop	Slant-roofed	N / A		Very Poor	Good		Vertical Wood	Asphalt			Includes another shed	3g	17	17
1214	1711400001	3	Corn Crib	Transverse Aisle	N / A		Poor	Good		Horizontal Slats	Asphalt				3g	18	17
1213	1712100001	1	House	Upright and Wing	N / A	1908	Good	Fair		Aluminum Siding	Asphalt	Removed	Many modernizations through the years including but not limited to windows, siding	This is a farmstead that has evolved into an antique store	3g	14	17
1213	1712100001	2	Barn	Dairy Gambrel	N / A	1909	Good	Good		Vertical Wood	Asphalt			Includes concrete staved silo	3g	15	17
1213	1712100001	3	Garage	Side Gabled	N / A		Good	Good		Aluminum Siding	Asphalt			Store	3g	12	17
1213	1712100001	4	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3g	13	17
1206	1712100008	1	House	Upright and Wing	N / A	1890-1910	Good	Poor		Vinyl Siding	Asphalt		Totally changed!	Main upright is barely recognizable and everything else is all new	3f	4	17
1206	1712100008	2	Barn	Front Gabled	N / A		Good	Poor		Vinyl Siding	Asphalt		Shed addition, dormer added		3f	5	17
1206	1712100008	3	Milkhouse	Front Gabled	N / A		Good	Fair		Vinyl Siding	Asphalt			Includes chicken coop, also totally redone	3f	3	17
1206	1712100008	4	Shed	Front Gabled	N / A		Good	Good		Vinyl Siding	Tin (Flat)			2 sheds with rounded arched roofs	3f	2	17
1206	1712100008	5	Shed	Uneven Gable	N / A		Good	Good		Vinyl Siding	Asphalt			Livestock shelter; open on one side	3f	6	17
1206	1712100008	6	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3f	1	17
1356	1712200002	1	House	Upright and Wing	N / A	1860-1890	Good	Fair		Aluminum Siding	Asphalt	Enclosed	Inset porch was enclosed; siding added	This was not where the previous survey map point was. Instead it was way back off the road down a farm lane. It looked abandoned.	3h	11	17
1356	1712200002	2	Barn	Transverse Frame	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			Includes concrete staved silo with tin gambrel roof	3h	5	17
1356	1712200002	3	Milkhouse	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Includes slant-roofed addition or connected shed	3h	6	17
1356	1712200002	4	Barn	Metal Pole Barn	N / A		Fair	Good		Tin (Flat)	Tin (Flat)				3h	10	17
1356	1712200002	5	Chicken Coop	Gambrel	N / A		Good	Good		Vertical Wood	Asphalt				3h	9	17
1356	1712200002	6	Outhouse	Slant-roofed	N / A		Good	Good		Beveled Clapboard	Asphalt				3h	8	17
1356	1712200002	7	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3h	7	17
1357	1712200004	1	House	Bungalow	N / A		Good	Good		Aluminum Siding	Asphalt			Front dormer	3h	4	17
1357	1712200004	2	Garage	Pyramidal	N / A		Good	Good		Vinyl Siding	Asphalt			2-Story, rectangular garage	3h	3	17
1357	1712200004	3	Shed	Side Gabled	N / A		Good	Good		Beveled Clapboard	Tin (Flat)			Open on one side	3h	2	17
1360	1712300003	1	House	Ranch	N / A	1950-present	Good	Good		Brick	Asphalt			Replacement house; this is still an active dairy	3g	24	17
1360	1712300003	2	Barn	Gothic Arched	N / A		Good	Good		Vertical Wood	Asphalt				3g	21	17
1360	1712300003	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Includes 3 concrete staved silos with metal dome roofs, however 1 is much shorter	3g	20	17
1360	1712300003	4	Milkhouse	Side Gabled	N / A		Good	Good		Clapboard	Asphalt			Includes a small slant-roofed corn crib, a chicken coop, a grain bin and another metal pole barn	3g	22	17
1360	1712300003	5	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			2 Barns/sheds	3g	23	17
1215	1712300004	1	vacant		N / A									All Gone!	3g	19	17
1361	1712400001	1	House	Upright and Wing	N / A		Good	Fair		Aluminum Siding	Asphalt	Removed	Many including windows, siding, etc.		3g	27	17
1361	1712400001	2	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			Includes 2 concrete staved silos with metal dome roofs	3g	31	17
1361	1712400001	3	Corn Crib	Transverse Aisle	N / A		Good	Good		Diagonal Slats	Asphalt			Also include side gabled milkhouse and metal grain bin	3g	30	17
1361	1712400001	4	Shed	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Livestock shed	3g	32	17
1361	1712400001	5	Corn Crib	Transverse Aisle	N / A		Fair	Good		Horizontal Slats	Asphalt		Doubled in length	Extra long and only one bay is slatted, the other is storage/small grains	3g	26	17
1361	1712400001	6	Shed	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Livestock shelter	3g	29	17
1361	1712400001	7	Hog House	Front Gabled	N / A		Fair	Good		Vertical Wood	Asphalt			Now being used for calves and heifers	3g	28	17
1361	1712400001	8	Garage	Side Gabled	N / A		Good	Good		Vinyl Siding	Asphalt			2-car	3g	25	17
1362	1713200003	1	House	l-house	N / A	1880-1900	Good	Fair		Vinyl Siding	Asphalt		New windows; porch added onto; Huge addition put on	Notice original l-house form in the middle	3g	33	17
1362	1713200003	2	Barn	Transverse Frame	N / A	1900-1930	Good	Good		Tin (Flat)	Asphalt			Includes an attached milkhouse and a concrete staved silo	3g	35	17
1362	1713200003	3	Outhouse	Slant-roofed	N / A		Good	Good		Tin (Flat)	Asphalt				3g	36	17
1362	1713200003	4	Chicken Coop	Octagonal	N / A		Good	Good		Vertical Wood	Asphalt			This is one of the pre-fab elongated octagonal chicken coops that during the 1940's housing crunch were quite often turned into little houses.	3g	37	17
1362	1713200003	5	Shed	Front Gabled	N / A		Good	Good		Tin (Flat)	Asphalt				3h	1	17
1362	1713200003	6	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3g	34	17
1744.5	1713300001	1	House	Upright and Wing	N / A		Fair	Fair		Aluminum Siding	Asphalt		Most windows changed and 2 shed additions		3l	26	17
1744.5	1713300001	2	Barn	Dairy Gambrel	N / A	1880-1920	Poor	Good		Asbestos	Wood Shingles				3l	23	17
1744.5	1713300001	2	Barn	Dairy Gambrel	N / A	1880-1920	Fair	Good		Asbestos	Wood Shingles				3l	23	17
1744.5	1713300001	3	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome			Also includes 1 Quonset shed	3l	24	17
1744.5	1713300001	4	Garage	Side Gabled	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3l	25	17
1216	1714200002	1	House	Upright and Wing	N / A		Good	Good		Aluminum Siding	Asphalt	Open	New siding and most of the windows were replaced, plus a front chimney was added	Full size side wing of same height as upright	3h	26	17
1216	1714200002	2	Summer Kitchen	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt		Door was updated	Original detached summer kitchen! Note chimney and 6-light windows	3h	25	17
1216	1714200002	3	Barn	Transverse Frame	N / A		Good	Good		Vertical Wood	Asphalt			Has shed addition to side	3h	21	17
1216	1714200002	4	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	none			Flat staves instead of ribbed staves	3h	22	17
1216	1714200002	5	Milkhouse	Uneven Gable	N / A		Fair	Good		Beveled Clapboard	Asphalt			Unusual rectangular footprint; possibly part is an addition	3h	19	17
1216	1714200002	6	Pumphouse	Side Gabled	N / A		Good	Good		Tin (Flat)	Asphalt		Has a lean-to shed addition	Larger than normal	3h	20	17
1216	1714200002	7	Hog House	Front Gabled	N / A		Poor	Fair		Vertical Wood	Wood Shingles			Being used as livestock shelter	3h	17	17
1216	1714200002	8	Shed	Slant-roofed	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Horse shelter	3h	18	17
1216	1714200002	9	Garage	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt			2-car	3h	24	17
1216	1714200002	10	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3h	23	17
1217	1714200007	1	House	Four-over-four	Foursquare	1900-1930	Good	Good		Aluminum Siding	Asphalt		Porch changed and side addition put on		3h	27	17

1217	1714200007	2	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)					3h	28	17
1217	1714200007	3	Grain Bin	Round	N / A		Good	Good		Tin (Corrugated)	Tin (Flat)					3h	29	17
1217	1714200007	4	Grain Bin	Round	N / A		Good	Good		Tin (Corrugated)	Tin (Flat)				A series of 3 grain bins, a hopper and a dryer	3h	30	17
1217	1714200007	5	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)					3h	31	17
1218	1714400001	1	House	Four-over-four	Foursquare	1900-1930	Fair	Fair		Aluminum Siding	Asphalt	Open			Notice fancy front window. This would be from turn-of-the-century or just after era. Porch posts could be older, so more investigation is necessary if age determination needs to be made.	3h	35	17
1218	1714400001	2	Barn	Three-bay Threshing	N / A		Good	Good		Vertical Wood	Asphalt				Notice that the front barn is the Three-bay Threshing barn and that besides having a large shed to the rear and then the Dairy Gambrel barn to the side	3h	2	17
1218	1714400001	3	Smokehouse	Front Gabled	N / A		Good	Good		Tin (Flat)	Asphalt					3h	34	17
1218	1714400001	4	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)					3h	33	17
1328	1715100011	1	House	Ranch	Ranch	1950-present	Good	Good		Aluminum Siding	Asphalt				Replacement house	3k	17	17
1328	1715100011	2	Barn	Dairy Gambrel	N / A		Good	Poor		Vertical Wood	Tin (Flat)		Has huge shed addition on one end		Includes concrete staved silo with metal dome roof	3k	13	17
1328	1715100011	3	Shed	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt					3k	15	17
1328	1715100011	4	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)					3k	18	17
1328	1715100011	5	Shed	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Asphalt				Used as large garage	3k	16	17
1328	1715100011	6	Shed	Quonset	N / A		Good	Good		Tin (Corrugated)	Tin (Corrugated)					3k	14	17
1328.5	1715200001	1	House	Raised Ranch	N / A	1930-1950	Good	Good	Cement Block	Aluminum Siding	Asphalt				Replacement house; attached garage; site is also an airport	3k	22	17
1328.5	1715200001	2	Barn	Dairy Gambrel	N / A	1880-1920	Good	Fair		Tin (Flat)	Asphalt		Converted into garage		Conversion included a large door on the end	3k	21	17
1328.5	1715200001	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				Includes small attached structure the size of a milkhouse	3k	19	17
1328.5	1715200001	4	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)					3k	20	17
1751.5	1715300006	1	Barn	Transverse Frame	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt				Includes a concrete staved silo with a metal dome roof; part of the "Shireland complex"	3o	4	17
1751.5	1715300006	2	Shed	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt				Also includes 2 concrete staved silos; note on this site there are a total of 3 staved silos with all three types of staves: ribbed, corrugated, and flat	3o	5	17
1751.5	1715300006	3	Corn Crib	Transverse Aisle	N / A		Fair	Good		Horizontal Slats	Asphalt				Only the far bay (south side) is slatted; also includes metal grain bin	3o	6	17
1751	1715300008	1	School	Front Gabled	N / A	1880-1920	Fair	Good		Clapboard	Asphalt				An original one-room schoolhouse that was never converted into a house	3o	1	17
1751	1715300008	2	Garage	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				Has sway in roof	3o	2	17
1753.5	1715300013	1	House	Front Gabled	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt	Open	New windows, siding		Decorative Diamond detracts from the look	3k	26	17
1753.5	1715300013	2	Shed	I-house	N / A		Good	Good		Tin (Flat)	Asphalt					3k	24	17
1753.5	1715300013	3	Barn	Gothic Arched	N / A		Good	Good		Tin (Flat)	Tin (Flat)					3k	25	17
1753.5	1715300013	4	Shed	Slant-roofed	N / A		Poor	Good	Cement Block	Tin (Flat)	Asphalt					3k	23	17
1328.7	1715400001	1	House	Upright and Wing	N / A	1860-1880	Good	Good	Granite	Asbestos	Asphalt	Enclosed	Siding and porch enclosure		Set way back off the road; still has its original 2-over-2 windows	3p	28	17
1328.7	1715400001	2	Barn	Transverse Frame	N / A		Very Poor	Good		Vertical Wood	Wood Shingles				Roof caving in; includes concrete staved silo and cement block milkhouse	3p	32	17
1328.7	1715400001	3	Garage	Pyramidal	N / A		Poor	Good		Asphalt	Asphalt				2-Car	3p	31	17
1328.7	1715400001	4	Pumphouse	Front Gabled	N / A		Poor	Good		Asphalt	Asphalt				Notice old door	3p	29	17
1328.7	1715400001	5	Shed	Quonset	N / A		Poor	Good		Vertical Wood	Tin (Flat)				Also includes small pyramidal shed/garage	3p	33	17
1328.7	1715400001	6	Corn Crib	Transverse Aisle	N / A		Very Poor	Good		Horizontal Slats	Wood Shingles		Has shed attachment		Overgrown	3p	30	17
1229	1716100012	1	House	Upright and Wing	N / A	1860-1890	Good	Good		Aluminum Siding	Asphalt	Open	New windows, siding and porch		Note old central chimney in back wing; this was an attached summer kitchen, not a later add-on. This site is part of the Donley's Wild West Town museum and amusement park	3l	18	17
1229	1716100012	2	Garage	Front Gabled	N / A		Good	Good		Aluminum Siding	Asphalt				Attached with breezeway; double door	3l	19	17
1228	1716100014	1	House	Upright and Wing	N / A	1880-1920	Good	Fair		Vinyl Siding	Asphalt	Open	Many, see below		Notice the different roof pitch from the upright to the wing; the wing is actually older with the upright either being rebuilt or added on; also, dormer was added and large shed rear addition	3l	20	17
1228	1716100014	2	Barn	Three-bay Threshing	N / A	1860-1880	Good	Poor		Tin (Flat)	Tin (Flat)				Includes poured concrete silo with conical roof	3l	21	17
1228	1716100014	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				Includes windmill	3l	22	17
1230	1716300011	1	House	I-house	N / A	1860-1880	Fair	Poor	Field Stone	Aluminum Siding	Asphalt	Removed	Changed windows, added chimney, dormers may have been added and shed addition to the rear		This site is being farmed by the modern house next door; house is overgrown and internally piled (appears that an elderly person is now out of here, but house not cleaned-out)	3o	12	17
1230	1716300011	2	Hog House	Gambrel	N / A		Poor	Good		Cement Block	Asphalt				Very neglected; now used for steers	3o	8	17
1230	1716300011	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)					3o	14	17
1230	1716300011	4	Shed	Metal Pole Barn	N / A		Poor	Good		Tin (Flat)	Tin (Flat)					3o	10	17
1230	1716300011	5	Shed	Metal Pole Barn	N / A		Poor	Good		Tin (Flat)	Tin (Flat)				Cattle shed	3o	9	17
1231	1716300018	1	House	Upright and Wing	N / A	1860-1890	Fair	Fair	Field Stone	Vinyl Siding	Asphalt	Open	New windows, siding and porch foundation; plus added second floor entrance		Several old unchanged farm buildings, but most in poor shape; note stone smokehouse. Prior survey photo is of back of the house	3z	23	17
1231	1716300018	2	Barn	Three-bay Threshing	N / A	1860-1880	Fair	Good	Field Stone	Vertical Wood	Wood Shingles				Still has original windows above main door, but needs work	3o	21	17
1231	1716300018	3	Barn	Dairy Gambrel	N / A	1880-1920	Fair	Good	Field Stone	Vertical Wood	Wood Shingles				Roof caving in in places	3o	23	17
1231	1716300018	4	Silo	Poured Concrete	N / A		Good	Good		Poured Concrete	Metal Dome				2 Silos and 2 front-gabled sheds	3o	20	17
1231	1716300018	5	Shed	Front Gabled	N / A		Good	Good		Vertical Wood	Wood Shingles				Attached to others, back portion totally caved-in	3o	19	17
1231	1716300018	6	Shed	Side Gabled	N / A		Falling down	Poor		Beveled Clapboard	Wood Shingles					3o	22	17
1231	1716300018	7	Corn Crib	Transverse Aisle	N / A		Poor	Good		Horizontal Slats	Wood Shingles				Both bays slatted; needs work	3o	17	17
1231	1716300018	8	Chicken Coop	Side Gabled	N / A		Poor	Good		Vertical Wood	Wood Shingles				Combination chicken coop / machine shed	3o	16	17
1231	1716300018	9	Shed	Front Gabled	N / A		Good	Good		Vertical Wood	Wood Shingles				2 Sheds together; possible former grainery/hog house	3o	18	17
1231	1716300018	10	Smokehouse	Front Gabled	N / A		Good	Good		Field Stone	Asphalt				This is perhaps the most significant structure on the property. Notice the brick gable; roof has been replaced; now being used as dog house	3z	24	17
1753	1716400001	1	House	I-house	N / A	1850-1870	Good	Good	Field Stone	Aluminum Siding	Asphalt	Open	Siding, front porch expanded, chimney added		Notice detail in next view; this house had more ornamentation that was stripped off when modernized. This is one of the few working dairy farms, but is owned and operated by an elderly brother and sister so will not remain after they are done farming.	3l	8	17
1753	1716400001	2	House		N / A										Second view to show the detailing on the rear porch	3l	7	17
1753	1716400001	3	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Tin (Flat)				This is actually 2 gambrel barns built together; the larger being the older one. This farm won the PMA (Pure Milk Assoc.) 1942 award for "Neatest and cleanest farm in Chicagoland".	3l	5	17
1753	1716400001	4	Milkhouse	Front Gabled	N / A		Good	Good		Vertical Wood	Tin (Flat)				Attached	3l	2	17
1753	1716400001	5	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome				Flat staves	3l	3	17
1753	1716400001	6	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome				2 Silos: 1 with flat staves and 1 with corrugated staves	3l	6	17

1753	1716400001	7	Scale	Slant-roofed	N / A		Good	Good		Beveled Clapboard	Tin (Flat)			This is one of the most complete farms with even their own truck weight scale	3l	4	17
1753	1716400001	8	Chicken Coop	Octagonal	N / A		Good	Good		Vertical Wood	Wood Shingles			This was used to house prisoners working the Marengo potato farms.	3l	1	17
1753	1716400001	9	Chicken Coop	Octagonal	N / A		Good	Good						Second view to show windows; partially pre-fabbed - This is a well-known form in Kane County for chicken coops. Some of these were used as second homes on farms due to their availability after the war during the housing shortage.	3k	29	17
1753	1716400001	10	Shed	Side Gabled	N / A		Good	Good		Beveled Clapboard	Tin (Flat)			Machine shed; note matching detailing on handle area to other structures	3k	33	17
1753	1716400001	11	Hog House	Front Gabled	N / A		Good	Good		Beveled Clapboard	Tin (Flat)				3k	32	17
1753	1716400001	12	Garage	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			3-Car doors	3k	28	17
1753	1716400001	13	Pumphouse	Side Gabled	N / A		Good	Good		Asbestos	Asphalt				3k	34	17
1753	1716400001	14	Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Asphalt			Both bays slatted; note wide belt-line band and window askew	3k	30	17
1753	1716400001	15	Chicken Coop	Front Gabled	N / A		Good	Good		Beveled Clapboard	Tin (Flat)				3k	31	17
1753	1716400001	16	Shed	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Close to house, so could have been used for food processing as a detached summer kitchen	3k	27	17
1753	1716400001	17	Shed	Front Gabled	N / A		Good	Good	Poured Concrete	Beveled Clapboard	Asphalt			Livestock shed	3k	36	17
1753	1716400001	18	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Corrugated)	Tin (Flat)			Include also 2 grain bins, dryer and open sided shed	3k	37	17
1753	1716400001	19	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Pole barn plus 3 more grain bins	3k	35	17
1752	1716400015	1	House	Front Gabled	N / A	1930-1950	Good	Good		Vinyl Siding	Asphalt		Totally modernized	Has attached garage	3l	9	17
1752	1716400015	2	House	Trailer	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3l	10	17
1752	1716400015	3	Barn	Dairy Gambrel	N / A	1880-1920	Fair	Good		Vertical Wood	Tin (Flat)		In the process of having a tin roof added	Has attached front-gabled milkhouse	3l	14	17
1752	1716400015	4	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome				3l	13	17
1752	1716400015	5	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome			Includes silo room	3l	17	17
1752	1716400015	6	Shed	Gambrel	N / A		Good	Good		Vertical Wood	Tin (Flat)			Horse barn	3l	11	17
1752	1716400015	7	Chicken Coop	Slant-roofed	N / A		Fair	Good		Beveled Clapboard	Tin (Corrugated)			Also includes a front gabled shed	3l	12	17
1752	1716400015	8	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			This is the office for this operation; unclear as to what type, but have sensors and someone came up to me before I could even get out of my vehicle.	3l	15	17
1752	1716400015	9	Shed	Slant-roofed	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3l	16	17
1799	1717100010	1	House	Four-over-four	N / A	1860-1880	Good	Fair		Vinyl Siding	Asphalt	Altered	Now has deck/porch combination; very modernized		1v	12	17
1799	1717100010	2	Barn	Three-bay Threshing	N / A	1850-1870	Fair	Good		Vertical Wood	Asphalt			One end is collapsing	1v	5	17
1799	1717100010	3	Barn	Transverse Frame	N / A		Good	Good		Vertical Wood	Asphalt			Added onto the three-bay barn; also includes a flat staved silo with no roof	1v	8	17
1799	1717100010	4	Shed	Front Gabled	N / A		Fair	Good		Vertical Wood	Asphalt			Leaning	1v	6	17
1799	1717100010	5	Chicken Coop	Side Gabled	N / A		Poor	Good	Poured Concrete	Molded Block	Wood Shingles			The old windows probably came out of the house. Rolled asphalt roofing was used over the wood shingle, but now that has worn away and exposed open holes in roof. Windmill in background	1v	10	17
1799	1717100010	6	Garage	Front Gabled	N / A		Poor	Good		Cement Block	Asphalt			Sliding double door; open holes in roof	1v	11	17
1799	1717100010	7	Shed	Quonset	N / A		Poor	Good		Tin (Corrugated)	Tin (Corrugated)				1v	7	17
1799	1717100010	8	Milkhouse	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt			One of few farm buildings in good shape	1v	13	17
1755	1717200003	1	House	Upright and Wing	N / A	1900-1930	Good	Good		Vinyl Siding	Asphalt	Enclosed	Modernized	Upright portion is new since last survey; porch added earlier	3w	37	17
1755	1717200003	2	Garage	Pyramidal	N / A		Good	Good		Vinyl Siding	Asphalt			Rectangular plan with hipped roof	3w	36	17
1755	1717200003	3	Garage	Front Gabled	N / A		Poor	Good		Beveled Clapboard	Tin (Flat)				3w	35	17
1754	1717200005	1	House	Cottage	N / A		Good	Good	Molded Block	Clapboard	Asphalt	Entry			3x	5	17
1754	1717200005	2	Shed	Side Gabled	N / A		Good	Fair		Beveled Clapboard	Tin (Corrugated)			Notice angled door wood	3x	3	17
1754	1717200005	3	Chicken Coop	Pyramidal	N / A		Good	Good		Beveled Clapboard	Asphalt			Rectangular with hipped roof	3x	2	17
1754	1717200005	4	Shed	Front Gabled	N / A		Good	Good		Tin (Flat)	Asphalt			Sliding double door	3x	1	17
1796	1717200016	1	gone		N / A									"Roland Machinery" commercial business now			17
1800	1717300001	1	Barn	Three-bay Threshing	N / A		Fair	Good		Vertical Wood	Wood Shingles				1m	31	17
1800	1717300001	2	House	Upright and Wing	Greek Revival	1850-1870	Very Poor	Good		Asphalt	Wood Shingles			Abandoned; this is "Frank Beck's" farm that the road was named after	1v	4	17
1800	1717300001	3	House		N / A									Second view to show cornice return; very overgrown	1v	2	17
1800	1717300001	4	Shed	Front Gabled	N / A		Fair	Good		Vertical Wood	Asphalt		Shed additions to both sides	Notice old 2-over-2 vertical paneled door	1m	30	17
1800	1717300001	5	Chicken Coop	Uneven Gable	N / A		Poor	Poor		Asphalt	Asphalt		Shed addition to front		1v	1	17
1800	1717300001	6	Shed	Side Gabled	N / A		Fair	Fair		Beveled Clapboard	Asphalt			Also includes tin roofed front gable shed	1v	3	17
1800	1717300001	7	Shed	Metal Pole Barn	N / A		Good	Good		Tin (Corrugated)	Tin (Corrugated)			Older version	1m	32	17
1800	1717300001	8	Shed	Pyramidal	N / A		Fair	Good		Vertical Wood	Tin (Flat)				1m	33	17
1800	1717300001	9	Shed		N / A		Falling down	Poor		Plywood	Tin (Flat)				1m	34	17
1800	1717300001	10	Shed	Front Gabled	N / A		Very Poor	Poor		Beveled Clapboard	Tin (Flat)			Also includes short round concrete bin with a tin roof	1m	35	17
1794	1717300004	1	House	Cottage	N / A	1900-1930	Good	Good		Clapboard	Asphalt	Open		Notice tapered square columns on porch	1m	29	17
1794	1717300004	2	Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Asphalt			Combination crib with only one side slatted and the bay for storage/shelled corn/oats; includes small slant-sided livestock shelter	1m	26	17
1794	1717300004	3	Shed	Front Gabled	N / A		Poor	Fair		Rolled Asphalt	Tin (Flat)		Shed addition		1m	27	17
1794	1717300004	4	Chicken Coop	Slant-roofed	N / A		Poor	Good		Rolled Asphalt	Asphalt			Also includes a cement block pyramidal 2-car garage	1m	28	17
1798	1717300011	1	House	Cross Gabled	N / A	1880-1920	Good	Good		Aluminum Siding	Asphalt	Enclosed	Front porch expanded and rear addition	Very well maintained farm	1v	21	17
1798	1717300011	2	Barn	Dairy Gambrel	N / A		Good	Good		Vertical Wood	Asphalt				1v	19	17
1798	1717300011	3	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome			2 silos	1v	20	17
1798	1717300011	4	Milkhouse	Front Gabled	N / A		Good	Good		Cement Block	Asphalt			Attached	1v	17	17
1798	1717300011	5	Shed	Side Gabled	N / A		Good	Good		Cement Block	Asphalt			Machine shed	1v	18	17
1798	1717300011	6	Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Asphalt			Both bays slatted; also include small slant-roofed hog house	1v	15	17
1798	1717300011	7	Shed	Front Gabled	N / A		Good	Good		Tin (Flat)	Asphalt			Shed addition on rear of corn crib	1v	16	17
1798	1717300011	8	Garage	Side Gabled	N / A		Good	Good		Aluminum Siding	Asphalt			3-Car doors	1v	14	17

1798	1717300011	9	Outhouse	Slant-roofed	N / A		Good	Good		Beveled Clapboard	Asphalt					1v	22	17
1797	1717400005	1	Outhouse	Side Gabled	N / A		Good	Good		Clapboard	Asphalt			Just a pumphouse and an outhouse left and a junky house trailer on spot where house and barn used to be		3z	22	17
1797	1717400005	2	Pumphouse	Side Gabled	N / A		Fair	Good		Clapboard	Rolled Asphalt					3z	21	17
1797.5	1717400011	1	House	Side Gabled	N / A	1880-1920	Good	Good		Asbestos	Asphalt			Former school; side wing added later; also includes 2-car detached garage		3z	37	17
1777	1718300004	1	House	Upright and Wing	N / A	1860-1890	Good	Poor	Field Stone	Aluminum Siding	Asphalt	Enclosed	Totally modernized	Additions galore; in good shape, but very changed; includes attached garage		c1	14	17
1777	1718300004	2	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt		Has shed addition to side	Includes livestock shelter (front-gabled shed in foreground)		c1	12	17
1777	1718300004	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)					c1	13	17
1777	1718300004	4	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Conical			Top like a wire mesh corn crib		c1	15	17
1777	1718300004	5	Shed	Front Gabled	N / A		Good	Good		Field Stone	Wood Shingles			Very old stone-walled structure; further investigation would need to be made to determine the original function; also includes wire mesh corn crib		c1	16	17
1778	1718300008	1	House	Cottage	Cape Cod	1950-present	Good	Good	Poured Concrete	Vinyl Siding	Asphalt	Open		Totally new replacement house with attached front-gabled 2-car garage; old house was a Greek Revival house		c1	18	17
1778	1718300008	2	Barn	Transverse Frame	N / A	1880-1920	Fair	Good		Vertical Wood	Wood Shingles			Includes concrete staved silo with no roof		c1	17	17
1778	1718300008	3	Outhouse	Side Gabled	N / A		Excellent (R)	Excellent		Clapboard	Asphalt					c1	19	17
1778	1718300008	4	Shed	Front Gabled	N / A		Fair	Good		Vertical Wood	Asphalt			Possibly former hog house		c1	20	17
1778	1718300008	5	Garage	Front Gabled	N / A		Poor	Good		Vertical Wood	Asphalt			Double sliding doors		c1	21	17
1776	1718400002	1	House	Upright and Wing	N / A	1880-1920	Good	Good	Field Stone	Clapboard	Asphalt	Open		Wing as tall as upright; note turn-of-the-century details of paired windows and round columns		c1	28	17
1776	1718400002	2	Barn	Dairy Gambrel	N / A		Good	Good		Vertical Wood	Asphalt			This is actually a composite barn made up of 2 Dairy Gambrel barns; also included in this photo is a front-gabled shed in foreground and a terra cotta tile silo with a wood shingled gambrel roof		c1	27	17
1776	1718400002	3	Shed	Pyramidal	N / A		Fair	Good		Beveled Clapboard	Asphalt			Rectangular hipped roof form		c1	22	17
1776	1718400002	4	Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Asphalt			Also includes another front gabled shed		c1	26	17
1776	1718400002	5	Shed	Front Gabled	N / A		Good	Good		Stucco	Asphalt			Vented for cooling		c1	24	17
1776	1718400002	6	Outhouse	Front Gabled	N / A		Good	Good		Clapboard	Asphalt			Steeper pitch than normal		c1	25	17
1782	1718400004	1	House	Four-over-four	N / A	1860-1930	Good	Good		Clapboard	Asphalt			Rectangular form; it is unclear whether this is an older house that was remodeled with some prairie style influences or a 1920's-1930's style house		c1	9	17
1782	1718400004	2	Shed	Side Gabled	N / A		Good	Good		Beveled Clapboard	Tin (Flat)			Machine shed		c1	10	17
1782	1718400004	3	Garage	Pyramidal	N / A		Fair	Good		Beveled Clapboard	Asphalt					c1	11	17
1784	1719200005	1	House	Upright and Wing	N / A	1860-1880	Good	Good	Field Stone	Clapboard	Asphalt	Open	Large side wing added; new windows; porch redone	This house had asbestos siding on it during the last survey. The asbestos has been removed to expose the original clapboard, but the original 2-over-2 windows have now been replaced with all new windows.		c1	5	17
1784	1719200005	2	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Includes also front gabled garage and slant-roofed shed				17
1783	1719200028	1	House	Upright and Wing	N / A	1880-1920	Good	Poor		Aluminum Siding	Asphalt	Enclosed	Very changed	Porch used to have a balcony railing for the upper story door access		c1	7	17
1783	1719200028	2	Barn	Transverse Frame	N / A		Fair	Good		Tin (Flat)	Tin (Flat)		Added onto			c1	6	17
1783	1719200028	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Also includes side gabled shed that could have been a detached summer kitchen (note chimney) and a broken eave hog house and an uneven gabled chicken coop		c1	8	17
1786	1719400004	1	House	Cross Gabled	Queen Anne	1880-1920	Good	Good	Field Stone	Aluminum Siding	Asphalt	Open and original	Rear addition	More details were stripped off when this house was resided		c1	35	17
1786	1719400004	2	Barn	Dairy Gambrel	N / A		Good	Good		Vertical Wood	Asphalt			Wider than normal; also includes front gabled shed to the side		c1	34	17
1786	1719400004	3	Barn	Dairy Gambrel	N / A		Good	Fair		Vertical Wood	Asphalt		Converted into a garage with upper living area	Even wider than the other barn with a shortened profile; also includes small side gabled shed		c1	36	17
1786	1719400004	4	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Also includes 2 wire mesh corn cribs		c1	33	17
1785	1719400009	1	House	Front Gabled	Greek Revival	1850-1870	Good	Good	Field Stone	Vinyl Siding	Asphalt	Open	New windows and siding	Cornice return remain		c1	31	17
1793	1720127010	1	House	T-plan	Queen Anne	1880-1920	Good	Good	Field Stone	Vinyl Siding	Asphalt	Open	New siding; some details lost when resided	Although it has been modernized, its integrity is still mainly intact; note bay window, pediment window hood caps; steep roof pitch and matching gable window		3z	29	17
1793	1720127010	2	Barn	Dairy Gambrel	N / A		Good	Fair		Tin (Flat)	Asphalt			Has been sided		3z	26	17
1793	1720127010	3	Milkhouse	Front Gabled	N / A		Good	Excellent		Field Stone	Asphalt			Wonderful stone milkhouse still in good shape without any major cracks; detached; second milkhouse period to the gambrel barn which is also the second barn		3z	25	17
1793	1720127010	4	Milkhouse	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			This was the original milkhouse that went with the original barn		3z	27	17
1793	1720127010	5	Barn		N / A		Good	Poor		Field Stone	Tin (Flat)			This is the original barn, but the top was taken off and a new tin top put on so now it looks more like a pole barn; also includes small metal pole barn to rear of the property		1m	25	17
1792	1720200002	1	House	Upright and Wing	N / A	1880-1920	Good	Fair		Aluminum Siding	Asphalt	Enclosed	Windows changed; stone facing added to lower story; major addition to side	The original look of this house has been greatly altered		1m	22	17
1792	1720200002	2	Barn	Gothic Arched	N / A		Good	Fair		Aluminum Siding	Asphalt		Added windows and changed entry	This barn was converted to business usage		1m	20	17
1792	1720200002	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)					1m	21	17
1790	1720300003	1	House	Four-over-four	Second Empire	1850-1870	Good	Good	Field Stone	Brick	Asphalt	Removed	Roof altered	This is a massive grand home that used to have a full façade front porch. The roof was also changed, but in a historically sensitive manner. Note the arched tops on the windows and that this house is a full 3-story house.		1y	13	17
1790	1720300003	2	Barn	Three-bay Threshing	N / A	1850-1870	Good	Good	Field Stone	Vertical Wood	Asphalt		New wood boards were mounted on top of the original boards	This barn has been well-care for without modernizing it; this also include a terra cotta tile silo with a gambrel asphalt roof		1y	12	17
1790	1720300003	3	Barn	Transverse Frame	N / A		Good	Good		Tin (Flat)	Asphalt			All of these structures are to the southwest of the house and main barn. Includes a large livestock barn, a milkhouse, a corn crib, a concrete staved silo, a machine shed and a hog house		1y	10	17
1791	1720400007	1	House	Upright and Wing	N / A	1860-1890	Good	Fair	Field Stone	Vinyl Siding	Asphalt	Now a deck	Side wing was made into a 2-story section; porch was removed and made into a deck	Modernized		3z	30	17
1791	1720400007	2	Garage	Pyramidal	N / A		Good	Good		Vinyl Siding	Asphalt					3z	31	17
1233	1721100004	1	House	Upright and Wing	N / A	1880-1900	Fair	Fair	Field Stone	Asbestos	Asphalt	Enclosed	Details removed	Could still be restored		3o	34	17
1233	1721100004	2	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good	Field Stone	Vertical Wood	Asphalt			Unusually flat gambrel that at first glance looks like a gabled roof; includes concrete staved silo with a metal dome roof		3o	33	17

1233	1721100004	3	Barn	Metal Pole Barn	N / A		Poor	Good		Tin (Flat)	Tin (Flat)					3o	32	17
1232	1721100015	1	House	Bungalow	N / A	1910-1940	Good	Good		Aluminum Siding	Asphalt	Enclosed		Note clipped gables including the dormer and original 3-over-1 windows		3o	31	17
1232	1721100015	2	Barn	Dairy Gambrel	N / A	1900-1930	Good	Good		Vertical Wood	Asphalt			Banked haymow entrance; includes concrete staved silo		3o	26	17
1232	1721100015	3	Chicken Coop	Uneven Gable	N / A		Good	Good		Beveled Clapboard	Asphalt			Some windows altered		3o	25	17
1232	1721100015	4	Pumphouse	Front Gabled	N / A		Good	Good		Wood Shingles	Asphalt					3o	30	17
1232	1721100015	5	Shed	Front Gabled	N / A		Good	Good		Tin (Flat)	Asphalt			Sliding door		3o	28	17
1232	1721100015	6	Shed	Front Gabled	N / A		Good	Good		Tin (Flat)	Asphalt			Garage door on 2 sides		3o	27	17
1232	1721100015	7	Shed	Side Gabled	N / A		Fair	Good		Tin (Flat)	Tin (Corrugated)			Machine shed		3o	29	17
1234	1721200007	1	House	Upright and Wing	Greek Revival	1850-1870	Good	Good	Field Stone	Aluminum Siding	Asphalt	Open	Upright portion is newer than the side wing	Side wing is the original house built circa 1860 with cornice returns and 2-over-2 windows; Upright is newer in the 1880-1900 time frame		3p	2	17
1234	1721200007	2	Pumphouse	Side Gabled	N / A		Good	Good		Clapboard	Asphalt			Newer wide clapboard not original		3p	1	17
1234	1721200007	3	Chicken Coop	Slant-roofed	N / A		Very Poor	Fair		Beveled Clapboard	Asphalt			Leaning and askew to foundation		3o	35	17
1234	1721200007	4	Garage	Pyramidal	N / A		Poor	Good		Beveled Clapboard	Asphalt					3o	37	17
1234	1721200007	5	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)					3o	36	17
1235	1721400002	1	House	I-house	N / A	1860-1880	Good	Good		Aluminum Siding	Asphalt	Open	Large chimney added on north side; base of porch redone; new windows and siding	Yet another farm in the Shireland complex		3p	3	17
1235	1721400002	2	Silo	Brick	N / A		Excellent (R)	Excellent	Poured Concrete	Brick	Asphalt			This brick silo was converted to a lookout tower. Finally a brick silo that is being maintained. This photo also includes a Three-bay threshing barn with a Dairy gambrel barn added onto the back of it		3p	4	17
1235	1721400002	3	Chicken Coop	Slant-roofed	N / A		Good	Good		Beveled Clapboard	Asphalt			Also includes a front gabled shed		3p	5	17
1235	1721400002	4	Shed	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt					3p	6	17
1236	1721400004	1	House	Upright and Wing	Greek Revival	1860-1880	Good	Good	Field Stone	Aluminum Siding	Asphalt	Removed	Side wing was expanded	Part of the "Shireland" complex; this site is used for all of the maintenance functions		3p	14	17
1236	1721400004	2	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good	Field Stone	Vertical Wood	Asphalt			Includes a concrete staved silo with a metal dome roof		3p	9	17
1236	1721400004	3	Milkhouse	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Also includes a side-gabled pumphouse		3p	13	17
1236	1721400004	4	Garage	Pyramidal	N / A		Good	Good		Terra Cotta Tile	Asphalt			Converted into office area		3p	11	17
1236	1721400004	5	Shed	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Machine shed		3p	8	17
1236	1721400004	6	Corn Crib	Transverse Aisle	N / A		Good	Fair		Plywood	Asphalt			Converted into a storage garage		3p	12	17
1236	1721400004	7	Shed	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Possible former detached summer kitchen		3p	10	17
1236	1721400004	8	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)					3p	7	17
1236	1721400004	9	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Separate driveway, but adjoining the other buildings		3p	22	17
1749	1722200004	1	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good	Field Stone	Vertical Wood	Asphalt			This barn goes with the farmstead across the road on site 1750		3n	36	17
1750	1722200005	1	House	Upright and Wing	N / A	1860-1890	Good	Poor		Aluminum Siding	Asphalt	Open	Windows, siding, most everything	This was an I-house that a large upright section was added to; again this site including the large barn across the street is part of the "Shireland" complex; gated so photos had to be from the road		3n	32	17
1750	1722200005	2	House	Ranch	N / A	1950-present	Good	Good		Aluminum Siding	Asphalt			"Hired hand's" house; secondary house on site		3n	31	17
1750	1722200005	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)					3n	33	17
1750	1722200005	4	Shed	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Machine shed		3n	34	17
1750	1722200005	5	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Enormous!		3n	30	17
1750	1722200005	6	Barn	Transverse Frame	N / A		Good	Good		Vertical Wood	Asphalt			Horse barn		3n	35	17
1750	1722200005	7	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Includes 2 very large grain bins and a concrete staved silo with a metal dome roof		3n	37	17
1747.5	1722200006	1	House	Upright and Wing	N / A	1880-1920	Good	Poor		Aluminum Siding	Asphalt			This is another rental unit in the "Shireland" complex; resident was skeptical of what "Shireland" would say about any photos so I had to take from a distance		3p	36	17
1747.5	1722200006	2	Pumphouse	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Includes: pumphouse, pyramidal garage, Three-bay threshing barn, side gabled machine shed and milkhouse		3p	34	17
1747.5	1722200006	3	Chicken Coop	Slant-roofed	N / A		Fair	Good		Beveled Clapboard	Tin (Flat)					3p	35	17
1747.5	1722200006	4	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			This is a large silver pole barn in background behind house (not another view of house)		3p	37	17
1748	1723101004	1	House	Upright and Wing	N / A	1880-1920	Good	Fair		Vinyl Siding	Asphalt	Open	Large chimney added	Enclosed rear porch		3n	29	17
1748	1723101004	2	Shed	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt					3n	27	17
1748	1723101004	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)					3n	28	17
1747	1723151003	1	House	Dual Uprights	N / A	1870-1890	Good	Good	Field Stone	Vinyl Siding	Asphalt	Open	New windows; resided except in gables	This is an unusual form where 2 large upright section are connected by a side wing in between; note that both uprights have the same gable ornamentation (corbels and patterned shingles) and that the first floor bay also has the same corbels		3n	24	17
1747	1723151003	2	Barn	Three-bay Threshing	N / A	1860-1880	Excellent (R)	Excellent	Field Stone	Vertical Wood	Asphalt			Note the impressive cupola; even with the metal addition to the front of this barn, it is still a significant structure		3n	23	17
1747	1723151003	3	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome			2 silos: one with ribbed staves and one with flat staves		3n	19	17
1747	1723151003	4	Pumphouse	Side Gabled	N / A		Fair	Good		Beveled Clapboard	Wood Shingles					3n	21	17
1747	1723151003	5	Corn Crib	Transverse Aisle	N / A		Fair	Good		Vertical Slats	Asphalt			Taller than most		3n	20	17
1747	1723151003	6	Milkhouse	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt					3n	26	17
1747	1723151003	7	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Corrugated)					3n	25	17
1747	1723151003	8	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)					3n	22	17
1746	1723176011	1	House	I-house	N / A	1860-1890	Good	Poor		Aluminum Siding	Asphalt	Enclosed	Large rear addition and modern deck added	Although the house doesn't have much historic integrity left in its outside view, this is a great collection of farm buildings that are being well care for and even has not one, but 2 outhouses: one for the house and one for the farm buildings		3n	18	17
1746	1723176011	2	Barn	Three-bay Threshing	N / A	1860-1880	Good	Good	Field Stone	Vertical Wood	Asphalt			Has been enlarged to the west		3n	17	17
1746	1723176011	3	Silo	Poured Concrete	N / A		Good	Good		Poured Concrete	none			Also includes an attached milkhouse		3n	16	17
1746	1723176011	4	Shed	Front Gabled	N / A		Good	Good		Vertical Wood	Tin (Flat)		Has shed addition to the rear	Machine shed with sliding doors on both facing sides		3n	4	17
1746	1723176011	5	Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Asphalt			Both bays are slatted		3n	8	17
1746	1723176011	6	Milkhouse	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt					3n	11	17
1746	1723176011	7	Pumphouse	Uneven Gable	N / A		Good	Good		Vertical Wood	Asphalt					3n	12	17

1746	1723176011	8	Shed	Side Gabled	N / A		Excellent (R)	Excellent	Vertical Wood	Asphalt						3n	13	17
1746	1723176011	9	Shed	Side Gabled	N / A		Good	Good	Plywood	Asphalt						3n	7	17
1746	1723176011	10	Chicken Coop	Slant-roofed	N / A		Good	Good	Vertical Wood	Asphalt			Windows changed			3n	6	17
1746	1723176011	11	Shed	Side Gabled	N / A		Good	Good	Plywood	Asphalt						3n	5	17
1746	1723176011	12	Outhouse	Slant-roofed	N / A		Good	Good	Vertical Wood	Asphalt			The outhouse for the house to the east of all of the buildings			3n	9	17
1746	1723176011	13	Outhouse	Slant-roofed	N / A		Good	Good	Vertical Wood	Asphalt			The outhouse amongst all of the farm buildings			3n	14	17
1746	1723176011	14	Shed	Slant-roofed	N / A		Good	Good	Beveled Clapboard	Asphalt			Machine shed			3n	15	17
1746	1723176011	15	Garage	Front Gabled	N / A		Good	Good	Aluminum Siding	Asphalt			2-Car doors			3n	10	17
1744	1723200009	1	House	Upright and Wing	N / A	1860-1890	Good	Good	Brick	Asphalt		New windows	According to renter brick facing was added in the 1970's, but this may not be the case; note all of the arches above the doors and windows; prior survey's map point in wrong place			3l	27	17
1744	1723200009	2	Chicken Coop	Side Gabled	N / A		Fair	Good	Beveled Clapboard	Asphalt						3l	28	17
1744	1723200009	3	Barn	Gothic Arched	N / A		Good	Good	Vertical Wood	Asphalt						3l	29	17
1744	1723200009	4	Corn Crib	Transverse Aisle	N / A		Good	Good	Tin (Perforated)	Tin (Flat)						3l	30	17
1744	1723200009	5	Grain Bin	Round	N / A		Good	Good	Tin (Corrugated)	Tin (Flat)			Includes a small side gabled shed and a flat sided quonset machine shed			3l	31	17
1744	1723200009	6	Milkhouse	Gothic Arched	N / A		Good	Good	Cement Block	Vertical Wood	Asphalt		One of the few gothic arched milkhouses			3l	32	17
1744	1723200009	7	Silo	Brick	N / A		Good	Good	Brick	none			Painted			3l	33	17
1745	1723200018	1	House	Front Gabled	N / A	1880-1920	Good	Good	Vinyl Siding	Asphalt	Open	Addition to rear and enclosed side porch	Simplified when siding added			3m	36	17
1745	1723200018	2	Barn	Transverse Frame	N / A		Good	Good	Vertical Wood	Asphalt			Has shed addition to rear			3m	35	17
1745	1723200018	3	Silo	Concrete Staved	N / A		Good	Good	Concrete Staved	Metal Dome			Flat staves plus another silo with ribbed staved, but no roof			3m	37	17
1745	1723200018	4	Barn	Dairy Gambrel	N / A		Good	Good	Beveled Clapboard	Asphalt			Very wide and low; unusual end molding			3m	31	17
1745	1723200018	5	Pumphouse	Front Gabled	N / A		Very Poor	Good	Beveled Clapboard	Wood Shingles						3m	26	17
1745	1723200018	6	Shed	Side Gabled	N / A		Good	Good	Beveled Clapboard	Asphalt						3m	27	17
1745	1723200018	7	Barn	Metal Pole Barn	N / A		Good	Good	Tin (Flat)	Tin (Flat)						3m	28	17
1745	1723200018	8	Chicken Coop		N / A		Good	Good	Plywood	Asphalt			Windows removed when resided			3m	29	17
1745	1723200018	9	Shed	Gambrel	N / A		Good	Good	Beveled Clapboard	Asphalt			Converted to a 2-car door garage			3m	30	17
1745	1723200018	10	Shed	Quonset	N / A		Good	Good	Tin (Corrugated)	Tin (Corrugated)						3m	32	17
1745	1723200018	11	Barn	Metal Pole Barn	N / A		Good	Good	Tin (Flat)	Tin (Flat)						3m	33	17
1745	1723200018	12	Barn	Metal Pole Barn	N / A		Good	Good	Tin (Flat)	Tin (Flat)			Includes 2 wire mesh corn cribs			3m	34	17
1745.5	1723200018	13	House	Cottage	N / A	1910-1940	Good	Good	Clapboard	Asphalt	none		Small hired hand's house; second house on site but now rented out separately and has a separate driveway			3n	1	17
1745.5	1723200018	14	Garage	Front Gabled	N / A		Good	Good	Tin (Flat)	Asphalt			2-Car doors			3n	2	17
1745.5	1723200018	15	Outhouse	Front Gabled	N / A		Very Poor	Good	Clapboard	Asphalt			Was the outhouse for the adjoining farm			3n	3	17
1744.3	1724200001	1	School Bell		N / A		Good	Good					This is a former school site and all that is left of the school is the school bell			3kk	8	17
1744.3	1724200001	2	House	Raised Ranch	N / A	1950-present	Good	Good	Aluminum Siding	Asphalt			This replacement house is on the actual location of the former school			3kk	11	17
1744.3	1724200001	3	Corn Crib	Transverse Aisle	N / A		Fair	Good	Vertical Wood	Asphalt			Slats have been filled in and converted to a storage shed			3kk	10	17
1744.3	1724200001	4	Barn	Metal Pole Barn	N / A		Good	Good	Tin (Flat)	Tin (Flat)						3kk	9	17
1743	1724300013	1	House	Upright and Wing	N / A	1860-1890	Fair	Fair	Asbestos	Asphalt	Enclosed		House used as a rental for landscaping business			3kk	2	17
1743	1724300013	2	Barn	Transverse Frame	N / A	1880-1920	Good	Good	Vertical Wood	Asphalt			Includes attached front gabled milkhouse			3kk	1	17
1743	1724300013	3	Silo	Concrete Staved	N / A		Good	Good	Concrete Staved	Metal Dome			Flat staves			3kk	5	17
1743	1724300013	4	Silo	Concrete Staved	N / A		Good	Good	Concrete Staved	Metal Dome			Ribbed staves			3kk	7	17
1743	1724300013	5	Windmill		N / A		Good	Fair					Blades missing			3kk	3	17
1743	1724300013	6	Barn	Metal Pole Barn	N / A		Good	Good	Tin (Flat)	Tin (Flat)						3kk	6	17
1743	1724300013	7	Barn	Metal Pole Barn	N / A		Good	Good	Tin (Flat)	Tin (Flat)						3kk	4	17
1743	1724300013	8	Shed	Metal Pole Barn	N / A		Good	Good	Tin (Flat)	Tin (Flat)			Livestock shed			3l	37	17
1743	1724300013	9	Barn	Metal Pole Barn	N / A		Good	Good	Tin (Flat)	Tin (Flat)			Uneven gabled roof			3l	34	17
1743	1724300013	10	Corn Crib	Transverse Aisle	N / A		Poor	Poor	Tin (Flat)	Tin (Flat)			Covered in tin			3l	35	17
1743	1724300013	11	Corn Crib	Transverse Aisle	N / A		Good	Good	Tin (Perforated)	Tin (Flat)						3l	36	17
1742	1724400002	1	House	Cottage	N / A	1910-1940	Good	Good	Stucco	Asphalt			Resort style collection of buildings with only the silo remaining of original farmstead			3kk	16	17
1742	1724400002	2	House	Cottage	N / A	1910-1940	Good	Good	Stucco	Asphalt						3kk	12	17
1742	1724400002	3	House	Cottage	N / A		Good	Good	Beveled Clapboard	Asphalt						3kk	15	17
1742	1724400002	4	Garage	Side Gabled	N / A		Good	Good	Stucco	Asphalt						3kk	13	17
1742	1724400002	5	Silo	Concrete Staved	N / A		Good	Good	Concrete Staved	none						3kk	14	17
1879	1724400006	1	House	Side Gabled	N / A	1930-1950	Fair	Fair	Asbestos	Asphalt			Across the road from site 1742; more resort style buildings			3kk	29	17
1879	1724400006	2	Garage	Pyramidal	N / A		Good	Good	Asbestos	Asphalt			Long rectangular form with full windows overlooking hill and marsh			3kk	30	17
1879	1724400006	3	Shed	Front Gabled	N / A		Good	Good	Asbestos	Asphalt						3kk	32	17
1879	1724400006	4	Garage	Side Gabled	N / A		Good	Good	Asbestos	Asphalt						3kk	33	17
1879	1724400006	5	House	Cottage	N / A		Good	Good	Asbestos	Asphalt			2 More cottages			3kk	34	17
1879	1724400006	6	Barn	Metal Pole Barn	N / A		Good	Good	Tin (Flat)	Tin (Flat)						3kk	31	17
1879	1724400006	7	Corn Crib	Round	N / A		Good	Good	Wire Mesh	Tin (Flat)			2 cribs			3kk	35	17
1880.5	1725100002	1	House	Cross Gabled	N / A	1860-1890	Good	Good	Vinyl Siding	Asphalt	Open		Although this house has been redone, it has a unique symmetrical style with its original 2-over-2 windows			3ll	11	17
1880.5	1725100002	2	Barn	Dairy Gambrel	N / A		Fair	Good	Vertical Wood	Asphalt			Banked haymow entrance; very large; includes concrete staved silo with a metal dome roof			3ll	8	17
1880.5	1725100002	3	Milkhouse	Front Gabled	N / A		Poor	Good	Beveled Clapboard	Wood Shingles		Lengthened	Attached; includes open sided metal pole barn livestock shelter			3ll	9	17
1880.5	1725100002	4	Shed	Metal Pole Barn	N / A		Good	Good	Tin (Flat)	Vertical Wood			Open sided machine shed			3ll	7	17
1880.5	1725100002	5	Grain Bin	Round	N / A		Good	Good	Tin (Corrugated)	Tin (Flat)			Also include metal pole barn in background			3ll	6	17
1880.5	1725100002	6	Garage	Pyramidal	N / A		Good	Good	Clapboard	Asphalt						3ll	10	17
1880	1725100005	1	House	Upright and Wing	N / A	1860-1890	Good	Good	Field Stone	Aluminum Siding	Open	Windows, siding, etc.	This is a 150 year family farm with two residences.			3ll	1	17
1880	1725100005	2	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good	Vertical Wood	Asphalt			Includes attached front gabled milkhouse			3kk	36	17
1880	1725100005	3	Silo	Brick	N / A		Good	Good	Brick	none			2 silos: one brick and one concrete staved; both with no roofs			3ll	3	17
1880	1725100005	4	Chicken Coop	Side Gabled	N / A		Good	Good	Beveled Clapboard	Asphalt			Note old 6-over-6 windows; these came from the house when new windows were put in the house			3kk	37	17
1880	1725100005	5	House	Ranch	N / A		Good	Good	Vinyl Siding	Asphalt			Secondary house for next generation			3ll	4	17
1880	1725100005	6	Barn	Metal Pole Barn	N / A		Good	Good	Tin (Flat)	Tin (Flat)			Includes round wire mesh corn crib			3ll	5	17

1880	1725100005	7	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)					3ll	2	17
1741	1725200006	1	House	Upright and Wing	Italianate	1860-1890	Good	Good	Field Stone	Clapboard	Asphalt	Open and original	Back added onto	Very overgrown; was an antique store; house has not been modernized; still has original windows; photo taken high due to undergrowth; note window hood ornaments and ornamentation in the gables		3kk	28	17
1741	1725200006	2	Barn	Transverse Frame	N / A	1880-1920	Good	Good	Field Stone	Vertical Wood	Asphalt					3kk	23	17
1741	1725200006	3	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome			Includes windmill		3kk	26	17
1741	1725200006	4	Shed	Side Gabled	N / A		Good	Good		Beveled Clapboard	Rolled Asphalt			Machine shed		3kk	27	17
1741	1725200006	5	House	Log cabin	N / A	1830-1840	Good	Good	Poured Concrete	Logs	Asphalt	Open		This is an original 1830's log cabin. However, it is not original to this site. It was moved from Ohio about 15 years ago.		3kk	25	17
1741	1725200006	6	Chicken Coop	Slant-roofed	N / A		Good	Fair		Beveled Clapboard	Asphalt			Windows boarded up		3kk	18	17
1741	1725200006	7	Shed	Side Gabled	N / A		Good	Good		Beveled Clapboard	Rolled Asphalt					3kk	20	17
1741	1725200006	8	Milkhouse	Side Gabled	N / A		Fair	Good	Field Stone	Beveled Clapboard	Asphalt			Attached		3kk	24	17
1741	1725200006	9	Garage	Front Gabled	N / A		Good	Good		Tin (Flat)	Asphalt		Gabled side wing addition	2 Sliding doors		3kk	21	17
1741	1725200006	10	Outhouse	Side Gabled	N / A		Falling down	Good		Clapboard	Rolled Asphalt			Period to the house		3kk	19	17
1741	1725200006	11	Outhouse	Slant-roofed	N / A		Poor	Good		Beveled Clapboard	Asphalt			Second outhouse; thought to be from another site		3kk	22	17
1250	1726200001	1	House	Bungalow	N / A	1910-1940	Good	Good	Poured Concrete	Brick	Asphalt	Enclosed		Extra large sized bricks		3ll	28	17
1250	1726200001	2	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good	Cement Block	Beveled Clapboard	Asphalt			Unusual not to have vertical boards for siding on the barn		3ll	27	17
1250	1726200001	3	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome			2 Silos: both concrete staved, but only one with a roof		3ll	24	17
1250	1726200001	4	Pumphouse	Front Gabled	N / A		Good	Good		Clapboard	Asphalt					3ll	18	17
1250	1726200001	5	Chicken Coop	Uneven Gable	N / A		Fair	Good		Beveled Clapboard	Asphalt			Except for missing windows, perfect symmetry as two section mirror each other		3ll	17	17
1250	1726200001	6	Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Asphalt			Only one bay is slatted for ear corn; the other is for shelled corn or other grain (oats, etc.)		3ll	20	17
1250	1726200001	7	Shed	Front Gabled	N / A		Very Poor	Good		Vertical Wood	Asphalt			Triple sliding doors		3ll	19	17
1250	1726200001	8	Garage	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			2 Sliding doors		3ll	16	17
1250	1726200001	9	Shed	Slant-roofed	N / A		Poor	Good		Vertical Wood	Asphalt			Enlarged for bigger equipment		3ll	22	17
1250	1726200001	10	Shed	Front Gabled	N / A		Good	Good		Plywood	Asphalt			Includes grain hopper on side		3ll	25	17
1250	1726200001	11	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)					3ll	23	17
1250	1726200001	12	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)					3ll	21	17
1250	1726200001	13	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Yet another!		3ll	29	17
1250	1726200001	14	Grain Bin	Round	N / A		Good	Good		Tin (Corrugated)	Tin (Flat)			2 Grain bins		3ll	26	17
1249	1726200005	1	House	Upright and Wing	N / A	1860-1890	Good	Fair	Field Stone	Vinyl Siding	Asphalt	Enclosed	Large rear addition; siding, windows changed	Note side wing frieze window		3ll	12	17
1249	1726200005	2	Barn	Dairy Gambrel	N / A	1880-1920	Fair	Good	Field Stone	Vertical Wood	Asphalt			Includes attached front gabled milkhouse		3ll	14	17
1249	1726200005	3	Silo	Brick	N / A		Fair	Good		Brick	none			Deteriorating; surfaces of brick are flaking off		3ll	15	17
1249	1726200005	4	Shed	Arched Roof	N / A		Good	Good		Beveled Clapboard	Tin (Flat)					3ll	13	17
1804	1726300001	1	House	Upright and Wing	N / A		Fair	Good		Asbestos	Asphalt		New windows and rear addition	Side wing is very small; new windows have altered the look; further examination was not possible due to mean dogs		3ll	31	17
1804	1726300001	2	Barn	Dairy Gambrel	N / A		Good	Good		Vertical Wood	Asphalt			Includes 2 concrete staved silos without roofs, a front gabled milkhouse, and a pumphouse		3ll	32	17
1804	1726300001	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Includes 3 large grain bins		3ll	33	17
1805	1726300006	1	House	Side Gabled	N / A	1850-1870	Good	Good	Field Stone	Clapboard	Asphalt	Inset and open	Side wing added	Very unique layout with an inset porch in the main section of the house; also note original 6-over-6 windows and square porch columns		3ll	30	17
1803	1727200006	1	House	Upright and Wing	N / A	1860-1890	Good	Fair	Field Stone	Aluminum Siding	Asphalt	Removed	Windows, siding changed plus a large side wing to other side added	New addition side wing has flat roof and not historically sensitive to the house		3ll	34	17
1803	1727200006	2	Garage	Front Gabled	N / A		Good	Good		Aluminum Siding	Asphalt			1 Double wide door		3ll	37	17
1803	1727200006	3	Milkhouse	Front Gabled	N / A		Fair	Good		Beveled Clapboard	Asphalt			Old barn gone		3ll	35	17
1803	1727200006	4	Grain Bin	Round	N / A		Good	Good		Tin (Corrugated)	Tin (Flat)			3 Large grain bins		3ll	36	17
1803	1727200006	5	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)					3m	1	17
1803	1727200006	6	Shed	Quonset	N / A		Good	Good		Beveled Clapboard	Tin (Corrugated)					3m	2	17
1801	1727300004	1	House	Upright and Wing	N / A	1880-1920	Fair	Fair	Field Stone	Aluminum Siding	Asphalt	Enclosed	Siding, windows and porch	Normal modernizations, but well-cared for		3m	18	17
1801	1727300004	2	Barn	Transverse Frame	N / A		Good	Fair	Cement Block	Tin (Flat)	Tin (Flat)			Banked haymow entrance; note steeper roof pitch than three-bay barns; includes concrete staved silo with corrugated staves and a metal dome roof		3m	14	17
1801	1727300004	3	Milkhouse	Front Gabled	N / A		Good	Good		Cement Block	Asphalt			Attached		3m	15	17
1801	1727300004	4	Barn	Gothic Arched	N / A		Good	Good		Beveled Clapboard	Asphalt			Includes front gabled shed and steel "A.O. Smith Harvestore" silo		3m	17	17
1801	1727300004	5	Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Asphalt			This is a combination corn crib / hog house that is located across the street (due to smell)		3m	11	17
1801	1727300004	6	House	Cottage	N / A	1910-1940	Good	Good		Asbestos	Asphalt			Secondary house; upper 6-pane windows may have been from the main house when windows were replaced; rectangular form with hipped roof		3m	12	17
1801	1727300004	7	Garage	Side Gabled	N / A		Good	Good		Cement Block	Asphalt			3 Single car doors		3m	16	17
1801	1727300004	8	Grain Bin	Round	N / A		Good	Good		Tin (Corrugated)	Tin (Flat)			One corrugated and one ribbed		3m	13	17
1238	1727300012	1	House	Upright and Wing	N / A	1880-1920	Good	Fair		Aluminum Siding	Asphalt	Inset and open	Windows, siding changed	Old barn on this site gone; not gable window, bay hood cover and gable bargeboard as indications of this house's more ornate beginnings		3r	15	17
1238	1727300012	2	Garage	Side Gabled	N / A		Good	Good		Cement Block	Asphalt			2 sheds/garages, both side gabled		3r	16	17
1802	1727400001	1	House	Cross Gabled	N / A	1880-1910	Good	Good	Granite	Vinyl Siding	Asphalt	Open	Siding and alum. Windows	Although front porch railing was changed this house still has a lot of details and could be restored; note front bay window with leaded transom window		3m	10	17
1802	1727400001	2	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Tin (Flat)	Tin (Flat)			Sided over; includes front gabled attached milkhouse and poured concrete silo with metal dome roof		3m	9	17
1802	1727400001	3	Shed	Side Gabled	N / A		Good	Good		Vertical Wood	Tin (Flat)			Machine shed		3m	5	17
1802	1727400001	4	Pumphouse	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt					3m	4	17

1802	1727400001	5	Hog House	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				3m	6	17
1802	1727400001	6	Garage	Side Gabled	N / A		Good	Good		Aluminum Siding	Asphalt			3 Single car doors	3m	3	17
1802	1727400001	7	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Includes a front gabled shed	3m	7	17
1802	1727400001	8	Garage	Side Gabled	N / A		Good	Good		Vinyl Siding	Asphalt			Part office/shop and part garage with a single garage door on the one side	3m	8	17
1795.5	1728100010	1	House	Upright and Wing	N / A	1880-1920	Fair	Good		Aluminum Siding	Asphalt			Very modernized and overgrown	3m	25	17
1795.5	1728100010	2	Barn	Three-bay Threshing	N / A	1860-1890	Good	Good	Field Stone	Vertical Wood	Tin (Flat)			Small barn; also includes slant roof chicken coop in poor condition another front gabled shed and a poured concrete silo with a metal dome roof	3m	23	17
1795.5	1728100010	3	Milkhouse	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Older style milkhouse (not for modern bulk tank, but for milk cans)	3m	24	17
1795	1728100017	1	House	Upright and Wing	N / A	1880-1920	Good	Good		Aluminum Siding	Asphalt		Windows, siding, porch	With shortened windows, it greatly changes the look of the house	3m	22	17
1795	1728100017	2	Garage	Front Gabled	N / A		Good	Good		Aluminum Siding	Asphalt			1 Single car door	3m	21	17
1795	1728100017	3	Pumphouse		N / A		Good	Good		Aluminum Siding	Asphalt				3m	19	17
1795	1728100017	4	Hog House		N / A		Good	Good		Vertical Wood	Asphalt				3m	20	17
1237	1728200001	1	House	Cottage	N / A	1900-1930	Good	Good		Clapboard	Asphalt			Cape Cod style but without the dormers; entire farmstead is very run-down, inactive and over-grown, but someone still lives in the house; all set well off the road down a treacherously rutted driveway	3p	19	17
1237	1728200001	2	Barn	Three-bay Threshing	N / A		Very Poor	Good		Vertical Wood	Wood Shingles			Shed addition to side; falling apart	3p	16	17
1237	1728200001	3	Hog House	Front Gabled	N / A		Very Poor	Good		Beveled Clapboard	Wood Shingles				3p	17	17
1237	1728200001	4	Shed	Front Gabled	N / A		Very Poor	Good		Beveled Clapboard	Tin (Flat)				3p	18	17
1237	1728200001	5	Garage	Pyramidal	N / A		Very Poor	Good		Beveled Clapboard	Asphalt			2 Single doors falling apart; includes additional front gabled shed	3p	15	17
1237	1728200001	6	Chicken Coop	Side Gabled	N / A		Poor	Good		Asphalt	Asphalt				3p	21	17
1237	1728200001	7	Chicken Coop	Uneven Gable	N / A		Falling down	Good		Clapboard	Asphalt				3p	20	17
1237.5	1728200006	1	House	Upright and Wing	N / A	1860-1890	Good	Good	Field Stone	Vinyl Siding	Asphalt	Enclosed	New windows, siding	Still has the pediment window hood ornaments	3p	23	17
1237.5	1728200006	2	Shed	Side Gabled	N / A		Good	Good		Asbestos	Asphalt			Includes 2 small sheds	3p	24	17
1237.7	1728200012	1	House	Upright and Wing	N / A	1850-1870	Poor	Good	Field Stone	Clapboard	Asphalt	Open	Back wing extended, but over a hundred years ago	This one is a shame; not only is it abandoned, but it is open and looks like it is going to be burned for fire training practice. It has all of its original, plaster, windows, hardware, moldings and railings; it is site back off the road by a spring	3p	26	17
1237.7	1728200012	2	House		N / A									Second view to show the front with the frieze windows above the porch; note that this started out as an I-house and was expanded backwards	3p	27	17
1237.7	1728200012	3	Barn	Three-bay Threshing	N / A	1840-1850	Falling down	Good	Field Stone	Vertical Wood	Wood Shingles			This is even a worst shame; this little barn is totally made of hand-hewn local timbers, some 16 inches thick; although it has a shed addition to the side the threshing door is still to the rear; garbage has been dumped inside and it is very overgrown	3p	25	17
1788	1729100006	1	House	I-house	N / A	1860-1880	Good	Fair	Field Stone	Vinyl Siding	Asphalt	Open	Windows, siding, rear porch enclosed	Original front porch minus the railing	1y	1	17
1788	1729100006	2	Shed	Gambrel	N / A		Good	Good	Molded Block	Beveled Clapboard	Asphalt			Molded block is evident in photo number 04 for this site	1y	2	17
1788	1729100006	3	Garage	Front Gabled	N / A		Good	Good		Aluminum Siding	Asphalt				1y	3	17
1788	1729100006	4	Pumphouse	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Tucked in behind the molded block shed	1y	4	17
1788	1729100006	5	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			In background	1y	5	17
1789	1729200001	1	House	Upright and Wing	N / A	1860-1890	Good	Good	Field Stone	Vinyl Siding	Asphalt		Side wing enlarged and porch altered not to mention windows and siding	Note side bay; this house had a lot more detail before being simplified and modernized	1y	8	17
1789	1729200001	2	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome			Old barn is gone	1y	6	17
1789	1729200001	3	Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Asphalt			Slats filled in and converted to garage	1y	7	17
1789	1729200001	4	Shed	Front Gabled	N / A		Poor	Good		Beveled Clapboard	Asphalt				1y	9	17
1787	1729351007	1	School	Front Gabled	Greek Revival	1840-1850	Very Poor	Good		Clapboard	Wood Shingles		First school converted into a shed; note that the second school was also a 1-room school, but larger and built in the 1880's	This is a tale of 3 schoolhouses for Harmony Hill; this was the first one; the second was moved to the historical society; the final and third one was converted into a house (see site 1797.5); then with rural consolidation in 1946 the need was no more!	1x	35	17
1787	1729351007	2	Barn	Dairy Gambrel	N / A	1900-1930	Good	Good		Vertical Wood	Tin (Flat)			Now used as a horse stable; includes attached hipped roof milkhouse	1m	1	17
1787	1729351007	3	School		N / A									Second view to show side windows; note also cornice returns	1x	34	17
1787	1729351007	4	Corn Crib	Transverse Aisle	N / A		Very Poor	Good		Horizontal Slats	Rolled Asphalt			Only one bay slatted	1x	36	17
1787	1729351007	5	House	Ranch	N / A	1950-present	Good	Good		Vinyl Siding	Asphalt			Replacement house for site	1x	37	17
1787	1729351007	6	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Used as a horse arena	1m	2	17
1625	1730100002	1	House	Upright and Wing	N / A	1860-1880	Very Poor	Good	Field Stone	Aluminum Siding	Asphalt	Open		House has been vacant for 15 years according to resident of second house	1x	22	17
1625	1730100002	2	House	Ranch	N / A	1950-present	Good	Good		Aluminum Siding	Asphalt			Secondary house on site; includes attached garage	1x	9	17
1625	1730100002	3	Barn	Three-bay Threshing	N / A	1860-1880	Good	Fair		Vertical Wood	Asphalt			Has been elongated to the side and then expanded to the rear	1x	20	17
1625	1730100002	4	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome				1x	17	17
1625	1730100002	5	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				1x	18	17
1625	1730100002	6	Grain Bin	Round	N / A		Good	Good		Tin (Corrugated)	Tin (Flat)			2 Grain bins	1x	21	17
1625	1730100002	7	Grain Bin	Round	N / A		Good	Good		Tin (Corrugated)	Tin (Flat)			3 More grain bins	1x	23	17
1627	1730100009	1	House	Four-over-four	Foursquare	1900-1920	Good	Good	Molded Block	Aluminum Siding	Asphalt	Open	Large rear wing added, plus alum. siding added	This is the second house on the site (see site 1626). This farm is still owned by the original Lockwood family, but farmed by renters. Note flare on roofline of this house and the wood staved silos	1x	32	17
1627	1730100009	2	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			Includes an attached milkhouse and a concrete staved silo with a metal dome roof	1x	24	17
1627	1730100009	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				1x	25	17
1627	1730100009	4	Garage	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			3-Car doors with the middle bay being gabled and enlarged	1x	26	17
1627	1730100009	5	Shed	Gambrel	N / A		Fair	Good		Beveled Clapboard	Wood Shingles				1x	27	17
1627	1730100009	6	Shed	Uneven Gable	N / A		Good	Good		Beveled Clapboard	Wood Shingles			Machine shed	1x	28	17
1627	1730100009	7	Hog House	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt				1x	29	17

1627	1730100009	8	Silo	Wood Staved	N / A		Good	Good		Vertical Wood	none			2 Wood staved silos that are still in reasonable shape! Also includes a small Gothic arch barn	1x	30	17
1627	1730100009	9	Shed	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Machine shed; also includes 3 large grain bins, a hopper and a grain dryer	1x	31	17
1626	1730100009	10	House	Cottage	N / A	1840-1850	Good	Good		Wood Shingles	Asphalt		Added onto both at the side and rear	This is one of the oldest house in the area. In the central core is the foundation and flooring for the Lockwood's original log cabin. It still does not have indoor plumbing or electricity. Shingles were mounted over the clapboard in 1917 to modernize	1x	33	17
1786.5	1730200009	1	House	Upright and Wing	N / A	1880-1920	Good	Poor		Plywood	Asphalt	Enclosed	Windows, siding and porch changed	Too modernized to have much historic integrity left	c1	3	17
1786.5	1730200009	2	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Old barn now gone; includes a side gabled garage	c1	1	17
1786.5	1730200009	3	Milkhouse	Pyramidal	N / A		Good	Good		Asbestos	Asphalt			Rectangular form with hipped roof	c1	2	17
1624	1730400001	1	House	Upright and Wing	N / A	1880-1920	Good	Good	Granite	Vinyl Siding	Asphalt	Enclosed	Rear wing added; modernized	Interesting collection of farm buildings, may warrant further investigation	1x	8	17
1624	1730400001	2	Shed	Slant-roofed	N / A		Good	Good		Clapboard	Asphalt			Usually slant roof is pitched away from the front instead of towards the front as this one is	1x	9	17
1624	1730400001	3	Chicken Coop	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Well-maintained; also includes another front gabled shed behind it	1x	10	17
1624	1730400001	4	Milkhouse	Side Gabled	N / A		Good	Good	Cement Block	Beveled Clapboard	Asphalt				1x	11	17
1624	1730400001	5	Hog House	Broken Eave	N / A		Good	Good		Beveled Clapboard	Asphalt			This may have been a chicken coop	1x	12	17
1624	1730400001	6	Barn	Transverse Frame	N / A		Good	Good		Vertical Wood	Asphalt			Also has side entrance between milking stalls and box stalls	1x	13	17
1624	1730400001	7	Outhouse	Side Gabled	N / A		Poor	Good		Clapboard	Asphalt				1x	14	17
1624	1730400001	8	Shed	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt			2 Livestock sheds: one with open sides	1x	15	17
1624	1730400001	9	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				1x	16	17
1623	1730400003	1	House	Raised Ranch	N / A	1950-present	Good	Good		Vertical Wood	Asphalt			Replacement house; also includes front gabled garage	1x	6	17
1623	1730400003	2	Barn	Dairy Gambrel	N / A	1900-1930	Fair	Good		Vertical Wood	Wood Shingles			Also includes a small concrete staved silo with no roof	1x	7	17
1623	1730400003	3	Shed	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Machine shed, but unusually wide with a center aisle	1x	5	17
1622	1730400004	1	House	Upright and Wing	N / A	1860-1880	Good	Good	Field Stone	Clapboard	Asphalt	Open	Side shed addition	Unusual front fenestration pattern!	1x	2	17
1622	1730400004	2	Barn	Three-bay Threshing	N / A		Good	Good		Vertical Wood	Asphalt		Shed addition to rear	In very good condition	1x	1	17
1622	1730400004	3	Shed	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt				1x	3	17
1622	1730400004	4	Garage	Front Gabled	N / A		Good	Good		Plywood	Asphalt				1x	4	17
1632	1731300001	1	Shed	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt			This site had the house and big barn removed in 2001; all that is left is some misc. farm buildings, none of which are significant	1v	30	17
1632	1731300001	2	Shed	Uneven Gable	N / A		Fair	Good		Beveled Clapboard	Asphalt			2 Livestock sheds	1v	32	17
1632	1731300001	3	Corn Crib	Transverse Aisle	N / A		Fair	Good		Horizontal Slats	Asphalt			2 bays on corn crib; 3 metal grain bins and 1 side gabled machine shed	1v	31	17
1632	1731300001	4	Barn	Metal Pole Barn	N / A		Very Poor	Good		Tin (Flat)	Tin (Flat)			Tin is removing itself storm-by-storm	1v	29	17
1621	1732100001	1	House	Upright and Wing	Greek Revival	1860-1880	Good	Good	Field Stone	Clapboard	Asphalt	Enclosed	New windows, siding, modernized	Some of the farm buildings on this site are also in section 31; the previous survey listed this site in section 31, but the PIN is for section 32	1m	7	17
1621	1732100001	2	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Tin (Flat)			Also includes a metal machine shed	1m	4	17
1621	1732100001	3	House	Trailer	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Secondary residence	1m	3	17
1621	1732100001	4	Shed	Gambrel	N / A		Poor	Good		Beveled Clapboard	Asphalt			Includes a slant-roofed shed; these Gambrel sheds were known to be used as "Potato barns"; at one time the Marengo area was known for their potato farms, so this may be a remnant structure	1m	5	17
1621	1732100001	5	Garage	Side Gabled	N / A		Good	Good		Tin (Flat)	Tin (Flat)			3-Car doors; includes also a cement block side gabled shed	1m	6	17
1619	1732100013	1	House	Side Gabled	N / A	1880-1920	Good	Good		Vinyl Siding	Asphalt	Open	Recently modernized and expanded	Includes a large attached garage	1m	16	17
1619	1732100013	2	Barn	Transverse Frame	N / A	1880-1920	Fair	Good		Vertical Wood	Asphalt			Banked haymow side entrance	1m	19	17
1619	1732100013	3	Barn		N / A									Second view of barn to show how this could have been a Three-bay threshing barn expanded (note the signature former row of windows above side door)	1m	18	17
1619	1732100013	4	Garage	Side Gabled	N / A		Good	Good		Vinyl Siding	Asphalt				1m	17	17
1620	1732100022	1	House	Upright and Wing	Greek Revival	1850-1870	Fair	Good	Field Stone	Asbestos	Asphalt	Open	Chimney added and 1930's style carport added to rear	This is yet another skelton farmstead that was taken out of family farming by the "Shireland" complex. This one is abandoned, but still has a lot of its original features including 6-pane windows and cornice returns.	1m	9	17
1620	1732100022	2	Barn	Transverse Frame	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			This is the bigger second barn in the back that was added onto the original barn; note the use of different colored roof shingles to advertise their shire horses to the public (this barn faces Interstate-90)	1m	15	17
1620	1732100022	3	Barn	Three-bay Threshing	N / A	1860-1890	Good	Good		Vertical Wood	Asphalt			This is the older barn of the two that is period to the house; it may have been lengthened	1m	14	17
1620	1732100022	4	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	none			Also includes small side gabled shed	1m	13	17
1620	1732100022	5	Corn Crib	Transverse Aisle	N / A		Good	Good		Vertical Wood	Asphalt			Converted to shed	1m	11	17
1620	1732100022	6	Shed	Uneven Gable	N / A		Good	Good		Vertical Wood	Asphalt			Horse shelter	1m	10	17
1620	1732100022	7	Grain Bin		N / A		Fair	Good		Tin (Corrugated)	Tin (Flat)			3 Grain bins	1m	12	17
1618	1732100023	1	House	Upright and Wing	Greek Revival	1850-1870	Good	Good	Field Stone	Clapboard	Asphalt	Enclosed		Since the last survey, this house has been unwrapped of its asphalt siding and the original clapboard has been restored; note also the triangular pediments above the windows that had been covered up	3z	33	17
1618	1732100023	2	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			Includes a milkhouse in very bad shape and a concrete staved silo with good adaptive reuse as a vine support	3z	36	17
1618	1732100023	3	Corn Crib	Transverse Aisle	N / A		Falling down	Good		Horizontal Slats	Wood Shingles			Both bays slatted but this one is in a very bad state of demolition by neglect	3z	34	17
1618	1732100023	4	Shed	Side Gabled	N / A		Good	Good		Clapboard	Asphalt			Unclear as to function, but possible grainery	3z	32	17
1618	1732100023	5	Shed	Side Gabled	N / A		Very Poor	Good		Vertical Wood	Rolled Asphalt			Machine shed	3z	35	17
1615.5	1732200002	1	Silo	Poured Concrete	N / A		Good	Good		Poured Concrete	none			Old barn gone; replaced with this metal pole barn; site now "Harmony Road Stables"	3t	18	17
1615.5	1732200002	2	Milkhouse	Side Gabled	N / A		Good	Good		Vertical Wood	Rolled Asphalt				3t	19	17
1615.5	1732200002	3	Shed	Side Gabled	N / A		Good	Good		Tin (Corrugated)	Tin (Corrugated)			Machine shed; also includes a metal pole barn	3t	21	17
1615.5	1732200002	4	Barn	Metal Pole Barn	N / A		Fair	Good		Tin (Flat)	Tin (Flat)			Older pole barn	3t	20	17
1615.5	1732200002	5	House	Ranch	N / A	1950-present	Good	Good		Brick	Asphalt			Replacement house	3t	22	17
1617	1732251011	1	House	Upright and Wing	N / A		Fair	Poor		Aluminum Siding	Asphalt	Enclosed	Windows, siding, etc.	However, unchanged from previous survey	1v	28	17

1617	1732251011	2	Shed	Side Gabled	N / A		Falling down	Good		Beveled Clapboard	Wood Shingles			Also includes a small slant-roofed chicken coop	1v	27	17
1617	1732251011	3	Silo	Poured Concrete	N / A		Good	Good		Poured Concrete	Metal Dome				1v	25	17
1617	1732251011	4	Grain Bin	Round	N / A		Good	Good		Tin (Corrugated)	Tin (Flat)			2 Grain bins	1v	26	17
1615	1733100003	1	House	Upright and Wing	N / A	1860-1890	Good	Poor		Aluminum Siding	Asphalt		Siding, windows, porches, etc.	Everything very modernized, even placement and sizes of windows changed	3t	15	17
1615	1733100003	2	Barn	Dairy Gambrel	N / A	1880-1920	Fair	Fair	Field Stone	Asbestos	Asphalt			Metal addition to the front and side	3t	12	17
1615	1733100003	3	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome			Also includes a round wire mesh corn crib	3t	11	17
1615	1733100003	4	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			2 of these	3t	13	17
1611	1733100004	1	House	Upright and Wing	N / A	1860-1890	Poor	Fair	Field Stone	Clapboard	Asphalt	Enclosed	When windows were changed, sizes were also changed and some removed	This house is now vacant and family members live in the modern ranch next door	3s	36	17
1611	1733100004	2	Barn	Three-bay Threshing	N / A	1860-1880	Good	Fair	Field Stone	Vertical Wood	Tin (Flat)			Includes 2 barns (not one with an addition); Note the smaller Three-bay barn that the big Transverse Frame barn was added around	3s	34	17
1611	1733100004	3	Chicken Coop	Slant-roofed	N / A		Fair	Fair		Beveled Clapboard	Asphalt		Converted into shed (note large garage entry doors)	Some windows missing; others are the 6-pane windows from the house	3s	37	17
1611	1733100004	4	Garage	Front Gabled	N / A		Good	Good		Vinyl Siding	Tin (Flat)			Used by the modern house	3s	35	17
1611	1733100004	5	Shed	Slant-roofed	N / A		Good	Good		Beveled Clapboard	Tin (Flat)			Machine shed	3t	2	17
1611	1733100004	6	Corn Crib	Transverse Aisle	N / A		Fair	Good		Horizontal Slats	Tin (Flat)			Unusual in that the slatted bays continue to be slatted all the way up to the roof instead of stopping at the gables and having solid, filled in gables; also includes slant-roofed livestock shelter	3y	3	17
1611	1733100004	7	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3t	1	17
1611	1733100004	8	Grain Bin	Round	N / A		Good	Good		Tin (Corrugated)	Tin (Flat)				3t	4	17
1610	1733200002	1	House	Upright and Wing	Greek Revival	1850-1870	Good	Good	Field Stone	Clapboard	Asphalt	Inset, but opened	Windows have been changed, but with same size windows; inset porch roof was cut back and picture window installed	Not only does this house have large scale cornice returns, but also has full pilasters; the formal front door surround does not have a transom or side lights, but does have extra molding to form a temple-like entrance	3s	32	17
1610	1733200002	2	Barn	Three-bay Threshing	N / A	1850-1870	Fair	Good	Field Stone	Tin (Flat)	Asphalt			Includes attached front gabled milkhouse	3s	26	17
1610	1733200002	3	Barn	Gothic Arched	N / A	1910-1940	Good	Good		Beveled Clapboard	Asphalt			Addition onto older barn; includes a slant-roofed livestock shelter	3s	28	17
1610	1733200002	4	Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Asphalt			Both bays slatted for ear corn	3s	31	17
1610	1733200002	5	Chicken Coop	Side Gabled	N / A		Fair	Fair		Vertical Wood	Wood Shingles		Converted to a garage	Central door flanked by balanced windows	3s	30	17
1610	1733200002	6	Shed	Front Gabled	N / A		Good	Good		Vertical Wood	Wood Shingles			The prior function of this shed is not definitive but could be a grainery with the absence of lower windows and the door not extending all the way down	3s	29	17
1610	1733200002	7	Shed	Uneven Gable	N / A		Fair	Good		Vertical Wood	Wood Shingles			Storage shed	3s	27	17
1616	1733300004	1	House	Side Gabled	Greek Revival	1850-1860	Good	Good		Clapboard	Asphalt	Open	Rear addition and garage	This is a "Samuel Morris" plaqued house by the historical society. It is one of the older houses complete with hand hewn beams throughout the basement (even in the back wing). Note the cornice returns, frieze windows and door surround	3t	16	17
1616	1733300004	2	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			3 Metal barns used for horse stabling and riding arena	3t	17	17
1614	1733300011	1	House	Upright and Wing	N / A		Good	Fair		Vinyl Siding	Asphalt	Enclosed	Windows, siding, etc.	With the smaller sized windows, this house's appearance has been altered; however, it is still an improvement over the alum. siding that was on the house during the previous survey	3t	9	17
1614	1733300011	2	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3t	8	17
1614	1733300011	3	Chicken Coop	Slant-roofed	N / A		Good	Good		Aluminum Siding	Asphalt			Converted to storage	3t	10	17
1610.3	1733300013	1	Cemetery		N / A									Interesting that the 1872 Platbook had this cemetery located on the north side of the road instead of where it is now on the south side; so either the platbook made a mistake or it started on the other side and was moved and continued on the south side	3s	33	17
1613	1733300016	1	House	Side Gabled	N / A	1850-1870	Good	Poor		Vinyl Siding	Asphalt		Windows, siding, etc.	All that's left is the house and a poured concrete silo with no roof; house does not retain much historic integrity	3t	7	17
1612	1733400003	1	Church	Front Gabled	N / A	1890-1930	Fair	Fair		Clapboard	Asphalt		Side entry added	Converted to a house long ago; needs work	3t	5	17
1609	1733400006	1	House	Front Gabled	N / A	1880-1920	Good	Poor		Aluminum Siding	Asphalt		Too numerous to mention	Very little left of original house	3s	25	17
1609	1733400006	2	Shed	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Machine shed	3s	23	17
1609	1733400006	3	Garage	Front Gabled	N / A		Good	Good		Aluminum Siding	Asphalt				3s	24	17
1608	1734100004	1	House	Cottage	N / A	1860-1890	Good	Poor	Field Stone	Plywood	Asphalt	Enclosed	Totally changed	One curious point is what the internal construction is like: whether it is hand hewn or what; since the original section is so small, it could have been built as a temporary structure, then enlarged; part of the town of Harmony	3s	22	17
1608	1734100004	2	Garage	Side Gabled	N / A		Good	Good		Plywood	Asphalt			Modern	3s	21	17
1608	1734100004	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3s	20	17
1238.7	1734100009	1	House	Cottage	Cape Cod	1910-1940	Fair	Poor		Plywood	Asphalt			Used as a rental; part of the town of Harmony	3r	21	17
1238.8	1734100010	1	Barn	Three-bay Threshing	N / A	1860-1880	Poor	Poor		Aluminum Siding	Asphalt		Converted into a house	At the crossroads community of Harmony; now used as income rental property	3r	22	17
1238.5	1734100016	1	House	Upright and Wing	N / A	1860-1890	Fair	Fair		Aluminum Siding	Asphalt		Modernized	Again another family farmstead that is now a rental for the inactive "Shireland" complex	3r	20	17
1238.5	1734100016	2	Barn	Dairy Gambrel	N / A		Good	Poor		Tin (Flat)	Tin (Flat)		Totally changed look with covering in tin	Also includes a front-gabled shed (possible former corn crib) and a concrete staved silo with a tin gambrel roof	3r	18	17
1238.5	1734100016	3	Milkhouse	Front Gabled	N / A		Fair	Good		Beveled Clapboard	Asphalt			Also includes a front-gabled shed	3r	19	17
1238.5	1734100016	4	Chicken Coop	Slant-roofed	N / A		Fair	Good		Beveled Clapboard	Asphalt				3r	17	17
1244	1734200003	1	House	Upright and Wing	N / A	1850-1930	Fair	Fair		Clapboard	Asphalt	Open	See below	This house has gone through major transition. It started out as a hand-hewn house which according to the owner, "Abe Lincoln bought to give to his servants so they could own property". Then in the 1930's a Sears house was built around the original house	3r	7	17
1240	1734300002	1	School	Front Gabled	Colonial Revival	1900-1930	Good	Fair		Brick	Asphalt			Former school that is now a reality office; old barn on site is gone; part of the town of Harmony	3s	15	17
1240.1	1734300005	1	Factory	Storefront	N / A	1910-1940	Fair	Good		Brick	Tin (Flat)			Old store/machine shop; part of the town of Harmony	3r	23	17
1239	1734300006	1	House	Front Gabled	N / A	1860-1880	Poor	Good	Field Stone	Asbestos	Asphalt	Open	Much the same except for the siding and the lower front door and flanking windows	This was a combination storefront/boarding house/shop keeper's house for the town of Harmony; note the original 4-over-4 upper windows; this structure would be interesting to further investigate	3r	24	17
1241	1734300014	1	House	Upright and Wing	N / A	1880-1910	Fair	Poor	Field Stone	Asbestos	Asphalt	Enclosed	Deck added; windows, siding, doors, etc. - all changed	Part of the town of Harmony, but not much historical feel left in this structure	3r	25	17

1241	1734300014	2	Garage	Side Gabled	N / A		Good	Good		Tin (Flat)	Asphalt				Former machine shed	3s	1	17	
1241	1734300014	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)						3s	2	17
1243	1734300019	1	House	Upright and Wing	Greek Revival	1850-1860	Good	Excellent	Field Stone	Clapboard	Asphalt	Open	Back porch added		Historic integrity intact in this one! This is the "Shapley" house. Side wing is original winter kitchen unmodified complete with cistern and pantry. Original detached summer kitchen was taken down. All original windows and moldings!	3s	7	17	
1243	1734300019	2	Barn	Dairy Gambrel	N / A	1880-1910	Fair	Good		Vertical Wood	Wood Shingles				Has attached front gabled milkhouse; needs work; overgrown	3s	8	17	
1243	1734300019	3	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome					3s	9	17	
1243	1734300019	4	Barn	Three-bay Threshing	N / A	1850-1870	Good	Excellent		Beveled Clapboard	Wood Shingles				This is the original hand-hewn threshing barn; there used to be a rear portion thought to be a hog house that was also hand-hewn; this rear portion was in too bad of shape and had to be taken down, but all of the hand-hewn timbers were saved	3s	6	17	
1242	1734300023	1	Church	Steepled	N / A	1860-1880	Good	Good		Clapboard	Wood Shingles				Town of Harmony church	3s	4	17	
1242	1734300023	2	House	Front Gabled	N / A	1880-1920	Good	Good		Vinyl Siding	Asphalt		Large rear addition		Parsonage for the church	3s	5	17	
1607	1734300031	1	House	Four-over-four	N / A	1860-1880	Good	Fair		Vinyl Siding	Asphalt	New porch	Modernized		This is not a Foursquare, but the older version that is a simplified Italianate; this one however has been very modernized complete with new attached garage; part of the town of Harmony	3s	18	17	
1607	1734300031	2	Shed	Side Gabled	N / A		Good	Fair		Vinyl Siding	Asphalt					3s	17	17	
1607	1734300031	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)					3s	19	17	
1245	1734400013	1	House	Four-over-four	N / A	1860-1880	Fair	Fair		Asbestos	Asphalt		Attached garage added since previous survey		This again is the older version, not a newer Foursquare	3r	5	17	
1245	1734400013	2	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good	Field Stone	Vertical Wood	Asphalt				Includes detached milkhouse and banked haymow entrance	3r	4	17	
1245	1734400013	3	Shed	Side Gabled	N / A		Poor	Poor		Beveled Clapboard	Asphalt				Converted into a garage	3r	6	17	
1246	1735100002	1	House	Upright and Wing	N / A	1850-1870	Fair	Fair	Field Stone	Asbestos	Asphalt	Inset, but enclosed	Windows, siding, doors		Used as rental on commercial site	3r	2	17	
1246	1735100002	2	Barn	Transverse Frame	N / A	1880-1920	Good	Fair		Vertical Wood	Asphalt		Large side addition		Includes a side gabled milkhouse and 2 concrete staved silos: one with flat staves and one with ribbed staves, but both with metal dome roofs	3q	36	17	
1246	1735100002	3	Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Wood Shingles				Both bays slatted; includes metal grain bin and windmill	3q	37	17	
1246	1735100002	4	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				Commercial center of property	3r	1	17	
1247	1735200002	1	House	Upright and Wing	N / A	1880-1900	Good	Fair		Asbestos	Asphalt	Open	Some windows changed		Could be beautiful if restored; interior woodwork still intact and not painted (varnished)	3q	32	17	
1247	1735200002	2	Barn	Transverse Frame	N / A	1880-1900	Good	Good	Field Stone	Vertical Wood	Asphalt				Includes concrete staved silo with metal dome roof	3q	35	17	
1247	1735200002	3	Milkhouse	Pyramidal	N / A		Good	Excellent		Molded Block	Asphalt					3q	34	17	
1247	1735200002	4	Garage	Side Gabled	N / A		Good	Good		Cement Block	Asphalt				3-Car doors	3q	33	17	
1245.5	1735200002	5	School	Front Gabled	N / A	1850-1870	Good	Good		Clapboard	Wood Shingles		None		All original! Windows are not boarded up, but have the original single sided shutters; also note sliding door to double seal the doorway; also original chimney; on same parcel as site 1247	3q	19	17	
1606	1735200011	1	House	Upright and Wing	Greek Revival	1850-1870	Falling down	Good	Field Stone	Clapboard	Wood Shingles	Inset, but enclosed	Chimney added		Original windows and everything else inside, too! This one is a shame; the asbestos has been removed since the last survey, but no care is being given to this house since a new house was built next to it	3q	20	17	
1606	1735200011	2	House		N / A										Second view to show woodshed back wing; windows added later; side door removed	3q	25	17	
1606	1735200011	3	House	Ranch	N / A	1950-present	Good	Good		Aluminum Siding	Asphalt				Second house on site; old house is abandoned and vacant	3q	21	17	
1606	1735200011	4	Barn	Transverse Frame	N / A	1860-1890	Good	Good		Vertical Wood	Asphalt		Shed addition to rear		Includes an attached side gabled milkhouse; notice the fancy cupola vent on barn	3q	28	17	
1606	1735200011	5	Shed	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				Machine shed	3q	27	17	
1606	1735200011	6	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome				Includes 2 more sheds and a gothic arched addition to barn	3q	26	17	
1606	1735200011	7	Garage	Side Gabled	N / A		Good	Good		Aluminum Siding	Asphalt				3-Car doors	3q	24	17	
1606	1735200011	8	Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Tin (Flat)				Both bays are slatted for ear corn	3q	23	17	
1606	1735200011	9	Chicken Coop	Slant-roofed	N / A		Poor	Good		Beveled Clapboard	Asphalt				Includes 2 coops, a wire mesh corn crib and a windmill	3q	22	17	
1248	1735400007	1	House	Upright and Wing	N / A	1860-1890	Very Poor	Poor		Aluminum Siding	Asphalt		Many		Abandoned	3q	29	17	
1248	1735400007	2	House	Tri-level	N / A	1950-present	Good	Good		Aluminum Siding	Asphalt				Second house on site	3q	30	17	
1248	1735400007	3	Corn Crib	Transverse Aisle	N / A		Fair	Good		Horizontal Slats	Wood Shingles				Both bays slatted	3q	31	17	
1605	1736100012	1	House	Upright and Wing	N / A	1860-1890	Fair	Good	Field Stone	Asbestos	Wood Shingles	Altered	Major addition		Expanded beyond original house, but current owners are starting to restore this house	3q	17	17	
1605	1736100012	2	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt				Includes concrete staved silo with no roof and a front gabled attached milkhouse	3q	16	17	
1605	1736100012	3	Chicken Coop	Slant-roofed	N / A		Very Poor	Fair		Clapboard	Asphalt				2 Coops put together	3q	14	17	
1605	1736100012	4	Chicken Coop	Slant-roofed	N / A		Poor	Fair		Clapboard	Asphalt				That makes coop number three; includes a front gabled shed	3q	13	17	
1605	1736100012	5	Chicken Coop	Slant-roofed	N / A		Fair	Good		Clapboard	Asphalt				Never enough chicken coops	3q	18	17	
1605	1736100012	6	Garage	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				2 Car doors	3q	15	17	
1604	1736200005	1	House	Side Gabled	N / A	1860-1880	Very Poor	Poor	Field Stone	Clapboard	Asphalt	Enclosed	Windows, etc.		Abandoned	3q	1	17	
1604	1736200005	2	Barn	Dairy Gambrel	N / A	1880-1920	Poor	Good		Vertical Wood	Tin (Flat)				Includes 2 concrete staved silo with metal dome roofs	3q	3	17	
1604	1736200005	3	Barn	Three-bay Threshing	N / A	1860-1880	Falling down	Poor		Vertical Wood	none					3q	4	17	
1604	1736200005	4	Chicken Coop	Slant-roofed	N / A		Falling down	Poor		Beveled Clapboard	Asphalt					3q	2	17	
1601	1736200008	1	House	Upright and Wing	N / A	1860-1890	Fair	Fair		Aluminum Siding	Asphalt				This site is set way off the road and is now a landscape business; it was heavily gated so there was no access; however, the house and dairy gambrel barn still exist and are barely visible	3q	5	17	
1602	1736300003	1	House	Ranch	N / A	1950-present	Good	Good		Aluminum Siding	Asphalt				Hipped roof; replacement house	3q	11	17	
1602	1736300003	2	Outhouse	Side Gabled	N / A		Excellent (R)	Excellent		Beveled Clapboard	Wood Shingles					3q	6	17	
1602	1736300003	3	Barn	Dairy Gambrel	N / A	1880-1920	Falling down	Poor		Vertical Wood	Asphalt					3q	9	17	
1602	1736300003	4	Shed	Front Gabled	N / A		Poor	Good		Beveled Clapboard	Asphalt					3q	8	17	
1602	1736300003	5	Corn Crib	Transverse Aisle	N / A		Poor	Fair		Diagonal Slats	Tin (Flat)				One bay is solid and the other has diagonal slats which are rare in this part of the county; too bad it is in such bad shape	3q	10	17	
1602	1736300003	6	Shed	Front Gabled	N / A		Poor	Good		Tin (Flat)	Rolled Asphalt				Open sided; also includes small tin covered side gabled shed	3q	7	17	
1603	1736400001	1	House	Ranch	N / A	1950-present	Fair	Fair		Aluminum Siding	Asphalt				"Hired hand's" house for the abandoned farm next door on site 1604	3q	12	17	