

Previous Site	Pin Number	Pin Suffix	Structure Type	Vernacular Form	Architectural Style	Circa	Condition	Integrity	Foundation	Walls	Roof	Porch	Alterations	History	Roll	Photo	Pin Prefix
2069	0401400017	1	House	Four-over-four	Italianate	1860-1880	Good	Fair	Field Stone	Aluminum Siding	Asphalt	Enclosed	New windows and siding, but the second story still has all of its original 2-over-2 windows	This farmstead on Zarnstoff Road is still in the Zarnstoff family. This is one of the older houses of this form that is a vernacular version of the Italianate style, not a Foursquare.	a	2	4
2069	0401400017	2	House		N / A									Second view to show the side wing which may be part of the original house	a	3	4
2069	0401400017	3	Shed	Side Gabled	N / A		Good	Good	Poured Concrete	Tin (Flat)	Tin (Flat)			Open Livestock shed	a	4	4
2069	0401400017	4	Garage	Front Gabled	N / A	1910-1940	Good	Good		Beveled Clapboard	Asphalt				a	5	4
2069	0401400017	5	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				a	6	4
2069	0401400017	6	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Includes 3 silos - one concrete staved silo with a metal dome roof and 2 "A.O.Smith Harvestore" silos (metal with a glass-lining)	a	7	4
2069	0401400017	7	Grain Bin	Round	N / A		Fair	Good		Tin (Corrugated)	Tin (Flat)			Also includes huge metal pole barn	a	8	4
2069	0401400017	8	Barn	Dairy Gambrel	N / A		Good	Good	Cement Block	Vertical Wood	Asphalt			Added onto to big barn for extra milking stalls	a	9	4
2069	0401400017	9	Milkhouse	Front Gabled	N / A		Fair	Good		Beveled Clapboard	Asphalt			Has shed addition in poor condition	a	10	4
2069	0401400017	10	Barn	Transverse Frame	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Note vented cupola; also has a small extension wing	a	11	4
2069	0401400017	11	Chicken Coop	Front Gabled	N / A		Good	Fair		Vertical Wood	Asphalt			May have been hog house; also includes yet another metal pole barn	a	12	4
2060	0402351005	1	House	Upright and Wing	Greek Revival	1850-1870	Good	Fair		Clapboard	Asphalt	Open, inset	New windows, siding and large deck on back	Cornice returns remain; used as a hunting lodge	b	4	4
2060	0402351005	2	Shed	Front Gabled	N / A	1910-1940	Fair	Fair		Clapboard	Asphalt		Windows changed and other modifications	Warming area for hunters	b	5	4
2060	0402351005	3	Barn	Dairy Gambrel	N / A	1910-1940	Fair	Good		Vertical Wood	Asphalt			Unusually short version; includes poured concrete silo with poured conical roof and detached milkhouse	b	6	4
2060	0402351005	4	Corn Crib	Transverse Aisle	N / A		Good	Good		Clapboard	Asphalt		Slatted area has been covered in clapboard and converted into storage shed		b	8	4
2060	0402351005	5	Shed	Front Gabled	N / A		Fair	Good		Clapboard	Asphalt				b	9	4
2019	0404300002	1	House	Four-over-four	Foursquare	1910-1940	Fair	Fair		Stucco	Asphalt		Added onto several times	Converted to a tavern with owner living above; also includes molded block shed	c	18	4
2019	0404300002	2	House		N / A									Second view to show Foursquare features prior to being converted into a tavern	c	17	4
2020	0404400016	1	House	Upright and Wing	N / A	1860-1880	Good	Poor		Vinyl Siding	Asphalt		Siding, windows, rear addition	Across from old Catholic church site (cemetery still across road to other side, but church moved into Richmond)	c	7	4
2020	0404400016	2	Garage	Pyramidal	N / A	1930-1950	Good	Good		Vinyl Siding	Asphalt			2-car	c	16	4
2020	0404400016	3	Barn	Three-bay Threshing	N / A	1860-1880	Poor	Poor		Wood Shingles	Tin (Flat)		Converted into shed and now in very bad shape	Shingles have worn to a point where this very visible eyesore looks "shaggy"	c	9	4
2020	0404400016	4	Chicken Coop	Slant-roofed	N / A		Poor	Poor		Wood Shingles	Tin (Flat)		Windows changed and resided with shingles	Attached to barn	c	8	4
2020	0404400016	5	Corn Crib	Transverse Aisle	N / A		Fair	Good		Horizontal Slats	Tin (Flat)				c	10	4
2021	0404400023	1	House	Four-over-four	Italianate	1850-1870	Good	Fair		Aluminum Siding	Asphalt	Open	Added onto multiple times	Has had most details removed including a widow's walk	c	13	4
2021	0404400023	2	Barn	Transverse Frame	N / A	1860-1890	Good	Good		Vertical Wood	Asphalt		Vents replaced with smaller ones and windows changed		c	12	4
2021	0404400023	3	Shed	Side Gabled	N / A	1940-1950	Good	Good		Tin (Corrugated)	Tin (Corrugated)			Early tin building made with the wide corrugated tin	c	15	4
2021	0404400023	4	Garage	Front Gabled	N / A	1950-present	Good	Good		Tin (Flat)	Tin (Flat)			Double-wide door	c	14	4
2022	0404400028	1	vacant		N / A									All Gone!	c	11	4
2020.5	0404451002	1	House	Upright and Wing	N / A	1860-1890	Fair	Poor		Aluminum Siding	Asphalt	Enclosed	Additions, alum. Siding, new windows, etc.	This farmstead was developed into "Andre's Steakhouse", "Days Inn" and a subdivision	c	6	4
2036	0406300003	1	House	Four-over-four	N / A		Fair	Fair		Aluminum Siding	Asphalt	Open		Has dormer, but needs more inspection to determine if it is the older or newer version of the 2-story pyramidal cube	h	30	4
2036	0406300003	2	Chicken Coop	Uneven Gable	N / A		Fair	Good		Clapboard	Asphalt				h	32	4
2036	0406300003	3	Shed	Side Gabled	N / A		Good	Good		Clapboard	Asphalt		Had a modern garage door put on one bay	Machine shed attached to chicken coop	h	33	4
2037	0406300003	4	House	Cottage	Cape Cod	1910-1940	Good	Good		Vinyl Siding	Asphalt		Shed addition to the side	On this site there was a similar house illustrated in the 1872 Plat Book, however further examination would need to be done to determine if the old house is inside of this one or not	h	31	4
2037	0406300003	5	Barn	Dairy Gambrel	N / A	1910-1940	Fair	Good		Clapboard	Asphalt			Note the surface is covered in clapboard instead of the more common vertical siding; also includes a poured concrete silo with a concrete conical roof and a attached milk house	h	34	4
2028	0406400006	1	House	Four-over-four	N / A	1880-1930	Good	Fair		Vinyl Siding	Asphalt		Modern deck added to the front along with the other modernizations	Not enough evidence to date this as either the newer or older version of this basic form; site is now rented as a fish hatchery	m	29	4
2028	0406400006	2	Barn	Gothic Arched	N / A	1900-1930	Good	Good		Tin (Flat)	Tin (Flat)		Front office area added	Includes 2 concrete staved silos with metal dome roofs	m	27	4
2028	0406400006	3	Outhouse	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt		Added big window	Was converted to a playhouse	m	30	4
2028	0406400006	4	Barn	Gothic Arched	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Added onto the big barn; also includes covered fish hatchery	m	28	4
2028	0406400006	5	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Huge buildings used for storage	m	26	4
2034	0406400007	1	House	Cottage	N / A	1910-1940	Good	Fair	Poured Concrete	Aluminum Siding	Asphalt				m	18	4
2034	0406400007	2	Barn	Dairy Gambrel	N / A	1910-1940	Good	Good		Vertical Wood	Asphalt				m	24	4
2034	0406400007	3	Garage	Pyramidal	N / A	1910-1940	Good	Good		Molded Block	Asphalt			2-car	m	20	4
2034	0406400007	4	Shed	Front Gabled	N / A		Good	Good	Cement Block	Beveled Clapboard	Asphalt				m	19	4
2034	0406400007	5	Shed	Side Gabled	N / A	1910-1940	Good	Good		Tin (Flat)	Tin (Flat)			Roof curves down onto wall	m	22	4
2034	0406400007	6	Grain Bin	Round	N / A		Good	Good		Tin (Flat)	Tin (Flat)				m	21	4
2034	0406400007	7	Corn Crib	Uneven Gable	N / A		Good	Good		Tin (Flat)	Tin (Flat)		Windows have been changed and covered with tin		m	23	4
2038	0407100001	1	House	Upright and Wing	Italianate	1860-1898	Good	Fair	Field Stone	Aluminum Siding	Asphalt	Original, open	Some trim was removed but most still exist, but the windows were changed when the siding was added	Notice the porch trim, decorative window hood moldings and the 2-story decorative bay; very large active farm; big house built in 1898	h	20	4
2038	0407100001	2	Garage	Front Gabled	N / A		Good	Good		Aluminum Siding	Asphalt			1-car, attached	h	23	4
2038	0407100001	3	House	Upright and Wing	N / A	1850-1870	Fair	Poor	Cement Block	Aluminum Siding	Asphalt		Original house burned; this back part was brought over from Hebron	Notice the cornice returns on the back wing of this house - - - this is the evidence of the original Greek Revival house that this started out as and then expanded into the big Italianate house	h	29	4
2038	0407100001	4	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				h	21	4

2038	0407100001	5	Hog House	Front Gabled	N / A	1942	Fair	Good		Beveled Clapboard	Tin (Flat)			Includes 2-car garage converted from corn crib	h	24	4
2038	0407100001	6	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Includes 2 Concrete staved silos with metal dome roofs	h	22	4
2038	0407100001	7	Grain Bin	Round	N / A		Good	Good		Tin (Corrugated)	Tin (Flat)			Includes 3 bins and a hopper	h	25	4
2038	0407100001	8	Grain Dryer		N / A		Good	Good		Tin (Flat)	Tin (Flat)				h	26	4
2038	0407100001	9	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				h	27	4
2038	0407100001	10	Shed	Slant-roofed	N / A		Good	Good		Tin (Flat)	Tin (Flat)				h	28	4
2035	0407100005	1	House	Upright and Wing	N / A	1880-1900	Good	Fair	Poured Concrete	Clapboard	Asphalt	Open with trim	Windows have been changed	Note gable fret-work and decorative trim on porch	h	35	4
2035	0407100005	2	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				h	36	4
2053	0407300002	1	House	Upright and Wing	Greek Revival	1850-1870	Fair	Poor	Field Stone	Aluminum Siding	Asphalt	Enclosed	Many - windows, siding and most everything else	1872 Plat Book illustration house, but not very recognizable	n	2	4
2053	0407300002	2	Garage	Side Gabled	N / A		Fair	Fair		Tin (Flat)	Tin (Flat)			Part of the "Crop Production Services" fertilizer business	n	3	4
2053	0407300002	3	Silo	Poured Concrete	N / A		Good	Good		Poured Concrete	Concrete Conical			Also includes a larger poured concrete silo with a metal dome roof	n	4	4
2053	0407300002	4	Storage Tanks	Round	N / A		Good	Good		Metal	Metal			7 Storage tanks	n	5	4
2053	0407300002	5	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Older barn covered with tin with another newer metal pole barn added	n	6	4
2053	0407300002	6	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Very large railroad building	n	7	4
2053	0407300002	7	House	Cottage	N / A		Fair	Fair		Vinyl Siding	Asphalt				n	8	4
2052	0407300006	1	House	Four-over-four	Foursquare	1900-1930	Good	Good		Vinyl Siding	Asphalt	Enclosed		Foursquare with roof balcony	n	9	4
2052	0407300006	2	Barn	Transverse Frame	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt		Non-altered	Excellent symmetry	n	15	4
2052	0407300006	3	Corn Crib	Transverse Aisle	N / A	1910-1940	Excellent (Restored)	Excellent		Horizontal Slats	Wood Shingles			Has gambrel roof and perpendicular gambrel vent; one of the few of this style of corn cribs in the area; most of this style are further south towards Kane County	n	12	4
2052	0407300006	4	Milkhouse	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Detached	n	14	4
2052	0407300006	5	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome				n	13	4
2052	0407300006	6	Chicken Coop	Uneven Gable	N / A		Good	Good		Vertical Wood	Asphalt			Also includes metal pole barn in behind	n	10	4
2052	0407300006	7	Garage	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				n	11	4
2054	0407400001	1	House	Bungalow	N / A	1930-1950	Good	Good		Vinyl Siding	Asphalt				m	36	4
2054	0407400001	2	Garage	Pyramidal	N / A	1950-present	Good	Good		Cement Block	Asphalt			4-car rectangular structure with hipped roof	m	35	4
2054	0407400001	3	Shed	Front Gabled	N / A		Good	Good		Plywood	Asphalt				m	37	4
2054.5	0407400001	4	House	Cottage	N / A		Fair	Good		Vinyl Siding	Asphalt			Second house on site, but of the south side of the road	m	34	4
2054.5	0407400001	5	Shed	Quonset	N / A		Fair	Good		Tin (Corrugated)	Tin (Flat)				n	1	4
2030	0407400004	1	vacant		N / A									All Gone! This was one of the few dual siding Greek Revival houses that still was in its original form, but the farm was bought for development and the house taken down. At least some materials were reused in other houses.	m	33	4
2027	0408100001	1	House	I-house	N / A	1860-1880	Good	Fair	Field Stone	Aluminum Siding	Asphalt		Porches have been enclosed; note that big barn is gone	I-house with intersecting gable back wing and the original 2-over-2 windows	m	17	4
2027	0408100001	2	Garage	Side Gabled	N / A		Poor	Good		Aluminum Siding	Asphalt			Combination Cape Cod cottage and garage	m	16	4
2027	0408100001	3	Garage	Side Gabled	N / A		Fair	Good		Aluminum Siding	Asphalt			Double door with bay window	m	15	4
2026	0408100004	1	House	Ranch	N / A	1950-present	Good	Good	Granite	Vinyl Siding	Asphalt			Second house on site; original house taken down in the mid 1980's to put up this one. The original house had a log cabin inside of it but was not saved.	m	12	4
2026	0408100004	2	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				m	11	4
2026	0408100004	3	Barn	Dairy Gambrel	N / A		Falling down	Poor		Vertical Wood	Asphalt			Across road on cell tower site; also includes concrete staved silo	m	13	4
2026	0408100004	4	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome				m	14	4
2024	0408100005	1	House	Upright and Wing	Greek Revival	1852	Excellent (Restored)	Excellent	Field Stone	Clapboard	Wood Shingles	Enclosed	Porch was removed, but had been "Queen Anne'd" at the turn-of-the-century, the look without it is more pure Greek Revival	One of the farmstead with the best historic integrity - - - This is William McConnel's first frame house which he later deeded over to his son, John; This one is a potential landmark house	p	6	4
2024	0408100005	2	Barn	Three-bay Threshing	N / A	1870-1900	Excellent (Restored)	Excellent		Vertical Wood	Wood Shingles			Beautifully restored with an attention to every detail.	p	7	4
2024	0408100005	3	Windmill		N / A		Good	Good		Steel				Complete with bladed!	p	8	4
2024	0408100005	4	Chicken Coop	Front Gabled	N / A		Good	Good		Clapboard	Wood Shingles		Converted possible original detached summer kitchen to chicken coop/shed	Notice original 6-over-6 windows that were moved from the house	p	9	4
2024	0408100005	5	House		N / A		Good	Good		Clapboard	Wood Shingles		The footprint has been unchanged, with the only exterior change being the addition of the cupola	The back wing which used to be the kitchen and woodshed was made into living area complete with using all old doors from the George Myers house (site 2030) and every detail perfect!	p	10	4
2024	0408100005	6	Garage	Side Gabled	N / A	1950-present	Good	Good		Vertical Wood	Tin (Flat)			Built new to be historically appropriate with the site; had workshop in back in the shed portion	p	11	4
2029	0408300001	1	House		N / A	1930-1950	Good	Good	Poured Concrete	Brick	Asphalt			Former school converted to a house; second school on this site; locally known as "Montalona School"	m	31	4
2029	0408300001	2	Garage	Front Gabled	N / A		Good	Good		Vinyl Siding	Asphalt			1 double door	m	32	4
2032	0408300002	1	House	Four-over-four	Italianate	1860-1880	Good	Good	Field Stone	Asbestos	Asphalt	Original - open	Cresting at peak removed; windows changed	This is the older version of a simplified Italianate not a Foursquare	o	22	4
2032	0408300002	2	House	Ranch	Ranch	1930-1950	Good	Good	Poured Concrete	Aluminum Siding	Asphalt			Also includes attached garage	o	21	4
2032	0408300002	3	Garage	Pyramidal	N / A	1930-1950	Good	Good		Beveled Clapboard	Asphalt				o	23	4
2032	0408300002	4	Barn	Dairy Gambrel	N / A	1880-1920	Excellent (Restored)	Excellent		Vertical Wood	Tin (Flat)			Includes concrete staved silo with metal gambrel roof and also includes attached milkhouse	o	24	4
2032	0408300002	5	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Tin (Gambrel)			2nd silo behind barn; also includes a small shed caving-in	o	25	4
2032	0408300002	6	Chicken Coop	Slant-roofed	N / A		Fair	Good		Beveled Clapboard	Asphalt				o	26	4
2032	0408300002	7	Shed	Side Gabled	N / A		Fair	Fair		Cement Block	Asphalt			Machine shed that had cement black ends added	o	27	4

2032	0408300002	8	Corn Crib	Octagonal	N / A		Poor	Good		Diagonal Slats	Asphalt			Includes 2 corn cribs: the octagonal one is the only octagonal corn crib left in Richmond Township; the other is a transverse aisle crib with an uneven gable and horizontal slats	o	28	4
2033	0408300008	1	House	Side Gabled	N / A		Good	Fair		Vinyl Siding	Asphalt		Addition to side and back entry added		p	12	4
2033	0408300008	2	Garage	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				p	13	4
2033	0408300008	3	Shed	Cottage	N / A	1930-1950	Fair	Fair		Tin (Flat)	Asbestos			Converted into warming house for hunt club.	p	14	4
2033	0408300008	4	Milkhouse	Side Gabled	N / A		Fair	Fair		Vertical Wood	Asphalt			Detached	p	15	4
2033	0408300008	5	Barn	Three-bay Threshing	N / A	1860-1890	Very Poor	Poor		Vertical Wood	Asphalt			Was in the process of being taken down when photo was taken and has since been totally removed (at least the boards were salvaged)	p	16	4
2033	0408300008	6	Shed	Front Gabled	N / A		Good	Good	Poured Concrete	Vertical Wood	Asphalt			Livestock quarters	p	17	4
2033	0408300008	7	Pumphouse	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				p	18	4
2033	0408300008	8	House	Cottage	N / A		Good	Fair		Plywood	Asphalt		Recently redone and is now being lived in again		p	21	4
2033	0408300008	9	Barn	Dairy Gambrel	N / A	1900-1930	Fair	Good		Vertical Wood	Asphalt			Includes large gambrel side wing and concrete staved silo with no roof	p	19	4
2033	0408300008	10	Shed	Side Gabled	N / A		Fair	Fair		Tin (Flat)	Tin (Flat)			Machine shed	p	20	4
2023	0408400015	1	House	Upright and Wing	Greek Revival	1870	Good	Good	Field Stone	Clapboard	Asphalt	Open, inset	Rear porch redone and enlarged; asphalt siding added on top of the clapboard	On the site of William McConnel (founder of Richmond) log cabin; all original doors, windows, plaster, floors; 1872 Plat Book illustration house; site of first cheese factory in entire county	c	19	4
2023	0408400015	2	House		N / A									Second view to show rear original summer kitchen and wood shed. Contrary to common belief extra wings were not necessarily additions but just the way houses were constructed in sections.	c	20	4
2023	0408400015	3	Barn	Composite	N / A	1880-1920	Good	Excellent	Field Stone	Vertical Wood	Asphalt			This is an amazing barn particularly when standing inside and viewing the multi-levels (5 levels).	c	21	4
2023	0408400015	4	Barn	Transverse Frame	N / A	1840-1850	Good	Good		Vertical Wood	Asphalt		When this barn was moved it was rotated 180 degrees to face the other direction	This barn is made of all hand-hewn timbers, some of which are a full 16 inches wide. It is the original barn period to William McConnel's log cabin.	c	22	4
2023	0408400015	5	Shed	Front Gabled	N / A	1860-1890	Good	Good	Field Stone	Vertical Wood	Asphalt		Access door was cut out and hinged to convert this to a garage	This is a double-lined building that was either used as a grainery or as an ice house. It is also up on large boulders so that there is complete air flow below it.	c	23	4
2023	0408400015	6	Chicken Coop	Uneven Gable	N / A	1880-1900	Good	Fair		Beveled Clapboard	Asphalt		It used to be a broken eave structure with a row of windows at the roof line, but it was filled in the last time it was re-roofed.	Has served as a chicken coop for years. The concrete floor was poured after it was built and the concrete floor is dated 1919.	c	24	4
2023	0408400015	7	Milkhouse	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Attached with walkway to main barn; note that there also 2 poured concrete silos - one with a poured conical roof and one with a metal dome roof.	p	4	4
2023	0408400015	8	House	Front Gabled	N / A	1860-1880	Fair	Fair	Field Stone	Clapboard	Asphalt		This structure had a large shed addition put on the south side.	This is the original "hired hands" or servants living quarters. It more recently was on apartment, but now needs quite a bit of work, however, it still is stable.	p	2	4
2023	0408400015	9	Corn Crib	Slant-Sided	N / A	1880-1920	Good	Good		Horizontal Slats	Asphalt			This was once a popular size for small quantities of corn, rather than its transverse aisle counterparts. This size was all that necessary since this farm was not for large production, but for personal consumption.	p	3	4
2023	0408400015	10	Hog House	Uneven Gable	N / A		Good	Good		Beveled Clapboard	Asphalt			Elaborate concrete on the inside, obviously they had the means to build structures right.	p	5	4
2023	0408400015	11	Corn Crib	Round	N / A		Good	Good		Wire Mesh	Tin (Flat)			Bottom vent still there	p	1	4
2025	0408400016	1	House	Bungalow	Bungalow	1910-1940	Good	Excellent	Molded Block	Clapboard	Asphalt	Open, original		This is one of the best examples of Bungalow architecture in the area, but its longevity is questionable since a subdivision has been planned by the current owner.	m	9	4
2025	0408400016	2	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good	Molded Block	Vertical Wood	Asphalt			Beautiful site with all farm building in matching molded concrete block foundations	m	6	4
2025	0408400016	3	Milkhouse	Pyramidal	N / A	1910-1940	Good	Good		Molded Block	Asphalt			Rectangular hipped roof version, detached	m	7	4
2025	0408400016	4	Shed	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Machine shed, but note decorative panels on doors	m	8	4
2025	0408400016	5	House	Ranch	N / A	1950-present	Good	Good		Brick	Asphalt			Second house on site	m	10	4
2055	0410100001	1	House	Upright and Wing	Italianate	1870-1890	Good	Fair		Vinyl Siding	Asphalt		New windows on second floor, lots of decorative moldings removed, sided over and rear wing was remuddled	There is pictorial evidence of how showy and elaborate this house used to be. There was ornamentation that came down and practically covered the gables - lots of fret-work	b	34	4
2055	0410100001	2	House		N / A									Second view to show rear wing with inset porch and 2-over-2 windows	c	1	4
2055	0410100001	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Hunt Club business	c	3	4
2055	0410100001	4	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				c	5	4
2055	0410100001	5	Garage	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				b	35	4
2055	0410100001	6	Shed	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				c	2	4
2055	0410100001	7	Chicken Coop	Front Gabled	N / A		Good	Good		Asbestos	Asphalt			Brood huts for the pheasants and other game that is raised for shooting at this hunt club	c	4	4
2058	0410200016	1	House	Upright and Wing	Spanish Colonial	1920-1940	Good	Good		Brick	Clay Tile			Rambling house with secondary structure connected in wings.	b	24	4
2058	0410200016	2	House	Upright and Wing	N / A		Good	Fair		Beveled Clapboard	Asphalt			Original house on site remodeled to have more of a 1930's appearance to compliment the new 1930's house. This was used as a caretaker's house and also includes a small detached garage.	b	23	4
2056	0410300002	1	House	Cottage	N / A	1880-1900	Good	Good		Vinyl Siding	Asphalt		Newer side wing addition	Former school	b	31	4
2056	0410300002	2	Garage	Front Gabled	N / A	1910-1940	Good	Good		Clapboard	Asphalt			1-Car	b	32	4
2056	0410300002	3	Shed	Slant-roofed	N / A		Fair	Good		Beveled Clapboard	Asphalt			Long machine shed type	b	33	4
2218	0410400005	1	House	I-house	N / A	1880-1900	Fair	Fair	Field Stone	Aluminum Siding	Asphalt	Removed	New windows, siding and additions	Commercial property	b	20	4
2218	0410400005	2	House		N / A									Second view to show major back wing and added enclosed porches; plan is intersecting gables	b	21	4
2218	0410400005	3	Barn		N / A		Good	Good		Cement Block	Asphalt			Huge building with window look-outs in back and loading bays.	b	19	4
2218	0410400005	4	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				b	18	4
2218	0410400005	5	Garage	Slant-roofed	N / A		Good	Good		Tin (Flat)	Tin (Flat)				b	22	4
2057	0410400009	1	House	Four-over-four	Foursquare	1900-1930	Good	Poor		Vinyl Siding	Asphalt		Very altered with different sized windows and entrances changed	Former farm, then antique store, now a horse stable business	b	25	4
2057	0410400009	2	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			ALL GONE! Has since burned to the ground in an accidental fire that killed several horses	b	26	4
2057	0410400009	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				b	27	4

2057	041040009	4	Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Asphalt			Combination bays of one solid and one slatted	b	29	4
2057	041040009	5	Shed	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Livestock barn	b	30	4
2074	041110004	1	vacant		N / A									All Gone! Burned for fire training practice; was the Miller family farmstead	b	3	4
2073	041120003	1	House	Cottage	N / A	1900-1930	Good	Good		Clapboard	Wood Shingles			Was formerly a school, "Washington School"	b	2	4
2073	041120003	2	Garage	Front Gabled	N / A		Good	Good		Clapboard	Wood Shingles			Detached garage but with an attached walkway	b	1	4
2073.5	041120004	1	House	Cottage	N / A		Good	Good		Clapboard	Asphalt			Second house on Washington School site (was teacher's house), but split off into a separate parcel when school was converted into a house.	a	36	4
2072	041120006	1	House	Upright and Wing	N / A	1860-1880	Fair	Good	Field Stone	Wood Shingles	Asphalt	Enclosed	Windows changed and siding changed to wood shingles	Part of an organic farming operation	a	26	4
2072	041120006	2	House		N / A								Rear porch also enclosed	Second view to show rear wing of house	a	32	4
2072	041120006	3	Barn	Transverse Frame	N / A	1880-1920	Good	Good	Molded Block	Vertical Wood	Asphalt			Interesting skewed uneven gable	a	29	4
2072	041120006	4	Silo	Poured Concrete	N / A		Good	Good		Poured Concrete	Concrete Conical			Also shows shed addition of back of barn	a	35	4
2072	041120006	5	Milkhouse	Slant-roofed	N / A		Fair	Good		Molded Block	Poured Concrete		Windows and door gone		a	30	4
2072	041120006	6	Shed	Front Gabled	N / A		Poor	Fair		Clapboard	Tin (Flat)		Shed additions	May have been the original barn period to the house	a	28	4
2072	041120006	7	Shed	Side Gabled	N / A		Poor	Fair		Vertical Wood	Asphalt		Shed additions		a	27	4
2072	041120006	8	Chicken Coop	Side Gabled	N / A		Fair	Fair		Clapboard	Asphalt			Converted into a greenhouse	a	33	4
2059	041130001	1	House	Upright and Wing	N / A		Poor	Fair		Asbestos	Asphalt	Open		Abandoned and soon will be demolished as a subdivision has been proposed for this farm	b	17	4
2059	041130001	2	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			Also includes concrete staved silo with metal dome roof	b	10	4
2059	041130001	3	Milkhouse	Front Gabled	N / A		Fair	Good		Cement Block	Wood Shingles			Attached	b	13	4
2059	041130001	4	Chicken Coop	Slant-roofed	N / A		Good	Good		Beveled Clapboard	Asphalt		Windows changed		b	15	4
2059	041130001	5	Shed	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Corrugated)			Early version in bad shape	b	11	4
2059	041130001	6	Shed	Side Gabled	N / A		Poor	Good		Tin (Corrugated)	Tin (Corrugated)			Machine shed	b	12	4
2059	041130001	7	House	House Trailer	N / A		Poor	Good		Tin (Flat)	Tin (Flat)				b	14	4
2071.5	041210001	1	House	Upright and Wing	N / A	1860-1880	Fair	Fair	Field Stone	Aluminum Siding	Asphalt	Open		Unusually tall side wing; adaptive reuse into a home business selling antique motorcycle parts, rugs, and metal sculpture	a	17	4
2071.5	041210001	2	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			Includes poured concrete silo; 1916 Sears barn according to owner	a	20	4
2071.5	041210001	3	House	Trailer	N / A		Poor	Good		Tin (Flat)	Tin (Flat)			Includes slant-roofed shed	a	19	4
2071.5	041210001	4	Shed	Slant-roofed	N / A		Fair	Good		Terra Cotta Tile	Asphalt				a	22	4
2071.5	041210001	5	Garage	Slant-roofed	N / A		Fair	Good		Tin (Corrugated)	Asphalt			Combination of slant-roofed garage, front-gabled shed and slant-roofed chicken coop made into a shed - all using various materials	a	21	4
2071.5	041210001	6	Shed	Side Gabled	N / A		Poor	Good		Tin (Flat)	Asphalt			3 more sheds	a	23	4
2071.5	041210001	7	Shed	Uneven Gable	N / A		Fair	Good		Asbestos	Tin (Flat)				a	24	4
2071.5	041210001	8	Shed	Slant-roofed	N / A		Fair	Good		Vertical Wood	Tin (Flat)			This shed is part of the original barn	a	25	4
2071.5	041210001	9	Gazebo		N / A		Good	Good		Wood Shingles	Asphalt				a	18	4
2070	041210004	1	House	Ranch	Ranch	1930-1950	Good	Good	Poured Concrete	Brick	Asphalt			Original house set back farther from road	1b	17	4
2070	041210004	2	Barn	Transverse Frame	N / A	1880-1920	Fair	Good		Vertical Wood	Asphalt		Older barn removed from site	Includes 2 concrete staved silos with metal dome roofs; note that this farm used to be a chicken farm. Long chicken coop have been removed from site	a	13	4
2071	041230017	1	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			This is built over the original barn foundation; old house was replaced with new house; site of "Richmond Country Market"	a	16	4
2071	041230017	2	Silo	Poured Concrete	N / A		Good	Good	Concrete Conical	Poured Concrete	Asphalt				a	15	4
2071	041230017	3	Milkhouse	Front Gabled	N / A		Good	Good	Poured Concrete	Cement Block	Asphalt				a	14	4
2718	041310004	1	House	Upright and Wing	N / A	1880-1900	Good	Good		Vinyl Siding	Asphalt	Open	New windows, but same size; resided; porch redone, but better than it was at previous survey photo	Back of the house is the oldest section according to the owner	1c	19	4
2720	041310007	1	House	Upright and Wing	N / A	1860-1880	Good	Good	Field Stone	Vinyl Siding	Asphalt	Open	The upper upright has 6-over-6 windows and all others are 2-over-2 windows	House was in the Winn family as in Winn Road	2a	25	4
2720	041310007	2	Barn	Gothic Arched	N / A	1910-1940	Good	Good	Poured Concrete	Vertical Wood	Asphalt			Has attached milkhouse with roof caving in and small slant-roofed shed	2a	3	4
2720	041310007	3	Silo	Brick	N / A	1880-1920	Falling down	Fair		Brick	none			Double layered brick chimney; outer coat of red brick has mostly broken away; lighter colored brick is still partially intact	d	2	4
2720	041310007	4	Garage	Front Gabled	N / A		Good	Good		Vinyl Siding	Asphalt				2a	26	4
2719	041310009	1	House	Upright and Wing	N / A	1870-1890	Good	Poor		Clapboard	Asphalt		New windows put in that are much smaller; porches changed; plus the other normal changes	Altered, but kept in condition	a2	23	4
2719	041310009	2	Shed	Front Gabled	N / A		Good	Good		Clapboard	Asphalt				a2	21	4
2719	041310009	3	Garage	Side Gabled	N / A		Good	Good		Clapboard	Asphalt			Extra wide 2-car	a2	2	4
2719	041310009	4	Shed	Front Gabled	N / A		Poor	Fair		Clapboard	Asphalt				d	1	4
2731	041320011	1	House	Ranch	N / A		Good	Good		Aluminum Siding	Asphalt			On site of "Imerson" Log cabin; second house in back is on the exact site, but it is not known whether any of the log cabin remains inside	b2	14	4
2731	041320011	2	Shed	Quonset	N / A		Good	Good		Tin (Corrugated)	Tin (Flat)			Includes 2 other metal pole barns and is used as a horse stable	b2	16	4
2731	041320011	3	Garage	Side Gabled	N / A		Good	Good		Aluminum Siding	Asphalt				b2	15	4
2720.2	041330010	1	House	Upright and Wing	N / A	1850-1870	Good	Good	Field Stone	Clapboard	Asphalt	Open	Porch railings are new, most everything else original	Formerly Walter Winn's house (founder of the "Pure Milk Association"); this is an interesting site with an owner/farmer that has a tremendous depth of historical knowledge of the area.	d	8	4
2720.2	041330010	2	Barn	Transverse Frame	N / A	1908	Good	Good	Molded Block	Vertical Wood	Asphalt		Lower doors changed	Also includes a poured concrete silo which was built in 1909	d	6	4
2720.2	041330010	3	Garage	Side Gabled	N / A	1910-1940	Good	Good		Beveled Clapboard	Tin (Flat)			Note older style garage doors	d	28	4
2720.2	041330010	4	Shed	Side Gabled	N / A		Good	Good		Vertical Wood	Tin (Flat)				d	7	4

2720.2	0413300010	5	Shed	Side Gabled	N / A		Falling down	Poor		Beveled Clapboard	Asphalt			Machine shed	d	18	4
2720.2	0413300010	6	Corn Crib	Slant-Sided	N / A		Fair	Good		Horizontal Slats	Tin (Flat)			Small rectangular corncrib	d	4	4
2720.2	0413300010	7	Pumphouse	Side Gabled	N / A		Fair	Good		Clapboard	Tin (Flat)				d	3	4
2720.2	0413300010	8	Shed	Front Gabled	N / A		Good	Good		Vinyl Siding	Asphalt			3 Small sheds used for poultry cover	d	5	4
2720.5	0413400005	1	House	Upright and Wing	Greek Revival	1850-1860	Fair	Poor	Cobblestone	Vinyl Siding	Asphalt	Open but smaller	Many, but the cornice returns still remain	This site is not even visible from the road since it is just past a crest of a hill. I only discovered this site due to 1872 Plat Book research. There are 2 Plat Book illustration houses on this site.	d	13	4
2720.5	0413400005	2	House		N / A									Second picture to show the detail of the cobblestone foundation. Although the cobblestone is more south in the county, his neighbor was a mason by trade.	d	14	4
2720.5	0413400005	3	House	Upright and Wing	Carpenter Gothic	1860-1870	Good	Excellent		Clapboard	Asphalt	Original, open		This house is not only an 1872 Plat Book house, but it was moved from Richmond when the new Catholic church was built.	d	10	4
2720.5	0413400005	4	Barn	Dairy Gambrel	N / A	1890-1940	Good	Good		Beveled Clapboard	Asphalt			Includes poured concrete silo with a conical roof	d	11	4
2720.5	0413400005	5	Barn	Dairy Gambrel	N / A		Poor	Good		Tin (Flat)	Asphalt			This appears to have been built as an addition rather than being an older version	d	15	4
2720.5	0413400005	6	Corn Crib	Transverse Aisle	N / A		Good	Good		Beveled Clapboard	Asphalt			Both bays are now filled-in for use as storage	d	9	4
2720.5	0413400005	7	Shed	Front Gabled	N / A		Poor	Fair		Beveled Clapboard	Wood Shingles				d	17	4
2720.5	0413400005	8	Chicken Coop	Slant-roofed	N / A		Good	Good		Vertical Wood	Asphalt			Windows changed	d	12	4
2720.5	0413400005	9	Outhouse	Front Gabled	N / A		Good	Good		Clapboard	Wood Shingles				d	16	4
2217	0414100001	1	House	Upright and Wing	N / A	1860-1880	Good	Good	Field Stone	Aluminum Siding	Asphalt	Enclosed	North bay is an entrance that has been closed in	This is a unique home with not only 2-over-2 windows, but 2-pane frieze windows. Notice the perfect symmetry in this house and the unusually long upright portion	e	22	4
2217	0414100001	2	Garage	Side Gabled	N / A		Good	Good		Asbestos	Tin (Flat)			3-Car	e	23	4
2217	0414100001	3	Silo	Poured Concrete	N / A		Good	Good		Poured Concrete	Concrete Conical			Old barn is gone	b2	21	4
2217	0414100001	4	Corn Crib	Slant-roofed	N / A		Poor	Good		Horizontal Slats	Tin (Flat)			This is Hillview Hunt Club owned by Markamp Investments	e	24	4
2217	0414100001	5	Barn	Metal Pole Barn	N / A		Fair	Good		Tin (Flat)	Tin (Flat)				e	25	4
2217	0414100001	6	Shed	Metal Pole Barn	N / A		Very Poor	Good		Tin (Flat)	Tin (Flat)				e	28	4
2217	0414100001	7	Shed	Slant-roofed	N / A		Very Poor	Fair		Tin (Corrugated)	Tin (Corrugated)				e	27	4
2217	0414100001	8	Shed		N / A		Falling down	Poor		Terra Cotta Tile	Asphalt			Roof caved-in on this terra cotta tile shed	e	26	4
2211	0414100004	1	House	Upright and Wing	N / A	1860-1890	Good	Fair		Aluminum Siding	Asphalt	Open	New windows, siding, etc.		b3	25	4
2211	0414100004	2	Garage	Front Gabled	N / A		Fair	Fair		Asbestos	Asphalt			Extra deep machine shed	e	30	4
2211	0414100004	3	Milkhouse	Front Gabled	N / A		Good	Good		Cement Block	Asphalt			Also includes barn foundation with a new top on it and poured concrete silo	e	33	4
2211	0414100004	4	Chicken Coop	Broken Eave	N / A		Fair	Fair		Aluminum Siding	Rolled Asphalt				e	32	4
2211	0414100004	5	Pumphouse	Side Gabled	N / A		Fair	Good		Beveled Clapboard	Asphalt				e	34	4
2211	0414100004	6	Outhouse	Side Gabled	N / A		Fair	Good		Beveled Clapboard	Wood Shingles			Unusual layout - most side gabled outhouses have a centered door, but this one is to one side	e	31	4
2211	0414100004	7	Shed	Front Gabled	N / A		Poor	Good		Beveled Clapboard	Asphalt			Possible hog house	e	29	4
2219	0414200008	1	House	Upright and Wing	Greek Revival	1850-1870	Good	Fair	Field Stone	Vinyl Siding	Asphalt	Open			e	19	4
2219	0414200008	2	Garage	Front Gabled	N / A		Good	Good		Vinyl Siding	Asphalt				e	20	4
2219	0414200008	3	Shed	Side Gabled	N / A		Fair	Good		Beveled Clapboard	Wood Shingles		Missing door and windows	Possible former milkhouse	e	21	4
2219	0414200008	4	Grain Bin	Round	N / A		Good	Good		Tin (Corrugated)	Tin (Flat)				e	22	4
2209	0414300009	1	House	Cross Gabled	N / A	1880-1910	Good	Good	Field Stone	Clapboard	Wood Shingles	Open, original		Although a non-active farm, this is a wonderful collection of farm structures	e	36	4
2209	0414300009	2	Barn	Transverse Frame	N / A	1880-1920	Good	Good	Poured Concrete	Vertical Wood	Tin (Flat)			Includes a poured concrete silo with decorative painting on the top collar	b3	30	4
2209	0414300009	3	Shed	Front Gabled	N / A		Good	Good		Vertical Wood	Tin (Flat)			Possible former hog house	b3	31	4
2209	0414300009	4	Shed	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Livestock shed	b3	32	4
2209	0414300009	5	Pumphouse	Front Gabled	N / A		Good	Good		Beveled Clapboard	Wood Shingles				e	37	4
2209	0414300009	6	Shed	Front Gabled	N / A		Good	Good		Clapboard	Wood Shingles				f	1	4
2220	0414400003	1	House	Ranch	N / A	1950-present	Good	Good		Vinyl Siding	Asphalt			New replacement house	e	14	4
2220	0414400003	2	Barn	Gothic Arched	N / A	1910-1940	Fair	Fair	Poured Concrete	Vertical Wood	Asphalt			Extra tall version with a poured concrete silo	e	15	4
2220	0414400003	3	Garage	Side Gabled	N / A		Poor	Good		Clapboard	Asphalt			Machine shed	e	16	4
2220	0414400003	4	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				e	17	4
2220	0414400003	5	Shed	Metal Pole Barn	N / A		Good	Fair		Tin (Flat)	Tin (Flat)			A series of 4 sheds all built onto each other	e	18	4
2214	0415000000	1	vacant		N / A									All gone!			4
2215	0415177002	1	House	Four-over-four	Foursquare	1900-1930	Good	Good	Poured Concrete	Aluminum Siding	Asphalt	Enclosed	New windows, siding and chimney	Surrounded by a subdivision	g	3	4
2215	0415177002	2	Barn	Dairy Gambrel	N / A		Good	Good		Vertical Wood	Asphalt			Includes concrete staved silo (no roof) and rear shed addition	g	2	4
2215	0415177002	3	Shed	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Possible former pumphouse or milkhouse	g	4	4
2213.5	0415300005	1	House	Four-over-four	N / A	1880-1920	Good	Fair		Vinyl Siding	Asphalt			Note concrete root cellar built into hill	f	36	4
2213.5	0415300005	2	Barn	Dairy Gambrel	N / A	1880-1920	Poor	Good		Vertical Wood	Wood Shingles			Also include silo that is crumbling	g	1	4
2213	0415300006	1	House	Cross Gabled	N / A	1880-1910	Good	Good		Clapboard	Asphalt	Open	Added sun porch to east side and balcony above it; also changed windows	Stately, set off the road in a beautiful wooded site	f	33	4
2213	0415300006	2	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			Includes pumphouse and milkhouse	f	35	4

2213	0415300006	3	Garage	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				f	34	4
2212	0415400001	1	House	Upright and Wing	N / A	1860-1880	Good	Fair	Field Stone	Vinyl Siding	Asphalt	Enclosed			f	29	4
2212	0415400001	2	Barn	Gothic Arched	N / A	1910-1940	Good	Good	Poured Concrete	Beveled Clapboard	Asphalt			Includes poured concrete silo with conical roof	f	31	4
2212	0415400001	3	Shed	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt				f	32	4
2212	0415400001	4	Garage	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt				f	30	4
2210	0415400004	1	House	Side Gabled	Cape Cod		Good	Good		Vinyl Siding	Asphalt				b3	27	4
2210	0415400004	2	Barn	Dairy Gambrel	N / A		Good	Good		Vertical Wood	Asphalt			Includes concrete staved silo	b3	26	4
2210	0415400004	3	Shed	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			2 sheds	b3	28	4
2210	0415400004	4	Shed	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Livestock shed	e	35	4
2210	0415400004	5	Shed	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Machine shed	b3	29	4
2018	0416326002	1	House	Front Gabled	N / A		Good	Good		Aluminum Siding	Asphalt			Currently "Signs of All Kinds" store.	f	27	4
2017	0416376002	1	Barn	Dairy Gambrel	N / A		Good	Good		Vertical Wood	Asphalt			Has shed addition	f	26	4
2216	0416400004	1	House	Four-over-four	Italianate	1860-1890	Fair	Poor	Field Stone	Aluminum Siding	Asphalt	Enclosed	New windows, siding, widow's walk, chimney, etc.	Was at one time Dr. Bennett's house (First Village President of Richmond).	g	9	4
2216	0416400004	2	Silo	Molded Block	N / A	1910-1940	Good	Good		Molded Block	Concrete Conical			Molded block silos are almost as rare in our county as wood staved silos.	g	5	4
2216	0416400004	3	Shed	Metal Pole Barn	N / A		Fair	Fair		Tin (Flat)	Tin (Flat)			Series of 3 metal pole barn-styled sheds for storage of the owner's smaller scale railroad cars; Also included is the transverse aisle corn crib with horizontal slats; (one metal barn has a molded block foundation which used to be the big barn)	g	7	4
2216	0416400004	4	Grain Bin	Round	N / A		Fair	Good		Tin (Corrugated)	Tin (Flat)				g	6	4
2024.5	0417200003	1	House	Upright and Wing	Greek Revival	1850-1870	Fair	Fair	Field Stone	Clapboard	Asphalt	Removed	First floor windows were changed and doors	Note that there used to be 2 houses back here and the George McConnel house that was in the 1872 Plat Book burned in the mid 1980's. This was a smaller house for hired hand's.	m	1	4
2024.5	0417200003	2	House	Cottage	Cape Cod	1930-1950	Good	Good		Aluminum Siding	Asphalt	Open		Has 2-door attached garage; this site is so far back off the road that it is not visible from the road	m	5	4
2024.5	0417200003	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				m	4	4
2024.5	0417200003	4	Barn	Transverse Frame	N / A	1870-1900	Good	Good		Vertical Wood	Asphalt			Extremely large barn, but not surprising since the McConnel family was very prosperous	m	2	4
2024.5	0417200003	5	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				m	3	4
254	0417300006	1	House	Upright and Wing	N / A	1890-1930	Good	Good	Poured Concrete	Aluminum Siding	Asphalt	Enclosed	Has 2 extra cubes added-on besides the normal modernizations	This is an farmstead that is actually still farming	o	7	4
254	0417300006	2	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome			This includes 3 concrete staved silos with metal dome roofs. However, 2 of them are the usual ribbed staves and 1 is corrugated staves that makes the silo look like a corduroy texture.	o	6	4
254	0417300006	3	Barn	Transverse Frame	N / A	1880-1920	Good	Good	Poured Concrete	Vertical Wood	Asphalt			Includes a side gabled, attached milkhouse	o	5	4
254	0417300006	4	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				o	4	4
254	0417300006	5	Shed	Front Gabled	N / A		Good	Good		Beveled Clapboard	Tin (Flat)				o	3	4
254	0417300006	6	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Also includes 3 more silos and one grain bin. One silo is another concrete staved and 2 are metal "A.O.Smith Harvestore" silos.	o	1	4
254	0417300006	7	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Two more metal pole barns	o	2	4
2050	0418100006	1	House	Upright and Wing	Greek Revival	1850-1870	Poor	Fair	Field Stone	Asbestos	Asphalt	Removed	New windows		n	23	4
2050	0418100006	2	Barn	Transverse Frame	N / A	1870-1900	Poor	Good		Vertical Wood	Wood Shingles		Large shed extension added to one side	Includes a hog house (full of hogs), a concrete staved silo and a metal A.O.Smith Harvestore silo	p	22	4
2050	0418100006	3	Shed	Front Gabled	N / A		Poor	Fair		Beveled Clapboard	Wood Shingles			In process of being sided	n	24	4
2050	0418100006	4	Shed	Front Gabled	N / A		Falling down	Poor		Beveled Clapboard	Wood Shingles				n	21	4
2051	0418100009	1	House	Upright and Wing	Italianate	1860-1880	Good	Excellent	Field Stone	Vinyl Siding	Asphalt	Original - open	Some of the windows were changed, but all else is original	This is one that Springfield (IHPA) had inquired about (they thought it had National Register potential). Note the original fret-work on the porch, the bay, the gables (verge boards) and window hood ornamentation	n	20	4
2051	0418100009	2	House		N / A									Second view to show details in the ornamentation			4
2051	0418100009	3	Garage	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			3-door machine shed/garage and 2 metal pole barns behind it	n	19	4
2051	0418100009	4	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Also includes 7 metal grain bins	n	18	4
2051	0418100009	5	House	Ranch	N / A	1950-present	Good	Good		Vinyl Siding	Asphalt			Second house on site	n	16	4
2031	0418400004	1	House	Four-over-four	Foursquare	1910-1940	Good	Good	Poured Concrete	Vinyl Siding	Asphalt	Enclosed porches	Porches enclosed	Wonderful collection of farm buildings; house has a Prairie influence	n	33	4
2031	0418400004	2	Corn Crib	Gambrel	N / A		Good	Good		Tin (Flat)	Asphalt			Large transverse aisle corn crib with perpendicular, gambrel vent	n	27	4
2031	0418400004	3	Shed	Side Gabled	N / A		Fair	Good		Vertical Wood	Asphalt			Machine shed	n	26	4
2031	0418400004	4	Shed	Front Gabled	N / A		Good	Good		Clapboard	Asphalt			Machine shed	n	28	4
2031	0418400004	5	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			Includes 2 silos (1 poured concrete with a concrete dome, 1 concrete staved with a metal dome and 1 poured concrete with no roof), and a hog house	n	29	4
2031	0418400004	6	Pumphouse	Front Gabled	N / A		Poor	Good		Vertical Wood	Wood Shingles				n	30	4
2031	0418400004	7	Hog House	Front Gabled	N / A		Poor	Good		Vertical Wood	Asphalt				n	31	4
2031	0418400004	8	Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Wood Shingles				n	32	4
2031	0418400004	9	Shed	Side Gabled	N / A		Good	Good		Tin (Flat)	Asphalt			Machine shed	n	34	4
2031	0418400004	10	Barn	Dairy Gambrel	N / A	1880-1920	Fair	Good		Vertical Wood	Wood Shingles				n	35	4
2031	0418400004	11	Grain Bin	Round	N / A		Good	Good		Tin (Corrugated)	Tin (Flat)			Include grain dryer, also	n	36	4
2031	0418400004	12	Chicken Coop	Uneven Gable	N / A		Good	Good	Wood Shingles	Tin (Flat)	Asphalt				n	25	4

254.5	0419200001	1	House	Upright and Wing	Greek Revival	1840-1850	Falling down	Fair		Clapboard	Wood Shingles	Open	Never modernized even for plumbing	This is obviously falling into the earth. However, it is one of the few 1840's houses in the county. It is part hand-hewn log structure and part frame construction. Although abandoned for years, it has remained due to being set way back off the road.	o	12	4
254.5	0419200001	2	House		N / A									Second view to show overall structure. It is 1 and 1/2 stories with 2 small sleeping rooms above the parlor and back room. Summer kitchen is to the side with cistern and hand-pump sink. Access to basement it through trap-door on porch.	o	11	4
254.5	0419200001	3	Shed	Side Gabled	N / A	1840-1855	Falling down	Fair		Vertical Wood	Wood Shingles			This is the oldest of the barns/sheds. It may have been a small barn that was converted into a shed after the big barn was built	o	8	4
254.5	0419200001	4	Hog House	Front Gabled	N / A	1850-1870	Falling down	Fair		Vertical Wood	Wood Shingles			Also includes a metal grain bin and a chicken coop that is falling down	o	9	4
254.5	0419200001	5	Silo	Poured Concrete	N / A	1880-1900	Good	Good		Poured Concrete	Concrete Conical			This farmstead went through an upgrade around the turn-of-the-century when it was a profitable dairy farm. A large transverse frame barn was built along with other structures. The barn was recently taken down by new speculative owners.	o	10	4
2008	0419400011	1	House	Four-over-four	N / A	1860-1880	Good	Fair	Field Stone	Aluminum Siding	Asphalt	Removed and smaller	Side wing added, windows changed, and siding added	This is the older version of the 2-story pyramidal cube, but with no extra details at all	3y	2	4
2008	0419400011	2	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good	Poured Concrete	Vertical Wood	Asphalt			Includes attached milkhouse and poured concrete silo with conical roof	p	25	4
2008	0419400011	3	Chicken Coop	Broken Eave	N / A		Fair	Fair		Beveled Clapboard	Asphalt		Windows changes and asphalt siding put over clapboards	Also includes front gabled shed that may have been a transverse aisle corn crib converted to shed	p	27	4
2008	0419400011	4	Hog House	Side Gabled	N / A		Good	Good	Poured Concrete	Beveled Clapboard	Asphalt			May have been for poultry or other livestock	p	24	4
2008	0419400011	5	Outhouse	Side Gabled	N / A		Good	Good		Clapboard	Asphalt			Standard outhouse	p	23	4
2008	0419400011	6	Pumphouse	Front Gabled	N / A		Fair	Fair		Beveled Clapboard	Asphalt			Includes windmill	p	26	4
255	0420100001	1	House	Front Gabled	N / A	1860-1890	Good	Fair	Granite	Vinyl Siding	Asphalt	Removed	New smaller windows; major siting change with removal of one wing		o	20	4
255	0420100001	3	Shed	Front Gabled	N / A		Good	Fair		Aluminum Siding	Asphalt		Functionally altered		o	19	4
255	0420100001	4	Machine Shed	Side Gabled	N / A		Good	Good		Stucco	Asphalt				o	16	4
255	0420100001	5	Pumphouse	Front Gabled	N / A		Good	Good		Clapboard	Asphalt				o	15	4
255	0420100001	6	Corn Crib	Round	N / A		Good	Good		Wire Mesh	Tin (Flat)				o	17	4
255	0420100001	7	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				o	14	4
255	0420100001	8	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				o	13	4
255	0420100001	9	Grain Bin	Round	N / A		Good	Good		Tin (Flat)	Tin (Flat)				o	18	4
255	0420100001	10	Barn	Dairy Gambrel	N / A	1911	Good	Good		Vertical Wood	Asphalt			Includes poured concrete silo with conical roof	o	20	4
356	0420100006	1	House	Upright and Wing	Greek Revival	1850-1870	Poor	Poor		Vinyl Siding	Asphalt	Enclosed	Although modernized, the roof was raised up and the cornice returns were removed; new windows, etc.	Not much historic integrity left, but at least this one wasn't wiped off the face of the earth. Note that next to this is an abandoned cemetery that was not moved, but tilled over.	o	30	4
356	0420100006	2	Shed	Metal Pole Barn	N / A		Fair	Good		Tin (Flat)	Tin (Flat)			Older version with roof curved down onto sides	o	30	4
357	0420300003	1	House	Upright and Wing	N / A	1860-1890	Fair	Poor		Aluminum Siding	Asphalt	Altered	Major addition on side; porch changed; new windows and siding		o	31	4
357	0420300003	2	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt				o	32	4
357	0420300003	3	Pumphouse	Front Gabled	N / A		Good	Good		Cement Block	Asphalt				o	34	4
357	0420300003	4	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				o	33	4
2010	0420300012	1	House	Upright and Wing	N / A	1860-1890	Good	Good		Tin (Flat)	Asphalt	Open	Add picturesque horse stables	This barn was featured in the "Year of the Barn" calendar. This also includes a poured concrete silo with a conical roof	g	16	4
2010	0420300012	2	Barn	Transverse Frame	N / A	1860-1890	Good	Good		Tin (Flat)	Asphalt				g	17	4
2009	0420300021	1	House	Upright and Wing	N / A	1860-1890	Fair	Poor		Aluminum Siding	Asphalt	Enclosed	Added onto in several places; new windows; enclosed porch	On route of "FAP 420" next to new area that Richmond annexed.	g	18	4
2009	0420300021	2	Silo	Poured Concrete	N / A		Good	Good		Poured Concrete	Concrete Conical			Old barn foundation ruins next to it	g	21	4
2009	0420300021	3	Milkhouse	Front Gabled	N / A		Fair	Good		Vertical Wood	Asphalt			Also includes shed converted into living space	g	20	4
2009	0420300021	4	Shed	Side Gabled	N / A		Good	Good		Clapboard	Asphalt			Machine shed	g	22	4
2009	0420300021	5	Shed	Front Gabled	N / A		Poor	Poor		Asbestos	Wood Shingles			Built into hill	g	19	4
2012	0421100001	1	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			Only remaining structure on this site. The rest have been removed by the new owner for a subdivision	g	10	4
2016	0421100003	1	House	Cross Gabled	N / A	1880-1900	Fair	Fair		Aluminum Siding	Asphalt	Enclosed	Many, many, many	No apparent historical integrity left	f	25	4
2014	0421100007	1	House	Upright and Wing	N / A	1860-1890	Fair	Poor		Vinyl Siding	Asphalt		Dormers added; side wing replaced with large upright wing	Has been a crossroads restaurant for years and years as a compliment to the tavern on the opposite corner (hence the long-term locally known name of "Whiskey Corners")	f	22	4
2013	0421251015	1	Depot	Side Gabled	N / A	1860-1890	Fair	Fair		Vinyl Siding	Asphalt	Enclosed entry	Corners were hanging in disrepair, so were clipped off	All of the decorative shingles are underneath the siding. This is the original Richmond railroad depot station, but was moved away from the railroad tracks and converted into a restaurant	f	23	4
2015	0421251017	1	House	Upright and Wing	N / A	1860-1880	Good	Fair		Vinyl Siding	Asphalt	Enclosed	Modernized and a major addition to the side	Rental property; also includes a 2-car garage	f	24	4
2011	0421300002	1	House	Four-over-four	Foursquare	1900-1930	Good	Fair	Poured Concrete	Vinyl Siding	Asphalt	Enclosed	Addition and deck added	Farmstead set up on the hill overlooking the valley above the Nippersink Creek	g	15	4
2011	0421300002	2	Barn	Three-bay Threshing	N / A	1870-1890	Good	Good		Vertical Wood	Asphalt			Includes poured concrete silo with conical roof	g	11	4
2011	0421300002	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				g	13	4
2011	0421300002	4	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				g	14	4
2011	0421300002	5	Shed	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				g	12	4
2205	0421400008	1	House	Four-over-four	Foursquare	1910-1940	Good	Good	Molded Block	Clapboard	Asphalt	Originally enclosed		Complete with dormer	r	12	4
2205	0421400008	2	Barn	Dairy Gambrel	N / A	1900-1930	Good	Good		Vertical Wood	Asphalt			Includes gambrel milkhouse and poured concrete silo	r	9	4
2205	0421400008	3	Garage	Pyramidal	N / A		Good	Fair		Beveled Clapboard	Asphalt			Connected to rear of house back wings	r	11	4
2205	0421400008	4	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				r	10	4
2206	0422200001	1	Barn	Dairy Gambrel	N / A	1910-1940	Good	Good		Vertical Wood	Asphalt			Bungalow house has already been taken down by developer, Peter Bell, to clear way for the subdivision	f	12	4
2206	0422200001	2	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				f	13	4

2208	0422200011	1	House	Upright and Wing	Greek Revival	1850-1870	Good	Good	Field Stone	Clapboard	Asphalt	Open - rear	Minor change of windows to this wonderful house that is still totally intact	Has full unbroken cornice returns that continue across to form a full triangular pediment across the front façade. Also still has its front door surround complete with transom and side lights and the corner pilasters	f	2	4
2208	0422200011	2	House		N / A									Second photo to show rear view; notice back wing that was summer kitchen, not a later addition	f	3	4
2208	0422200011	3	Barn	Three-bay Threshing	N / A	1845-1860	Poor	Excellent		Vertical Wood	Tin (Perforated)			Composite barn but built two section, one as an addition; has hand-hewn timbers; includes poured concrete silo with conical roof	f	5	4
2208	0422200011	4	Garage	Gambrel	N / A		Good	Good		Tin (Flat)	Asphalt				f	4	4
2208	0422200011	5	Corn Crib	Slant-roofed	N / A		Falling down	Good		Horizontal Slats	Wood Shingles			Long, narrow single bay crib	f	6	4
2206.3	0422300018	1	House	Upright and Wing	N / A	1850-1870	Good	Fair		Aluminum Siding	Asphalt		Extra side wings added through the years	Main section of house has hand-hewn timbers. Original Thomas family descendants still own it; north border of the Nippersink Creek; set back off the road back by the railroad tracks	f	18	4
2206.3	0422300018	2	House		N / A									Second view to show rear of house and attached side gabled garage	f	14	4
2206.3	0422300018	3	Barn	Dairy Gambrel	N / A	1880-1920	Poor	Poor		Vertical Wood	Asphalt		Gambrel roof was removed when under disrepair	Includes milkhouse and concrete staved silo; farm building have never been painted	f	19	4
2206.3	0422300018	4	Shed	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			2 sheds; one may have been a corn crib	f	20	4
2206.3	0422300018	5	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome				f	21	4
2256	0422400007	1	House	Upright and Wing	Greek Revival	1850-1870	Fair	Fair	Field Stone	Asbestos	Asphalt	Partially enclosed	Most of the windows are changed and a stone addition was put on the back of the house	House has some hand-hewn timbers, but needs work. Stone work is note as old as the house (140+ years) but still is very old and could date back as far as 100 years)	v	16	4
2256	0422400007	2	Garage	Front Gabled	N / A		Good	Good		Tin (Flat)	Asphalt				v	17	4
2256	0422400007	3	Barn	Three-bay Threshing	N / A	1850-1870	Fair	Fair		Asbestos	Tin (Flat)		Shed addition to side		v	18	4
2256	0422400007	4	Chicken Coop	Side Gabled	N / A	1860-1890	Falling down	Poor		Clapboard	Rolled Asphalt				v	19	4
2259	0422400008	1	House	Upright and Wing	N / A	1880-1900	Fair	Fair	Granite	Aluminum Siding	Asphalt	Removed		Notice that although this house has a triangular pediment in the gable, it is not a remodeled Greek Revival. Instead it is a remodeled Queen Anne (note the higher pitched roof, the windows with the transoms and the foundation is dressed granite)	v	13	4
2259	0422400008	2	Garage	Pyramidal	N / A		Good	Good		Aluminum Siding	Asphalt			Deep rectangular shape	v	12	4
2258	0422400008	3	House	Four-over-four	N / A	1900-1930	Good	Good		Aluminum Siding	Asphalt		This might have been a garage made into a house or the first house on the site	Second house on property; both are rental units (site 2258 and 2259) are the same parcel	v	15	4
2770	0422400011	1	vacant		N / A									This was a Foursquare that was burned for fire practice	v	25	4
2261	0422400025	1	House	Cross Gabled	Queen Anne	1880-1910	Excellent (Restored)	Excellent	Granite	Clapboard	Asphalt	Original - open	None!	This house was overgrown, vacant and had porches falling off. New owners not only tamed the yard and restored the house, but rebuilt the porches using the old ones as patterns	v	11	4
2261	0422400025	1	Barn	Three-bay Threshing	N / A	1860-1880	Falling down	Poor		Clapboard	Wood Shingles			This one is too far gone to bring back	v	10	4
2206.5	0422400032	1	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome			Also include modern garage on the site of the old barn	f	15	4
2206.5	0422400032	2	House	Cottage	Cape Cod	1950-present	Good	Good	Poured Concrete	Vinyl Siding	Asphalt	Open			f	16	4
2206.5	0422400032	3	Chicken Coop	Side Gabled	N / A		Fair	Fair		Clapboard	Asphalt				f	17	4
2221	0423200012	1	House	Upright and Wing	N / A	1860-1880	Fair	Fair	Field Stone	Aluminum Siding	Asphalt	Open	Some of the windows have been replaced, the siding put on and the entire inside modernized	Note the frieze windows	e	10	4
2221	0423200012	2	Silo	Poured Concrete	N / A		Good	Good		Poured Concrete	Metal Dome			2 Silos	e	12	4
2221	0423200012	3	Shed	Front Gabled	N / A		Fair	Good		Vertical Wood	Asphalt				e	13	4
2221	0423200012	4	Garage	Side Gabled	N / A		Fair	Good		Aluminum Siding	Asphalt			Machine shed	e	11	4
2207	0423301001	1	House	Four-over-four	Italianate	1860-1880	Fair	Good		Clapboard	Asphalt	Open entry		This is a transitional house - notice the Greek Revival pilasters, but the 2-over-2 windows and simplified hood moldings	f	7	4
2207	0423301001	2	Shed	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			2 Sheds, one which is older	f	8	4
2207	0423301001	3	Garage	Front Gabled	N / A		Good	Good		Stucco	Asphalt			Note the shortened silo made into a shed	f	9	4
2207	0423301001	4	Barn	Dairy Gambrel	N / A	1916	Fair	Good		Stucco	Asphalt			Big impressive barn that has a stucco/cement coating; however, the stucco has failed and it has been patched but in a different color	f	10	4
2207	0423301001	5	Silo	Poured Concrete	N / A		Poor	Good		Poured Concrete				Concrete is failing and rebar is showing	f	11	4
2262	0423351003	1	House	Cross Gabled	N / A	1870-1890	Fair	Fair		Aluminum Siding	Asphalt	Enclosed			v	9	4
2262	0423351003	1	House		N / A		Good	Good		Tin (Flat)	Asphalt						4
2262	0423351003	2	Shed	Front Gabled	N / A		Fair	Fair		Beveled Clapboard	Asphalt			3 Sheds	v	6	4
2262	0423351003	3	Shed	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				v	5	4
2263	0423351009	1	House	Upright and Wing	N / A	1880-1900	Good	Good		Vinyl Siding	Asphalt		New windows and modernization		v	8	4
2263	0423351009	3	Outhouse	Side Gabled	N / A		Fair	Good		Clapboard	Asphalt				v	3	4
2263	0423351009	4	Shed	Front Gabled	N / A		Fair	Fair		Plywood	Asphalt				v	4	4
2263	0423351009	5	Garage	Front Gabled	N / A		Good	Good		Clapboard	Asphalt				2v	3	4
2263	0423351009	6	Garage	Front Gabled	N / A		Good	Good		Vinyl Siding	Asphalt				v	7	4
2260	0423351011	1	Barn		N / A		Falling down	Poor						Partially collapsed and falling into the ground; old house gone; all overgrown with trees growing through collapsed barn			4
2257	0423351012	1	House	Upright and Wing	N / A	1860-1890	Good	Good		Vinyl Siding	Asphalt	Open	Added large upright at the turn-of-the-century to older smaller house	Note 2-over-2 windows in the smaller two wings; also note the patterned shingles in the upright	v	14	4
2257	0423351012	2	House		N / A									Second view to show the Queen Anne upright section of the house	v	1	4
2257	0423351012	3	Shed	Front Gabled	N / A		Good	Good		Plywood	Asphalt				v	2	4
2736	0423400006	1	House	Upright and Wing	N / A	1860-1890	Good	Fair		Clapboard	Asphalt		Siding totally redone and new windows		e	4	4
2736	0423400006	2	House		N / A									It is hard to determine what portions are original	e	3	4
2736	0423400006	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				e	2	4
2222	0423400010	1	House	Upright and Wing	N / A		Good	Fair		Vinyl Siding	Asphalt	Enclosed	New windows, siding, etc.		e	5	4
2222	0423400010	2	Barn	Dairy Gambrel	N / A		Fair	Fair		Vertical Wood	Asphalt			Has shed addition and attached milkhouse	e	7	4

2222	0423400010	3	Silo	Poured Concrete	N / A		Good	Good		Poured Concrete					Has reinforcing rings on the bottom portion	2v	9	4
2222	0423400010	4	Shed	Gambrel	N / A		Good	Good		Clapboard	Tin (Flat)					e	8	4
2222	0423400010	5	Shed	Side Gabled	N / A		Fair	Fair		Clapboard	Asphalt				Machine shed	e	6	4
2735	0424300004	1	House	Bungalow	Bungalow	1910-1940	Good	Good		Stucco	Asphalt	Open			Note molded block porch post standards; dormers and wood shingle siding on second story	d	33	4
2735	0424300004	2	Garage	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt				2-car	d	34	4
2735	0424300004	3	Shed	Side Gabled	N / A		Fair	Good		Stucco	Asphalt				Shed is on back parcel 04-25-101-004	e	1	4
2734	0424300005	1	House	Upright and Wing	N / A	1930-1950	Good	Good	Stucco	Vertical Wood	Asphalt				Has an oriental influence	d	37	4
2734	0424300005	2	Garage	Gambrel	N / A		Good	Good		Vertical Wood	Asphalt					d	36	4
2734	0424300005	3	Shed	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt				Shed is actually on parcel behind that abuts the Nippersink creek (04-25-101-005)	d	35	4
2733	0424300009	1	House	Upright and Wing	N / A	1860-1890	Good	Good		Aluminum Siding	Asphalt	Screened-in	Rear porch enclosed and attached garage made into living area		Larger than normal rear wing	d	32	4
2733	0424300009	2	Chicken Coop	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt					d	31	4
2733	0424300009	3	Barn	Transverse Frame	N / A	1880-1920	Fair	Fair		Vertical Wood	Asphalt				Very small barn	d	30	4
2733	0424300009	4	Barn	Three-bay Threshing	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt		Stable overhang added			d	28	4
2733	0424300009	5	Shed	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt				Horse stable; note old door (probably from house)	d	29	4
2732	0424300011	1	House	Upright and Wing	Greek Revival	1850-1860	Excellent (Restored)	Excellent	Cobblestone	Clapboard	Asphalt	Open and original	No recent modernizations, but an older side wing was added a long time ago and is in accordance with the rest of the house		This is an excellent example of Greek Revival architecture with all of the normal features (cornice returns, 6-over-6 windows, pilasters, square porch posts, etc.) This house still retains all of its historic integrity	d	20	4
2732	0424300011	2	Shed	Front Gabled	N / A		Good	Good		Clapboard	Asphalt				This was the detached summer kitchen that has been converted now to other uses	d	25	4
2732	0424300011	3	Barn	Transverse Frame	N / A	1860-1890	Good	Good		Vertical Wood	Asphalt				This is a very small barn, more like an extra tall shed	d	23	4
2732	0424300011	4	Shed	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				Livestock shed	d	24	4
2732	0424300011	5	Shed	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt				This may have been either a corn crib or a hog house	d	26	4
2732	0424300011	6	Chicken Coop	Pyramidal	N / A		Good	Good		Vertical Wood	Asphalt				Notice old windows (1850's Greek Revival window possibly from the house)	d	22	4
2732	0424300011	7	Shed	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt				Further examination would be needed to determine prior function; but since this is on the back of the other shed it could be hog production	d	27	4
2732	0424300011	8	Garage	Front Gabled	N / A		Good	Good		Clapboard	Asphalt				Modern	d	21	4
2720.7	0424401006	1	House	Front Gabled	N / A	1850-1870	Good	Fair		Asbestos	Asphalt		Big addition to rear		This is the "George Andrews" 1872 Plat Book illustration house	d	19	4
2713	0425000000	1	vacant		N / A										All Gone! (This was on the southwest corner of Route 12 and Bliven Street and was burned for fire training practice)			4
2708	0425300011	1	House	Upright and Wing	N / A	1890-1920	Good	Good		Vinyl Siding	Asphalt	Open	Porches redone			l	12	4
2708	0425300011	2	Barn	Transverse Frame	N / A	1880-1920	Poor	Fair		Vertical Wood	Asphalt				Has falling-in attached milk house	l	11	4
2708	0425300011	3	Silo	Poured Concrete	N / A		Good	Good		Poured Concrete	Concrete Conical				Wider and shorter than normal	l	9	4
2708	0425300011	4	Shed		N / A		Falling down	Poor								l	10	4
2738	0426102003	1	House	Upright and Wing	Greek Revival	1850-1870	Fair	Fair		Clapboard	Asphalt		Shed addition; modernized			t	20	4
2737	0426102003	2	Store		N / A		Good	Good		Vertical Wood	Asphalt				Former Solon Mills Post Office building	t	19	4
2739	0426103001	1	House	Upright and Wing	N / A	1860-1890	Good	Fair		Clapboard	Asphalt	Extended - open	Added gable ornament			t	21	4
2742	0426103002	1	House	Upright and Wing	N / A	1870-1890	Good	Good		Vinyl Siding	Asphalt	Replaced with deck	Resided again, but this time in appropriate style			t	24	4
2741	0426103003	1	House	Front Gabled	N / A	1850-1870	Fair	Good	Field Stone	Brick	Asphalt	none	Very little changes		Notice construction is of "Cream City" brick by the Richardson brother that was a brick mason. This matches the bricks on the Richardson homestead. Notice extra large four-pane store windows that are original complete with the bottom panels and transom	t	23	4
2740	0426103003	1	House	Upright and Wing	N / A	1850-1870	Good	Good		Vinyl Siding	Asphalt		New windows		Attached to corner store; was shopkeepers house	t	22	4
2753	0426104001	1	House	Side Gabled	N / A	1850-1870	Good	Good		Brick	Asphalt		Sky lights added with latest change of ownership		For years and years this was a bar and restaurant. In recent years it has now become office space. Notice the use of two colors of bricks to form patterns that make it look like half-timbering.	t	18	4
2752	0426104001	2	vacant		N / A										This house sat abandoned for years and was burn for fire training practice in 1988. It was a upright and wing vernacular house. However, note the pitch of the roof and the patterned shingles in the gable. This was a Queen Anne house.			4
2748	0426106002	1	House	Cottage	N / A	1910-1940	Fair	Fair		Brick	Asphalt	none	Converted into a house		Former Solon Mills School situated next to the cemetery	2t	2	4
2747	0426106004	1	House	Front Gabled	N / A	1850-1870	Good	Good		Vinyl Siding	Asphalt	none	Converted into a house		Formerly was the Solon Mills church	2t	3	4
2744	0426107001	1	House	Cross Gabled	N / A	1880-1920	Good	Good	Molded Block	Vinyl Siding	Asphalt	Enclosed			Judging by the bay window on the other side of the house, this house would have had Queen Anne detailing, but none remain. Site also include a 3-car garage.	2t	5	4
2745	0426107002	1	House	Upright and Wing	Italianate	1860-1880	Good	Good	Field Stone	Asbestos	Asphalt	Small entryway porch	None apparent other than siding		This is a transitional house that has 6-over-6 windows, but an Italianate layout and paired corbels or brackets at the roof-line	2t	6	4
2745	0426107002	2	Garage	Front Gabled	N / A		Good	Good		Aluminum Siding	Asphalt				Note old double garage door	2v	3	4
2746	0426107004	1	Barn	Dairy Gambrel	N / A	1900-1930	Good	Fair		Vinyl Siding	Asphalt		Converted into business and living area including sky lights		Was also a factory for some time. Is built right next to the road.	2t	7	4
2746	0426107004	2	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt				Site also includes this small barn and a small cottage house	2v	6	4
2746	0426107004	3	Outhouse	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt					2v	5	4
2746	0426107004	4	Chicken Coop	Slant-roofed	N / A		Good	Good		Vinyl Siding	Asphalt		Windows removed and converted into shed			2v	4	4
2743	0426108005	1	House	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				Former business converted into a house	t	25	4
2749	0426109001	1	House	Cross Gabled	N / A	1890-1910	Good	Fair		Vinyl Siding	Asphalt	Changed	Patterned shingles in the gables covered the last time it was resided		May have been house for the barn on site 2746 since it is directly across the road and is of the same age	2t	8	4
2749	0426109001	2	Chicken Coop	Front Gabled	N / A		Good	Good		Stucco	Asphalt				Note large 4-pane windows	v	13	4
2749	0426109001	3	Garage	Side Gabled	N / A		Good	Good		Aluminum Siding	Asphalt				Small 2-car garage added onto big garage	v	12	4

2749	0426109001	4	Barn	Carriage	N / A	1880-1920	Good	Good		Tin (Flat)	Asphalt		Converted from carriage barn to large garage	This would have been a proper carriage barn back in the horse and buggy days with even 2 stalls for the carriage horses. Note also included is an side gabled outhouse next to the barn.	v	11	4
2749	0426109001	5	Corn Crib	Slant-Sided	N / A		Good	Good		Horizontal Slats	Asphalt			Gabled, single bay version for small quantity of storage	v	10	4
2750	0426128001	1	House	Upright and Wing	N / A	1860-1890	Good	Fair		Aluminum Siding	Asphalt	Enclosed	Windows changed and large chimney added to front of side wing	Unchanged at all from previous survey	2t	9	4
2750	0426128001	2	Garage	Pyramidal	N / A		Good	Good		Aluminum Siding	Asphalt			2 Garages - 1 side gabled and 1 pyramidal	v	15	4
2751	0426128002	1	House	Bungalow	Bungalow	1910-1940	Good	Good		Stucco	Asphalt			Includes a 2-story older shed/garage	2t	10	4
2771	0426176005	1	House	Upright and Wing	N / A	1860-1880	Good	Good		Clapboard	Asphalt	Open	Expanded in back	Yet another hunt club - this is used as a warming house/lodge for the hunt club, "The Prairie Club"	k	32	4
2771	0426176005	2	Barn	Transverse Frame	N / A	1860-1890	Fair	Good		Vertical Wood	Wood Shingles				k	36	4
2771	0426176005	3	Silo	Poured Concrete	N / A		Fair	Good		Poured Concrete	Concrete Conical			Also includes a side wing to the barn	k	4	4
2771	0426176005	4	Hog House	Front Gabled	N / A		Fair	Fair		Cement Block	Rolled Asphalt			Possibly used for other livestock, also	k	35	4
2771	0426176005	5	Shed	Quonset	N / A		Poor	Good		Tin (Corrugated)	Tin (Corrugated)				k	33	4
2771	0426176005	6	Shed	Front Gabled	N / A		Falling down	Poor		Beveled Clapboard	Wood Shingles				k	37	4
2255	0426301006	1	House	Four-over-four	N / A	1860-1880	Fair	Fair		Asbestos	Asphalt		Porch enclosed and expanded; new windows	Older version of this style; this farmstead sits nestled into the meanders of the Nippersink Creek	v	23	4
2255	0426301006	2	Barn	Transverse Frame	N / A	1900-1930	Good	Good		Beveled Clapboard	Asphalt			Small storage barn	v	21	4
2255	0426301006	3	Shed	Side Gabled	N / A		Good	Fair		Beveled Clapboard	Asphalt			Now a garage/storage shed, but formerly for poultry or other livestock	v	20	4
2255	0426301006	4	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			Includes windmill	v	22	4
2255	0426301006	5	Silo	Poured Concrete	N / A		Good	Good		Poured Concrete	Concrete Conical				v	24	4
2254	0426352012	1	House	Upright and Wing	N / A		Good	Good		Clapboard	Asphalt	Screened-in	New windows	Note that side wing is as tall as upright portion	l	37	4
2254	0426352012	2	Garage	Side Gabled	N / A		Good	Good		Vinyl Siding	Asphalt				l	36	4
2709.5	0426403014	2	Barn	Three-bay Threshing	N / A	1840-1855	Good	Good		Vertical Wood	Wood Shingles			Needs a new roof; has hand-hewn timbers; site is way back off the road, so was missed last time	l	2	4
2709.5	0426403014	3	Barn		N / A									Interior view to show timbering style hand-hewn beams	l	5	4
2709.5	0426403014	4	Shed	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Machine shed	l	1	4
2709.5	0426403014	5	Shed	Side Gabled	N / A		Fair	Good	Field Stone	Beveled Clapboard	Wood Shingles			Needs work; possibly the hog house	l	3	4
2709.5	0426403014	6	Shed	Slant-roofed	N / A		Fair	Good		Vertical Wood	Asphalt				l	4	4
2709.5	0426403014	7	Shed	Slant-roofed	N / A		Good	Good		Beveled Clapboard	Asphalt			Possible former chicken coop	l	6	4
2709.5	0426403014	8	Milkhouse	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Attached	l	7	4
2709.5	0426403014	9	Barn	Transverse Frame	N / A	1860-1890	Good	Good		Vertical Wood	Asphalt			Built onto end of big barn and then haymows connected	l	8	4
2223	0427100001	1	House	Four-over-four	Italianate	1860-1880	Good	Good		Clapboard	Asphalt		Widow's walk removed	Unusually large version of this style house. Instead of 2 sets of windows across or even 3 sets, this one has 4 sets of windows. This is abandoned and will soon be coming down due to neighboring town houses	s	27	4
2223	0427100001	2	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			Needs new roof; this farmstead if very visible from Route 12	s	26	4
2764	0427201001	1	House	Four-over-four	Federal	1840-1850	Excellent (Restored)	Excellent	Field Stone	Brick	Asphalt	Open entry	Very few and minor; Widow's walk removed and one porch screened-in	This is one of the few active dairy farms sited on the Nippersink Creek. The original owners, the Gardner family, still own this farm. The interior is all original woodwork and plaster, but well taken care of.	t	2	4
2764	0427201001	2	Barn	Dairy Gambrel	N / A	1880-1900	Good	Good		Vertical Wood	Tin (Flat)			Includes attached milkhouse, attached grainery and two silos	t	3	4
2764	0427201001	3	Shed	Slant-roofed	N / A		Good	Good		Vertical Wood	Asphalt			Has 2 levels with the upper entrance being banked	t	4	4
2764	0427201001	4	Grain Bin	Round	N / A		Good	Good		Tin (Corrugated)	Tin (Flat)				t	5	4
2764	0427201001	5	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				t	6	4
2764	0427201001	6	House		N / A									Second view to show rear of the house; note hipped roof summer kitchen	t	7	4
2766	0427226018	1			N / A									This house pictured in the previous is gone due to an accidental burn-down. A modern house was built in it's place.			4
2768	0427229008	1	House	Front Gabled	N / A	1880-1920	Good	Good		Aluminum Siding	Asphalt	Enclosed		Note patterned shingles in gable	t	10	4
2768	0427229008	2	Barn	Carriage	N / A	1880-1920	Good	Good		Beveled Clapboard	Asphalt		Converted to a garage	For carriages and a horse	t	12	4
2763	0427230012	1	House	Front Gabled	N / A		Good	Good		Vinyl Siding	Asphalt	Enclosed	Modernized		s	28	4
2762	0427230013	1	House	Upright and Wing	N / A		Good	Fair		Vinyl Siding	Asphalt	Enclosed	Modernized including even a deck		s	29	4
2761	0427230016	1	House	T-Plan	Queen Anne	1880-1920	Good	Good		Clapboard	Asphalt	Redone	Either there used to be a fancy balcony or this is just a direct rebuild of the porch	Note belt line molding and corner brackets for bays; also front transom window	s	31	4
2761	0427230016	2	Garage	Front Gabled	N / A		Good	Good		Plywood	Asphalt				s	30	4
2759	0427231008	1	House	Cross Gabled	Queen Anne	1880-1910	Good	Good		Clapboard	Asphalt	Enclosed	Much detailing has been removed	Notice gable ornamentation	s	35	4
2759	0427231008	2	Chicken Coop	Uneven Gable	N / A		Good	Good		Vertical Wood	Asphalt				s	36	4
2765	0427231010	1	House	Four-over-four	N / A	1900-1930	Good	Good		Tin (Flat)	Asphalt		Redone	Rental property	t	9	4
2767	0427231011	1	House	Front Gabled	N / A		Good	Fair		Aluminum Siding	Asphalt	Enclosed	New windows		t	11	4
2759.5	0427231013	1	House	Cottage	Cape Cod		Good	Good		Vinyl Siding	Asphalt				s	33	4
2755	0427232009	1	House	Cross Gabled	N / A	1890-1920	Fair	Good		Aluminum Siding	Asphalt		New windows and detail ornamentation removed; porches are gone	Notice that these cornice returns have angled tops which is the turn-of-the-century version	t	14	4
2769	0427232011	1	House		N / A									New house instead of this cottage/shed			4
2756	0427232014																4
2760	0427233001	1	House	Cottage	Queen Anne	1890-1920	Excellent (Restored)	Excellent		Clapboard	Asphalt			Has square tower over porch with steep roof line	s	34	4

2758	0427233005	1	House	Upright and Wing	Greek Revival	1850-1870	Fair	Poor		Aluminum Siding	Asphalt		Rear addition	t	8	4
2758	0427233005	2	Shed	Front Gabled	N / A		Fair	Fair		Asbestos	Asphalt			t	17	4
2758	0427233005	3	House	Upright and Wing	Greek Revival									t	16	4
2754	0427234004	1	House	Cottage	N / A		Fair	Fair		Aluminum Siding	Asphalt			t	13	4
2757	0427234005	1	House	I-house	N / A	1880-1900	Good	Fair		Vinyl Siding	Asphalt	Open	New windows, resided twice	t	15	4
2253	0427400003	1	House	Cottage	Cape Cod	1930-1950	Good	Good		Aluminum Siding	Asphalt			l	33	4
2253	0427400003	1	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			l	35	4
2253	0427400003	2	Silo	Poured Concrete	N / A		Good	Good		Poured Concrete	Concrete Conical			l	34	4
2204	0428200006	1	Silo	Wood Staved	N / A	1880-1900	Good	Good	Poured Concrete	Wood Staved	Wood Shingles			r	15	4
2204	0428200006	2	Barn	Dairy Gambrel	N / A	1880-1900	Good	Good		Vertical Wood	Tin (Flat)			r	16	4
2204	0428200006	3	Barn	Dairy Gambrel	N / A		Good	Good		Vertical Wood	Asphalt			r	19	4
2204	0428200006	4	House	Ranch	N / A	1950-present	Good	Good		Vinyl Siding	Asphalt			r	18	4
2204	0428200006	5	Silo	Poured Concrete	N / A		Good	Good		Poured Concrete	Concrete Conical			o	37	4
2204	0428200006	6	Outhouse	Side Gabled	N / A		Good	Good		Vertical Wood	Wood Shingles			o	36	4
2204	0428200006	7	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			r	17	4
2203	0428200007	1	House	Front Gabled	N / A		Fair	Good		Stucco	Asphalt			r	14	4
2203	0428200007	2	Garage	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt			r	13	4
2202	0428200025	1	House	Upright and Wing	N / A		Good	Fair		Vinyl Siding	Asphalt	Enclosed	Changed windows, siding etc.	r	28	4
2202	0428200025	2	Barn	Gothic Arched	N / A		Good	Good		Vertical Wood	Asphalt			r	27	4
2202	0428200025	3	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome			r	26	4
2202	0428200025	4	Garage	Pyramidal	N / A		Good	Good		Vinyl Siding	Asphalt			r	24	4
2202	0428200025	5	Outhouse	Side Gabled	N / A		Good	Good		Clapboard	Asphalt			r	23	4
2202	0428200025	6	Chicken Coop	Broken Eave	N / A		Good	Fair		Vertical Wood	Asphalt		Windows were removed to convert it to a shed.	r	22	4
2202	0428200025	7	Corn Crib	Gambrel	N / A		Good	Good		Horizontal Slats	Asphalt			r	21	4
2202	0428200025	8	Garage	Pyramidal	N / A		Good	Good		Tin (Flat)	Asphalt			r	20	4
2202	0428200025	9	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			r	25	4
2201	0428400005	1	House	Upright and Wing	Greek Revival	1850-1870	Good	Good	Field Stone	Tin (Flat)	Asphalt	Inset, but now enclosed		r	33	4
2201	0428400005	1	House		N / A		Good	Good		Tin (Flat)	Asphalt			r		4
2201	0428400005	2	Barn	Transverse Frame	N / A	1880-1920	Fair	Good		Vertical Wood	Wood Shingles			r	30	4
2201	0428400005	3	Barn	Gothic Arched	N / A		Good	Good		Vertical Wood	Asphalt			r	31	4
2201	0428400005	4	Chicken Coop	Side Gabled	N / A		Fair	Good		Beveled Clapboard	Asphalt			r	29	4
2201	0428400005	5	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			r	32	4
358	0429100008	1	Shed	Front Gabled	N / A		Good	Good		Clapboard	Tin (Flat)			o	35	4
2005	0430100011	1	House	Upright and Wing	N / A	1860-1880	Fair	Poor	Field Stone	Clapboard	Asphalt	Open	All new windows of different sizes	q	8	4
2005	0430100011	2	House	House Trailer	N / A		Good	Good		Tin (Flat)	Tin (Flat)			q	9	4
2005	0430100011	3	Barn	Dairy Gambrel	N / A		Fair	Fair		Vertical Wood	Asphalt			q	11	4
2005	0430100011	4	Shed	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			q	12	4
2005	0430100011	5	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			q	10	4
2005	0430100011	6	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			q	13	4
2005	0430100011	7	Barn	Metal Pole Barn	N / A	1950-present	Good	Good		Tin (Flat)	Tin (Flat)			Q	13	4
2006	0430100015	1	House	Cottage	N / A	1910-1940	Good	Good	Poured Concrete	Vinyl Siding	Asphalt			q	3	4
2006	0430100015	2	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Tin (Flat)	Asphalt		Shed addition to front for cattle	q	5	4
2006	0430100015	3	Silo	Steel	N / A		Good	Good		Steel	Steel			q	4	4
2006	0430100015	4	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome			q	6	4
2006	0430100015	5	Garage	Front Gabled	N / A		Good	Good		Aluminum Siding	Asphalt			q	2	4
2006	0430100015	6	Corn Crib	Slant-Sided	N / A		Good	Good		Horizontal Slats	Asphalt			p	35	4
2006	0430100015	7	Chicken Coop	Slant-roofed	N / A		Good	Good		Vertical Wood	Asphalt		Windows changed	p	34	4
2006	0430100015	8	Shed	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			q	7	4
2006	0430100015	9	Corn Crib	Round	N / A		Good	Good		Wire Mesh	Tin (Flat)			p	36	4
2006	0430100015	10	Silo	Steel	N / A		Good	Good		Steel	Steel			p	37	4
2006	0430100015	11	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			q	1	4
2007	0430200024	1	House	Upright and Wing	N / A		Good	Good		Aluminum Siding	Asphalt	Enclosed	New windows	p	33	4
2007	0430200024	2	Shed	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt			p	32	4
2007	0430200024	3	Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Tin (Flat)			p	30	4
2007	0430200024	4	Garage	Side Gabled	N / A		Good	Good		Aluminum Siding	Asphalt			p	29	4
2007	0430200024	5	Barn	Dairy Gambrel	N / A		Good	Good		Vertical Wood	Asphalt			p	31	4
2007	0430200024	6	Chicken Coop	Side Gabled	N / A		Good	Good		Asbestos	Asphalt			p	28	4

2004	0430300004	1	House	Upright and Wing	Italianate	1860-1880	Good	Good	Field Stone	Vinyl Siding	Asphalt	Open - original		This farmstead had another house further back off the road which was a Greek Revival house situated next to the spring. This house was the "modern" house built around 1870. Its historic integrity is totally intact.	q	16	4
2004	0430300004	2	Barn	Dual Aisle	N / A	1850-1870	Good	Good		Vertical Wood	Asphalt			Includes front gable milkhouse and haymow dormer. This is a very rare type of barn with dual outside aisles and a central haymow/threshing bay with upper levels above the side stall bays. The upper level is floored-in with full logs laid side-by-side.	q	19	4
2004	0430300004	3	Silo	Poured Concrete	N / A		Good	Good		Poured Concrete	Concrete Conical				q	17	4
2004	0430300004	4	Outhouse	Side Gabled	N / A		Good	Good		Clapboard	Asphalt				q	20	4
2004	0430300004	5	Garage	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			2-door	q	15	4
2004	0430300004	6	Chicken Coop	Slant-roofed	N / A		Good	Good		Beveled Clapboard	Asphalt			Includes 2 small poultry sheds, also	q	21	4
2004	0430300004	7	Hog House	Front Gabled	N / A		Falling down	Good		Clapboard	Wood Shingles			This is a very rare type of hog house. Too bad it is too far gone to bring back. It is the only hog house that was located that had a built-in corn crib! (The corner bay that is gone was the horizontal slatted corn crib.)	q	18	4
359	0430400003	1	vacant		N / A									All Gone! Replaced by gravel pit. Had access into the root cellar/ basement via a trap-door on the front porch. The barn was across the road, but also gone.			4
360	0430400012	1	House	Upright and Wing	N / A	1860-1880	Good	Good		Aluminum Siding	Asphalt	Screened-in	Side wing addition on the north end; windows changed	Well cared for	g	23	4
360	0430400012	2	Root Cellar		N / A		Good	Good		Field Stone				Built into hillside	g	25	4
360	0430400012	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				g	26	4
360	0430400012	4	Shed	Gambrel	N / A		Good	Good		Plywood	Asphalt				g	24	4
2288	0431000000	1	(gone)		N / A									All Gone! (New house in its place)			4
120	0431100007	1	House	Upright and Wing	N / A	1860-1880	Good	Good	Field Stone	Stucco	Asphalt	Enclosed	Porch enclosed in the 1920's using molded block foundation; windows changed but still the size	Wonderful old farmstead tucked into rolling oak savannas and creekside	q	32	4
120	0431100007	2	Barn	Transverse Frame	N / A	1860-1890	Good	Good		Vertical Wood	Asphalt			Includes an attached gabled milkhouse	r	1	4
120	0431100007	3	Garage	Pyramidal	N / A		Good	Good		Vertical Wood	Wood Shingles			1-car	q	33	4
120	0431100007	4	Chicken Coop	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Note that the original 6-over-6 windows from the house were used in this chicken coop	q	34	4
120	0431100007	5	Shed	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Livestock shed; also includes concrete staved silo with metal dome roof	q	37	4
120	0431100007	6	Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Wood Shingles			Both bays are slatted for ear corn	q	363	4
120	0431100007	7	Shed	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Long deep machine shed	q	35	4
120	0431100007	8	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				q	31	4
361	0431200001	1	House	Upright and Wing	N / A		Good	Fair		Vertical Wood	Asphalt	Enclosed	All new windows (including sizes and shapes) resided and new chimney plus addition	Adaptive reuse into a horse stable run by volunteers for developmentally disabled kids	g	27	4
361	0431200001	2	Barn	Transverse Frame	N / A		Good	Good		Aluminum Siding	Asphalt			Has side addition and large gabled milkhouse	g	29	4
361	0431200001	3	Silo	Poured Concrete	N / A		Good	Good		Poured Concrete	Concrete Conical				g	31	4
361	0431200001	4	Shed	Side Gabled	N / A		Good	Good		Aluminum Siding	Asphalt			Old machine shed and shop that was connected to the barn via the barn shed addition; note the old doors	g	28	4
361	0431200001	5	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Used as a riding arena	g	32	4
361	0431200001	6	Pumphouse	Gambrel	N / A		Good	Good		Wood Shingles	Asphalt				g	30	4
361.5	0431200015	1	House	Ranch	N / A		Good	Good		Aluminum Siding	Asphalt		Has been converted to office space	Addition to rear that connects it to the former garage; used as MCCD Natural Resource Management department headquarters	k	1	4
361.5	0431200015	2	Barn	Dairy Gambrel	N / A		Good	Fair		Tin (Flat)	Tin (Flat)				k	3	4
361.5	0431200015	3	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome				k	4	4
361.5	0431200015	4	Garage	Side Gabled	N / A		Good	Good		Plywood	Asphalt			Converted to office space	k	5	4
361.5	0431200015	5	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				k	2	4
119.5	0431451003	1	Garage	Side Gabled	N / A		Good	Good		Aluminum Siding	Asphalt				r	3	4
119	0431451004	1	Mill	Upright and Wing	N / A	1840-1860	Good	Good		Vinyl Siding	Asphalt	Enclosed		Former "Barnard Mill"; is now a restaurant	r	4	4
119.3	0431452001	1	House	Upright and Wing	N / A	1860-1880	Good	Poor		Aluminum Siding	Asphalt		New everything	Barn is across street, now a separate parcel (site 118)	r	2	4
118	0431452002	1	House	Four-over-four	N / A	1910-1930	Good	Good		Clapboard	Asphalt	Enclosed		Enclosed second story sleeping porch; has a prairie style influence	r	7	4
118	0431452002	2	Barn	Dairy Gambrel	N / A		Good	Good		Vertical Wood	Asphalt			Originally went with house across the street	r	5	4
118	0431452002	3	Shed	Front Gabled	N / A		Good	Good		Vinyl Siding	Asphalt			Former machine shed converted into commercial business building	r	6	4
2288.5	0431453002	1	House	Side Gabled	N / A		Good	Good		Asbestos	Asphalt			Includes front gabled garage; across the Nippersink Creek from the mill	r	8	4
2225.5	0432100009	1	House	Cross Gabled	N / A	1890-1910	Good	Poor		Aluminum Siding	Asphalt		Porch expanded out, enclosed, then made into 2 story living area	MCCD staff housing	k	6	4
2225.5	0432100009	2	Barn	Transverse Frame	N / A	1880-1920	Poor	Poor		Asbestos	Tin (Flat)			Locally known as the "bat" barn since there is a large colony of bats who live there	k	8	4
2225.5	0432100009	3	Shed	Side Gabled	N / A		Very Poor	Poor		Asbestos	Asphalt			Machine shed converted into multi-car garage	k	7	4
2225.5	0432100009	4	House	Ranch	N / A		Good	Good		Asbestos	Asphalt			MCCD Intern housing	k	9	4
2225.5	0432100009	5	Shed	Metal Pole Barn	N / A		Very Poor	Good		Tin (Flat)	Tin (Flat)				k	10	4
2225.5	0432100009	6	Barn	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt			MCCD Region 1 Shop for maintenance crew	k	11	4
2225.5	0432100009	7	Shed	Front Gabled	N / A		Very Poor	Poor		Asbestos	Rolled Asphalt				k	12	4
2225	0432200010	1	House	Upright and Wing	Greek Revival	1850-1855	Excellent (Restored)	Excellent	Field Stone	Clapboard	Wood Shingles	none	Original summer kitchen was removed, but by using photos, it is going to be rebuilt exactly like the original	This house was built by Elon and Mary Powers as their first frame house after settling on this parcel in 1843. It is part of Glacial Park, owned by MCCD and is being restored by volunteers.	k	13	4
2225	0432200010	2	Barn	Three-bay Threshing	N / A		Good	Good		Tin (Flat)	Tin (Flat)			This is a pre-civil war barn period to the house, but it has been covered with tin. The original random-width planking is still under the tin and will at some point be restored.	k	14	4

2225	0432200010	3	Silo	Concrete Staved	N / A		Poor	Poor		Concrete Staved	none			Has since been taken down; was not period to the 1850's, but to the later dairy farming	k	1	4
2226	0432400001	1	House	Upright and Wing	N / A	1880-1920	Poor	Poor		Vertical Wood	Asphalt			Was part of horse stable; is not worth the money to maintain, so these farmstead buildings are going to be removed so that the Glacial Park entrance can be reworked through this site to remove the dangerous sharp curve in the roadway.	k	16	4
2226	0432400001	2	Barn	Transverse Frame	N / A		Poor	Poor		Tin (Flat)	Asphalt			Includes poured concrete silo	k	17	4
2226	0432400001	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Used as an arena	k	18	4
2227	0432400003	1	Barn	Transverse Frame	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			Has been converted into MCCC's education program area	k	19	4
2227	0432400003	2	Hog House	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Converted into MCCC Nursery Office	k	20	4
2227	0432400003	3	Shed	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				k	21	4
2227	0432400003	4	House	Side Gabled	N / A	1950-present	Good	Good		Clapboard	Asphalt	Open		Replacement house used for staff housing	k	24	4
2227	0432400003	5	Shed	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				k	25	4
2227	0432400003	6	Garage	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				k	26	4
2227	0432400003	7	Windmill		N / A		Good	Fair		Steel				Some blades missing	k	23	4
2227	0432400003	8	Outhouse	Front Gabled	N / A		Good	Good		Clapboard	Wood Shingles				k	24	4
2227	0432400003	9	Pumphouse	Side Gabled	N / A		Good	Good		Beveled Clapboard	Wood Shingles				k	22	4
2224	0433200009	1	House	Upright and Wing	N / A	1860-1880	Fair	Poor		Aluminum Siding	Asphalt	Enclosed	Windows changed	Part of horse stable operation	s	6	4
2224	0433200009	2	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Horse stable and arena	s	5	4
2224	0433200009	3	Shed	Side Gabled	N / A		Good	Good		Tin (Flat)	Asphalt			Machine Shed	s	7	4
2224	0433200009	4	Barn	Three-bay Threshing	N / A	1860-1880	Very Poor	Poor		Vertical Wood	Asphalt			Has been added onto several times; includes concrete staved silo	s	8	4
2301	0433400004	1	House	Cross Gabled	N / A	1880-1920	Fair	Poor		Vinyl Siding	Asphalt	Enclosed	Converted to office space	Was MCCC office area, but now has been converted to intern housing	k	28	4
2301	0433400004	2	Barn	Three-bay Threshing	N / A	1860-1880	Excellent (Restored)	Excellent	Field Stone	Vertical Wood	Asphalt			This barn is original and in excellent shape. It is much older than the house and probably went with an older house on this site.	k	31	4
2301	0433400004	3	Shed	Side Gabled	N / A		Good	Good		Clapboard	Asphalt			Machine shed	k	30	4
2301	0433400004	4	Garage		N / A		Good	Good		Aluminum Siding	Asphalt				k	29	4
2300	0433400044	1	House	I-house	N / A	1860-1880	Poor	Poor		Wood Shingles	Asphalt	Added	Rear addition and new windows	Part of landscaping business	s	1	4
2300	0433400044	2	Shed	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Office for business	s	3	4
2300	0433400044	3	Barn	Composite	N / A	1880-1900	Fair	Fair		Vertical Wood	Asphalt			A series of farm buildings: 1 large transverse frame barn connected to another one that is perpendicular, 2 sheds and 3 silos (2 metal & 1 concrete staved)	s	2	4
2300	0433400044	4	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				s	4	4
2228	0434100006	1	House	Bungalow	N / A	1900-1930	Good	Good		Clapboard	Asphalt	Enclosed			s	9	4
2228	0434100006	2	Shed	Gambrel	N / A	1910-1940	Good	Good		Beveled Clapboard	Asphalt		Has shed addition	Includes small uneven gable shed	s	11	4
2228	0434100006	3	Shed	Front Gabled	N / A		Good	Good		Clapboard	Asphalt				s	10	4
2201.5	0434100009	1	Barn		N / A		Falling down	Poor		Beveled Clapboard	Wood Shingles				r	37	4
2201.5	0434100009	2	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome			Includes side gabled machine shed and another shed falling down	r	36	4
2201.5	0434100009	3	Chicken Coop	Uneven Gable	N / A		Good	Good		Clapboard	Vinyl Siding				r	34	4
2201.5	0434100009	4	Shed	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Former hog house or other livestock	r	35	4
2252	0434200010	1	House	Upright and Wing	N / A	1880-1920	Good	Good		Aluminum Siding	Asphalt	Altered and enclosed	Too covered by alum. To determine whether this was built as an upright and wing or if one section was later added on to the other	Very modernized	l	31	4
2252	0434200010	2	Shed	Uneven Gable	N / A	1850-1870	Fair	Good		Vertical Wood	Wood Shingles			This is actually a very old little barn that was added onto			4
2252	0434200010	3	Milkhouse	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				l	29	4
2252	0434200010	4	Barn	Three-bay Threshing	N / A	1850-1870	Good	Excellent	Field Stone	Vertical Wood	Wood Shingles			This could be restored	l	27	4
2252	0434200010	5	Silo	Poured Concrete	N / A		Good	Good		Poured Concrete	Concrete Conical				l	28	4
2252	0434200010	6	Shed	Slant-roofed	N / A		Good	Good		Beveled Clapboard	Asphalt			Addition onto barn	l	23	4
2252	0434200010	7	Shed	Side Gabled	N / A		Poor	Good		Clapboard	Wood Shingles				l	26	4
2252	0434200010	8	Hog House	Side Gabled	N / A		Fair	Good		Beveled Clapboard	Wood Shingles				l	32	4
2252	0434200010	9	Shed	Side Gabled	N / A		Fair	Good		Vertical Wood	Wood Shingles			Machine shed	l	25	4
2252	0434200010	10	Chicken Coop	Uneven Gable	N / A		Very Poor	Good		Clapboard	Wood Shingles			Note that the original 2-over-2 windows from the house were used on the chicken coop when they were replaced	l	24	4
2200.5	0434300002	1	House	Four-over-four	Italianate	1870-1890	Fair	Good		Asbestos	Asphalt	Enclosed	Porch enclosed from the inside so that ornamentation is still intact	This entire farmstead looked abandoned; notice paired corbels (decorative brackets at roof)	s	12	4
2200.5	0434300002	2	Hog House	Front Gabled	N / A		Very Poor	Good		Beveled Clapboard	Wood Shingles		Converted to garage		s	13	4
2200.5	0434300002	3	Barn	Gothic Arched	N / A		Poor	Good		Vertical Wood	Asphalt			Includes gabled milkhouse and poured concrete silo	s	14	4
2200	0434300005	1	House	Side Gabled	N / A	1880-1920	Good	Good		Aluminum Siding	Asphalt				s	15	4
2200	0434300005	2	Barn	Three-bay Threshing	N / A	1850-1870	Good	Good		Vertical Wood	Tin (Flat)			Includes attached large milkhouse	s	20	4
2200	0434300005	3	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	none			A collection of 3 silos, one of each major type: poured concrete, concrete staved and metal A.O. Smith Harvestore	s	19	4
2200	0434300005	4	Shed	Side Gabled	N / A		Good	Good		Vertical Wood	Wood Shingles			Machine shed	s	18	4

2200	0434300005	5	Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Wood Shingles			Also hog house	s	21	4
2200	0434300005	6	Corn Crib	Broken Eave	N / A		Good	Good		Vertical Wood	Rolled Asphalt			Very large for this style	s	17	4
2200	0434300005	7	Garage	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt				s	16	4
2229	0434400007	1	House	Upright and Wing	N / A	1860-1880	Good	Good		Aluminum Siding	Asphalt	Enclosed	Very modernized		l	8	4
2229	0434400007	2	Barn	Transverse Frame	N / A	1880-1920	Fair	Fair		Vertical Wood	Asphalt			Uneven gable due to one side being larger	l	9	4
2229	0434400007	3	Shed	Side Gabled	N / A		Fair	Fair		Vertical Wood	Asphalt			A series of 3 sheds of varying materials and styles	l	2	4
2229	0434400007	4	Shed	Side Gabled	N / A		Fair	Fair		Vertical Wood	Asphalt			Machine shed an a poured concrete silo	l	3	4
2229	0434400007	5	Hog House	Front Gabled	N / A		Fair	Good		Vertical Wood	Asphalt				l	4	4
2229	0434400007	6	Shed	Uneven Gable	N / A		Fair	Good		Beveled Clapboard	Asphalt			Machine shed	l	5	4
2229	0434400007	7	Milkhouse	Front Gabled	N / A		Fair	Good		Beveled Clapboard	Asphalt			Includes a molded block addition, too	l	10	4
2229	0434400007	8	Shed	Side Gabled	N / A		Falling down	Good		Vertical Wood	Asphalt				l	7	4
2229	0434400007	9	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				l	6	4
2229	0434400007	10	Grain Bin	Round	N / A		Good	Good		Tin (Corrugated)	Tin (Flat)			5 Bins	l	1	4
2251	0435300003	1	House	Cottage	N / A		Fair	Good		Vinyl Siding	Asphalt				l	13	4
2251	0435300003	2	Garage	Front Gabled	N / A		Good	Good		Wood Shingles	Asphalt				l	12	4
2251	0435300003	3	Milkhouse	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt				l	11	4
2251	0435300003	4	Barn	Three-bay Threshing	N / A	1860-1880	Fair	Poor		Tin (Flat)	Asphalt			Has been added onto both at the end and to the side	l	19	4
2251	0435300003	5	Silo	Poured Concrete	N / A		Good	Good		Poured Concrete	Concrete Conical				l	18	4
2251	0435300003	6	Chicken Coop	Slant-roofed	N / A		Good	Good		Asbestos	Asphalt			Notice old 6-pane windows	l	14	4
2251	0435300003	7	Shed	Side Gabled	N / A		Good	Good		Plywood	Asphalt				l	15	4
2251	0435300003	8	Garage	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Machine shed	l	16	4
2251	0435300003	9	Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Asphalt			Taller and narrower than normal	l	17	4
2251	0435300003	10	Grain Bin	Round	N / A		Good	Good		Tin (Corrugated)	Tin (Flat)			3 Bins	l	20	4
2251	0435300003	11	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				l	21	4
2250	0435400001	1	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				l	23	4
2250	0435400001	2	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			This is part of the "Stade Family Farm" business. The house used to be across the street, but has been replaced with modern construction.	l	26	4
2250	0435400001	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				l	22	4
2250	0435400001	4	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Open on one side	l	25	4
2250	0435400001	5	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Includes house trailer	l	24	4
2250	0435400001	6	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Open on side	l	28	4
2250	0435400001	7	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome			6 silos: 2 Harvestore and 4 concrete staved	l	27	4
2248	0435400004	1	House	Upright and Wing	N / A	1860-1890	Good	Good		Aluminum Siding	Asphalt	Enclosed			l	29	4
2248	0435400004	2	Barn	Transverse Frame	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			Includes poured concrete silo	l	34	4
2248	0435400004	3	Milkhouse	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Detached	l	33	4
2248	0435400004	4	Chicken Coop	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				l	32	4
2248	0435400004	5	Shed	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				l	31	4
2248	0435400004	6	Hog House	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt				l	35	4
2248	0435400004	7	Corn Crib	Slant-Sided	N / A		Good	Good		Horizontal Slats	Tin (Flat)				l	30	4
2709	0436100006	1	House	Upright and Wing	N / A		Good	Good		Asbestos	Asphalt	Enclosed	Very changed: windows, siding, etc.	Site is way back off the road and only the silo is visible	l	21	4
2709	0436100006	2	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				l	17	4
2709	0436100006	3	Shed	Front Gabled	N / A		Fair	Good		Tin (Flat)	Tin (Flat)			Possible small barn underneath siding	l	20	4
2709	0436100006	4	Shed	Front Gabled	N / A		Poor	Poor		Asbestos	Tin (Flat)		Shed addition		l	16	4
2709	0436100006	5	Milkhouse	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				l	19	4
2709	0436100006	6	Shed	Slant-roofed	N / A		Good	Good		Beveled Clapboard	Asphalt			Also includes wire mesh corn crib	l	15	4
2709	0436100006	7	Silo	Poured Concrete	N / A		Good	Good		Poured Concrete	Concrete Conical				l	14	4
2709	0436100006	8	Corn Crib	Slant-roofed	N / A		Falling down	Good		Vertical Slats	Asphalt			Long, tall, narrow, single bay version	l	13	4
2709	0436100006	9	Gazebo	Hexagonal	N / A		Good	Good		Vertical Wood	Wood Shingles			New	l	18	4
2710	0436200006	1	House	Upright and Wing	N / A	1880-1900	Poor	Fair		Clapboard	Asphalt	Partially enclosed	Window removed		j	25	4
2710	0436200006	2	Barn	Transverse Frame	N / A	1880-1920	Fair	Good		Vertical Wood	Asphalt			Includes gabled milkhouse	j	23	4
2710	0436200006	3	Grain Bin	Round	N / A		Good	Good		Tin (Corrugated)	Tin (Flat)				j	24	4
2710	0436200006	4	Chicken Coop	Slant-roofed	N / A		Good	Fair		Beveled Clapboard	Asphalt		Some windows removed		j	21	4
2710	0436200006	5	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				j	22	4
2247	0436300001	1	House	Four-over-four	N / A		Good	Fair		Aluminum Siding	Asphalt	Enclosed		Includes side wing	j	3	4
2247	0436300001	2	Barn	Transverse Frame	N / A	1900-1930	Good	Good	Cement Block	Vertical Wood	Asphalt				j	5	4
2247	0436300001	3	Milkhouse	Side Gabled	N / A		Good	Good		Clapboard	Asphalt			Detached	j	4	4
2247	0436300001	4	Secondary House	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Former livestock shed	j	2	4
2247	0436300001	5	Shed	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt				j	1	4

2247	0436300001	6	Grain Bin	Round	N / A		Good	Good		Tin (Corrugated)	Tin (Flat)			Includes a new metal pole barn	j	6	4
2246	0436300004	1	House	Upright and Wing	N / A	1860-1880	Fair	Fair		Clapboard	Asphalt	Enclosed	Deck added	Still has some original windows	j	9	4
2246	0436300004	2	Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			Pumpkin farm	j	7	4
2246	0436300004	3	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				j	8	4
2246	0436300004	4	House	House Trailer	N / A		Poor	Good		Tin (Flat)	Tin (Flat)				j	10	4
2707	0436400004	1	House	Cross Gabled	N / A	1870-1900	Good	Good	Field Stone	Clapboard	Asphalt		Rear addition		j	16	4
2707	0436400004	2	Barn	Transverse Frame	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			Includes concrete staved silo with metal dome roof	j	13	4
2707	0436400004	3	Milkhouse	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Attached	j	12	4
2707	0436400004	4	Shed	Slant-roofed	N / A		Fair	Good		Vertical Wood	Asphalt				j	14	4
2707	0436400004	5	Barn	Three-bay Threshing	N / A	1860-1880	Good	Good		Vertical Wood	Asphalt				j	11	4
2707	0436400004	6	Shed	Front Gabled	N / A		Good	Good		Aluminum Siding	Asphalt				j	17	4
2707	0436400004	7	Shed	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Livestock shed	j	18	4
2707	0436400004	8	Hog House	Front Gabled	N / A		Poor	Good		Vertical Wood	Wood Shingles				j	19	4
2707	0436400004	9	Chicken Coop	Slant-roofed	N / A		Fair	Good		Vertical Wood	Asphalt		Some windows removed		j	20	4
2707	0436400004	10	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				j	15	4
2711	0436400006	1	House	Side Gabled	N / A		Good	Fair		Vinyl Siding	Asphalt	Enclosed	Modernized	Back in middle of block	j	28	4
2711	0436400006	2	Barn	Transverse Frame	N / A		Good	Good		Vertical Wood	Asphalt			Includes attached milkhouse	j	32	4
2711	0436400006	3	Shed	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Former hog house covered in tin	j	33	4
2711	0436400006	4	Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome				j	37	4
2711	0436400006	5	Silo	Steel	N / A		Good	Good		Steel	Steel			"A.O. Smith Harvestore"	j	36	4
2711	0436400006	6	Garage	Pyramidal	N / A		Good	Good		Vinyl Siding	Asphalt			2-car	j	27	4
2711	0436400006	7	Outhouse	Side Gabled	N / A		Good	Good		Clapboard	Asphalt				j	26	4
2711	0436400006	8	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				j	29	4
2711	0436400006	9	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				j	35	4
2711	0436400006	10	Shed	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				j	31	4
2711	0436400006	11	Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				j	30	4
2711	0436400006	12	Grain Bin	Round	N / A		Good	Good		Tin (Corrugated)	Tin (Flat)			5 Bins	j	34	4