

Previous Site	Pin Number	Structure Type	Vernacular Form	Architectural Style	Circa	Condition	Integrity	Foundation	Walls	Roof	Porch	Alterations	History	Roll	Photo	Prefix	
1919	13-01-000-000																13
1916	13-01-000-000																13
1918	13-01-000-000																13
1915	13-01-000-000																13
1917	13-01-000-000																13
143	13-02-151-001	01 House	Side Gabled	N / A	1860-1890	Good	Fair	Field Stone	Vinyl Siding	Asphalt		New windows, siding and an addition on rear	Note the original STONE Cabin behind house	RR	23		13
143	13-02-151-001	02 Cabin	Front Gabled	N / A		Good	Excellent		Field Stone	Asphalt			This is the original stone cabin for this site! A thorough examination was made of this structure inside and out. The windows and door frame are original (complete with square nails) and there was a cookstove to the center rear of the cabin.	RR	25		13
143	13-02-151-001	03 Garage	Side Gabled	N / A	1950-present	Good	Good	Poured Concrete	Vinyl Siding	Asphalt			2-car with workshop area	RR	24		13
143	13-02-151-001	04 Shed	Side Gabled	N / A	1950-present	Good	Good		Vertical Wood	Asphalt			Horse stable	RR	26		13
142	13-02-152-001	01 House	Ranch	Ranch	1950-present	Good	Good		Aluminum Siding	Asphalt			The previous survey photos for this site were on site 144.	RR	28		13
142	13-02-152-001	02 Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Dome				RR	27		13
1922	13-02-200-006	01 House	Upright and Wing	N / A	1860-1890	Good	Good		Clapboard	Asphalt		Addition to rear	Very close to road, next to Cold Springs Schoolhouse	RR	34		13
1923	13-02-300-028	01 House	Upright and Wing	N / A	1860-1880	Good	Good		Clapboard	Wood Shingles		Has been modernized, but tastefully in accordance with old architectural style	Has stone upright section	TT	1		13
1923	13-02-300-028	02 Barn	Dairy Gambrel	N / A	1880-1920	Good	Good	Poured Concrete	Vertical Wood	Asphalt				TT	2		13
1923	13-02-300-028	03 Garage	Side Gabled	N / A		Good	Good		Tin (Flat)	Asphalt			3-car with second story dormer area	TT	3		13
1923	13-02-300-028	04 Shed	Front Gabled	N / A		Good	Good		Beveled Clapboard	Wood Shingles			Possible former pumphouse	TT	4		13
1920	13-02-400-019	01 School	Front Gabled	N / A	1860-1880	Good	Good		Clapboard	Asphalt			Former Cold Springs School; now used as Village of Bull Valley offices	RR	35		13
140	13-03-100-001	01 House	I-house	N / A	1860-1890	Fair	Poor	Field Stone	Vertical Wood	Asphalt		Additions, windows, siding and chimney are new	This house has no apparent old features left; its historic integrity is non-existent.	GG	27		13
140	13-03-100-001	02 Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Tin (Flat)			Also includes the original three-bay threshing barn for this site and a concrete staved silo with a metal dome roof	GG	26		13
140	13-03-100-001	03 Shed	Front Gabled	N / A	1880-1920	Good	Good		Clapboard	Asphalt			May have been pumphouse	GG	24		13
140	13-03-100-001	04 Garage	Side Gabled	N / A	1950-present	Good	Good	Poured Concrete	Vertical Wood	Asphalt				GG	25		13
144	13-03-200-007	01 House	Cottage	Cape Cod	1910-1940	Good	Fair	Poured Concrete	Vertical Wood	Asphalt			Possible second house on this site	RR	30		13
144	13-03-200-007	02 Shed	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Includes a horse stable and a storage shed	RR	29		13
141	13-03-300-004	01 House	Upright and Wing	Greek Revival	1860-1870	Good	Excellent	Field Stone	Clapboard	Asphalt	Inset and open		Wonderful house in its original form with nearly no modifications. Note the frieze windows being a four-light window instead of the more common 3-light windows. Also, note this is a later Greek Revival with its 2-over-2 windows instead of 6-over-6.	QQ	37		13
141	13-03-300-004	02 Shed	Side Gabled	N / A		Excellent (New)	Good						Too soon to tell whether this shed/barn will be in accordance with the house architecture.	QQ	36		13
1933.5	13-04-400-003	01 House	Four-over-four	Foursquare	1890-1910	Good	Good	Granite	Clapboard	Asphalt			Possibly the second house on this site; picture from previous survey was on wrong map point	RR	1		13
1933.5	13-04-400-003	02 Garage	Front Gabled	N / A		Good	Good		Plywood	Asphalt			3-car	RR	2		13
1933	13-04-400-007	01 House	Front Gabled	Colonial Revival	1880-1920	Good	Good		Vinyl Siding	Asphalt	Open	New windows and porch		RR	7		13
1933	13-04-400-007	02 Garage	Side Gabled	N / A	1930-1950	Good	Good	Poured Concrete	Clapboard	Asphalt			2-car	RR	5		13
1933	13-04-400-007	03 Coop	Uneven Gable	N / A		Good	Good		Clapboard	Asphalt				RR	4		13
1933	13-04-400-007	04 Shed	Side Gabled	N / A	1950-present	Good	Good		Plywood	Asphalt			Horse Stable	RR	6		13
1933	13-04-400-007	05 Shed	Front Gabled	N / A	1950-present	Good	Good		Plywood	Asphalt			Playhouse	RR	3		13
1932	13-04-400-008	01 House	Upright and Wing	Greek Revival	1850-1860	Fair	Good	Field Stone	Wood Shingles	Asphalt	Open Inset porch	Although alum. Storm windows were added, the original windows are still under them. Also, wood shingles were put over the clapboard in the 1910's.	This is a working dairy farm on the edge of Wood stock and Bull Valley. The entire set of farm buildings retain their original details.	RR	21		13
1932	13-04-400-008	02 Kitchen	Side Gabled	N / A		Good	Good		Wood Shingles	Asphalt		Was detached, but the area between the side wing and summer kitchen was connected	Note the chimney for the summer kitchen; also woodshed storage in back	RR	20		13
1932	13-04-400-008	03 Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			This is one of the longest dairy gambrel barns in the area; photo also includes one of the 3 concrete staved silos	RR	22		13
1932	13-04-400-008	04 Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Dome			Includes large dairy gambrel addition that is only dwarfed by the huge scale of the big barn	RR	19		13
1932	13-04-400-008	05 Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Dome				RR	18		13
1932	13-04-400-008	06 Barn	Dual Aisle	N / A	1850-1870	Fair	Good		Vertical Wood	Asphalt			Very wide barn with 2 aisles instead of just one center aisle; also has a cross gable for access into the center from the side; also common of this style is to have haymow area on the ground level	RR	17		13
1932	13-04-400-008	07 Shed	Gambrel	N / A	1900-1930	Good	Good		Beveled Clapboard	Tin (Flat)				RR	12		13
1932	13-04-400-008	08 Shed	Front Gabled	N / A		Fair	Good		Vertical Wood	Asphalt				RR	14		13
1932	13-04-400-008	09 Shed	Uneven Gable	N / A		Good	Good		Vertical Wood	Asphalt				RR	11		13
1932	13-04-400-008	10 Corn Crib	Transverse Aisle	N / A		Fair	Good		Beveled Clapboard	Asphalt		Has had slats filled-in		RR	15		13
1932	13-04-400-008	11 Shed	Side Gabled	N / A	1930-1950	Good	Good		Vertical Wood	Asphalt				RR	13		13
1932	13-04-400-008	12 Outhouse	Slant-roofed	N / A		Good	Good		Wood Shingles	Asphalt				RR	10		13
1932	13-04-400-008	13 Grain Bin	Round	N / A		Good	Good		Tin (Corrugated)	Tin (Flat)			Includes grain dryer	RR	16		13
1108	13-07-300-022	01 House	Four-over-four	Foursquare	1880-1920	Good	Fair	Cement Block	Aluminum Siding	Asphalt	Enclosed	Resided	Unclear if this is the older version or the newer version of this form; too covered up with alum. To tell	3A	17		13
1108	13-07-300-022	02 Barn	Dairy Gambrel	N / A	1880-1920	Good	Fair	Field Stone	Plywood	Asphalt			Includes tall concrete staved silo with no roof	3A	16		13
1108	13-07-300-022	03 Garage	Front Gabled	N / A	1910-1940	Good	Good	Poured Concrete	Beveled Clapboard	Asphalt			2-car	3A	9		13
1108	13-07-300-022	04 Coop	Side Gabled	N / A		Good	Excellent	Field Stone	Beveled Clapboard	Wood Shingles		Original coop added onto in the early 1900's	Field stone wall still in good shape	3A	10		13
1108	13-07-300-022	05 Garage	Front Gabled	N / A	1910-1940	Fair	Good	Poured Concrete	Beveled Clapboard	Asphalt			Has chimney for workshop heat	3A	15		13
1108	13-07-300-022	06 Milkhouse	Side Gabled	N / A	1900-1930	Good	Good	Poured Concrete	Beveled Clapboard	Asphalt			Has tiny addition	3A	14		13
1108	13-07-300-022	07 Coop	Broken Eave	N / A		Fair	Fair	Poured Concrete	Beveled Clapboard	Wood Shingles		Windows have been removed	Was possibly a small hog house	3A	18		13

Previous Site	Pin Number	Structure Type	Vernacular Form	Architectural Style	Circa	Condition	Integrity	Foundation	Walls	Roof	Porch	Alterations	History	Roll	Photo	Prefix
1108	13-07-300-022	08 Shed	Side Gabled	N / A		Poor	Good		Vertical Wood	Wood Shingles			Machine shed	3A	13	13
1108	13-07-300-022	09 Shed	Side Gabled	N / A		Poor	Fair		Cement Block	Asphalt				3A	11	13
1108	13-07-300-022	10 Shed	Side Gabled	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Machine shed	3A	12	13
1105.5	13-07-452-002	01 Cemetery		N / A	1850-1870	Good	Good		Tin (Flat)	Asphalt			Very old stones; no new ones, but it is being mowed	3A	19	13
1106	13-07-452-003	01 House	Front Gabled	N / A	1880-1920	Good	Fair		Vinyl Siding	Asphalt	Removed supports	Added side porch roof and residing	Has had details stripped off; also has had an attached garage added	3A	8	13
1106	13-07-452-003	02 Shed	Side Gabled	N / A		Good	Good	Cement Block	Clapboard	Asphalt				3A	7	13
1105	13-07-477-002	01 Garage	Side Gabled	N / A		Fair	Fair		Aluminum Siding	Asphalt			Has extra workspace area	3A	3	13
1105	13-07-477-002	01 House	Side Gabled	N / A		Fair	Poor		Aluminum Siding	Asphalt		Windows changed and none appropriate siding used	Major additions; not apparent historic integrity left	3A	4	13
1934.2	13-09-126-014	01 House	Side Gabled	Greek Revival		Good	Fair		Clapboard	Asphalt	Open	Added onto and cornice returns removed except for part of one	Has original 6-over-6 windows and pilaster remnant on back	3Y	8	13
1934	13-09-126-015	01 House	Cottage	Cape Cod		Good	Good		Clapboard	Asphalt			This is the structure that matches the previous survey photo, but when the old sites were matched, this one was taken. However, it is the one next door that is the really old and is now 1934.2	3Y	9	13
1934.5	13-09-226-002	01 House	Upright and Wing	N / A		Good	Good		Clapboard	Wood Shingles		Has had 2 bay windows added and rear addition	Very well cared for; notice back wing which was attached summer kitchen with wood shed behind	RR	9	13
1934.5	13-09-226-002	02 Barn	Three-bay Threshing	N / A		Good	Good		Vertical Wood	Asphalt		Has been made into a garage		RR	8	13
1893.3	13-09-426-006	01 House	Cottage	N / A	1860-1920	Fair	Poor	Field Stone	Aluminum Siding	Asphalt	Altered	Hardly recognizable! Has been turned from a Greek Revival into a Bungalow	NOTE the TOMBSTONES in the SIDEWALK on this site! This was built as a hired hand's house for the neighboring McConnel house, but this has now been split into a separate parcel.	XX	31	13
1893.3	13-09-426-006	02 Tombstones		N / A		Good	Good					Moved to be used as a front sidewalk to this house	These came from the abandoned McConnel cemetery on the back of the farm; note that these burials are not McConnel's (they are thought to be of servants).	XX	32	13
1893.3	13-09-426-006	03 Barn	Dairy Gambrel	N / A	1880-1900	Good	Excellent	Field Stone	Vertical Wood	Slate		none	This is a McConnel barn for the McConnel farm next door. When the second house was split into a separate parcel, they also took the barn. Note that this is the only barn in any of the survey data with a slate roof! (The McConnel's were very well-to-do).	XX	29	13
1893.3	13-09-426-006	04 Barn		N / A		Good	Good		Tin (Flat)	Asphalt			Second view to show close-up of the slate; also on full view notice the symmetry of the windows around the banked entrance door.	XX	28	13
1893.3	13-09-426-006	05 Garage	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			2-car	XX	30	13
1898.5	13-09-426-013	01 House	Upright and Wing	Greek Revival	1850-1860	Fair	Fair	Cobblestone	Aluminum Siding	Asphalt		Alum. Siding added, some windows changed, porch enclosed	This is the A.B. McConnel farmstead, which still has a McConnel descendent living there. It is an 1872 Plat Book illustration house, but would take a lot of work to bring it back. However, beyond the obvious, it has remained internally unchanged.	XX	27	13
1898.2	13-09-426-017	01 Barn	Dairy Gambrel	N / A	1880-1920	Fair	Fair		Vertical Wood	Asphalt			Now used as maintenance sheds for the golf course. House was a very grand Queen Anne that got run-down and has since been demolished. Note castle top on poured concrete silo.	XX	24	13
1898.2	13-09-426-017	02 Garage	Side Gabled	N / A	1910-1940	Good	Good		Molded Block	Asphalt			Large machine shed	XX	25	13
1898.2	13-09-426-017	03 Shed	Gambrel	N / A	1950-present	Poor	Good		Plywood	Asphalt				XX	26	13
1930	13-10-000-000	01		N / A									Totally gone!			13
1931	13-10-000-000	01		N / A									Totally gone!			13
1929	13-10-126-002	01 House	Upright and Wing	N / A	1860-1890	Good	Good		Clapboard	Asphalt		Bays & additions	Well maintained	SS	19	13
1929	13-10-126-002	02 Garage	Front Gabled	N / A		Good	Good		Clapboard	Asphalt			2-car with living space above	SS	18	13
1899	13-10-300-003	01 House	Upright and Wing	N / A	1860-1880	Fair	Fair		Aluminum Siding	Asphalt			This was a former school made into a home	XX	23	13
1899	13-10-300-003	02 Outhouse	Side Gabled	N / A		Good	Good		Asbestos	Asphalt			From the school	XX	21	13
1899	13-10-300-003	03 Garage	Front Gabled	N / A	1910-1940	Fair	Fair		Asbestos	Asphalt			1-car	XX	22	13
1898	13-10-300-004	01 House	Upright and Wing	Greek Revival	1850-1870	Fair	Good	Field Stone	Brick	Asphalt		Windows changed and front door changed with elimination of transom and side lights	This is one of the decorative brick houses where the bricks form a protruding eave and dentils. There are only a few examples of these left. However, this one needs major brick repairs due to large cracks that could be structural.	XX	10	13
1898	13-10-300-004	02 Barn	Transverse Frame	N / A	1880-1900	Poor	Good		Vertical Wood	Wood Shingles			Includes a large gable rear addition	XX	13	13
1898	13-10-300-004	03 Barn	Three-bay Threshing	N / A	1860-1880	Poor	Poor		Vertical Wood	Asphalt		Has shed additions on both sides		XX	12	13
1898	13-10-300-004	04 Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome			Includes 3 silos	XX	15	13
1898	13-10-300-004	05 Garage	Side Gabled	N / A	1950-present	Fair	Good		Beveled Clapboard	Asphalt			Includes open pole barn structure behind it	XX	11	13
1898	13-10-300-004	06 Shed	Front Gabled	N / A		Very Poor	Poor		Tin (Flat)	Tin (Flat)				XX	14	13
1901	13-10-300-005	01 House	Four-over-four	Foursquare	1880-1920	Good	Good		Wood Shingles	Asphalt	Enclosed		Note that this is where the site 1901 map point is and that the 1901 picture was wrong. However, the wrong house in the 1901 picture has been demolished for a subdivision.	XX	19	13
1901	13-10-300-005	02 Garage	Side Gabled	N / A	1910-1940	Good	Good		Clapboard	Asphalt			2-car; has large dormer	XX	18	13
1901	13-10-300-005	03 Coop	Slant-roofed	N / A		Good	Good		Beveled Clapboard	Asphalt		Made into a garage		XX	16	13
1901	13-10-300-005	04 Shed	Side Gabled	N / A	1950-present	Good	Good		Plywood	Asphalt			Summer house	XX	17	13
1925	13-11-100-027	01 Cabin	Side Gabled	N / A	1840-1850	Excellent (Restored)	Excellent		Log	Wood Shingles		Added onto at rear in historically sensitive additions	This log cabin was discovered during remodeling. It had been sealed inside of modernized house, but never altered. When discovered, the owners exposed it once again for all to admire!	SS	31	13
1925	13-11-100-027	02 House	Front Gabled	N / A		Good	Good	Limestone	Log	Wood Shingles	Open		Added on to the back of the log cabin	SS	32	13
1925	13-11-100-027	03 Barn	Carriage	N / A		Good	Good		Vertical Wood	Wood Shingles		Porch added and entire structure converted into living space	This house mimics the connected houses out east except a different order (little house, big house, barn)	SS	33	13
1924	13-11-100-036	01 Barn	Three-bay Threshing	N / A	1860-1890	Good	Good		Vertical Wood	Asphalt		Originally a barn that was made into a house.	Sited on the parcel next to the log cabin and was formerly part of that site.	SS	34	13
1924	13-11-100-036	02 Barn		N / A		Good	Good		Vertical Wood	Asphalt			Second view to show roadside area	SS	35	13
1924	13-11-100-036	03 Garage	Side Gabled	N / A	1950-present	Good	Good		Vertical Wood	Asphalt			2-car	SS	36	13
1924	13-11-100-036	04 Shed	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Horse stable	SS	37	13
1928	13-11-300-001	01		N / A									All gone! Now a subdivision			13
1926	13-11-400-002	01 House	Side Gabled	N / A	1860-1890	Good	Fair	Field Stone	Clapboard	Wood Shingles		Large screened-in porch added	Sited next to large glacial kettle hole	SS	29	13
1926	13-11-400-002	02 Garage	Pyramidal	N / A	1910-1940	Excellent (Restored)	Excellent	Poured Concrete	Brick	Wood Shingles			2-car; Perfect!	SS	28	13
1926	13-11-400-002	03 Shed	Front Gabled	N / A	1930-1950	Good	Good		Clapboard	Asphalt				SS	30	13
1927	13-11-400-006	01 House	Cottage	Bungalow	1910-1940	Fair	Good	Poured Concrete	Clapboard	Asphalt	Enclosed		With clipped gables	SS	27	13

Previous Site	Pin Number	Structure Type	Vernacular Form	Architectural Style	Circa	Condition	Integrity	Foundation	Walls	Roof	Porch	Alterations	History	Roll	Photo	Prefix
1927	13-11-400-006	02 Barn	Gothic Arched	N / A	1910-1940	Falling down	Poor		Vertical Wood	Asphalt				SS	26	13
1927	13-11-400-006	03 Silo	Molded Block	N / A	1910-1940	Good	Excellent		Molded Block	Clapboard			This silo is the best part of this otherwise run-down site	SS	25	13
1927	13-11-400-006	04 Milkhouse	Front Gabled	N / A		Poor	Good		Tin (Flat)	Asphalt			Detached	SS	24	13
1927	13-11-400-006	05 Shed	Side Gabled	N / A		Very Poor	Poor		Clapboard	Asphalt			2 sheds	SS	23	13
1927	13-11-400-006	06 Shed	Side Gabled	N / A		Fair	Fair		Clapboard	Wood Shingles			Livestock quarters	SS	22	13
1927	13-11-400-006	07 Garage	Front Gabled	N / A		Very Poor	Fair		Asbestos	Asphalt				SS	21	13
1927	13-11-400-006	08 Coop	Uneven Gable	N / A		Falling down	Poor		Clapboard	Asphalt				SS	20	13
1914	13-12-200-024	01 Barn	Dairy Gambrel	N / A		Good	Good		Tin (Flat)	Asphalt			Includes poured concrete silo	RR	37	13
1914	13-12-200-024	02 Shed	Side Gabled	N / A	1950-present	Good	Good		Vertical Wood	Asphalt				RR	36	13
1914	13-12-200-024	03 Shed	Gambrel	N / A		Good	Good		Vertical Wood	Tin (Flat)				SS	1	13
1913.5	13-12-300-002	01 House	Upright and Wing	N / A		Good	Fair		Vinyl Siding	Asphalt		Additions galore!	Includes attached garage and attached conservatory	SS	2	13
1913.5	13-12-300-002	02 Barn	Three-bay Threshing	N / A	1860-1890	Good	Good		Vertical Wood	Asphalt				SS	4	13
1913.5	13-12-300-002	03 Pumphouse	Side Gabled	N / A		Good	Good		Stone	Wood Shingles			Has been redone	SS	3	13
1913	13-12-300-020	01 House	Upright and Wing	Colonial Revival	1880-1920	Good	Good	Granite	Clapboard	Asphalt			A transitional house from Queen Anne to Dutch Revival to Colonial Revival	SS	5	13
1913	13-12-300-020	02 Barn	Transverse Frame	N / A	1880-1920	Fair	Good		Vertical Wood	Asphalt			Has large gable addition in front	SS	16	13
1913	13-12-300-020	03 Silo	Brick	N / A	1880-1920	Good	Good		Brick	Wood Shingles			Truly unique silo that started out as a poured concrete silo then had half again its height added in the form of 2-tone bricks to form a pattern. Besides being of 2 materials, there are no other brick silos in our area with a 2-tone decorative pattern.	SS	10	13
1913	13-12-300-020	04 Shed	Uneven Gable	N / A		Falling down	Poor		Beveled Clapboard	Asphalt			On back of barn and caving in	SS	13	13
1913	13-12-300-020	05 Shed	Front Gabled	N / A		Poor	Good		Beveled Clapboard	Asphalt		Windows broken out	Has had a machine addition to the one end; Vented for livestock	SS	12	13
1913	13-12-300-020	06 Shed	Front Gabled	N / A		Fair	Good		Vertical Wood	Wood Shingles			Possibly older small barn moved and attached to big barn	SS	11	13
1913	13-12-300-020	07 Outhouse	Side Gabled	N / A	1900-1930	Good	Good		Beveled Clapboard	Wood Shingles				SS	14	13
1913	13-12-300-020	08 Garage	Front Gabled	N / A	1910-1940	Very Good	Excellent		Beveled Clapboard	Wood Shingles				SS	8	13
1913	13-12-300-020	09 Coop	Front Gabled	N / A	1910-1940	Good	Good		Beveled Clapboard	Asphalt			Extra large and tall with two dormers	SS	7	13
1913	13-12-300-020	10 Pumphouse	Side Gabled	N / A		Good	Good		Beveled Clapboard	Wood Shingles				SS	6	13
1913	13-12-300-020	11 Playhouse	Log	N / A	1950-present	Fair	Good		Log	Asphalt				SS	15	13
1913	13-12-300-020	12 Garage	Front Gabled	N / A		Fair	Good		Beveled Clapboard	Asphalt			Double	SS	9	13
1910	13-13-100-003	01 House	Front Gabled	Greek Revival	1850-1870	Good	Good		Clapboard	Asphalt		New windows and new clapboard	Note diagonal sided corn crib	UU	4	13
1910	13-13-100-003	02 Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Tin (Flat)			Has attached milkhouse	UU	3	13
1910	13-13-100-003	03 Corn Crib	Dual Aisled	N / A		Good	Good		Diagonal Slats	Asphalt			Very unique corncrib; not only is it one of the few with diagonal slats, but this one has 2 aisles, and even more unusual they run perpendicular to the roof line instead of parallel as in a transverse aisle corn crib.	UU	1	13
1910	13-13-100-003	04 Pumphouse	Gambrel	N / A		Good	Good		Vertical Wood	Asphalt				UU	2	13
1912	13-13-100-031	01 House	Four-over-four	Classic Revival	1850-1870	Good	Good		Masonry	Wood Shingles	Open	Has small addition to rear	Remarkable farmstead locally known as "Mighty Oaks"; very stately and well maintained	TT	7	13
1912	13-13-100-031	02 Barn	Transverse Frame	N / A	1860-1890	Good	Good		Vertical Wood	Asphalt		Has had some windows added		TT	15	13
1912	13-13-100-031	03 Silo	Concrete Staved	N / A		Good	Good		Flat Concrete Staved	none			Unusual flat, non-ribbed staves	TT	6	13
1912	13-13-100-031	04 Milkhouse	Side Gabled	N / A		Good	Good	Poured Concrete	Beveled Clapboard	Asphalt			Made into shed	TT	9	13
1912	13-13-100-031	05 Chapel	Side Gabled	N / A		Good	Poor		Beveled Clapboard	Asphalt			Former pumphouse converted into a chapel complete with stained glass and steeple	TT	8	13
1912	13-13-100-031	06 Coop	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt		Windows changed		TT	12	13
1912	13-13-100-031	07 Shed	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Horse stable	TT	5	13
1912	13-13-100-031	08 Shed	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				TT	10	13
1912	13-13-100-031	09 Milkhouse	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Very small	TT	11	13
1912	13-13-100-031	10 Shed	Slant-roofed	N / A		Good	Good		Beveled Clapboard	Asphalt			Used as a platform for skeet shooting	TT	13	13
1912	13-13-100-031	11 Shed	Pyramidal	N / A		Good	Good		Beveled Clapboard	Asphalt			Used to launch targets for skeet shooting	TT	14	13
1390	13-13-200-023	01 House	Upright and Wing	N / A	1860-1890	Good	Poor		Vinyl Siding	Asphalt	Enclosed	Additions, new windows and enclosed porches		TT	22	13
1390	13-13-200-023	02 Shed	Front Gabled	N / A		Fair	Good		Aluminum Siding	Asphalt				TT	20	13
1390	13-13-200-023	03 Garage	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt				TT	21	13
1390.5	13-13-200-034	01 House	Side Gabled	N / A	1910-1940	Fair	Fair		Aluminum Siding	Asphalt			Parcel was split in two; milkhouse in all that's left on this parcel of the original farmstead	TT	23	13
1390.5	13-13-200-034	01 Milkhouse	Pyramidal	N / A	1910-1940	Good	Good	Cement Block	Beveled Clapboard	Asphalt				TT	25	13
1390.5	13-13-200-034	03 Barn	Metal Pole Barn	N / A	1950-present	Good	Good	Poured Concrete	Tin (Flat)	Asphalt				TT	24	13
1909	13-13-300-006	01 House	Pyramidal	Italianate	1850-1870	Excellent (Restored)	Excellent	Field Stone	Clapboard	Asphalt	Original open porch	NONE!	This is one of our commission's landmarked houses. It is the Christopher Walkup house. Original everything!	WW	14	13
1909	13-13-300-006	02 House		N / A		Excellent (Restored)	Excellent		Clapboard	Asphalt			Second view to show back wing	WW	15	13
1909	13-13-300-006	03 Garage	Side Gabled	N / A	1910-1940	Excellent (Restored)	Excellent	Poured Concrete	Clapboard	Asphalt			2-Story with rear extension	WW	12	13
1909	13-13-300-006	04 Garage	Pyramidal	N / A		Good	Good		Clapboard	Asphalt				WW	13	13

Previous Site	Pin Number	Structure Type	Vernacular Form	Architectural Style	Circa	Condition	Integrity	Foundation	Walls	Roof	Porch	Alterations	History	Roll	Photo	Prefix
1451	13-13-300-008	01 House	Upright and Wing	Queen Anne	1880-1920	Good	Good		Clapboard	Asphalt	Removed		Extra tall 2-story side wing	WW	7	13
1451	13-13-300-008	02 Shed	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			2-story with shed addition	WW	8	13
1908	13-13-300-012	01 House	Front Gabled	N / A	1850-1870	Fair	Poor		Brick	Asphalt		Has been added on to both the front and back	The photo from the previous survey was of the next house north which is a bungalow. This is what was at this map point.	WW	6	13
1450	13-13-300-020	01 House	Four-over-four	Foursquare	1910-1940	Good	Good	Granite	Clapboard	Asphalt	Open		Notice protruding rectangular bay with semi-circle transom window; this has more style than the normal foursquare and has Prairie influences	WW	5	13
1450	13-13-300-020	02 Barn	Three-bay Threshing	N / A		Good	Good		Vertical Wood	Asphalt			Built into the hillside	WW	4	13
1450	13-13-300-020	03 Milkhouse	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				WW	3	13
1450	13-13-300-020	04 Corn Crib	Transverse Aisle	N / A		Good	Fair		Clapboard	Asphalt			Building is not leaning rather it has one side as a slant sided bay where it use to be slatted	WW	2	13
1450	13-13-300-020	05 Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				WW	1	13
1911	13-14-200-007	01 Barn	Transverse Frame	N / A		Falling down	Fair		Vertical Wood	Wood Shingles			This is the older barn on the site.	TT	16	13
1911	13-14-200-007	02 Milkhouse	Side Gabled	N / A		Falling down	Poor		Beveled Clapboard	Wood Shingles			The ruins of the collapsed dairy barn are behind this.	TT	17	13
1911	13-14-200-007	03 Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				TT	18	13
1911	13-14-200-007	04 Silo	Concrete Staved	N / A		Very Poor	Poor		Concrete Staved	none				TT	19	13
1905.5	13-14-300-001	01 Cemetery		N / A		Abandoned						All stones removed! Corn field is growing over the graves.	All that remains is the driveway. However, when inquiring about it at the farm next door, I was told that would explain the tombstones that he found in his barn when he bought the farmstead. Now a subdivision is building over it.	XX	1	13
1905.5	13-14-300-001	02 Tombstone		N / A									"Susan, wife of I.K. Torbert, died Apr. 14, 1853" This is one of the tombstones found in the neighbor barn.	WW	32	13
1905.5	13-14-300-001	03 Tombstone		N / A									"Mary Casy, died Jan. 23, 1851, aged 17 years" One of the tombstone found in the neighbor's barn.	WW	33	13
1905.5	13-14-300-001	04 Tombstone		N / A									"She is not dead, but sleepeth" One of the tombstones found in the neighbor's barn.	WW	34	13
1905	13-14-300-002	01 House	I-house	N / A		Fair	Fair		Vinyl Siding	Asphalt		New windows and side addition	This is the farm that has the lost cemetery tombstones.	WW	30	13
1905	13-14-300-002	02 Shed	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Machine shed	WW	31	13
1905	13-14-300-002	03 Windmill		N / A		Good	Good		Tin (Flat)	Blades			One of the few windmills that is still complete	WW	29	13
1905	13-14-300-002	04 Chicken Coop	Uneven Gable	N / A		Good	Fair		Vertical Wood	Asphalt		Converted into a shed		WW	28	13
1904	13-14-300-012	01 House	Upright and Wing	N / A		Fair	Poor		Aluminum Siding	Asphalt		Very altered		WW	37	13
1904	13-14-300-012	02 Barn	Dairy Gambrel	N / A	1880-1920	Fair	Good		Asbestos	Asphalt			Also includes gabled small barn which is the older barn.	WW	36	13
1904	13-14-300-012	03 Silo	Poured Concrete	N / A		Good	Good		Poured Concrete	Conical				WW	35	13
1906	13-14-400-005	01 House	Upright and Wing	Greek Revival	1850-1870	Good	Good	Field Stone	Clapboard	Wood Shingles		Additional porch rooms, but tastefully done	The "J.C.Button" 1872 Plat Book illustration house; on a 10-acre parcel adjacent to Bull Valley and currently for sale	WW	26	13
1906	13-14-400-005	02 House		N / A									Second view to show back of house	WW	21	13
1906	13-14-400-005	03 House		N / A									Third view to show stone face which is also in the 1872 plat book version of this house.			13
1906	13-14-400-005	04 Barn	Three-bay Threshing	N / A	1845-1860	Fair	Good		Vertical Wood	Wood Shingles		Has been added onto	Needs repairs	WW	22	13
1906	13-14-400-005	05 Shed	Side Gabled	N / A		Poor	Good		Vertical Wood	Wood Shingles			Haymow extension with pass through into cattle area below	WW	25	13
1906	13-14-400-005	06 Barn	Front Gabled	N / A		Fair	Good	Cement Block	Vertical Wood	Wood Shingles			Horse barn	WW	19	13
1906	13-14-400-005	07 Milkhouse	Side Gabled	N / A		Fair	Good		Clapboard	Wood Shingles			Attached	WW	20	13
1906	13-14-400-005	08 Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Wood Shingles				WW	24	13
1906	13-14-400-005	09 Garage	Front Gabled	N / A		Excellent (Restored)	Good		Clapboard	Wood Shingles			1-car, but taller	WW	23	13
1907	13-14-477-004	01 House	I-house	N / A		Good	Good		Clapboard	Wood Shingles			One of the commission plaqued landmarks, the "Ormsby-Stark" house; there is a much old house inside of this, but it was added on to and made into an Italianate around the turn-of-the-century	WW	17	13
1907	13-14-477-004	02 Garage	Pyramidal	N / A		Good	Good		Clapboard	Wood Shingles			Attached with a hip roof.	WW	16	13
1907	13-14-477-004	03 Shed	Slant-roofed	N / A		Good	Good		Aluminum Siding	Asphalt			Possibly a former chicken coop.	XX	2	13
1900	13-15-000-000	01		N / A									GONE! Subdivision in its place			13
1902	13-15-200-002	01		N / A					Clapboard	Asphalt		Has a porch behind the enclosed porch		XX	6	13
1902	13-15-200-002	01 House	Upright and Wing	N / A		Good	Good		Clapboard	Asphalt	Inset	Added onto back		XX	5	13
1902	13-15-200-002	03 Shed	Side Gabled	N / A		Good	Good		Clapboard	Asphalt			Has a shed addition to one end	XX	9	13
1902	13-15-200-002	04 Shed	Uneven Gable	N / A		Good	Good		Vertical Wood	Asphalt		Converted to a garage		XX	7	13
1902	13-15-200-002	05 Shed	Front Gabled	N / A		Fair	Good		Plywood	Asphalt				XX	8	13
1903	13-15-200-008	01 House	I-house	N / A		Fair	Fair		Aluminum Siding	Diagonal Slats			This entire farm was sold and has become a subdivision, "The Sanctuary". The house is empty and will soon be taken down.	XX	4	13
1903	13-15-200-008	02 Garage	Side Gabled	N / A		Good	Good		Aluminum Siding	Asphalt			1-car with shop	XX	3	13
1903	13-15-200-008	03 Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				XX	2	13
1882	13-16-400-008	01 House	Side Gabled	Classic Revival	1900-1930	Good	Good		Brick	Asphalt	Open	Converted from home into offices	This picture is in site 1883's pin point on map	XX	34	13
1882	13-16-400-008	02 Shed	Gambrel	N / A	1900-1930	Good	Good		Brick	Asphalt			Includes greenhouse	XX	33	13
1883	13-16-400-011	01 House	Four-over-four	Foursquare	1910-1940	Good	Good		Vinyl Siding	Asphalt		Small addition	Old photo is in site 1882's pin point	XX	35	13
1177	13-17-100-014	01 House	Front Gabled	N / A	1880-1920	Good	Good		Vinyl Siding	Asphalt	Enclosed			3A	37	13
1177	13-17-100-014	02 Barn	Carriage	N / A	1880-1920	Poor	Good		Beveled Clapboard	Wood Shingles			Includes Pumphouse	3A	34	13
1177	13-17-100-014	03 Chicken Coop	Slant-roofed	N / A		Good	Good		Beveled Clapboard	Asphalt				3A	33	13
1177	13-17-100-014	04 Garage	Uneven Gable	N / A		Good	Good		Vertical Wood	Asphalt				3A	35	13
1177	13-17-100-014	05 Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3A	36	13
1177.1	13-17-100-016	01 House	Side Gabled	N / A	1910-1940	Poor	Poor		Aluminum Siding	Asphalt				3A	32	13
1177.1	13-17-100-016	02 Garage	Front Gabled	N / A	1910-1940	Good	Good		Aluminum Siding	Asphalt				3A	31	13
1177.1	13-17-100-016	03 Milkhouse	Pyramidal	N / A		Good	Good		Vertical Wood	Asphalt				3A	30	13
1179	13-17-300-007	01 House	Upright and Wing	N / A	1860-1880	Good	Poor		Aluminum Siding	Asphalt			Side wing is taller than upright	3B	4	13

Previous Site	Pin Number	Structure Type	Vernacular Form	Architectural Style	Circa	Condition	Integrity	Foundation	Walls	Roof	Porch	Alterations	History	Roll	Photo	Prefix
1179	13-17-300-007	02 Barn	Three-bay Threshing	N / A	1850-1870	Good	Good		Vertical Wood	Asphalt				3B	1	13
1179	13-17-300-007	03 Garage	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				3B	2	13
1179	13-17-300-007	04 Corn Crib	Transverse Aisle	N / A		Good	Poor		Vertical Wood	Asphalt			Open slats of corn crib were covered	3B	3	13
1109	13-18-100-005	01 House	Upright and Wing	N / A		Good	Fair		Aluminum Siding	Asphalt		New windows and siding		3A	26	13
1109	13-18-100-005	02 Barn	Dairy Gambrel	N / A	1880-1920	Poor	Good	Field Stone	Vertical Wood	Wood Shingles				3A	20	13
1109	13-18-100-005	03 Garage	Pyramidal	N / A	1950-present	Fair	Good		Aluminum Siding	Asphalt				3A	24	13
1109	13-18-100-005	04 Milkhouse	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Detached	3A	23	13
1109	13-18-100-005	05 Shed	Front Gabled	N / A		Fair	Good		Beveled Clapboard	Asphalt			Livestock shed with vent, probably a hog house	3A	22	13
1109	13-18-100-005	06 Shed	Front Gabled	N / A		Fair	Good		Beveled Clapboard	Asphalt				3A	21	13
1109	13-18-100-005	07 Shed	Front Gabled	N / A		Fair	Good		Vertical Wood	Tin (Flat)				3A	25	13
1107	13-18-200-001	01 House	Upright and Wing	N / A	1860-1890	Good	Fair		Clapboard	Asphalt	Extend, but open	New windows and siding		3A	5	13
1107	13-18-200-001	02 Garage	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt				3A	6	13
1104	13-18-200-007	01		N / A									All Gone! Modern ranch and business in its place			13
1176	13-18-200-008	01 House	Four-over-four	Foursquare	1910-1940	Good	Good		Aluminum Siding	Asphalt			True Foursquare completed with dormer	3A	28	13
1176	13-18-200-008	02 Garage	Front Gabled	N / A		Good	Good		Vinyl Siding	Asphalt			2-car	3A	27	13
1176	13-18-200-008	03 Shed	Front Gabled	N / A		Good	Good		Vinyl Siding	Asphalt			Behind the fence	3A	29	13
1178	13-18-400-001	01 House	Cottage	Cape Cod	1950-present	Good	Good		Vinyl Siding	Asphalt			Replacement house; includes attached garage	3B	9	13
1178	13-18-400-001	02 Barn	Three-bay Threshing	N / A		Good	Good		Vertical Wood	Tin (Flat)			Has shed addition at end	3B	8	13
1178	13-18-400-001	03 Shed	Front Gabled	N / A		Fair	Good		Beveled Clapboard	Tin (Flat)			Note old door from the original house with the 2 vertical non-raised panels, but falling apart	3B	7	13
1178	13-18-400-001	04 Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3B	6	13
1178	13-18-400-001	05 Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3B	5	13
1178.4	13-18-400-002	01 Cemetery		N / A		Fair	Poor						Most of the stones have been removed, but at least it is now being taken care of	3B	17	13
1178.3	13-18-400-004	01 Barn	Three-bay Threshing	N / A	1860-1880	Good	Excellent	Field Stone	Vertical Wood	Asphalt				3B	14	13
1178.3	13-18-400-004	02 House	Cottage	Cape Cod	1950-present	Good	Good		Vinyl Siding	Asphalt			New replacement house on south side of driveway. Original house was on north side of driveway.	3B	16	13
1178.3	13-18-400-004	03 Shed	Front Gabled	N / A	1860-1890	Good	Good		Beveled Clapboard	Asphalt			Note Greek Revival entrance door (2 vertical panels over 2 vertical panels, all being flat not raised)	3B	10	13
1178.3	13-18-400-004	04 Outhouse	Slant-roofed	N / A		Good	Good		Beveled Clapboard	Asphalt				3B	11	13
1178.3	13-18-400-004	05 Corn Crib	Transverse Aisle	N / A	1880-1920	Fair	Good		Horizontal Slats	Asphalt			Combination crib that has one slotted bay for ear corn and one solid bay for shelled corn or grain. Later the solid bay usually becomes a storage shed	3B	12	13
1178.3	13-18-400-004	06 Milkhouse	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Detached	3B	13	13
1178.3	13-18-400-004	07 Garage	Side Gabled	N / A		Good	Good		Plywood	Asphalt			Double wide	3B	15	13
1121	13-19-100-005	01 House	Bungalow	N / A	1900-1930	Good	Good		Aluminum Siding	Asphalt			Well maintained site set back off the road with two houses	3B	29	13
1121	13-19-100-005	02 House	Cottage	N / A	1930-1950	Good	Good		Aluminum Siding	Asphalt			Worker's cottage	3B	27	13
1121	13-19-100-005	03 Barn	Three-bay Threshing	N / A	1860-1890	Good	Good		Vertical Wood	Asphalt			Includes concrete staved silo with metal dome roof	3B	23	13
1121	13-19-100-005	04 Corn Crib	Gothic Arched	N / A		Good	Good		Horizontal Slats	Asphalt			Unusually large transverse aisle corn crib with gothic arched roof; also has shed addition and one closed in bay for grain and storage	3B	24	13
1121	13-19-100-005	05 Coop	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Chicken coop converted to storage; may also have had hog house usage	3B	25	13
1121	13-19-100-005	06 Garage	Side Gabled	N / A		Good	Good		Clapboard	Asphalt			Also has a slant-roofed small chicken coop next to it (but not attached)	3B	26	13
1121	13-19-100-005	07 Shed	Gambrel	N / A		Good	Good		Plywood	Asphalt				3B	28	13
1122	13-19-300-001	01 House	Upright and Wing	N / A		Good	Good		Aluminum Siding	Asphalt		Rear addition, but still the original windows	Site set way back off the road	3B	33	13
1122	13-19-300-001	02 Barn	Dairy Gambrel	N / A		Good	Good		Tin (Flat)	Asphalt			Note includes 2 concrete silos; note also the row of windows above the door	3B	31	13
1122	13-19-300-001	03 Outhouse	Side Gabled	N / A	1860-1880	Good	Good		Vertical Wood	Wood Shingles			Replacement roof; all else original and older than most (complete with square nails)	3B	30	13
1122	13-19-300-001	04 Garage	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Double-deep	3B	32	13
1123	13-19-400-001	01 Coop	Side Gabled	N / A		Very Poor	Fair		Clapboard	Wood Shingles			Very run-down; also includes another shed or cottage	3Y	13	13
1123	13-19-400-001	02 Corn Crib	Transverse Aisle	N / A		Very Poor	Fair		Horizontal Slats	Wood Shingles				3Y	12	13
1123	13-19-400-001	03 Barn	Three-bay Threshing	N / A	1860-1880	Very Poor	Fair		Vertical Wood	Wood Shingles			Includes attached milkhouse and concrete staved silo; all of the farm buildings are abandoned	3Y	11	13
1123	13-19-400-001	04 House	Upright and Wing	N / A		Poor	Poor		Clapboard	Asphalt		Totally unrecognizable; converted to a mansard roof and totally remuddled	Underneath this is the original farmhouse which is on the north side of the road. All other farm buildings are on the south side of the road.	3Y	10	13
1124	13-19-400-003	01 Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	none			Old site at the end of Perkins Road on Dean Street; all that's left is this silo	3B	35	13
1897	13-20-200-002	01 vacant		N / A									All gone!	ZZ	10	13
1125	13-20-300-012	01 Shed		N / A		Poor	Poor						All that's left is this one falling down shed	3B	34	13
1895	13-21-300-009	01 House	Cottage	N / A		Fair	Fair		Clapboard	Asphalt			The original farmstead was demolished and these three little cottages were built in its place	ZZ	3	13
1894	13-21-300-017	01 House	Cottage	Cape Cod	1910-1940	Good	Good	Poured Concrete	Wood Shingles	Asphalt		Has addition to the side		ZZ	7	13
1894	13-21-300-017	02 Garage	Side Gabled	N / A	1910-1940	Good	Good		Wood Shingles	Asphalt			3-car with additional workshop space	ZZ	6	13
1126.5	13-21-300-021	01 Silo	Wood Staved	N / A	1950-present	Good	Good		Wood Staved	Wood Shingles			This is an excellent reproduction, in fact it was so good that it needed to be documented as a reproduction and not an old restored wood staved silo	ZZ	11	13
1892.5	13-22-100-004	01 House	Upright and Wing	N / A	1850-1870	Fair	Poor	Field Stone	Vinyl Siding	Asphalt		Huge addition to the side plus new windows and siding	This site is now way down a lane and was the site of a former ostrich farm and now just low-income rental housing. Although it was an 1872 Plat Book illustration house, it has virtually no historic integrity.	YY	1	13
1892.5	13-22-100-004	02 Garage	Front Gabled	N / A	1930-1950	Good	Good	Poured Concrete	Clapboard	Asphalt				XX	37	13

Previous Site	Pin Number	Structure Type	Vernacular Form	Architectural Style	Circa	Condition	Integrity	Foundation	Walls	Roof	Porch	Alterations	History	Roll	Photo	Prefix
1892.5	13-22-100-004	03 Coop	Broken Eave	N / A	1930-1950	Poor	Poor		Tin (Flat)	Rolled Asphalt			Clapboard and tin combo from the poultry operation	YY	2	13
1892.5	13-22-100-004	04 Grain Bin	Oval	N / A	1930-1950	Good	Good		Tin (Perforated)	Tin (Flat)			Uncommon shape; longer than normal with separate bins	XX	36	13
1892.3	13-22-200-007	01 House	Four-over-four	Italianate	1850-1870	Good	Good	Field Stone	Clapboard	Asphalt			This is one of those older version of the pyramidal 2-story houses, a vernacular version of an Italianate, not the newer Foursquare version	YY	3	13
1892.3	13-22-200-007	02 Barn	Gothic Arched	N / A	1910-1940	Fair	Poor		Vertical Wood	Asphalt		Either the Gothic arched barn was added onto the wife 3-aisle barn or the other way around	The Gothic arched barn is unremarkable, but the wider barn is unique in that the 2 outer aisle are on the extreme outside instead of running in-between stalls	YY	4	13
1892	13-22-427-002	01 Barn	Gothic Arched	N / A	1910-1940	Poor	Fair		Vertical Wood	Asphalt			There are actually 5 gothic arched barns on this site!	YY	7	13
1892	13-22-427-002	02 Barn	Gothic Arched	N / A		Poor	Fair		Vertical Wood	Asphalt				YY	7	13
1892	13-22-427-002	03 Barn	Gothic Arched	N / A		Poor	Fair		Vertical Wood	Asphalt			Include 2 concrete staved silos on this site	YY	8	13
1892	13-22-427-002	04 Milkhouse	Front Gabled	N / A		Fair	Fair		Beveled Clapboard	Asphalt				YY	9	13
1891	13-22-476-004	01 House	Four-over-four	Foursquare	1910-1940	Good	Fair		Aluminum Siding	Asphalt		Full front façade porch has been removed		YY	12	13
1891	13-22-476-004	02 Barn	Dairy Gambrel	N / A	1900-1930	Good	Good		Vertical Wood	Asphalt			Includes attached gabled milkhouse	YY	10	13
1891	13-22-476-004	03 Garage	Side Gabled	N / A	1930-1950	Fair	Fair		Aluminum Siding	Asphalt				YY	11	13
1884.5	13-23-200-002	01 House	Upright and Wing	N / A	1860-1890	Good	Poor		Clapboard	Asphalt		Had had addition to one side, all new windows, new siding and porch enclosed	Aside from the above alterations, the one saving historic feature is that the original front door still there complete with side lights	3A	1	13
1884.5	13-23-200-002	02 Garage	Side Gabled	N / A		Good	Good		Clapboard	Asphalt				3A	2	13
1884	13-23-300-022	01 Garage	Front Gabled	N / A		Falling down	Poor		Beveled Clapboard	Wood Shingles			House and all other buildings are gone; this is all that's left	YY	5	13
1885	13-23-400-001	01 House	Upright and Wing	N / A	1860-1890	Good	Good	Poured Concrete	Asbestos	Asphalt	Porch removed	Windows changed and porch altered	Rear addition also	VV	29	13
1885	13-23-400-001	02 Shed	Uneven Gable	N / A		Fair	Good		Plywood	Asphalt			Shed turned into playhouse	VV	26	13
1885	13-23-400-001	03 Coop	Uneven Gable	N / A		Good	Fair		Beveled Clapboard	Asphalt		Some windows removed		VV	25	13
1885	13-23-400-001	04 Garage	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			2-car	VV	24	13
1885	13-23-400-001	05 Grain Bin	Round	N / A		Good	Good		Tin (Corrugated)	Tin (Flat)			Includes 2 grain bins and a dryer	VV	27	13
1885	13-23-400-001	06 Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Also includes metal tanks	VV	28	13
1449	13-24-100-003	01 House	Four-over-four	Italianate	1860-1880	Good	Good		Clapboard	Asphalt	Enclosed		This is the older version that has been modernized to look like a Foursquare, but is really a vernacular Italianate	VV	37	13
1449	13-24-100-003	02 Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			Includes 2 attached milk houses and one concrete staved silo with metal dome roof	VV	35	13
1449	13-24-100-003	03 Barn	Three-bay Threshing	N / A	1850-1870	Excellent (Restored)	Excellent		Vertical Wood	Tin (Flat)			Unusually tall version; notice fancy cutwork on lower gable edge	VV	36	13
1449	13-24-100-003	04 Shed	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt				VV	34	13
1448.5	13-24-100-013	01 House	Cross Gabled	Queen Anne	1880-1920	Good	Good		Clapboard	Wood Shingles			Some changes, but still keeping the original feel	WW	11	13
1448.5	13-24-100-013	02 Barn	Transverse Frame	N / A	1880-1920	Good	Good		Asbestos	Asphalt				WW	9	13
1448.5	13-24-100-013	03 Corn Crib	Round	N / A		Good	Good	Poured Concrete	Clapboard	Wood Shingles			Very unusual! This corn crib was made into a multisided shed	WW	10	13
1446	13-24-200-004	01 House	Four-over-four	Italianate	1860-1880	Fair	Good	Field Stone	Asbestos	Asphalt		Very little changes	Still has the original 2-over-2 windows; not a Foursquare but the old version that based on a simplified Italianate	VV	18	13
1446	13-24-200-004	02 Barn	Dairy Gambrel	N / A	1880-1920	Poor	Good		Vertical Wood	Wood Shingles			Falling apart on one end	VV	21	13
1446	13-24-200-004	03 Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome			2 Silos	VV	22	13
1446	13-24-200-004	04 Shed	Gambrel	N / A		Poor	Fair		Asbestos	Wood Shingles				VV	23	13
1446	13-24-200-004	05 Garage	Front Gabled	N / A		Poor	Poor		Clapboard	Wood Shingles			2-car	VV	20	13
1446	13-24-200-004	06 Shed	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Machine Shed	VV	19	13
1448	13-24-200-010	01 House	Upright and Wing	Greek Revival	1850-1870	Fair	Fair		Asbestos	Asphalt			Side wing is a turn-of-the-century addition; on site of landscape business	UU	19	13
1448	13-24-200-010	02 House		N / A									Second view to show the back summer kitchen wing.	VV	31	13
1448	13-24-200-010	03 Barn	Transverse Frame	N / A	1860-1890	Good	Good		Vertical Wood	Asphalt			Has attached milkhouse	VV	32	13
1448	13-24-200-010	04 Shed	Side Gabled	N / A	1860-1880	Good	Good		Vertical Wood	Asphalt				VV	30	13
1447	13-24-300-009	01 House	Double Cube	Italianate	1850-1870	Good	Good	Field Stone	Clapboard	Asphalt	Removed		This is a transitional house that has both Greek Revival and Italianate features. However, in massing it is Italianate, so it has been classified as such. Notice the side lights on the formal front door and 2-over-2 windows	VV	33	13
1441	13-24-476-010	01 House	Upright and Wing	Greek Revival	1860-1880	Fair	Poor		Aluminum Siding	Asphalt		Windows, siding, porches, etc.	The cornice returns are about all that's left of the original historic integrity	UU	15	13
1445	13-25-127-001	01 House	Upright and Wing	N / A	1860-1890	Fair	Fair		Aluminum Siding	Asphalt		Modernized plus additions		VV	15	13
1445	13-25-127-001	02 Barn	Dairy Gambrel	N / A	1880-1920	Fair	Fair		Asbestos	Asphalt			Also includes 2 sheds	VV	17	13
1445	13-25-127-001	03 Shed	Front Gabled	N / A		Fair	Fair		Tin (Flat)	Asphalt			Includes 3 sheds	VV	16	13
1411	13-25-127-002	01 School	Front Gabled	Prairie	1910-1940	Good	Good		Brick	Asphalt			Former Ridgefield School that has had adaptive reuse as a religious school	UU	37	13
1410	13-25-127-003	01 House	Cottage	Cape Cod	1900-1930	Good	Good		Aluminum Siding	Asphalt						13
1409	13-25-127-005	01 House	Four-over-four	Italianate	1860-1880	Fair	Fair		Aluminum Siding	Asphalt	Enclosed	Has some original windows left but most replaced	Looks like either a railing at the house peak was removed	UU	36	13
1408	13-25-127-006	01 House	Upright and Wing	N / A	1860-1880	Fair	Poor		Aluminum Siding	Asphalt	Removed	Windows, siding and added onto		UU	35	13
1887	13-25-151-001	01 House	Upright and Wing	N / A	1860-1880	Fair	Poor		Aluminum Siding	Asphalt	Enclosed	All changed . . .		YY	20	13
1887	13-25-151-001	02 Barn	Dairy Gambrel	N / A	1880-1920	Fair	Good		Vertical Wood	Wood Shingles			Needs a new roof	YY	18	13
1887	13-25-151-001	03 Shed	Side Gabled	N / A		Fair	Good		Vertical Wood	Wood Shingles			Machine shed	YY	19	13
1887	13-25-151-001	04 Garage	Side Gabled	N / A		Very Poor	Poor		Plywood	Wood Shingles				YY	17	13
1425	13-25-201-001	01 Store		N / A		Good	Poor						Has been replaced or totally altered into another form			13
1431	13-25-201-005	01 House	Upright and Wing	N / A	1880-1920	Fair	Fair		Clapboard	Asphalt	Redone	Addition to rear	Note the patterned shingles in the gable; this house shows a Queen Anne influence	UU	27	13
1424	13-25-201-006	01 Store	Front Gabled	N / A	1850-1870	Good	Good		Clapboard	Asphalt			Rear addition	UU	26	13
1423	13-25-201-006															13

Previous Site	Pin Number	Structure Type	Vernacular Form	Architectural Style	Circa	Condition	Integrity	Foundation	Walls	Roof	Porch	Alterations	History	Roll	Photo	Prefix
1397	13-25-201-007	01 Store		N / A		Good	Good		Molded Block	Flat				UU	25	13
1397	13-25-201-007	02 Store		N / A		Good	Good		Molded Block				Rear addition to rest of store	UU	28	13
1395	13-25-202-003	01 Store		N / A		Good	Good		Brick	Asphalt			On same parcel as site 1396	UU	20	13
1396	13-25-202-003	02 House	Upright and Wing	Greek Revival	1850-1860	Good	Excellent		Clapboard	Asphalt			Has been a store or business for years and once was a boarding house	UU	21	13
1430	13-25-202-004	01 vacant		N / A									All gone!			13
1429	13-25-202-004	01 vacant		N / A									All gone!			13
1426	13-25-202-006	01 House	Upright and Wing	N / A	1860-1880	Good	Good		Asbestos	Asphalt			Side wing was always some sort of business of varying types	UU	22	13
1427	13-25-202-007	01 House	Upright and Wing	Italianate	1860-1880	Good	Good		Clapboard	Asphalt	Open		Note 2-over-2 windows and original Italianate porch posts	UU	23	13
1435	13-25-203-003	01 Barn	Carriage	N / A		Fair	Fair		Clapboard	Asphalt		Doors altered		UU	12	13
1428	13-25-203-004	01 House	Upright and Wing	Greek Revival	1850-1870	Good	Good		Vinyl Siding	Asphalt			Note cornice returns	UU	24	13
1399	13-25-204-002	01 vacant		N / A									All gone!			13
1398	13-25-204-005	01 vacant		N / A									All gone!			13
1403	13-25-205-003	01 House	Upright and Wing	N / A		Fair	Fair		Aluminum Siding	Asphalt		New windows and siding	Note side frieze window	VV	11	13
1404	13-25-205-004	01 House	Cottage	Dutch Revival	1910-1940	Good	Good		Clapboard	Asphalt				VV	9	13
1405	13-25-205-005	01 House	Cottage	N / A		Fair	Fair		Aluminum Siding	Asphalt		Front addition		VV	10	13
1402	13-25-206-001	01 House	Upright and Wing	Greek Revival	1850-1870	Good	Fair		Clapboard	Asphalt			This was built as a storefront with living quarters in the rear	VV	14	13
1401	13-25-206-002	01 House	Cottage	N / A		Good	Good		Clapboard	Asphalt			Former church	VV	13	13
1400	13-25-206-003	01 House	Cottage	Cape Cod	1910-1940	Good	Good		Vertical Wood	Asphalt				VV	12	13
1419	13-25-206-006	01 House	Cottage	N / A	1930-1950	Good	Good		Clapboard	Asphalt				UU	38	13
1420	13-25-206-007	01 House	Upright and Wing	N / A	1860-1890	Poor	Poor		Asbestos	Asphalt		Lots		VV	4	13
1421	13-25-206-008	01 House	Cross Gabled	Queen Anne	1890-1910	Good	Fair		Clapboard	Asphalt	Enclosed			VV	3	13
1421	13-25-206-008	02 Garage	Side Gabled	N / A	1900-1930	Good	Good		Clapboard	Asphalt				VV	7	13
1422	13-25-207-001	01 House	Bungalow	N / A	1910-1940	Good	Good		Field Stone	Asphalt	Enclosed			UU	29	13
1422	13-25-207-001	02 Garage	Gambrel	N / A		Good	Good		Vertical Wood	Asphalt				VV	5	13
1407	13-25-208-001	01 House	Cottage	N / A	1910-1940	Good	Good		Vinyl Siding	Asphalt				UU	34	13
1406	13-25-208-002	01 House	Upright and Wing	N / A	1880-1920	Good	Good		Vinyl Siding	Asphalt				UU	33	13
1418	13-25-209-001	01 House	Upright and Wing	N / A		Good	Good		Clapboard	Asphalt	Enclosed			UU	39	13
1412	13-25-209-002	01 House	Bungalow	N / A	1910-1940	Good	Good		Aluminum Siding	Asphalt				VV	1	13
1413	13-25-209-003	01 House	Cottage	N / A		Good	Good		Aluminum Siding	Asphalt				VV	2	13
1417	13-25-209-004	01 House	Upright and Wing	N / A	1880-1920	Good	Fair		Vinyl Siding	Asphalt				VV	6	13
1414	13-25-209-005	01 House	Upright and Wing	N / A	1880-1900	Fair	Good		Aluminum Siding	Asphalt				UU	31	13
1416	13-25-210-001	01 House	Cross Gabled	N / A	1880-1920	Fair	Fair		Vinyl Siding	Asphalt	Enclosed			UU	30	13
1415	13-25-210-003	01 Church		N / A	1860-1870	Good	Good		Clapboard	Asphalt			Illustrated in the 1872 Plat Book	UU	32	13
1444	13-25-226-003	01 House	Upright and Wing	N / A	1880-1920	Good	Fair		Vinyl Siding	Asphalt		Added onto		UU	5	13
1440	13-25-226-004	01 House	Upright and Wing	N / A	1860-1880	Good	Fair		Vinyl Siding	Asphalt		Modernized		UU	18	13
1442	13-25-226-005	01 House	Front Gabled	N / A		Good	Good		Vinyl Siding	Asphalt				UU	17	13
1443	13-25-226-006	01 House	Upright and Wing	N / A	1880-1900	Good	Poor		Vinyl Siding	Asphalt		2-story addition to the front and numerous other changes		UU	16	13
1433	13-25-226-008	01 House	Four-over-four	N / A	1860-1880	Good	Good		Clapboard	Asphalt	Open		Tastefully restored	UU	13	13
1433	13-25-226-008	02 Barn	Carriage	N / A		Good	Fair		Vertical Wood	Asphalt		Sky-lights and other windows added	Used now as a garage	UU	14	13
1437	13-25-226-009	01 House	I-house	N / A		Good	Good		Vinyl Siding	Asphalt		Windows, siding		UU	8	13
1434	13-25-226-009															13
1438	13-25-226-011	01 House	Pyramidal	N / A	1900-1930	Fair	Poor						No longer contributing			13
1439	13-25-226-012	01 House	Four-over-four	N / A	1850-1870	Good	Good		Asbestos	Asphalt	Enclosed		Older version	UU	11	13
1432	13-25-226-019	01 House	Upright and Wing	N / A	1880-1920	Good	Fair		Asbestos	Asphalt			Note that this is a steeper pitched roof and the angle on the cornice returns; (Greek Revival ones are flat)	UU	6	13
1432	13-25-226-019	02 Garage	Pyramidal	N / A		Good	Good		Asbestos	Asphalt				UU	7	13
1436	13-25-227-002	01 House	Cross Gabled	N / A	1880-1920	Good	Good		Clapboard	Asphalt			Note decorative moldings above windows, porch trim and patterned shingles in the gables	UU	9	13
1436	13-25-227-002	02 Garage	Side Gabled	N / A		Fair	Good		Aluminum Siding	Asphalt				UU	10	13
1394	13-25-227-006	01 House	Four-over-four	Foursquare	1910-1940	Poor	Poor		Vinyl Siding	Asphalt		Very modernized and new deck	Lots of traffic and usage due to being very active horse stable	TT	27	13
1394	13-25-227-006	02 Barn	Dairy Gambrel	N / A	1880-1920	Very Poor	Poor		Vinyl Siding	Asphalt		Converted dairy barn into horse stable with small stalls	Very overcrowded; site includes 7 horse barns	TT	26	13
1874	13-25-276-001	01 House	Side Gabled	Greek Revival	1850-1870	Good	Good		Stucco	Asphalt		Has had major additions, but all tastefully done		TT	31	13
1874	13-25-276-001	02 House		N / A									Second photo to show rear view	TT	30	13
1874	13-25-276-001	03 Garage	Side Gabled	N / A	1880-1920	Good	Fair		Clapboard	Asphalt		Old carriage barn converted into a garage	Also includes a small front-gabled garage	TT	29	13
1874	13-25-276-001	04 Shed	Side Gabled	N / A		Good	Good		Clapboard	Asphalt			Shed converted into cottage	TT	28	13
1874	13-25-276-001	05 Shed	Front Gabled	N / A		Good	Good		Clapboard	Asphalt				TT	32	13
1871	13-25-300-007	01 vacant		N / A									All gone!			13
1873	13-25-400-008	01 House	Upright and Wing	N / A	1860-1880	Fair	Poor		Aluminum Siding	Asphalt				TT	37	13
1873	13-25-400-008	02 Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt				TT	36	13
1873	13-25-400-008	03 Shed	Front Gabled	N / A		Fair	Good		Clapboard	Tin (Flat)			Livestock shed	TT	34	13
1873	13-25-400-008	04 Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				TT	35	13
1873	13-25-400-008	05 Grain Bin	Round	N / A		Fair	Fair		Tin (Corrugated)	Tin (Flat)				TT	33	13
1886	13-26-100-005	01 House	Upright and Wing	N / A	1860-1890	Fair	Good		Aluminum Siding	Asphalt				YY	16	13
1886	13-26-100-005	02 Barn	Dairy Gambrel	N / A	1880-1920	Fair	Fair		Asbestos	Asphalt			Includes detached milkhouse	YY	13	13
1886	13-26-100-005	03 Shed	Front Gabled	N / A		Poor	Fair		Asphalt	Asphalt			Includes garage	YY	14	13
1886	13-26-100-005	04 Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Also includes corn crib built as multi-faceted horizontal wood slats	YY	15	13
1888	13-26-300-010	01 House	Four-over-four	N / A	1880-1920	Good	Good		Asbestos	Asphalt	Screened-in	Large hipped roof side wing		YY	31	13
1888	13-26-300-010	02 Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			Includes concrete staved silo and milkhouse	YY	32	13
1888	13-26-300-010	03 Pumphouse	Pyramidal	N / A		Good	Good		Stucco	Asphalt				YY	33	13
1870	13-26-400-002	01 House	Four-over-four	Italianate	1860-1880	Good	Good		Clapboard	Asphalt	Inset	Addition to side	Is a simplified version of a vernacular Italianate	YY	28	13
1870	13-26-400-002	02 Barn	Metal Pole Barn	N / A		Fair	Good		Tin (Flat)	Tin (Flat)			Includes concrete staved silo	YY	30	13
1870	13-26-400-002	03 Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Asphalt			Includes windmill and one small shed	YY	29	13
1891.5	13-27-200-024	01 House	Upright and Wing	N / A	1860-1890	Good	Fair		Asbestos	Asphalt	Enclosed			ZZ	37	13
1891.5	13-27-200-024	02 Barn	Composite	N / A		Poor	Fair		Tin (Flat)	Wood Shingles			Includes concrete staved silo	ZZ	35	13
1891.5	13-27-200-024	03 Pumphouse	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt			Includes windmill	ZZ	34	13

Previous Site	Pin Number	Structure Type	Vernacular Form	Architectural Style	Circa	Condition	Integrity	Foundation	Walls	Roof	Porch	Alterations	History	Roll	Photo	Prefix
1891.5	13-27-200-024	04 Garage	Side Gabled	N / A		Good	Good		Aluminum Siding	Asphalt			3-car	ZZ	33	13
1890	13-27-200-029	01 House	Front Gabled	N / A	1880-1920	Good	Good		Clapboard	Asphalt			Former school	YY	37	13
1890	13-27-200-029	02 Shed	Front Gabled	N / A		Good	Good		Clapboard	Asphalt			Sun-room	ZZ	1	13
1889	13-27-400-027	01 House	Four-over-four	Foursquare	1900-1930	Good	Good		Clapboard	Asphalt			Attached garage	YY	36	13
1889	13-27-400-027	02 Shed	Gambrel	N / A		Good	Good		Vertical Wood	Asphalt			Has Cupola	YY	34	13
1889	13-27-400-027	03 Garage	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				YY	35	13
1127	13-28-100-008	01 vacant		N / A									All gone!	ZZ	15	13
1896	13-28-100-009	01 House	Upright and Wing	N / A	1860-1890	Fair	Good		Clapboard	Asphalt			Original windows and porch	ZZ	5	13
1896	13-28-100-009	02 Barn	Dairy Gambrel	N / A		Very Poor	Fair		Vertical Wood	Asphalt				ZZ	4	13
1126	13-28-100-012	01 House	Four-over-four	Foursquare	1900-1930	Good	Good		Clapboard	Asphalt				ZZ	14	13
1126	13-28-100-012	02 Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			Include attached milkhouse and concrete staved silo	ZZ	12	13
1126	13-28-100-012	03 Corn Crib	Slant-Sided	N / A		Good	Good		Horizontal Slats	Asphalt			Converted to a shed	ZZ	13	13
1893	13-28-200-005	01 House	Cottage	N / A	1900-1930	Good	Good		Aluminum Siding	Asphalt				ZZ	8	13
1893	13-28-200-005	02 Shed	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				ZZ	9	13
1181	13-29-100-013	01 House	Cross Gabled	N / A	1880-1920	Good	Fair		Vinyl Siding	Asphalt	Enclosed	Major 2-story addition to side		3C	9	13
1181	13-29-100-013	02 Barn	Three-bay Threshing	N / A	1860-1890	Good	Excellent	Field Stone	Vertical Wood	Asphalt			Built into hillside	3C	6	13
1181	13-29-100-013	03 House	Cottage	N / A	1950-present	Good	Good		Vinyl Siding	Asphalt			Secondary house	3C	8	13
1181	13-29-100-013	04 House	Trailer	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3C	10	13
1181	13-29-100-013	05 Milkhouse	Side Gabled	N / A		Good	Good		Cement Block	Asphalt				3C	7	13
1181	13-29-100-013	06 Shed	Uneven Gable	N / A		Good	Good		Plywood	Asphalt				3C	5	13
1181	13-29-100-013	07 Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3C	11	13
1182	13-29-300-003	01 House	Cross Gable	N / A	1900-1920	Good	Good		Aluminum Siding	Asphalt			Large addition to side	3C	13	13
1182	13-29-300-003	02 Barn	Uneven Gable	N / A		Good	Good		Vertical Wood	Asphalt				3C	14	13
1182	13-29-300-003	03 Shed	Gambrel	N / A		Good	Good		Wood Shingles	Asphalt			Has shingles in gables	3C	12	13
1183	13-29-300-013	01 House	Upright and Wing	N / A	1860-1890	Good	Good		Aluminum Siding	Asphalt	Screened-in			3C	20	13
1183	13-29-300-013	02 Barn	Transverse Frame	N / A		Good	Good	Field Stone	Vertical Wood	Asphalt				3C	18	13
1183	13-29-300-013	03 Shed	Front Gabled	N / A		Fair	Good		Tin (Flat)	Asphalt			2 shed of varying forms and materials	3C	17	13
1183	13-29-300-013	04 Shed	Quonset	N / A		Good	Good		Tin (Flat)	Asphalt				3C	16	13
1183	13-29-300-013	05 Shed	Front Gabled	N / A		Good	Good		Aluminum Siding	Asphalt				3C	15	13
1183	13-29-300-013	06 Train car		N / A		Poor	Good		Vertical Wood	Wood Shingles				3C	19	13
1342	13-30-100-002	01 House	T-Plan	N / A	1860-1890	Fair	Poor		Aluminum Siding	Asphalt			Very altered and currently rented	3C	32	13
1342	13-30-100-002	02 Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			Includes concrete staved silo	3C	31	13
1342	13-30-100-002	03 Pumphouse		N / A		Fair	Fair		Asbestos	Asphalt				3C	30	13
1342	13-30-100-002	04 House	Slant-Sided	N / A		Good	Good		Diagonal Slats	Tin (Flat)			There are very few with diagonal slats in this area	3C	29	13
1180	13-30-226-001	01 House	Four-over-four	Foursquare	1910-1940	Good	Good		Vinyl Siding	Asphalt			Extra wide; has been added onto	3C	1	13
1180	13-30-226-001	02 Barn	Dairy Gambrel	N / A	1900-1930	Good	Good		Vertical Wood	Asphalt				3B	37	13
1180	13-30-226-001	03 Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Asphalt		Has shed addition to one side		3C	2	13
1180	13-30-226-001	04 Pumphouse	Front Gabled	N / A		Good	Good	Field Stone	Tin (Flat)	Asphalt			Includes slant-roofed shed	3C	3	13
1180	13-30-226-001	05 Coop	Chicken Uneven Gable	N / A		Good	Good		Beveled Clapboard	Asphalt				3C	4	13
1180	13-30-226-001	06 Garage	Side Gabled	N / A		Good	Good		Clapboard	Asphalt			5-car plus work area	3B	36	13
1129	13-30-351-011	01 House	Four-over-four	N / A	1860-1890	Good	Good		Clapboard	Asphalt			Very Overgrown	3C	26	13
1129	13-30-351-011	02 Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			Includes terra cotta tile silo	3C	28	13
1129	13-30-351-011	03 Milkhouse	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Detached	3C	27	13
1129	13-30-351-011	04 Corn Crib	Dual Aisle	N / A		Good	Good		Horizontal Slats	Asphalt			Unusual configuration of layout	3C	25	13
1129	13-30-351-011	05 Garage	Pyramidal	N / A		Good	Good		Clapboard	Asphalt				3C	24	13
1128	13-30-400-012	01 House	I-house	N / A	1860-1880	Good	Good		Clapboard	Asphalt			Original porch and windows	3C	21	13
1128	13-30-400-012	02 Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			Includes milkhouse	3C	22	13
1128	13-30-400-012	03 Shed	Side Gabled	N / A		Good	Good		Tin (Flat)	Asphalt			Two shed of varying form and material, but both in only fair condition. (No, it isn't a photo of the horse sculpture)	3C	23	13
1190	13-31-100-005	01 Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	Metal Dome			Includes metal pole barn	3C	33	13
1190	13-31-100-005	02 Pumphouse	Side Gabled	N / A		Good	Good		Field Stone	Wood Shingles			Very picturesque	3C	34	13
1189	13-31-100-007	01 House	Cottage	Cape Cod	1910-1940	Good	Good		Vinyl Siding	Asphalt		Addition on front		3D	5	13
1189	13-31-100-007	02 Barn	Transverse Frame	N / A		Good	Good		Vertical Wood	Asphalt			Includes 2 silos: one poured concrete and one concrete staved	3D	6	13
1189	13-31-100-007	03 Milkhouse	Side Gabled	N / A		Good	Good	Cement Block	Tin (Flat)	Tin (Flat)				3D	7	13
1188	13-31-100-016	01 Shed	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt			Machine shed	3D	9	13
1188	13-31-100-016	02 Milkhouse	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt				3D	8	13
1185	13-31-200-016	01 House	Upright and Wing	N / A	1860-1880	Good	Good		Brick	Asphalt			Original windows and porch	3D	21	13
1185	13-31-200-016	02 Garage	Side Gabled	N / A		Good	Good		Vinyl Siding	Asphalt				3D	19	13
1186	13-31-200-018	01 Shed	Front Gabled	N / A		Good	Good		Asphalt	Asphalt				3D	20	13
1186	13-31-200-018	02 Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			Note shed extension overhang for cattle protection	3D	18	13
1187	13-31-300-006	01 House	Side Gabled	N / A	1930-1950	Poor	Poor		Vinyl Siding	Asphalt			This site is owner by the Conservation District and they are in the process of taking down these buildings	3D	10	13
1187	13-31-300-006	02 Shed	Ranch	N / A		Very Poor	Poor		Plywood	Asphalt			Summer housing	3D	11	13
1187	13-31-300-006	03 Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	none				3D	13	13
1187	13-31-300-006	04 Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Asphalt				3D	14	13
1187	13-31-300-006	05 Shed	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt				3D	15	13
1187	13-31-300-006	06 Coop	Chicken Uneven Gable	N / A		Poor	Poor		Beveled Clapboard	Asphalt			Shed addition on former window side	3D	16	13
1187	13-31-300-006	07 Shed	Uneven Gable	N / A		Very Poor	Poor		Asbestos	Asphalt			2 sheds	3D	17	13

Previous Site	Pin Number	Structure Type	Vernacular Form	Architectural Style	Circa	Condition	Integrity	Foundation	Walls	Roof	Porch	Alterations	History	Roll	Photo	Prefix
1187	13-31-300-006	08 Shed	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt				3D	12	13
1191	13-31-300-007	01 House	Upright and Wing	Queen Anne	1890-1910	Fair	Poor		Asbestos	Asphalt	Enclosed		Details stripped when resided	3C	35	13
1191	13-31-300-007	02 Shed	Side Gabled	N / A		Good	Good		Cement Block	Asphalt				3C	36	13
1191	13-31-300-007	03 Shed	Front Gabled	N / A		Good	Good		Cement Block	Asphalt				3C	37	13
1191	13-31-300-007	04 Barn	Gothic Arched	N / A	1910-1940	Good	Good	Poured Concrete	Vertical Wood	Tin (Flat)			Includes detached milkhouse and concrete staved silo	3D	3	13
1191	13-31-300-007	05 Shed	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				3D	1	13
1191	13-31-300-007	06 Barn	Metal Pole Barn	N / A		Poor	Poor		Tin (Flat)	Tin (Flat)			Plus an open air shelter	3D	4	13
1344	13-32-100-007	01 House	Upright and Wing	N / A		Fair	Poor		Asbestos	Asphalt			Appears not lived in; chain across driveway	3D	25	13
1344	13-32-100-007	02 Shed	Side Gabled	N / A		Very Poor	Poor		Asbestos	Asphalt				3D	26	13
1344	13-32-100-007	03 Corn Crib	Transverse Aisle	N / A		Good	Good		Horizontal Slats	Asphalt			Combo slatted and solid bays	3D	27	13
1184	13-32-100-030	01 House	Four-over-four	Foursquare	1880-1920	Good	Good		Vertical Wood	Asphalt	Addition to side			3D	24	13
1184	13-32-100-030	02 Barn	Dairy Gambrel	N / A	1880-1920	Good	Good		Vertical Wood	Asphalt			Includes concrete staved silo	3D	22	13
1184	13-32-100-030	03 Corn Crib	Transverse Aisle	N / A		Very Poor	Good		Horizontal Slats	Asphalt				3D	23	13
1344.5	13-32-200-002	01 House	Front Gabled	N / A	1880-1920	Good	Fair		Clapboard	Asphalt			Former school!	3D	28	13
1344.5	13-32-200-002	02 Garage	Front Gabled	N / A		Good	Good		Vertical Wood	Asphalt				3D	29	13
1344.5	13-32-200-002	03 Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3D	30	13
1344.5	13-32-200-002	04 Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3D	31	13
1812	13-32-200-005	01 House	Upright and Wing	N / A	1860-1880	Fair	Fair		Aluminum Siding	Asphalt			Added onto	3E	6	13
1812	13-32-200-005	02 Shed	Quonset	N / A		Good	Good		Tin (Corrugated)	Tin (Corrugated)			Doors along side	3E	4	13
1812	13-32-200-005	03 Garage	Pyramidal	N / A		Poor	Good		Aluminum Siding	Asphalt				3E	7	13
1812	13-32-200-005	04 Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)			2 pole building and modified chicken coop	3E	5	13
1346	13-32-200-008	01 House	Four-over-four	Foursquare	1900-1930	Good	Good	Molded Block	Clapboard	Asphalt				3E	3	13
1345	13-32-200-014	01 Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3D	33	13
1345	13-32-200-014	01 House	Cottage	N / A	1900-1930	Good	Good		Clapboard	Asphalt			Newly redone clapboard and windows	3D	32	13
1345	13-32-200-014	02 Barn	Transverse Frame	N / A	1900-1940	Good	Good	Molded Block	Vertical Wood	Asphalt			Includes concrete staved silo and attached milkhouse	3D	34	13
1347	13-32-400-002	01 House	Bungalow	N / A	1910-1940	Good	Good		Molded Block	Asphalt				3D	35	13
1348	13-32-400-004	01 Barn	Gothic Arched	N / A		Very Poor	Fair		Asbestos	Asphalt				3E	2	13
1348	13-32-400-004	02 Silo	Brick	N / A		Falling down	Poor		Brick	none				3E	1	13
1348	13-32-400-004	03 Shed	Slant-roofed	N / A		Fair	Good		Asbestos	Asphalt				3D	37	13
1348	13-32-400-004	04 Shed	Side Gabled	N / A		Poor	Good		Asbestos	Asphalt			Includes 3 sheds	3D	36	13
1811	13-33-300-012	01 House	Cottage	N / A	1910-1940	Good	Good		Aluminum Siding	Asphalt				3E	15	13
1811	13-33-300-012	02 Barn	Dairy Gambrel	N / A	1880-1920	Fair	Good		Vertical Wood	Asphalt			Includes wire mesh corn crib	3E	20	13
1811	13-33-300-012	03 Milkhouse	Gambrel	N / A		Good	Good		Vertical Wood	Asphalt				3E	18	13
1811	13-33-300-012	04 Pumphouse	Side Gabled	N / A		Fair	Good		Vertical Wood	Asphalt				3E	17	13
1811	13-33-300-012	05 Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	none				3E	11	13
1811	13-33-300-012	06 Barn	Transverse Frame	N / A	1880-1900	Fair	Good		Vertical Wood	Asphalt				3E	19	13
1811	13-33-300-012	07 Silo	Poured Concrete	N / A		Good	Good		Poured Concrete	Conical				3E	16	13
1811	13-33-300-012	08 Chicken Coop	Front Gabled	N / A		Poor	Poor		Vertical Wood	Asphalt				3E	12	13
1811	13-33-300-012	09 Grainery	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				3E	10	13
1811	13-33-300-012	10 Shed	Slant-roofed	N / A		Poor	Poor		Beveled Clapboard	Asphalt			Has shed addition	3E	9	13
1811	13-33-300-012	11 Chicken Coop	Slant-roofed	N / A		Poor	Poor		Vertical Wood	Asphalt				3E	13	13
1811	13-33-300-012	12 Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Tin (Flat)				3E	14	13
1811	13-33-300-012	13 Shed	Quonset	N / A		Good	Good		Tin (Corrugated)	Tin (Corrugated)				3E	8	13
1878	13-33-400-008	01 House	Cottage	Cape Cod	1910-1940	Good	Good		Aluminum Siding	Asphalt			Horse stable that includes several metal pole barns used for stables and arenas	ZZ	18	13
1878	13-33-400-008	02 Barn	Dairy Gambrel	N / A		Good	Good		Tin (Flat)	Asphalt			Has shed addition	ZZ	17	13
1878	13-33-400-008	03 Garage	Pyramidal	N / A		Good	Good		Cement Block	Asphalt			3-car rectangular version	ZZ	16	13
1875	13-34-100-014	01 House	Cross Gabled	N / A	1880-1920	Good	Good		Vinyl Siding	Asphalt			Wonderful old farmstead beautifully maintained	ZZ	32	13
1875	13-34-100-014	02 Barn	Dairy Gambrel	N / A	1880-1920	Excellent (Restored)	Excellent		Vertical Wood	Asphalt				ZZ	31	13
1875	13-34-100-014	03 Shed	Side Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				ZZ	28	13
1875	13-34-100-014	04 Chicken Coop	Slant-roofed	N / A		Good	Good		Beveled Clapboard	Asphalt				ZZ	30	13
1875	13-34-100-014	05 Chicken Coop	Front Gabled	N / A		Good	Good		Beveled Clapboard	Asphalt				ZZ	27	13
1875	13-34-100-014	06 Shed	Front Gabled	N / A		Fair	Good		Vertical Wood	Asphalt				ZZ	29	13
1877	13-34-300-003	01 House	Upright and Wing	N / A	1860-1880	Good	Fair		Vinyl Siding	Asphalt	Many additions		Overgrown from roadside, so could only take from the back and was limited due to questionable dogs	ZZ	20	13
1877	13-34-300-003	02 Corn Crib	Transverse Aisle	N / A		Good	Good		Vertical Wood	Asphalt			Totally covered with shed addition	ZZ	19	13
1877	13-34-300-003	03 Pumphouse	Side Gabled	N / A		Good	Good		Vertical Wood	Asphalt				ZZ	21	13
1876	13-34-300-004	01 House	Front Gabled	N / A		Good	Good		Asbestos	Asphalt				ZZ	25	13
1876	13-34-300-004	02 Garage	Side Gabled	N / A		Good	Good		Clapboard	Asphalt				ZZ	24	13
1876	13-34-300-004	03 Silo	Concrete Staved	N / A		Good	Good		Concrete Staved	none			Old barn was burned the week before photos were taken	ZZ	22	13
1876	13-34-300-004	04 Corn Crib	Transverse Aisle	N / A		Falling down	Poor		Horizontal Slats	Asphalt				ZZ	23	13

Previous Site	Pin Number	Structure Type	Vernacular Form	Architectural Style	Circa	Condition	Integrity	Foundation	Walls	Roof	Porch	Alterations	History	Roll	Photo	Prefix
1869	13-34-400-011	01 Barn	Metal Pole Barn	N / A		Good	Good		Tin (Flat)	Asphalt			Includes concrete staved silo, but that's all that's left	ZZ	26	13
1872	13-36-100-002	01 Barn	Dairy Gambrel	N / A		Good	Good		Vertical Wood	Asphalt			Includes silo and shed addition	YY	22	13
1872	13-36-100-002	02 Shed		N / A		Good	Good		Tin (Flat)	Tin (Flat)				YY	23	13
1872	13-36-100-002	03 Garage	Pyramidal	N / A	1910-1940	Good	Good		Wood Shingles	Asphalt			Has clipped gable	YY	24	13