

McHenry County




Illinois

Township Key

Chemung	Alden	Hebron	
Dunham	Hartland		
Marengo	Seneca		
Riley	Not Included in Survey		

Alden Township

T46N, R6E



MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 1



Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-1-1 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 14809 State Line Road _____

Lat/Long: 42.493921/-88.483705 _____

Primary Use: Residential /Ag _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: seven _____

List Observed Structures: (A) residence; (B) barn; (C,D,E) silos; (F) metal shed/barn; (G) pole barn _____

Residence Detail

Style: 2-story Cross Gabled

Wall materials: wood

Roof materials: metal

Foundation materials: unknown

Other distinguishing features

Barn Detail

Style: Gambrel roof dairy

Wall materials: vertical wood

Roof materials: metal

Foundation materials: unknown

Other distinguishing features

Any obvious Additions/Alterations: milk house and shed attached to barn

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): three concrete silos, metal clad double shed/barn, pole barn

Property Group Date Range: early 20th century

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1908-1951



AL-1-1: 14809 State Line Road – Residence, Barns, Silos

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number:AL-1-2 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name:_____

Address: 14623 State Line Road_____

Lat/Long: 42.492967/-88.481072_____

Primary Use: Residential_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: two_____

List Observed Structures: (A) residence; (B) barn_____

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features

Barn Detail

Style: Gabled

Wall materials: wood

Roof materials: vinyl

Foundation materials: unknown

Other distinguishing features

Any obvious Additions/Alterations: front porch may have been enclosed

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: early 20th century

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.

circa 1977 assessor date

circa 1972-1992



AL-1-2: 14623 State Line Road - Residence



AL-1-2: 14623 State Line Road - Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-1-3 _____ Surveyor Name: M. Prchal, C. Flynn _____

Current Property or Structure Name: _____

Address: State Line Road _____

Lat/Long: 42.491749/-88.477650 _____

Primary Use: Agriculture _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) silo; (B) pole barn _____

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): concrete silo

Property Group Date Range: early to mid 20th century

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 2004 assessor date

circa 1903-1951



AL-1-3: State Line Road – Silo, Pole Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-1-4 _____ Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 14401 State Line Road _____

Lat/Long: 42.488302/-88.475161 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence _____

Residence Detail

Style: Ranch

Wall materials: wood/vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): attached garage

Property Group Date Range: mid-20th century

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1936 assessor date

circa 1908-1951



AL-1-4: 14401 State Line Road – Residence

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 2



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-2-1 _____ Surveyor Name: M. Prchal, C. Flynn _____

Current Property or Structure Name: _____

Address: 16003 State Line Road _____

Lat/Long: 42.494494/-88.508162 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) barn _____

Residence Detail

Style: Gabled El

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features

Barn Detail

Style: Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features

Any obvious Additions/Alterations: side-gabled wing may have been enlarged

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: circa 1870s

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

before 1862



AL-2-1: 16003 State Line Road - Residence



AL-2-1: 16003 State Line Road - Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-2-2 _____ Surveyor Name: M. Prchal, C. Flynn _____

Current Property or Structure Name: _____

Address: State Line Road _____

Lat/Long: 42.493020/-88.499423 _____

Primary Use: Agriculture _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: three _____

List Observed Structures: (A) silo; (B) silo; (C) pole barn _____

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): (A,B) two concrete silos

Property Group Date Range: early-mid 20th c.

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

before 1847-1862




AL-2-2: State Line Road – Silos, Pole Barn



AL-2-2: State Line Road – Centennial Farm Sign

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 3



Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-3-1 _____ Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 16003 State Line Road _____

Lat/Long: 42.494505/-88.524163 _____

Primary Use: Agriculture /Res _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: eleven _____

List Observed Structures: (A) residence; (B) residence #2-trailer; (C) barn; (D) pole barn; (E,F,G,H,I) silos; (J) shed complex; (K) livestock barn

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: metal

Foundation materials: unknown

Other distinguishing features

Barn Detail

Style: Gambrel roof dairy

Wall materials: wood, vinyl

Roof materials: metal

Foundation materials: unknown

Other distinguishing features

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): Trailer residence (B); two concrete silos (E,F); three concrete stave silos (G,H,I); metal and wood shed complex (J); large metal and frame livestock barn (K).

Property Group Date Range: late 19th - early 20th century

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

circa 1940-1950 assessor date

circa 1908-1951



AL-3-1: 16003 State Line Road – Residence 2,
Barns, Silos, Shed



AL-3-1: 16003 State Line Road – Silos, Barn



AL-3-1: 16003 State Line Road – Residence,
Silos, Bins

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-3-2 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 16755 State Line Road _____

Lat/Long: 42.494587/-88.523601 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) shed _____

Residence Detail

Style: Ranch with two-story wing and garage

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: mid-20th century

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1962 assessor date

circa 1908-1951



AL-3-2: 16755 State Line Road – Residence, Shed

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 4



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet

Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-4-1 _____ Surveyor Name: M. Prchal, C. Flynn _____

Current Property or Structure Name: _____

Address: 11117 Alden Road _____

Lat/Long: 42.488173/-88.544831 _____

Primary Use: Agriculture /Res _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) silo; (C) silo; (D) silo; (E) metal bin (F) pole barn _____

Residence Detail

Style: Raised Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

Barn Detail

Style: demolished

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): (B,C) two concrete stave silos, (D) concrete silo; (E) metal bin; (F) metal pole barn

Property Group Date Range: early-mid 20th century

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 2002 assessor date

before 1862



AL-4-1: 11117 Alden Road – Silos, Bin, Pole Barn



AL-4-1: 11117 Alden Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-4-2 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 17713 State Line Road _____

Lat/Long: 42.494487/-88.543584 _____

Primary Use: Ag/Res _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) barn; (C) silo; (D) garage; (E) wire bins (F) pole barn _____

Residence Detail

Style: Front Gabled/Bungalow

Wall materials: vinyl, stone face

Roof materials: metal

Foundation materials: concrete

Other distinguishing features

Barn Detail

Style: Gambrel-roof dairy

Wall materials: wood

Roof materials: metal

Foundation materials: unknown

Other distinguishing features

Any obvious Additions/Alterations: stone face added to enclosed front porch

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): (C) concrete silo, (D) garage; (E) wire bins; (F) metal pole barn

Property Group Date Range: L 19th – E 20th century

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1953 assessor date

before 1862




AL-4-2: 17713 State Line Road – Residence, Barn,
Bins, Garage



AL-4-2: 17713 State Line Road – Barns, Silo

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 5





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-5-1 _____ Surveyor Name: M. Prchal, C. Flynn _____

Current Property or Structure Name: _____

Address: 10614-10856 Gasch Road _____

Lat/Long: 42.489561/-88.569685 _____

Primary Use: Ag/Res _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) barn/shed; (C) silo; (D) pole barn; (E) shed _____

Residence Detail

Style: Foursquare

Wall materials: brick

Roof materials: asphalt/concrete tile

Foundation materials: unknown

Other distinguishing features

Barn Detail

Style: Banked

Wall materials: vertical wood

Roof materials: metal

Foundation materials: concrete

Other distinguishing features: Red

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): (C) concrete silo, (D) pole barn; (E) shed

Property Group Date Range: L 19th – E 20th century

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

circa 1940 assessor date

before 1862



AL-5-1: 10614-10856 Gasch Road - Silo



AL-5-1: 10614-10856 Gasch Road – Barn, Sheds



AL-5-1: 10614-10856 Gasch Road - Barn



AL-5-1: 10614-10856 Gasch Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-5-2 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 18515 State Line Road _____

Lat/Long: 42.494421/-88.558384 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) pole barn _____

Residence Detail

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: Mid-Late 20th century

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1958 assessor date

before 1862-1892



AL-5-2: 18515 State Line Road – Residence



AL-5-2: 18515 State Line Road – Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-5-3 _____ Surveyor Name: M. Prchal, C. Flynn _____

Current Property or Structure Name: _____

Address: 18101 State Line Road _____

Lat/Long: 42.492055/-88.553166 _____

Primary Use: Agriculture _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) Barn; (B) shed/barn _____

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Barn Detail

Style: Gabled roof

Wall materials: wood

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): (C) concrete silo, (D) pole barn; (E) shed

Property Group Date Range: Late 19th century

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

A residence and farmstead are shown in this location on 1872 township map.

before 1862



AL-5-3: 18101 State Line Road – Barns

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-5-4 _____ Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 14419 Alden Road _____

Lat/Long: 42.493095/-88.550581 _____

Primary Use: Ag/Res _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: seven _____

List Observed Structures: (A) residence; (B) barn; (C) silo; (D) shed; (E) garage; (F) shed, (G) pole barn;

Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features

Barn Detail

Style: Gabled roof dairy

Wall materials: vertical wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: Red

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): (C) concrete silo, (D) shed; (E) garage, (F) shed; (G) pole barn

Property Group Date Range: L 19th – E 20th century

Number of photos taken for this property*: five _____

* Attach Photo log, additional notes and map of resource location.

circa 1910 assessor date

before 1862



AL-5-4: 14419 Alden Road – Residence,
Garage, Shed




AL-5-4: 14419 Alden Road – Barn, Silo, Shed



AL-5-4: 14419 Alden Road – Barn

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 6





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-6-1 _____ Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 20003 State Line Road _____

Lat/Long: 42.494612/-88.587583 _____

Primary Use: Ag/Res _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) barn; (C) silo; (D) shed/garage; (E) small shed

Residence Detail

Style: Italianate

Wall materials: wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: appears to be abandoned

Barn Detail

Style: Gabled roof dairy

Wall materials: vertical wood

Roof materials: shingle/gone

Foundation materials: concrete

Other distinguishing features: collapsing

Any obvious Additions/Alterations: Looks like a Foursquare now.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): (C) concrete stave silo, (D) shed/garage; (E) small shed

Property Group Date Range: L 19th – E 20th century

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1850 assessor date

circa 1908-1951



AL-6-1: 20003 State Line Road – Barn, Silo, Sheds



AL-6-1: 20003 State Line Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-6-2 _____ Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 19609 State Line Road _____

Lat/Long: 42.493664/-88.58422 _____

Primary Use: Res/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: one _____

List Observed Structures: (A) Gambrel roofed barn in background _____

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Barn Detail

Style: Gambrel roof

Wall materials: unknown

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): (C) concrete silo, (D) pole barn; (E) shed

Property Group Date Range: Early 20th century

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1970 assessor date

circa 1957-1975



AL-6-2: 19609 State Line Road – Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-6-3 __ Surveyor Name: M. Prchal, C. Flynn _____

Current Property or Structure Name: _____

Address: 11305 Gasch Road _____

Lat/Long: 42.490284/-88.570078 _____

Primary Use: Res/Ag _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) barn; (C) silo; (D) outhouse; (E) two small sheds; (F) pole barn

Residence Detail

Style: Gabled Ell

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: remodeled

Barn Detail

Style: Gambrel-roof dairy

Wall materials: vertical wood

Roof materials: metal

Foundation materials: fieldstone

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): (C) concrete stave silo, (D) outhouse; (E) two small sheds; (F) pole barn

Property Group Date Range: L 19th – E 20th century

Number of photos taken for this property*: five _____

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

before 1862



AL-6-3: 11305 Gasch Road - Residence

THE PLACE KNOWN YEARS AGO AS "THE WOODRICH FARM"
 Helen Schmitz who lived on farm from 1936-1964 had
 10 acre farm on what is now Gasch Road - the 4
 ch rd.

THE - The wooden fence was not there - not w
 just took down in June, 1995. Of course, the
 The porch is the same, but we just screened
 assure system with running water, septic tank
 ility was put in in 1976. The house was heated
 by living room (gasic room), and a kitchen
 when we lived there, the outside of the house
 was. Evidently, the asbestos shingles were
 we left the farm. That was, no doubt, done
 or during the winter months - that was the met
 he time.

On the north side was a long, narrow room (we
 east corner of the room was a small walk-in cl
 the north and east side look as though they s
 as so the windows in the living room, which
 (our music room). Above this room was a bed
 closet on the west and north side of the ro
 in the same spot also. The stove pipe from
 through this room to the chimney on the roof
 ed a little heat to this bedroom.

Leading to the upstairs was in the kitchen
 same spot as the kitchen is now. Only no cu
 s in the southwest corner of the kitchen, an
 by it. The kitchen stove stood on the sou
 ere one went down to the basement (this room
 in a small hallway at the top of the stairs, I
 went through a low door to room over the kil
 were room. Now it has been changed so that
 up the door. The upstairs window to the nor
 (in class). The upstairs window can be see
 the bottom (under the cave troughs.


THE - This is the back of the house...

AL-6-3: 11305 Gasch Road – History Page



AL-6-3: 11305 Gasch Road – Residence, Barns, Sheds

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 7





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-7-1 _____ Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 19314 Hebron Road _____

Lat/Long: 42.479999/-88.575802 _____

Primary Use: agriculture _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) concrete stave silo

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: Early-Mid. 20th century

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1920-1940

before 1862



AL-7-1: 19314 Hebron Road – Silo

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-7-2 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 19602 Hebron Road _____

Lat/Long: 42.479948/-88.580553 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: X _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: Late 19th-Early 20th century

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1910 assessor date

circa 1908-1951



AL-7-2: 19602 Hebron Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-7-3 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 19704 Hebron Road _____

Lat/Long: 42.479990/-88.582313 _____

Primary Use: residential /Ag _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) small barn; (C) garage; (D) pole barn

Residence Detail

Style: Gabled El

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone, concrete

Other distinguishing features:

Barn Detail

Style: Center Bay – Gabled roof

Wall materials: vinyl, wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: front porch enclosed, given concrete foundation

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): C – garage: asphalt, vinyl, unknown; (D) pole barn to rear

Property Group Date Range: Late 19th century

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1970 assessor date

before 1862



AL-7-3: 19704 Hebron Road – Barns, Garage



AL-7-3: 19704 Hebron Road - Residence

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 8





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-8-1 _____ Surveyor Name: M. Prchal, C. Flynn _____

Current Property or Structure Name: _____

Address: 18612 Hebron Road _____

Lat/Long: 42.479896/-88.561251 _____

Primary Use: Res/Ag _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) barn (C) shed; (D) shed; (E) garage

Residence Detail

Style: Cross Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Gabled roof dairy barn

Wall materials: vinyl

Roof materials: metal

Foundation materials: fieldstone

Other distinguishing features: attached milkhouse

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): (C) shed with fieldstone fnd; (D) shed with fieldstone fnd.; (E) garage

Property Group Date Range: L 19th century

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

before 1862



AL-8-1: 18612 Hebron Road – Barns, Sheds, Garage



AL-8-1: 18612 Hebron Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-8- 2 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 19018 Hebron Road _____

Lat/Long: 42.479937/-88.569216 _____

Primary Use: Residential /Ag _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) barn (C) shed; (D) shed; (E) garage

Residence Detail

Style: Front Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): (B) garage; (C) wood-sided shed

Property Group Date Range: L 19th century

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1930 assessor date.

circa 1862-1872



AL-8-2: 19018 Hebron Road – Residence, Sheds, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-8-3 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 10808 Gasch Road _____

Lat/Long: 42.483808/-88.569328 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) barn (C) shed

Residence Detail

Style: Ranch

Wall materials: wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): (C) wood-sided shed

Property Group Date Range: L 19th – Mid 20th century

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1984 assessor date

circa 1956-1957



AL-8-3: 10808 Gasch Road – Barn, Shed



AL-8-3: 10808 Gasch Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-8-4 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 10912 Gasch Road _____

Lat/Long: 42.485286/-88.569352 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) pole barn

Residence Detail

Style: No style

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: Mid 20th century

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1940 assessor date

before 1862



AL-8-4: 10912 Gasch Road – Residence



AL-8-4: 10912 Gasch Road - Barn

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 9





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-9-1 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 17214 Hebron Road _____

Lat/Long: 42.480099/-88.533486 _____

Primary Use: Res/Ag _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) barn; (C) small shed; (D) larger metal shed; (E) pole barn

Residence Detail

Style: Italianate

Wall materials: vinyl

Roof materials: metal

Foundation materials: fieldstone (covered)

Other distinguishing features:

Barn Detail

Style: round-roof dairy

Wall materials: vinyl

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: projecting peaks

Any obvious Additions/Alterations: addition to west side; recessed angled corner

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): (C) small shed; (D) metal shed; (E) pole barn

Property Group Date Range: L 19th – E 20th century

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

before 1862



AL-9-1: 17214 Hebron Road - Residence



AL-9-1: 17214 Hebron Road – Barns, Sheds



AL-9-1: 17214 Hebron Road – Sign

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number:AL-9-2 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name:_____

Address: 17211 Hebron Road_____

Lat/Long: 42.479172/-88.533293_____

Primary Use: Residential_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence_____

Residence Detail

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: Mid-Late 20th century

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.

circa 1977 assessor date

circa 1970-1988



AL-9-2: 17211 Hebron Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: : AL-9-3 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 17419 Hebron Road _____

Lat/Long: 42.479069/-88.538692 _____

Primary Use: Res/Ag _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: nine _____

List Observed Structures: (A) residence; (B) small shed; (C) shed complex; (D) barn; (E,F,G) silos; (H) bin; (I) pole barn

Residence Detail

Style: Gabled El

Wall materials: asbestos shingle

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

Barn Detail

Style: Round roof

Wall materials: concrete block

Roof materials: metal

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations: enclosed front porch

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): (B) small shed; (C) metal shed complex; (D) concrete barn; (E,F,G) concrete silos; (H) metal bins; (I) pole barn

Property Group Date Range: L 19th – E 20th century

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

before 1862



AL-9-3: 17419 Hebron Road – Residence



AL-9-3: 17419 Hebron Road – Shed Complex



AL-9-3: 17419 Hebron Road – Barns, Silos, Bin



AL-9-3: 17419 Hebron Road – Bin, Pole Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: 13-122: L-9-4 __ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 17616 Hebron Road _____

Lat/Long: 42.479853/-88.541447 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) pole barn/shed _____

Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

distinguishing features:

Any obvious Additions/Alterations: enclosed front porch, addition to rear of wing.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: Late 19th- Early 20th c.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1862-1872



AL-9-4: 17616 Hebron Road – Residence, Pole Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-9-5 _____ Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 18013 Hebron Road _____

Lat/Long: 42.479236/-88.549116 _____

Primary Use: Res/Ag _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) barn; (C) sheds

Residence Detail

Style: Gabled Ell

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Gabled Banked barn

Wall materials: vertical wood

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: enclosed front porch

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): (C) metal shed complex, obscured

Property Group Date Range: L 19th – E 20th century

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

circa 1862-1872



AL-9-5: 18013 Hebron Road - Barn



AL-9-5: 18013 Hebron Road – Residence



AL-9-5: 18013 Hebron Road – Sheds

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-9-6 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 10913 Alden Road _____

Lat/Long: 42.484354/-88.539915 _____

Primary Use: Residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) garage

Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): (B) garage: vinyl, asphalt, unknown fnd.

Property Group Date Range: Early-Mid. 20th century

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1925 assessor date

circa 1957-1970

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-9-6: 10913 Alden Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-9-7 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 10552 Alden Road _____

Lat/Long: 42.485224/-88.540032 _____

Primary Use: agriculture _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: three _____

List Observed Structures: (A) concrete stave silo, top missing; (B) concrete stave silo, (C) vertical wood milk house

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): concrete slab foundation

Property Group Date Range: Early-Mid. 20th century

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

before 1862



AL-9-7: 10552 Alden Road – Silos, Milk House

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 10



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15 Survey Number: AL-10-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: HW Wood Products

Address: 16306 Hebron Road

Lat/Long: 42.479189/-88.514852

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 8

List Observed Structures: (A) Res (B) pole building (C) machine shed (D) shed (E) outbuilding (F) coop (G) pole building (H) shelter

Residence Detail

Style: Ranch

Wall materials: aluminum

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features
picture window, concrete stoop

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small gabled shed C - frame machine shed with metal siding D - gambrel shed

E - mansard roof outbuilding F - small coop G - gabled pole building with timber extension

H - machine shelter

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

before 1862



AL-10-1: 16306 Hebron Road – Pole Building, Sheds, Outbuilding



AL-10-1: 16306 Hebron Road – Coop, Pole Building



AL-10-1: 16306 Hebron Road – Residence, Shelter

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15 Survey Number: AL-10-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: Knickerbocker Road

Lat/Long: 42.486766/-88.517342

Primary Use: Ag

Is this a record of a single structure or group (give total number of structures):

Single: Group: _____ Number Structures in Group: _____

List Observed Structures: Barn

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Barn Detail

Style: Gambrel Raised

Wall materials: board

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features
Tall rooftop vent

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

residence and other structures are modern and set back from road

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 2002 assessor date

before 1862



AL-10-2: Knickerbocker Road – Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15 Survey Number: AL-10-3 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16619 Hebron Road

Lat/Long: 42.479269/-88.522140

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 6

List Observed Structures: (A) Res (B) Barn (C) silo (D) pole building (E) small barn (F) greenhouse

Residence Detail

Style: Side Gabled

Wall materials: stucco/plaster

Roof materials: asphalt

Foundation materials:

Other distinguishing features: no second floor windows on front

Barn Detail

Style: Gabled Three Bay

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

expansion of rear roofline, side addition including concrete porch

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc:

C - concrete stave silo D - modern pole building E - small gabled outbuilding

F - metal greenhouse frame

Number of photos taken for this property*: 4

* Attach Photo log, additional notes and map of resource location.

circa 1862-1872



AL-10-3: 16619 Hebron Road – Barns, Silo, Pole Building, Greenhouse



AL-10-3: 16619 Hebron Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15 Survey Number: AL-10-4 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 11810 Hebron Road

Lat/Long: 42.479760/-88.525060

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 7

List Observed Structures: (A) Res (B) garage (C) barn (D) silo (E) silo (F) machine shed (G) Res 2

Residence Detail

Style: Gothic

Wall materials: aluminum

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: small paired gables

Any obvious Additions/Alterations
attached garage

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc:

B - garage D - concrete stave silo E - poured concrete silo F - timber drive in machine shed

G- Second Residence: Bungalow w/ aluminum or asbestos siding/asphalt roof/concrete foundation/front steps and stoop

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

circa 1910, 1956 assessor date

before 1862



AL-10-4: 11810 Hebron Road – Residence,
Garage, Silo



AL-10-4: 11810 Hebron Road – Barn, Shed, Silo



AL-10-4: 11810 Hebron Road – Residence 2

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15 Survey Number: AL-10-5 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: MI Caledonia

Address: 10310 Alden Road

Lat/Long: 42.475947/-88.530227

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res/old schoolhouse (B) garage

Residence Detail

Style: Front Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: front entry porch

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations
rear addition

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc:

B - garage

may be relocated Kingsley School (S 9)

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1977 assessor date

before 1862



AL-10-5: 10310 Alden Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15 Survey Number: AL-10-6 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 10310 Alden Road

Lat/Long: 42.4755532/-88.530782

Primary Use: Ag

Is this a record of a single structure or group (give total number of structures):

Single: X Group: _____ Number Structures in Group: _____

List Observed Structures: silos

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc:

concrete stave silo

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1977 assessor date

circa 1975-1988



AL-10-6: 10310 Alden Road – Silo

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 11



Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number:AL-11-1 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name:_____

Address: 105705 Hebron Road_____

Lat/Long: 42.479024/-88.491003_____

Primary Use: res/agri_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: four_____

List Observed Structures: (A) residence; (B) barn; (C) shed/garage (D) pole barn

Residence Detail

Style: Ranch

Wall materials: wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): (C) shed/garage-“Melvin’s Garage”; (D) pole barn

Property Group Date Range: Early-Mid. 20th century

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.

circa 1968 assessor date

before 1862



AL-11-1: 105705 Hebron Road – Residence



AL-11-1: 105705 Hebron Road – Barns, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number:AL-11-2 _____ Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 115109 Hebron Road _____

Lat/Long: 42.479044/-88.4911831 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Upright and Wing

Wall materials: asbestos

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: diagonal corner windows, décor. peak

Barn Detail

Style: Banked

Wall materials: wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: Late 19th - Early 20th century

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

before 1862



AL-11-2: 115109 Hebron Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-11-3 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 15312 Hebron Road _____

Lat/Long: 42.479746/-88.495620 _____

Primary Use: res/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: 13 _____

List Observed Structures: (A) residence; (B) barn; (C) milk house; (D) milk house; (E) concrete stave silo; (F) concrete stave silo; (G) concrete silo; (H) concrete stave silo; (I-K) metal storage bins; (L) metal pen/shed; (M) pole barn.

Residence Detail

Style: Gothic Revival

Wall materials: vinyl, wood

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: decorative gable peaks

Barn Detail

Style: Gambrel-roof dairy

Wall materials: vinyl, wood

Roof materials: metal

Foundation materials: concrete

Other distinguishing features: two milk houses

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Late 19th century

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

circa 1992 assessor date

before 1862



AL-11-3: 15312 Hebron Road – Silos, Bins, Barn, Milk Houses



AL-11-3: 15312 Hebron Road – Pole Barn



AL-11-3: 15312 Hebron Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-11-4 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 15517 Hebron Road _____

Lat/Long: 42.479217/-88.499736 _____

Primary Use: res/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: seven _____

List Observed Structures: (A) residence; (B) barn; (C) concrete silo; (D) metal shed; (E) small wooden shed; (F) wooden shed; (G) garage.

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

Barn Detail

Style: Gambrel-roof dairy

Wall materials: vertical wood

Roof materials: asphalt over shingle

Foundation materials: plank covered

Other distinguishing features: dormer;
flared roof ends, ramp

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Late 19th century

Number of photos taken for this property*: six_____

* Attach Photo log, additional notes and map of resource location.

circa 1862-1872



AL-11-4: 15517 Hebron Road – Barn, Silo, Shed



AL-11-4: 15517 Hebron Road – Residence, Sheds, Garage



AL-11-4: 15517 Hebron Road – Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-11-5 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 15805 Hebron Road _____

Lat/Long: 42.479207/-88.506879 _____

Primary Use: res/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: seven _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) metal bin; (E) wood-sided shed; (F) small barn, only wood framing left; (G) metal-clad garage.

Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete-covered

Other distinguishing features:

Barn Detail

Style: Gabled roof

Wall materials: vertical wood

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: dormer;
flared roof ends, ramp

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Late 19th century

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

before 1862



AL-11-5: 15805 Hebron Road – Barns, Bin, Silo, Shed



AL-11-5: 15805 Hebron Road – Barns, Bin, Sheds, Silo



AL-11-5: 15805 Hebron Road – Residence



AL-11-5: 15805 Hebron Road – Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-11-6 _____ Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 16308 Hebron Road _____

Lat/Long: 42.479811/-88.509616 _____

Primary Use: res/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: three _____

List Observed Structures: (A) barn; (B) concrete stave silo; (C) concrete stave silo

Residence Detail

Style: remodeled Barn

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Barn Detail

Style: Gabled roof

Wall materials: vertical wood

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: remodeled

Any obvious Additions/Alterations: barn has numerous added windows. Shed extension lined with windows, solar panels(?) on extension roof.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): two concrete stave silos

Property Group Date Range: Late 19th – Early 20th century

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

circa 1992 assessor date

before 1862



AL-11-6: 16308 Hebron Road – Silos




AL-11-6: 16308 Hebron Road – Barn



AL-11-6: 16308 Hebron Road – Barn

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 12



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number:AL-12-1 _____ Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 14418 Hebron Road _____

Lat/Long: 42.479290/-88.479940 _____

Primary Use: res/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: three _____

List Observed Structures: (A) residence (B) metal garage/shed; (C) smaller shed

Residence Detail

Style: Gabled El

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: s

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: two-story addition to south end

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): smaller wood and metal-clad shed

Property Group Date Range: Late 19th – Early 20th century

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1892-1903

circa 1957-1963



AL-12-1: 14418 Hebron Road – Residence



AL-12-1: 14418 Hebron Road – Shed



AL-12-1: 14418 Hebron Road – Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-12-2 _____ Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 14502 Hebron Road _____

Lat/Long: 42.480205/-88.480862 _____

Primary Use: res/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: two _____

List Observed Structures: (A) residence (B) concrete stave silo

Residence Detail

Style: Gabled El

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): smaller wood and metal-clad shed

Property Group Date Range: Late 19th century

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1930 assessor date

circa 1862-1872



AL-12-2: 14502 Hebron Road – Residence, Silo

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-12-3 _____ Surveyor Name: M. Prchal, C. Flynn _____

Current Property or Structure Name: _____

Address: 14612 Hebron Road _____

Lat/Long: 42.479739/-88.483730 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Minimal Traditional

Wall materials: wood

Roof materials: metal

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: Mid-20th century

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1950 assessor date

circa 1957-1963

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-12-3: 14612 Hebron Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-12-4 _____ Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 14612 Hebron Road _____

Lat/Long: 42.479778/-88.484184 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Gabled EI

Wall materials: clapboard

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: two-story addition with garage to west. Stone addition to lower east side.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: Late 19th c.

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1998 assessor date

circa 1957-1963



AL-12-4: 14612 Hebron Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-12-5 _____ Surveyor Name: M. Prchal, C. Flynn _____

Current Property or Structure Name: _____

Address: 14801 Hebron Road _____

Lat/Long: 42.479096/-88.60033 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three _____

List Observed Structures: (A) garage; (B) tool shed; (C) utilities shed

Residence Detail

Style: demolished

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: Early 20 c.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.


circa 1930 assessor date

before 1862



AL-12-5: 14801 Hebron Road – Garage, Sheds

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 13



Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-13-1 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 15002 IL Rt. 173 _____

Lat/Long: 42.462662/-88.489235 _____

Primary Use: res/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: five _____

List Observed Structures: (A) residence (B) barn; (C) silo; (D) wooden shed; (E) metal quonsett shed

Residence Detail

Style: Upright and Wing

Wall materials: asbestos shingle

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: needs work

Barn Detail

Style: Gambrel roof

Wall materials: vertical board

Roof materials: metal

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): C-concrete stave silo; (D) wood sided shed; (E) metal quonsett shed

Property Group Date Range: Late 19th century

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1862-1872

circa 1872-1892



AL-13-1: 15002 Illinois Route 173 – Barn, Silo, Quonset Shed



AL-13-1: 15002 Illinois Route 173 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-13-2 _____ Surveyor Name: M. Prchal, C. Flynn _____

Current Property or Structure Name: _____

Address: 14806 IL Rt. 173 _____

Lat/Long: 42.463218/-88.485981 _____

Primary Use: Res _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Ranch

Wall materials: stone and wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: Mid-20th century

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1975 assessor date

circa 1954-1956

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-13-2: 14806 Illinois Route 173 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-13-3 _____ Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 14401 IL Rt. 173 _____

Lat/Long: 42.462208/-88.478804 _____

Primary Use: res/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) barn, (C) silo

Residence Detail

Style: Gabled El

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features: wing is one and half story

Barn Detail

Style: Gambrel roof

Wall materials: vertical board/vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations: barn has attached shed structure

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): concrete stave silo

Property Group Date Range: Early-20th century

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date

circa 1908-1939



AL-13-3: 14401 Illinois Route 173 – Residence



AL-13-3: 14401 Illinois Route 173 – Barn, Silo

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 14



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-14-1 _____ Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 16008 IL Rt. 173 _____

Lat/Long: 42.460704/-88.510084 _____

Primary Use: res/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: three _____

List Observed Structures: (A) residence (B) wood sided shed; (C) pole barn

Residence Detail

Style: Cross Gabled/Queen Anne

Wall materials: clapboard, shingle

Roof materials: metal

Foundation materials: concrete block-covered

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: Late 19th century

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1900

circa 1908-1939



AL-14-1: 16008 Illinois Route 173 – Residence



AL-14-1: 16008 Illinois Route 173 – Shed



AL-14-1: 16008 Illinois Route 173 – Pole Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-14-2 _____ Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 15820 IL Rt. 173 _____

Lat/Long: 42.461823/-88.505296 _____

Primary Use: res _____

Is this a record of a single structure or group (give total number of structures):

Single: X _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Ranch

Wall materials: vertical wood

Roof materials: metal

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: possibly a remodeled older home

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: Mid-20th century

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1972 assessor date

before 1862



AL-14-2: 15802 Illinois Route 173 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/18/15_____ Survey Number: AL-14-3 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 15417 IL Rt. 173 _____

Lat/Long: 42.461707/-88.497746 _____

Primary Use: res/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) garage; (C) pole barn; (D) metal shed/garage; (E) wood-sided shed; (F) smaller wood-sided shed

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features: side bay; porch trim

Any obvious Additions/Alterations: addition to rear

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Mid-20th century

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.

circa 1910 assessor date

circa 1939-1951



AL-14-3: 15417 Illinois Route 173 – Residence, Garage



AL-14-3: 15417 Illinois Route 173 – Barn, Sheds

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 15





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom




Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number





Copyright 2013 Esri, DeLorme, NAVTEQ, Tom Tom



Township Location

**DETAIL:
ALDEN TOWNSHIP
SECTION 15**



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16619 Route 173, Alden

Lat/Long: 42.458176/-88.522772

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 5 (2 obscured by trees)

List Observed Structures: (A) Res (B) small barn/shed (C) garden shed (D) and (E) obscured by trees

Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small gabled shed/barn C - small garden shed D and E - obscured

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1940 assessor date



AL-15-1: 16619 Illinois Route 173 – Residence, Sheds

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16605 Route 173, Alden

Lat/Long: 42.458463/-88.521558

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage

Residence Detail

Style: Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials:

Other distinguishing features

front porch has decorative spindle railings/frieze/brackets

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gambrel 2-bay garage/carriage house

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

before 1862



AL-15-2: 16605 Illinois Route 173 – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-3 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16536 Route 173, Alden

Lat/Long: 42.458906/-88.521431

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage

Residence Detail

Style: Foursquare

Wall materials: aluminum

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations
modern band of 5 windows

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B -gabled garage

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1892-1903



AL-15-3: 16536 Illinois Route 173 – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-4 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16535 Route 173, Alden

Lat/Long: 42.458486/-88.521378

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: X Group: _____ Number Structures in Group: _____

List Observed Structures: Res

Residence Detail

Style: Side Gabled

Wall materials: aluminum and vinyl

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations
enclosed front porch and rear addition

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1930 assessor date



AL-15-4: 16535 Illinois Route 173 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-5 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: Alden Community United Methodist Church

Address: 16532 Route 173, Alden

Lat/Long: 42.458974/-88.521006

Primary Use: Church

Is this a record of a single structure or group (give total number of structures):

Single: X Group: _____ Number Structures in Group: _____

List Observed Structures: Church

Residence Detail

Style: Gabled Front

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone/concrete block

Other distinguishing features

six sided steeple

wide frieze band

Any obvious Additions/Alterations

later wing

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

McHenry County Plaque #11 "Alden Methodist Church 1863"

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

circa 1892-1903

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-5: 16532 Illinois Route 173 – Church



AL-15-5: 16532 Illinois Route 173 – Plaque

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-6 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16621 Route 173, Alden

Lat/Long: 42.458541/-88.521003

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage/barn

Residence Detail

Style: Cape Cod

Wall materials: aluminum

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small barn/garage behind residence

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1950 assessor date



AL-15-6: 16621 Illinois Route 173 – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-7 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16527 Route 173, Alden

Lat/Long: 42.458525/-88.520631

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 1

List Observed Structures: Res

Residence Detail

Style: Gabled EI

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features
hooded second floor window
hooded door and first floor double window

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small barn/garage behind residence

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date



AL-15-7: 16527 Illinois Route 173 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-8 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: Route 173, Alden

Lat/Long: 42.459021/-88.520291

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res _____ (B) garage

Residence Detail

Style: Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: limestone and concrete block

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations
enclosed front porch

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - modern gabled garage

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1924 assessor date



AL-15-8: Illinois Route 173 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-9 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16526 Route 173, Alden

Lat/Long: 42.458999/-88.520312

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res _____ (B) garage

Residence Detail

Style: Foursquare

Wall materials: board

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features
spindle front porch columns and rails

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled garage

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date



AL-15-9: 16526 Illinois Route 173 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-10 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16524 Route 173, Alden

Lat/Long: 42.459008/-88.520091

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res _____ (B) barn

Residence Detail

Style: Foursquare

Wall materials: aluminum

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Doric columns on front porch/ off-center porch entrance

Pyramid center front dormer with half-circle window

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

circa 1910 assessor date



AL-15-10: 16524 Illinois Route 173 – Residence



AL-15-10: 16524 Illinois Route 173 – Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-11 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16606 Route 173, Alden

Lat/Long: 42.459017/-88.519878

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res _____ (B) garage

Residence Detail

Style: Gabled EI

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Spindle porch supports

Hooded second story double window

Any obvious Additions/Alterations

rear addition

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - Gambrel roofed two car garage/barn

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1910 assessor date



AL-15-11: 16606 Illinois Route 173 – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-12 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16519 Route 173, Alden

Lat/Long: 42.458647/-88.519592

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res _____ (B) garage

Residence Detail

Style: Bungalow

Wall materials: aluminum

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features

Wide dormer

eave brackets

pyramid roof enclosed front porch

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - Pyramid roof two bay garage/carriage house

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date



AL-15-12: 16519 Illinois Route 173 – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-13 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16602 Route 173, Alden

Lat/Long: 42.459063/-88.519518

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 6

List Observed Structures: (A) Res (B) garage (C) Barn (D) silo (E) grain bin (F) shed

Residence Detail

Style: Front Gabled 1 1/2 story

Wall materials: aluminum

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features

Doric column porch supports

Any obvious Additions/Alterations

Barn Detail

Style: Gambrel T-Plan Dairy Barn

Wall materials: board

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

multi-paned windows
gambrel milk house
dormers

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - Pyramid roof one car garage D - formed concrete silo E - metal grain bin F - timber long barn

property also includes concrete block foundation

Number of photos taken for this property*: 4

* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date



AL-15-13: 16602 Illinois Route 173 – Residence,
Garage



AL-15-13: 16602 Illinois Route 173 – Bin, Silo,
Barn, Shed



AL-15-13: 16602 Illinois Route 173 - Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-14 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16517 Route 173, Alden

Lat/Long: 42.458686/-88.519318

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: X Group: _____ Number Structures in Group: _____

List Observed Structures: Res

Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete (visible)

Other distinguishing features

Any obvious Additions/Alterations

Enclosed front porch

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-14: 16517 Illinois Route 173 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-15 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16511 Route 173, Alden

Lat/Long: 42.458720/-88.518885

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res _____ (B) garage

Residence Detail

Style: Upright and Wing

Wall materials: aluminum

Roof materials: asphalt

Foundation materials: concrete (visible)

Other distinguishing features

Any obvious Additions/Alterations

Enclosed front porch (not recent)

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - pyramid roof garage

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

circa 1924, 1944 assessor date



AL-15-15: 16511 Illinois Route 173 - Residence



AL-15-15: 16511 Illinois Route 173 - Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-16 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16503 Route 173, Alden

Lat/Long: 42.458681/-88.518339

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: X Group: _____ Number Structures in Group: _____

List Observed Structures: Res

Residence Detail

Style: Greek Revival Gabled EI

Wall materials: board

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features
carved columns on corners of building
rounded window hoods
multi-pane windows
frieze band windows
2 porches

Any obvious Additions/Alterations
door facing east boarded up (not recent)

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

circa 1850-1860

NRHP Eligible

before 1862

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-16: 16503 Illinois Route 173 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-17 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16500 Route 173, Alden

Lat/Long: 42.459092/-88.518213

Primary Use: Commercial

Is this a record of a single structure or group (give total number of structures):

Single: X Group: _____ Number Structures in Group: _____

List Observed Structures: commercial building and garage

Residence Detail

Style: Foursquare w/ attached

garage

Wall materials: concrete block Roof

materials: asphalt

Foundation materials: concrete block

Other distinguishing features

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

includes attached 2 car garage with flat roof

May be connected to AL-15-18 to the east

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1950 assessor date



AL-15-17: 16500 Illinois Route 173 – Commercial Building, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-18 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: Alden Resale

Address: 16500 Route 173, Alden

Lat/Long: 42.459103/-88.518047

Primary Use: Commercial

Is this a record of a single structure or group (give total number of structures):

Single: X Group: _____ Number Structures in Group: _____

List Observed Structures: Resale shop

Residence Detail

Style: Gabled w/ false front

Wall materials: board

Roof materials: asphalt

Foundation materials: concrete (visible)

Other distinguishing features
multi-pane display windows

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

May be connected to AL-15-17 to the west

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-18: 16500 Illinois Route 173 – Resale Shop

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-19 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16413 Route 173, Alden

Lat/Long: 42.458778/-88.516939

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage

Residence Detail

Style: Greek Revival

Wall materials: asbestos

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features
accentuated cornice returns/wide eaves

Any obvious Additions/Alterations
enclosed porch (not recent)

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - three bay garage with partially gabled roof

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

circa 1910 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-19: 16413 Illinois Route 173 - Garage



AL-15-19: 16413 Illinois Route 173 - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-20 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16416 Route 173, Alden

Lat/Long: 42.459270/-88.517158

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage

Residence Detail

Style: Upright and Wing

Wall materials: aluminum

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features
double window on Upright front

Any obvious Additions/Alterations
enclosed porch (not recent)/front stoop

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - modern gabled single car garage

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-20: 16416 Illinois Route 173 - Residence



AL-15-20: 16416 Illinois Route 173 - Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-21 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: Hebron-Alden-Greenwood Fire Protection District

Address: 16410 Route 173, Alden

Lat/Long: 42.459260/-88.516965

Primary Use: Fire Department

Is this a record of a single structure or group (give total number of structures):

Single: X Group: _____ Number Structures in Group: _____

List Observed Structures: Fire Department building/garage

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Concrete block flat roofed building with 3 truck bays. There is a small water tower located behind the building.

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

C. 1940-1950

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-21: 16410 Illinois Route 173 – Fire Department

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-22 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: Route 173, Alden

Lat/Long: 42.459254/-88.516742

Primary Use: _____

Is this a record of a single structure or group (give total number of structures):

Single: X Group: _____ Number Structures in Group: _____

List Observed Structures: garage

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Textured concrete block gabled building with one large garage bay and glass block windows. There is a second, modern multi-bay shed to the rear of the property.

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1930 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-22: Illinois Route 173 – Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-23 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16417 Route 173, Alden

Lat/Long: 42.458863/-88.516511

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage

Residence Detail

Style: Front Gabled

Wall materials: aluminum

Roof materials: asphalt

Foundation materials: fieldstone (w/concrete block at porch)

Other distinguishing features
enclosed front porch and entry porch off side

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled garage

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1910 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-23: 16417 Illinois Route 173 – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-24 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16409 Route 173, Alden

Lat/Long: 42.458762/-88.516219

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 3

List Observed Structures: (A) Res (B) garage (C) shed

Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Columns on front porch

Rear extension

brick chimney with wide top

decorative trim at corners near frieze band

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled garage/carriage house (may be modern) C - shed

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-24: 16409 Illinois Route 173 - Residence



AL-15-24: 16409 Illinois Route 173 – Garage, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-25 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16401 Route 173, Alden

Lat/Long: 42.458728/-88.515801

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: X Group: _____ Number Structures in Group: 1

List Observed Structures: Old School/Apartment building

Residence Detail

Style: Italianate School house

Wall materials: board

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features

Square front entry with curved pyramid roof

Bell tower

parapet over front door

Any obvious Additions/Alterations

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

property appears to be divided into multiple residential units

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1927 assessor date



AL-15-25: 16401 Illinois Route 173 – Old School/Apartment

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-26 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16222 Route 173, Alden

Lat/Long: 42.459571/-88.515385

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res _____ (B) garage/carriage house _____

Residence Detail

Style: Italianate

Wall materials: board

Roof materials: asphalt (fishscale)

Foundation materials:

Other distinguishing features

triangular window crowns

wide eaves with decorative brackets

square front bay/box window

double windows on second floor

single story section of house to east has central dormer

entry porch

widows walk platform (no railing)

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled carriage house with cupola/vent

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-26: 16222 Illinois Route 173 – Residence,
Garage/Carriage House

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-27 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16112 Route 173

Lat/Long: 42.460240/-88.512016

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res _____ (B) barn

Residence Detail

Style: Gabled EI

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features
small window gable on front of EI
awning over first floor window on Gable
double window second floor
front porch and side entry porch

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

C. 1860-1880

before 1862



AL-15-27: 16112 Illinois Route 173 - Residence



AL-15-27: 16112 Illinois Route 173 – Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-28 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16116 Route 173

Lat/Long: 42.460480/-88.511125

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res _____ (B) barn _____

Residence Detail

Style: Cross Gabled/Gothic

Wall materials: board

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features
accentuated gables
first floor bay window
gabled dormer

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

C. 1860-1880



AL-15-28: 16116 Illinois Route 173 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-29 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9109 Alden Road, Alden

Lat/Long: 42.458388/-88.518227

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res _____ (B) garage

Residence Detail

Style: Prairie/Bungalow

Wall materials: stucco

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features
full front porch w/ windows
shed-roof dormer with 6 windows

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - large gabled barn/garage

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

C. 1920-1930



AL-15-29: 9109 Alden Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-30 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9108 Alden Road, Alden

Lat/Long: 42.458461/-88.517451

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res _____ (B) garage

Residence Detail

Style: Cross Gabled

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features

wrap around porch

double windows with hoods centered on gable

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - two story Cross Gabled carriage house with three bays (sliding barn doors w/windows) and second floor

balcony and gabled dormer

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

circa 1910, 1920 assessor date



AL-15-30: 9108 Alden Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-31 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9016 Alden Road, Alden

Lat/Long: 42.458050/-88.517531

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res _____ (B) garage

Residence Detail

Style: Front Gabled

Wall materials: asbestos or wide board

Roof materials: asphalt

Foundation materials:

Other distinguishing features
enclosed front porch

Any obvious Additions/Alterations
side extension (not recent)

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gable roofed two bay garage with board siding

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1910, 1920 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-31: 9016 Alden Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-32 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9103 Alden Road, Alden

Lat/Long: 42.457990/-88.518155

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res _____ (B) garage

Residence Detail

Style: T-Plan

Wall materials: asbestos

Roof materials: asphalt

Foundation materials: limestone

Other distinguishing features

Arts and Crafts decoration in gable
decorative brackets on porch

Any obvious Additions/Alterations

redone front porch (new wood) including new spindle supports

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gable roofed two car garage

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-32: 9103 Alden Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-33 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9108 Alden Road, Alden

Lat/Long: 42.457701/-88.517395

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res _____ (B) garage

Residence Detail

Style: Gabled El

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features

gabled dormers

original window "awning"

enclosed corner front porch with prairie style windows

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled small barn/carriage house/garage

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date



AL-15-33: 9108 Alden Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-34 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9107 Alden Road, Alden

Lat/Long: 42.457704/-88.518074

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res _____ (B) garage

Residence Detail

Style: Bungalow

Wall materials: aluminum

Roof materials: asphalt

Foundation materials: brick

Other distinguishing features

Tuscan columns on porch

leaded window glass in front window

wide gabled front dormer

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B -small gabled garage/shed

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date



AL-15-34: 9107 Alden Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-35 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9013 Alden Road, Alden

Lat/Long: 42.457398/-88.518046

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 4

List Observed Structures: (A) Res _____ (B) garage/barn (C) barn (D) coop

Residence Detail

Style: T Plan

Wall materials: aluminum

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features
enclosed corner/bayed front porch

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - Gambreled garage/barn C - small frame shed roofed coop

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date



AL-15-35: 9013 Alden Road - Coop



AL-15-35: 9013 Alden Road – Residence, Barn, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-36 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9014 Alden Road, Alden

Lat/Long: 42.457305/-88.517451

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res _____ (B) garage/barn

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features

wide trim over windows

enclosed front porch

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1910 assessor date



AL-15-36: 9014 Alden Road – Residence, Garage/Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-37 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9204 Alden Road, Alden

Lat/Long: 42.459414/-88.517656

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res _____ (B) garage

Residence Detail

Style: Gabled

Wall materials: wood and brick

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

additions to front

re-done roof line

hard to tell where, if any, original residence remains

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small gabled garage

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1950 assessor date



AL-15-37: 9204 Alden Road - Residence



AL-15-37: 9204 Alden Road – Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-38 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9203 Alden Road, Alden

Lat/Long: 42.459478/-88.518274

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res _____ (B) garage

Residence Detail

Style: Gabled EI

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Classical style porch with Tuscan style columns

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled garage

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1895 assessor date



AL-15-38: 9203 Alden Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-39 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9206 Alden Road, Alden

Lat/Long: 42.459639/-88.517675

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: X Group: _____ Number Structures in Group: _____

List Observed Structures: Res

Residence Detail

Style: Gabled

Wall materials: aluminum

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

Any obvious Additions/Alterations

Enclosed gabled front entry space

Attached rear side gabled 2 car garage

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1930 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-39: 9206 Alden Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-40 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9205 Alden Road, Alden

Lat/Long: 42.459655/-88.518320

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res _____ (B) garage

Residence Detail

Style: Pyramid cottage

Wall materials: board/fishscale shingles

Roof materials: asphalt

Foundation materials: limestone

Other distinguishing features
eave brackets, elaborate cornice trim/geometric patterns
ornamental window trim
gabled front entry porch roof

Any obvious Additions/Alterations
small wing off rear - not new addition

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled garage

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

Eligible

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-40: 9205 Alden Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-41 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9209 Alden Road, Alden

Lat/Long: 42.459856/-88.518264

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res _____ (B) garage

Residence Detail

Style: Upright and wing

Wall materials: board/shingles (modern)

Roof materials: asphalt

Foundation materials: brick

Other distinguishing features

Any obvious Additions/Alterations

house has been remodeled/reshaped

Boxed bay window on upright may or may not be partially original

some elaborate decoration on upright cornice may be original

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled garage

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1910 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-41: 9209 Alden Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-42 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9210 Alden Road, Alden

Lat/Long: 42.459926/-88.517652

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: X Group: _____ Number Structures in Group: _____

List Observed Structures: Res

Residence Detail

Style: No style

Wall materials: brick

Roof materials: asphalt

Foundation materials: brick

Other distinguishing features

Any obvious Additions/Alterations

Mansard roof added to create second floor
front porch enclosed/new windows and door

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1910 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-42: 9210 Alden Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-43 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9211 Alden Road, Alden

Lat/Long: 42.459965/-88.518305

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: stone

Other distinguishing features

Any obvious Additions/Alterations
May be modified Upright and Wing
Front picture window

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - 2 story garage/carriage house

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-43: 9211 Alden Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-44 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9214 Alden Road, Alden

Lat/Long: 42.460226/-88.517843

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: X Group: _____ Number Structures in Group: _____

List Observed Structures: Res

Residence Detail

Style: Gothic/Italianate

Wall materials: aluminum (?)

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features

square entry way

steep centered gable at front

clipped corner

Any obvious Additions/Alterations

roofline of house has been changed and it's difficult to pin down exact style and original elements

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1910 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-44: 9214 Alden Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-45 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9215 Alden Road, Alden

Lat/Long: 42.460329/-88.518383

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage

Residence Detail

Style: Ranch

Wall materials: aluminum

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

9 pane large front window

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - 2 car garage

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1964 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-45: 9215 Alden Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-46 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9218 Alden Road, Alden

Lat/Long: 42.460454/-88.517739

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage

Residence Detail

Style: Gabled

Wall materials:

Roof materials: asphalt

Foundation materials:

Other distinguishing features
front porch spindle supports

Any obvious Additions/Alterations

House has two distinct parts - a 2 story gabled section and a 1 story front gabled section. It is difficult to determine the timeline of building. There is also a large extension to the rear. Window and door trim are consistent on both parts of the house.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small garage

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-46: 9218 Alden Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-47 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9220 Alden Road, Alden

Lat/Long: 42.460629/-88.517868

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage

Residence Detail

Style: Front Gabled

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features
front entry porch spindle supports
rear porch

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small gabled garage

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-47: 9220 Alden Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-48 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9301 Alden Road, Alden

Lat/Long: 42.460662/-88.518371

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage

Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features

Any obvious Additions/Alterations

wing with deck added to side of house - brick foundation

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - modern gabled garage

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1910 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-48: 9301 Alden Road - Residence



AL-15-48: 9301 Alden Road – Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-49 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9304 Alden Road, Alden

Lat/Long: 42.460809/-88.517929

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage

Residence Detail

Style: Gable EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features
entry porch

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - garage

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-49: 9304 Alden Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-50 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: Sedgemoor Antiques

Address: 9230 Alden Road, Alden

Lat/Long: 42.460955/-88.517919

Primary Use: Commercial

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Commercial building (B) garage

Residence Detail

Style: Boomtown Commercial/False front

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features
multi-pane windows

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - barn/carriage house/garage

- originally W.W. Fleming General Store

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date

Eligible

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-50: 9230 Alden Road – Commercial Building



AL-15-50: 9230 Alden Road – Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-51 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9314 Alden Road, Alden

Lat/Long: 42.460995/-88.518430

Primary Use: Garage

Is this a record of a single structure or group (give total number of structures):

Single: X Group: _____ Number Structures in Group: _____

List Observed Structures: Garage

Residence Detail

Style: Commercial garage

Wall materials: concrete block

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

C. 1920

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-51: 9314 Alden Road – Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-52 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: Alden Train Depot

Address: 9351 Alden Road, Alden

Lat/Long: 42.461294/-88.518431

Primary Use: vacant

Is this a record of a single structure or group (give total number of structures):

Single: X Group: _____ Number Structures in Group: _____

List Observed Structures: depot

Residence Detail

Style: Gabled

Wall materials: vertical board

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

C. 1890

Eligible

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-52: 9351 Alden Road – Depot

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-53 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: Alden Grist Mill

Address: 9320 Alden Road, Alden

Lat/Long: 42.461804/-88.518103

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 3

List Observed Structures: (A) Mill (B) garage (C) garage

Residence Detail

Style: Gabled

Wall materials: board and metal

Roof materials: metal

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B and C - modern garage buildings

Number of photos taken for this property*: 6

* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date

Eligible

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-53: 9320 Alden Road – Garage, Mill



AL-15-53: 9320 Alden Road – Mill



AL-15-53: 9320 Alden Road - Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-54 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9405 Alden Road

Lat/Long: 42.462488/-88.518943

Primary Use: residence

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 3

List Observed Structures: (A) Res (B) garage (C) pole building

Residence Detail

Style: No style

Wall materials: modern board

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

remodeled/reconfigured and difficult to tell original style

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - modern garage C - modern pole building

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-54: 9405 Alden Road – Residence, Garage, Pole Building

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-55 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: Alden Cemetery

Address: Alden Road

Lat/Long: 42.463595/-88.518946

Primary Use: cemetery

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: _____

List Observed Structures: headstones, gates, caretakers shed

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Gates include modern brick posts with steel fencing

headstones from middle to late 19th century to present

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

circa 1903-1908

before 1862-1872

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-55: Alden Road – Cemetery

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-56 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9507 Alden Road

Lat/Long: 42.463373/-88.519811

Primary Use: industrial

Is this a record of a single structure or group (give total number of structures):

Single: X Group: _____ Number Structures in Group: _____

List Observed Structures: industrial building

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

concrete block industrial building completely obscured by trees

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1954-1956

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-56: 9507 Alden Road – Industrial Building

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-57 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9507 Alden Road

Lat/Long: 42.464089/-88.520096

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage

Residence Detail

Style: Hipped roof cottage/Minimal Traditional

Wall materials: vertical board

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - detached double bay garage

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1965 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-57: 9507 Alden Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-58 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9523 Alden Road

Lat/Long: 42.465097/-88.520672

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage

Residence Detail

Style: Ranch

Wall materials: aluminum

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - detached gabled single bay garage

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1957 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-58: 9523 Alden Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-59 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9604 Alden Road

Lat/Long: 42.465617/-88.520091

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) shed

Residence Detail

Style: Ranch

Wall materials: aluminum

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features
attached front garage

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small garden shed

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1977 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-59: 9604 Alden Road – Residence, Garage, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-60 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9613 Alden Road

Lat/Long: 42.466024/-88.521484

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 3

List Observed Structures: (A) Res (B) outbuilding (C) metal shed

Residence Detail

Style: Greek Revival

Wall materials: asbestos

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features
some remaining wood cornice/corner features (false columns)
exposed foundation on north side

Any obvious Additions/Alterations
attached garage (not recent)

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - fieldstone shed/milkhouse/outbuilding with board gabled and metal roof

C - metal machine shed

Number of photos taken for this property*: 4

* Attach Photo log, additional notes and map of resource location.

circa 1910 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-60: 9613 Alden Road – Residence, Garage



AL-15-60: 9613 Alden Road – Outbuilding



AL-15-60: 9613 Alden Road - Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-61 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: Knickerbocker Road

Lat/Long: 42.468157/-88.519960

Primary Use: Bridge

Is this a record of a single structure or group (give total number of structures):

Single: X Group: _____ Number Structures in Group: _____

List Observed Structures: Bridge _____

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Art Deco concrete bridge

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

C. 1920-1940

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-61: Knickerbocker Road – Bridge

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-62 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9907 Knickerbocker Road

Lat/Long: 42.469872/-88.519962

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 5

List Observed Structures: (A) Res (B) garage (C) shed (D) barn foundation (E) crib

Residence Detail

Style: Modern Split level

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

(A) Residence and (B) garage are less than 50 years old. Property also includes (C) a timber frame shed/milkhouse,

(D) a concrete barn foundation in process of demolition, and (E) a partial crib building.

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

circa 1910, 1976 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-62: 9907 Knickerbocker Road – Residence,
Garage, Crib



AL-15-62: 9907 Knickerbocker Road – Shed, Barn
Foundation

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-63 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 9007 Alden Road

Lat/Long: 42.470464/-88.526489

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 5

List Observed Structures: (A) Res (B) shed (C) crib (D) Barn (E) smokehouse

Residence Detail

Style: Upright and Wing

Wall materials:

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

bay window on wing

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - small shed C - gabled crib building E - brick smokehouse

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date

Barn Detail

Style: Gabled Hay Barn

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features



AL-15-63: 9007 Alden Road – Residence, Shed, Crib,
Smokehouse



AL-15-63: 9007 Alden Road – Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15 Survey Number: AL-15-64 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 16410 Route 173, Alden

Lat/Long: 42.459387/-88.516399

Primary Use: garage

Is this a record of a single structure or group (give total number of structures):

Single: X Group: _____ Number Structures in Group: _____

List Observed Structures: garage _____

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

gabled garage

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1930 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-15-64: 16410 Illinois Route 173 – Garages

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 16





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: AL-16-1 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 9503 Wright Road _____

Lat/Long: 42.464098/-88.540730 _____

Primary Use: res/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) barn; (C) silo; (D) shed not visible

Residence Detail

Style: No style

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials: metal

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: originally Gabled EI - several additions

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa L.19th –E. 20th century

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date

circa 1872-1892



AL-16-1: 9503 Wright Road – Residence, Barn, Silo

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: AL-16-2 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 9701 Wright Road _____

Lat/Long: 42.466385/-88.540774 _____

Primary Use: res/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) barn; (C) metal pole barn garage; (D) metal pole barn

Residence Detail

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: poss. field stone

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: L. 19th century

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1940 assessor date

before 1862

Barn Detail

Style: Gambrel roof

Wall materials: cc block/vert. board

Roof materials: unknown

Foundation materials: concrete

Other distinguishing features:



AL-16-2: 9701 Wright Road – Residence



AL-16-2: 9701 Wright Road – Garage



AL-16-2: 9701 Wright Road – Barns

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: AL-16-3 _____ Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 10015 Wright Road _____

Lat/Long: 42.471898/-88.540669 _____

Primary Use: res/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) wood-sided shed; (E) wood-sided shed with metal roof

Residence Detail

Style: Upright and Wing

Wall materials: clapboard?

Roof materials: asphalt

Foundation materials: field stone

Other distinguishing features:

Barn Detail

Style: Gabled roof

Wall materials: vertical board

Roof materials: shake and asphalt

Foundation materials: fieldstone

Other distinguishing features: gable flairs

Any obvious Additions/Alterations: wrap-around porch and portico, 2-story addition to rear

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: L.19th E.20th century

Number of photos taken for this property*: four_____

* Attach Photo log, additional notes and map of resource location.

circa 1930 assessor date

circa 1908-1939



AL-16-3: 10015 Wright Road – Sheds, Silo



AL-16-3: 10015 Wright Road – Residence, Barn, Silo

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: AL-16-4 _____ Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 9808 Wright Road _____

Lat/Long: 42.469551/-88.539927 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: No style

Wall materials: vertical board

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations. May have originally been Upright and Wing:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: L.19th E.20th century

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.


circa 2002 assessor date

before 1862



AL-16-4: 9808 Wright Road – Residence

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 17





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number:AL-17-1

Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name:_____

Address: 18910 Oak Grove Road_____

Lat/Long: 42.458580/-88.566289_____

Primary Use: residence_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: two_____

List Observed Structures: (A) residence; (B) barn

Residence Detail

Style: No style

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style: Gambrel roof

Wall materials: log

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: newer

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: L.19th century

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.

circa 2009 assessor date

before 1862



AL-17-1: 18910 Oak Grove Road – Residence



AL-17-1: 18910 Oak Grove Road – Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: AL-17-2 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 9809 Reese Road _____

Lat/Long: 42.468323/-88.560358 _____

Primary Use: agriculture _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: two _____

List Observed Structures: (A) fieldstone smokehouse (B) pole barn

Residence Detail

Style: no residence

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): fieldstone smokehouse (or other outbuilding). Roof is gone. Former farmyard.

Property Group Date Range: L.19th century

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1940 assessor date

circa 1903-1908



AL-17-2: 9809 Reese Road – Smokehouse, Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: AL-17-3 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 9920 Reese Road _____

Lat/Long: 42.470923/-88.559510 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) wood-sided lean-to shed

Residence Detail

Style: ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: attached garage

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: Mid-20th century

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1957-1988

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-17-3: 9920 Reese Road – Residence



AL-17-3: 9920 Reese Road – Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: AL-17-4 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 9704 Reese Road _____

Lat/Long: 42.466798/-88.559045 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) pole barn to rear, not visible

Residence Detail

Style: one-story Front Gabled

Wall materials: vinyl and stucco

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: Late 19th century

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1940 assessor date

circa 1908-1939



AL-17-4: 9704 Reese Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: AL-17-5 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 9518 Reese Road _____

Lat/Long: 42.464644/-88.553339 _____

Primary Use: equestrian _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: no structures observed

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: unknown

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1978 assessor date

before 1862

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-17-5: 9518 Reese Road – Sign

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: AL-17-6

Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 9508 Reese Road _____

Lat/Long: 42.464707/-88.557803 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence set way back and obscured

Residence Detail

Barn Detail

Style:

Style:

Wall materials:

Wall materials:

Roof materials:

Roof materials:

Foundation materials:

Foundation materials:

Other distinguishing features:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: unknown

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1980 assessor date

circa 1862-1872



AL-17-6: 9508 Reese Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: AL-17-7 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 9302 Reese Road _____

Lat/Long: 42.460789/-88.558904 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) barn/garage; (C) small shed; (D) pole barn; (E) milk or spring house

Residence Detail

Style: Gabled El

Wall materials: shingle

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): (B) wood-sided garage/barn; (C) small shed; (E) vertical wood sided milk or spring house with concrete foundation.

Property Group Date Range: L.19th – E.20th C.

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

circa 1908-1939



AL-17-7: 9302 Reese Road – Residence, Barns, Sheds, Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: AL-17-8

Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 18405 Oak Grove Road _____

Lat/Long: 42.458289/-88.556524 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) small tool shed

Residence Detail

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: Mid-20th century

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1964 assessor date

circa 1957-1988

Barn Detail

Style:

Wall materials:

Roof materials:


Foundation materials:

Other distinguishing features:



AL-17-8: 18405 Oak Grove Road – Residence, Shed

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 18



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: AL-18-1 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 19904 Oak Grove Road _____

Lat/Long: 42.459555/-88.585433 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) barn/garage; (C) pole barn; (D) 2nd barn (see barn detail)

Residence Detail

Style: Queen Anne

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Gabled roof

Wall materials: vertical wood board

Roof materials: metal

Foundation materials: fieldstone

Other distinguishing features: door, loft, windows

Any obvious Additions/Alterations: additions to rear

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): (B) wood-sided garage/barn; (C) pole barn.

Property Group Date Range: L.19th – E.20th C.

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

before 1862



AL-18-1: 19904 Oak Grove Road – Residence,
Garage, Barn



AL-18-1: 19904 Oak Grove Road – Barns



AL-18-1: 19904 Oak Grove Road – Barn Detail

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: AL-18-2 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 19118 Oak Grove Road _____

Lat/Long: 42.458623/-88.571426 _____

Primary Use: agriculture _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: two _____

List Observed Structures: (A-B) two metal grain bins on abandoned farmstead. No other structures

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: current group L.20th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1941-1951

before 1862

Barn Detail

Style:

Wall materials:

Roof materials:


Foundation materials:

Other distinguishing features:



AL-18-2: 19118 Oak Grove Road – Bins

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 19





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number:AL-19-1

Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name:_____

Address: 19411 Oak Grove Road_____

Lat/Long: 42.457786/-88.576936_____

Primary Use: residential_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: three_____

List Observed Structures: (A) residence; (B) garage; (C) Pole barn

Residence Detail

Style: Minimal Traditional

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: extension to west side. Enclosed front porch.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): garage/pole barn, possible 2nd pole barn

Property Group Date Range: Late 19th – Early 20th C.

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.

circa 1949 assessor date

before 1862-1872



AL-19-1: 19411 Oak Grove Road – Residence, Garage,
Pole Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-19-2

Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 19505 Oak Grove Road _____

Lat/Long: 42.457461/-88.578478 _____

Primary Use: agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three _____

List Observed Structures: (A) barn; (B) silo; (C) shed

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Barn Detail

Style: Side Gabled roof

Wall materials: vertical wood

board Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): concrete silo; small shed

Property Group Date Range: Late 19th – Early 20th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

before 1862-1872



AL-19-2: 19505 Oak Grove Road – Barn, Silo, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-19-3 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 19104 Crowley Road _____

Lat/Long: 42.443799/-88.570290 _____

Primary Use: resid/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) garage; (C-D) pole barns

Residence Detail

Style: Two-story Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): (B) garage: asphalt, vinyl, concrete

Property Group Date Range: Late 19th – Early 20th C.

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

circa 1862-1872



AL-19-3: 19104 Crowley Road – Residence



AL-19-3: 19104 Crowley Road – Garage, Pole Barns

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-19-4

Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 19212 Crowley Road _____

Lat/Long: 42.444097/-88.572632 _____

Primary Use: resid/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) garage; (C) pole barn/garage

Residence Detail

Style: No style

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations: front gabled addition to front

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): (C) pole bar/garage

Property Group Date Range: Early-Mid. 20th C.

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1930 assessor date

circa 1908-1939

Barn Detail

Style: Gambrel roof

Wall materials: wood

Roof materials: asphalt

Foundation materials: cc-covered

Other distinguishing features:



AL-19-4: 19212 Crowley Road – Residence, Garage, Pole
Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number:AL-19-5 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 19372 Crowley Road _____

Lat/Long: 42.444230/-88.582517 _____

Primary Use: agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: two _____

List Observed Structures: (A-B) two concrete stave silos on farmstead remnant

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: L.19th E. 20th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1941-1951

before 1862



AL-19-5: 19372 Crowley Road – Silos

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 20





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: AL-20-1 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 18609 Oak Grove Road _____

Lat/Long: 42.457782/-88.560767 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: seven _____

List Observed Structures: (A) residence; (B) pole barn; (C) barn; (D) silo; (E) shed(S);(F) pole barn

Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features:

Barn Detail

Style: Gabled roof

Wall materials: vertical wood board

Roof materials: metal

Foundation materials: fieldstone

Other distinguishing features: milk house

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): two pole barns, (D) concrete stave silo; (E) wood-sided shed(s).

Property Group Date Range: Late 19th C.

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

before 1862



AL-20-1: 18609 Oak Grove Road – Residence



AL-20-1: 18609 Oak Grove Road – Barns, Silo, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: AL-20-2 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 19011 Oak Grove Road _____

Lat/Long: 42.457709/-88.568400 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) barn; (C) small stone structure; (D) metal shed; (E) concrete silo

Residence Detail

Style: Front Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features:

Barn Detail

Style: Rounded roof dairy

Wall materials: wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: milk house

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): small stone structure-possible smoke house, metal shed, concrete silo.

Property Group Date Range: Late 19th C.

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1950 assessor date

before 1862



AL-20-2: 19011 Oak Grove Road – Residence, Shed



AL-20-2: 19011 Oak Grove Road – Barn, Stone Structure

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: AL-20-3 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: Rock Home Farm 1902_____

Address: 9006 Reese Road_____

Lat/Long: 42.456885/-88.559606_____

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: four_____

List Observed Structures: (A) residence #1; (B) residence #2; (C) barn; (D) shed

Residence Detail

Style: One Story Cube

Wall materials: wood

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features:

Barn Detail

Style: Center Bay - Banked

Wall materials: vertical wood board

Roof materials: metal

Foundation materials: fieldstone

Other distinguishing features: "Rock Home Farm"

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): Residence #2: possibly original Center Front Gable with Side Gable wings, Asphalt or shingle roof, stone foundation; small stone structure-possible smoke house, metal shed, concrete silo.

Property Group Date Range: L.19th – E.20th C.

Number of photos taken for this property*: four_____

* Attach Photo log, additional notes and map of resource location.

circa 1958 assessor date

before 1862



AL-20-3: 9006 Reese Road – Residence



AL-20-3: 9006 Reese Road – Residence 2



AL-20-3: 9006 Reese Road – Barn



AL-20-3: 9006 Reese Road – Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: AL-20-4 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 8605 Reese Road _____

Lat/Long: 42.451028/-88.560222 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) small wood-sided shed; (E) two possible small sheds to north of residence-obscured

Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: stone

Other distinguishing features:

Barn Detail

Style: Gabled roof

Wall materials: vertical wood board

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: shed-type extension

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): two possible sheds, obscured

Property Group Date Range: Late 19th C.

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.

circa 1910 assessor date

before 1862



AL-20-4: 8605 Reese Road – Residence



AL-20-4: 8605 Reese Road – Barn, Silo, Sheds

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: AL-20-5 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 8220 Reese Road _____

Lat/Long: 42.446435/-88.559492 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) large, low shed; (C) barn; (D) concrete silo

Residence Detail

Style: Upright and Wing

Wall materials: clapboard

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features: large stone chimney

Barn Detail

Style: Gabled roof

Wall materials: vertical wood board

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: one-story extension

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Late 19th C.

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date

before 1862-1872



AL-20-5: 8220 Reese Road – Residence



AL-20-5: 8220 Reese Road – Barn, Silo, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number:AL-20-6 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 18716 Crowley Road _____

Lat/Long: 42.443802/-88.563346 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) two adjoining coops/sheds with metal roofs; (C) shed or barn set back, obscured; (D) barn; (E) small wood sided animal shed

Residence Detail

Style: Cape Cod

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: stone chimney

Barn Detail

Style: Gabled roof

Wall materials: wood or vinyl

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: one-story extension

Any obvious Additions/Alterations: extension to west side

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Late 19th C.

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.

circa 1945 assessor date

before 1862




AL-20-6: 18716 Crowley Road – Sheds, Barn



AL-20-6: 18716 Crowley Road – Residence

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 21





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-21-1 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 17135 Rt. 173 _____

Lat/Long: 42.448826/-88.531295 _____

Primary Use: residence. _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: one _____

List Observed Structures: (A) residence _____

Residence Detail

Style: Minimal Traditional

Wall materials: brick tiles

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: Front and Side Gabled

Any obvious Additions/Alterations: steeply pitched roof; attached garage

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Mid 20th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1930 assessor date

before 1862



AL-21-1: 17135 Illinois Route 173 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-21-2 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 17406 Rt. 173 _____

Lat/Long: 42.444062/-88.536891 _____

Primary Use: residence. _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence/nursery business _____

Residence Detail

Style: No style

Wall materials: brick

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: Mansard roof

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Mid 20th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1940, 1940 assessor date

circa 1939-1988

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-21-2: 17406 Illinois Route 173 – Residence/Nursery
Business

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-21-3 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 17804 Rt. 173_____

Lat/Long: 42.443911/-88.544889_____

Primary Use: residence. _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence _____

Residence Detail

Style: No style

Wall materials: vinyl and wood shingle

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: E.20th c.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1986 assessor date

before 1862

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-21-3: 17804 Illinois Route 173 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-21-4 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 17409 Rt. 173_____

Lat/Long: 42.457574/-88.537001_____

Primary Use: resid/agri. _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) barn; (C) silo; (D) shed/garage; (E) small shed _____

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: EI wing has front-gable

Barn Detail

Style: Banked dairy

Wall materials: vertical wood boards

Roof materials: asphalt over wood shingle

Foundation materials: fieldstone

Other distinguishing features:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): concrete stave silo; (D) shed/garage, vertical wood; (E) small shed, wood-sided

Property Group Date Range: L.19th C.

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1910 assessor date

before 1862



AL-21-4: 17409 Illinois Route 173 - Residence



AL-21-4: 17409 Illinois Route 173 - Sheds



AL-21-4: 17409 Illinois Route 173 – Barn, Silo

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number:AL-21-5 Surveyor Name: M. Prchal, C. Flynn _____

Current Property or Structure Name: _____

Address: 17801 Rt. 173 _____

Lat/Long: 42.457466/-88.544206 _____

Primary Use: resid/agri. _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) smaller concrete stave silo; (E)

clapboard-sided garage/shed; (F) metal clad pole barn _____

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: L.19th C. Dairy barn E. 20th C.

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1910 assessor date

before 1862

Barn Detail

Style: Gambrel roof dairy

Wall materials: vertical wood boards

Roof materials:asphalt over wood shingle

Foundation materials: concrete block

Other distinguishing features: gables, cupolas, attached milk house



AL-21-5: 17801 Illinois Route 173 – Residence,
Garage



AL-21-5: 17801 Illinois Route 173 – Pole Barn



AL-21-5: 17801 Illinois Route 173 – Barn, Silos

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-21-6 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 17801 Rt. 173_____

Lat/Long: 42.457466/-88.544206_____

Primary Use: resid _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence_____

Residence Detail

Style: Ranch

Wall materials: vertical wood board, stoneface

Roof materials: tar paper?

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: Mid. 20th C.

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.

circa 1950 assessor date

before 1862

Barn Detail

Style:

Wall materials:

Roof materials:


Foundation materials:

Other distinguishing features:



AL-21-6: 17801 Illinois Route 173 – Residence

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 22





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-22-1 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 9020 Alden Road _____

Lat/Long: 42.456871/-88.517421 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) wood-sided garage _____

Residence Detail

Style: Gabled EI

Wall materials: clapboard

Roof materials: asphalt

Foundation materials: limestone

Other distinguishing features: front porch railing

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Late 19th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-22-1: 9020 Alden Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-22-2 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 9007 Alden Road _____

Lat/Long: 42.456880/-88.518011 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) wood-sided garage _____

Residence Detail

Style: Gabled EI

Wall materials: clapboard

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: front porch roof railing

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Late 19th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-22-2: 9007 Alden Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-22-3 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 9001 Alden Road _____

Lat/Long: 42.456621/-88.517984 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: one _____

List Observed Structures: (A) residence _____

Residence Detail

Style: Front Gable

Wall materials: wood shingle

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: front porch railing

Any obvious Additions/Alterations: attached garage

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Late 19th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1910 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-22-3: 9001 Alden Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-22-4 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 9003 Alden Road _____

Lat/Long: 42.456322/-88.517951 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: X _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence _____

Residence Detail

Style: Gabled El

Wall materials: wood shingle

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: front porch roof

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Late 19th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1930 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-22-4: 9003 Alden Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-22-5 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 8918 Alden Road _____

Lat/Long: 42.456322/-88.517951 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence _____

Residence Detail

Style: Gabled El

Wall materials: wide clapboard

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

Any obvious Additions/Alterations: Front Gable has eave returns; El portion double length

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Late 19th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-22-5: 8918 Alden Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-22-6 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 8915 Alden Road _____

Lat/Long: 42.456147/-88.517967 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) wood-sided garage _____

Residence Detail

Style: Cape Cod

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: Center front roof gable

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Late 19th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-22-6: 8915 Alden Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-22-7 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 8913 Alden Road _____

Lat/Long: 42.455940/-88.517970 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence _____

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: EI roof gable

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Late 19th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-22-7: 8913 Alden Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number:AL-22-8

Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 8911 Alden Road _____

Lat/Long: 42.455713/-88.517821 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) wood-sided garage _____

Residence Detail

Style: Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: no front roof gable

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Late 19th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1941-1951

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-22-8: 8911 Alden Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-22-9 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 8907 Alden Road _____

Lat/Long: 42.455425/-88.517680 _____

Primary Use: residence _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) vinyl-sided garage _____

Residence Detail

Style: Bungalow

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: handicap ramp

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Late 19th – E.20th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

No assessor date given

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-22-9: 8907 Alden Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-22-10 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 8717 Alden Road _____

Lat/Long: 42.453374/-88.517061 _____

Primary Use: garage _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: one _____

List Observed Structures: (A) garage with shed extension _____

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: E. 20th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1941-1951

circa 1939-1988

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-22-10: 8717 Alden Road – Garage with Shed Extension

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-22-11 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 8617 Alden Road _____

Lat/Long: 42.451842/-88.516424 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) shed/stable _____

Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: limestone

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: E.20th C.

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1930 assessor date

circa 1939-1988

Barn Detail

Style: One Story Gabled

Wall materials: vertical wood

Roof materials: metal

Foundation materials: unknown

Other distinguishing features:



AL-22-11: 8617 Alden Road – Shed/Stable



AL-22-11: 8617 Alden Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-22-12 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 8613 Alden Road _____

Lat/Long: 42.451587/-88.516377 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: X _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence _____

Residence Detail

Style: Side Gabled

Wall materials: wood clapboard

Roof materials: asphalt over wood shingle

Foundation materials: unknown

Other distinguishing features: abandoned

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: L.19th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1970 assessor date

circa 1862-1872

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-22-12: 8613 Alden Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-22-13 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 8514 Alden Road _____

Lat/Long: 42.450246/-88.515501 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) pole barn _____

Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt over wood shingle

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: extension to north

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: L.19th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

before 1862

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-22-13: 8514 Alden Road – Residence, Pole Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number:AL-22-14 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 8114 Alden Road _____

Lat/Long: 42.444066/-88.515584 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: six

List Observed Structures: (A) residence; (B) barn; (C,D) two wood-sided sheds with concrete foundations; (E) metal shed; (F) garage

Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt over wood shingle

Foundation materials: concrete covered stone

Other distinguishing features: double horizontal roof line

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: L.19th C.

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1970 assessor date

before 1862



AL-22-14: 8114 Alden Road – Barn, Sheds



AL-22-14: 8114 Alden Road – Barn, Garage



AL-22-14: 8114 Alden Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-22-15 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 16809 O'Brien Road _____

Lat/Long: 42.444068/-88.525096 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: five

List Observed Structures: (A) residence; (B) barn; (C) small shed; (D) animal shed; (E) 2nd small shed _____

Residence Detail

Style: Gabled EI

Wall materials: unknown

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: steep pitched roof

Any obvious Additions/Alterations: house is set way back

Barn Detail

Style: Raised Roof

Wall materials: vertical wood board

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Mid. 20th C.

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1923 assessor date

circa 1908-1939



AL-22-15: 16809 O'Brien Road – Barn, Sheds



AL-22-15: 16809 O'Brien Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-22-16 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 8315 Nolan Street _____

Lat/Long: 42.444068/-88.525096 _____

Primary Use: agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: five

List Observed Structures: (A) barn; (B,C) concrete silos _____

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Late 19th – E. 20th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1951-1954

before 1862

Barn Detail

Style: Gambrel Roof

Wall materials: vertical wood board

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:



AL-22-16: 8315 Nolan Street – Barn, Silos

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-22-17 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 16903 Rt. 173 _____

Lat/Long: 42.455988/-88.527523 _____

Primary Use: agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: two

List Observed Structures: (A) residence; (B) vinyl sided garage _____

Residence Detail

Style: Minimal Traditional

Wall materials: Vinyl

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Late 19th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1920, 40 assessor date

circa 1939-1988

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-22-17: 16903 Illinois Route 173 – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-22-18 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 16829 Rt. 173 _____

Lat/Long: 42.455966/-88.527528 _____

Primary Use: res/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: four

List Observed Structures: (A) residence; (B) vinyl sided garage; (C,D) small sheds _____

Residence Detail

Style: Side Gabled

Wall materials: fieldstone

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: side peaks angle down

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Late 19th - E. 20th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1920, 1940 assessor date

circa 1908-1939

Barn Detail

Style:

Wall materials:

Roof materials:


Foundation materials:

Other distinguishing features:



AL-22-18: 16829 Illinois Route 173 – Residence, Garage, Sheds

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 23





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-23-1 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 9103 Fink Road _____

Lat/Long: 42.456026/-88.491819 _____

Primary Use: res/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: six

List Observed Structures: (A) residence; (B) metal pole barn; (C) concrete stave silo; (D) vertical wood-sided shed;

(E) vertical wood sided shed/garage; (F) wood sided out-house _____

Residence Detail

Style: Cape Cod

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Late 19th - E. 20th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 2002 assessor date

before 1862

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-23-1: 9103 Fink Road – Residence, Barn, Silo, Sheds,
Outhouse

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-23-2 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 15402 O'Brien Road _____

Lat/Long: 42.443599/-88.498158 _____

Primary Use: res/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two

List Observed Structures: (A) residence; (B) concrete silo next to fieldstone foundation _____

Residence Detail

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Mid. 20th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1968 assessor date

before 1862

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-23-2: 15402 O'Brien Road – Residence, Silo,
Foundation

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-23-3 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 15404 O'Brien Road _____

Lat/Long: 42.443583/-88.498132 _____

Primary Use: res/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: six

List Observed Structures: (A) residence; (B) concrete silo next to fieldstone foundation; (C) shed; (D) shed; (E) shed;

(F) metal Quonsett _____

Residence Detail

Style: Side Gabled

Wall materials: asphalt brick face

Roof materials: asphalt over shake shingle

Foundation materials: fieldstone

Other distinguishing features: three roof dormers

Any obvious Additions/Alterations: abandoned and crumbling

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. Silo and foundation same as AL-23-1. Sheds are wood-sided with metal roofs.

Property Group Date Range: Late 19th C.

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

circa 1968 assessor date

before 1862

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials: fieldstone

Other distinguishing features:



AL-23-3: 15404 O'Brien Road – Residence, Silo



AL-23-3: 15404 O'Brien Road – Sheds, Quonset

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-23-4 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 15804 O'Brien Road _____

Lat/Long: 42.443855/-88.505294 _____

Primary Use: Res _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: two

List Observed Structures: (A) barn/ residence with attached concrete stave silo; (B) metal shed _____

Residence Detail

Style: Converted dairy barn

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: silo attached by vertical atrium

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): concrete stave silo attached to barn/residence by vertical windowed atrium.

Property Group Date Range: Early-Mid, 20th C.

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1979 assessor date

before 1862



AL-23-4: 15804 O'Brien Road – Barn/Residence, Silo, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-23-5 Surveyor Name: M. Prchal, C. Flynn _____

Current Property or Structure Name: _____

Address: 16117 Rt. 173 _____

Lat/Long: 42.457600/-88.508357 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: five

List Observed Structures: (A) residence (B) pole barn garage; (C,D,E) outbuildings set way back, not visible _____

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: set too far back to see

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: unknown

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1962 assessor date

before 1862

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-23-5: 16117 O'Brien Road – Residence, Garage,
Outbuildings

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 24



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-24-1

Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 8100 Fink Road _____

Lat/Long: 42.455601/-88.490880 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two

List Observed Structures: (A) residence; (B) crib _____

Residence Detail

Style: Side Gabled

Wall materials: wood clapboard

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features: long abandoned

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Property Group Date Range: Late 19th C.

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1941-1951

before 1862

Barn Detail

Style: round roof crib

Wall materials: wood board

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: large central roof cupola



AL-24-1: 8100 Fink Road – Residence



AL-24-1: 8100 Fink Road – Crib

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number AL-24-2 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 8302 Fink Road _____

Lat/Long: 42.446535/-88.491070 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: eight

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) wood-sided shed; (E) metal pole barn to north; (F) larger wood-sided shed/barn; (G) small wood sided shed to south; (H) metal garage to south _____

Residence Detail

Style: Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Late 19th C.

Number of photos taken for this property*: five _____

* Attach Photo log, additional notes and map of resource location.

circa 1920, 2002 assessor date

before 1862

Barn Detail

Style: Gabled roof

Wall materials: asbestos shingle?

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features:



AL-24-2: 8302 Fink Road – Barns, Silo, Shed



AL-24-2: 8302 Fink Road – Residence, Sheds, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-24-3 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 15008 O'Brien Road _____

Lat/Long: 42.443548/-88.489309 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: three

List Observed Structures: (A) residence; (B) barn with attached concrete stave silo; (C) small wooden shed with asphalt roof

Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features: lower corner window angled

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Late 19th C.

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.

circa 1890 assessor date

before 1862

Barn Detail

Style: Gabled roof

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features: obscured



AL-24-3: 15008 O'Brien Road – Residence



AL-24-3: 15008 O'Brien Road – Shed, Silo

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 25





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-25-1 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 15036 Durkee Road _____

Lat/Long: 42.431190/-88.491111 _____

Primary Use: resid _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group:

List Observed Structures: (A) residence _____

Residence Detail

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations: attached garage

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Mid. 20th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1974 assessor date

circa 1939-1988

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-25-1: 15036 Durkee Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-25-2 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 15030 Durkee Road _____

Lat/Long: 42.430337/-88.490454 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three

List Observed Structures: (A) residence; (B) garage; (C) metal shed _____

Residence Detail

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Mid. 20th C.

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1977 assessor date

circa 1939-1988

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-25-2: 15030 Durkee Road – Residence, Garage, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number:AL-25-3 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 14910 Durkee Road _____

Lat/Long: 42.429650/-88.488209 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three

List Observed Structures: (A) residence; (B) garage; (C) metal shed _____

Residence Detail

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Mid. 20th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1970 assessor date

circa 1939-1988

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-25-3: 14910 Durkee Road – Residence, Garage, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number:AL-25-4 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: "Willow Tree Acres"_____

Address: 14816 Durkee Road_____

Lat/Long: 42.429628/-88.488240_____

Primary Use: resid/agri_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: five

List Observed Structures: (A) residence; (B) barn; (C,D,E) three small sheds_____

Residence Detail

Style: No style

Wall materials: wood/vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: structures set way back from road – obscured.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: L. 19th C.

Number of photos taken for this property*: three_____

* Attach Photo log, additional notes and map of resource location.

circa 1930 assessor date

before 1862

Barn Detail

Style: Gabled roof

Wall materials: wood

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features:



AL-25-4: 14816 Durkee Road – Barn, Sheds



AL-25-4: 14816 Durkee Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-25-5 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 14216 Durkee Road _____

Lat/Long: 42.429138/-88.475975 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: six

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) detached milk house(E) low wood-sided shed; (F) low, long coop _____

Residence Detail

Style: Upright and Wing

Wall materials: vinyl/wood

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: awnings

Barn Detail

Style: Gabled roof

Wall materials: wood/vinyl

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: outbuildings set back from road – obscured.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: L. 19th C.

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

before 1862



AL-25-5: 14216 Durkee Road – Coop, Barn



AL-25-5: 14216 Durkee Road - Residence



AL-25-5: 14216 Durkee Road – Barn, Silo, Milk House, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-25-6 Surveyor Name: M. Prchal, C. Flynn _____

Current Property or Structure Name: _____

Address: 7319 Manley Road _____

Lat/Long: 42.433171/-88.482379 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: five

List Observed Structures: (A) residence; (B) barn; (C) detached milk house; (D) wood sided crib with metal roof; (E) garage

Residence Detail

Style: Upright and Wing

Wall materials: vinyl/wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Gabled roof dairy

Wall materials: vertical wood board

Roof materials: metal

Foundation materials: concrete

Other distinguishing features: probably E.20th C.

Any obvious Additions/Alterations: could be Front Gabled with side addition

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. There is also a concrete cattle trough next to barn

Property Group Date Range: L. 19th C.

Number of photos taken for this property*: five_____

* Attach Photo log, additional notes and map of resource location.

circa 1910 assessor date

circa 1862-1872



AL-25-6: 7319 Manley Road – Barn, Milk House, Crib,
Garage



AL-25-6: 7319 Manley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-25-7 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 7904 Manley Road _____

Lat/Long: 42.440553/-88.481351 _____

Primary Use: resid/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: four

List Observed Structures: (A) residence; (B) one-story concrete block shed/garage; (C) small tool shed; (D) metal storage bin

Residence Detail

Style: Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Property Group Date Range: E. 20th C.

Number of photos taken for this property*: two_____

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

circa 1908-1939

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-25-7: 7904 Manley Road – Shed/Garage, Shed, Bin



AL-25-7: 7904 Manley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number:AL-25-8 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 7909 Manley Road _____

Lat/Long: 42.441612/-88.482252 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group:

List Observed Structures: (A) residence _____

Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

Any obvious Additions/Alterations: one-story extension on west side

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Property Group Date Range: E. 20th C.

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1920, 1982 assessor date

before 1862

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-25-8: 7909 Manley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-25-9 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 14601 O'Brien Road _____

Lat/Long: 42.443194/-88.489129 _____

Primary Use: residential /Ag _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: six

List Observed Structures: (A)barn; (B) metal Quonset; (C) metal pole barn-red; (D) metal pole barn-white; (E,F) two metal storage bins

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. See AL-24-3 on N side of road

Property Group Date Range: L.19th - E. 20th C.

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

before 1862

Barn Detail

Style: Gabled roof - center bay dairy

Wall materials: vertical wood boards

Roof materials: metal

Foundation materials: fieldstone

Other distinguishing features: two metal roof cupolas, and ramp




AL-25-9: 14601 O'Brien Road – Bins, Barns



AL-25-9: 14601 O'Brien Road – Barns, Bins, Quonset

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 26



Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/23/15 Survey Number: AL-26-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 15512 Durkee Road

Lat/Long: 42.432770/-88.500620

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 6

List Observed Structures: (A) Res (B) Barn (C) silo (D) machine shed (E) shed (F) pole building

Residence Detail

Style: Four Square

Wall materials: concrete block

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

enclosed front porch

multi-pane windows

pyramid roof dormer

milkhouse

Any obvious Additions/Alterations

Barn Detail

Style: Gabled Livestock Barn

Wall materials: board and aluminum

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features attached

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete stave silo D - timber machine shed E - small gabled shed F - metal pole building

property also includes numerous modern pole buildings and grain silos

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

before 1862



AL-26-1: 15512 Durkee Road – Pole Building



AL-26-1: 15512 Durkee Road - Residence



AL-26-1: 15512 Durkee Road – Barn, Silo, Sheds

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/23/15 Survey Number: AL-26-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 15129 Durkee Road

Lat/Long: 42.430911/-88.491806

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 4

List Observed Structures: (A) Res (B) shed (C) silo (D) pole building

Residence Detail

Style: Upright and Wing/Clipped gable Bungalow

Wall materials: vertical board

Roof materials: asphalt

Foundation materials: brick

Other distinguishing features

Appears to have multiple building phases - possibly middle to late nineteenth century and early to middle twentieth

Any obvious Additions/Alterations

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - concrete block garage/shed w/ metal roof C - concrete silo with domed roof

D - modern metal pole building

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

circa 1985 assessor date

before 1862



AL-26-2: 15129 Durkee Road – Residence




AL-26-2: 15129 Durkee Road – Shed, Silo



AL-26-2: 15129 Durkee Road – Pole Building

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 27





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-27-1 Surveyor Name: M. Prchal, C. Flynn _____

Current Property or Structure Name: _____

Address: 16900 O'Brien Road _____

Lat/Long: 42.442329/-88.525718 _____

Primary Use: agri. _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: five _____

List Observed Structures: (A) barn; (B-C) concrete stave silos; (D) small metal shed; (E) metal storage bin _____

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Property Group Date Range: L. 19th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1910, 1970 assessor date

before 1862-1872

Barn Detail

Style: round-roofed dairy

Wall materials: concrete block

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:



AL-27-1: 16900 O'Brien Road – Barn, Silos, Shed, Bin

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-27-2 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 7505 Alden Road _____

Lat/Long: 42.434763/-88.514862 _____

Primary Use: resid/agri. _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) metal pole barn _____

Residence Detail

Style: 2 story Upright, 1.5 story Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Property Group Date Range: L. 19th C.

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1910 assessor date

before 1862-1872

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-27-2: 7505 Alden Road – Residence



AL-27-2: 7505 Alden Road – Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-27-3 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 16102 Durkee Road _____

Lat/Long: 42.433385/-88.511039 _____

Primary Use: resid/agri. _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: six _____

List Observed Structures: (A) residence #1; (B) barn; (C) concrete stave silo; (D) residence #2; (E) wood-sided crib, obscured; (F) garage

Residence Detail

Style: Ranch

Wall materials: vertical wood and stone-face

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): Residence #2: original one-story with fieldstone foundation. Front Gabled addition with brick face and vinyl siding.

Property Group Date Range: L. 19th C.

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

before 1862-1872

Barn Detail

Style: Gabled roof dairy

Wall materials: vertical board

Roof materials: unknown

Foundation materials: concrete block

Other distinguishing features: attached concrete milk house



AL-27-3: 16102 Durkee Road – Residence



AL-27-3: 16102 Durkee Road – Barn, Silo, Residence 2



AL-27-3: 16102 Durkee Road – Crib, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number:AL-27-4 Surveyor Name: M. Prchal, C. Flynn _____

Current Property or Structure Name: _____

Address: 16211 O'Brien Road _____

Lat/Long: 42.443085/-88.513041 _____

Primary Use: resid/agri. _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: four _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) pole barn _____

Residence Detail

Style: Gabled El

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features:

Barn Detail

Style: gambrel roof banked dairy

Wall materials: vertical board

Roof materials: asphalt

Foundation materials: fieldstone/cc

Other distinguishing features: attached concrete milk house

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: L. 19th C.

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

before 1862-1872



AL-27-4: 16211 O'Brien Road – Residence, Shed



AL-27-4: 16211 O'Brien Road – Barns, Silo

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 28





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-28-1 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 17602 Altenburg Road _____

Lat/Long: 42.431242/-88.540624 _____

Primary Use: resid/agri. _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: nine _____

List Observed Structures: (A) residence; (B) dairy barn; (C) shed (obscured); (D) wood-sided shed/garage; (E) metal open-faced shed; (F-G) concrete stave silos; (H) metal storage bin; (I) low, open animal shed

Residence Detail

Style: Upright and Wing

Wall materials: possibly stucco

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Barn Detail

Style: Gabled roof

Wall materials: vertical wood board

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: attached concrete milk house

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. Property set back from road.

Property Group Date Range: L. 19th - E. 20th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1920, 2004 assessor date

before 1862



AL-28-1: 17602 Altenburg Road – Residence, Barn, Silos, Sheds, Bin

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-28-2 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 7412 Shields Road _____

Lat/Long: 42.434405/-88.544909 _____

Primary Use: resid/agri. _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: seven _____

List Observed Structures: (A) residence; (B) dairy barn; (C) silo; (D) garage; (E) crib/barn; (F) small shed; (G)

Quonsett metal shed _____

Residence Detail

Style: Cross Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Barn Detail

Style: Gabled roof dairy

Wall materials: vertical wood board

Roof materials: metal

Foundation materials: fieldstone

Other distinguishing features: attached concrete milk house, shed addition

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): concrete stave silo; two wood sided sheds/crib; metal Quonsett shed.

Property Group Date Range: L. 19th - E. 20th C.

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

circa 1910 assessor date

circa 1908-1939



AL-28-2: 7412 Shields Road – Barns, Silo, Shed, Garage



AL-28-2: 7412 Shields Road – Residence



AL-28-2: 7412 Shields Road – Quonset Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-28-3 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 7507 Shields Road _____

Lat/Long: 42.4357606/-88.545616 _____

Primary Use: resid/agri. _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: five _____

List Observed Structures: (A) residence; (B) barn; (C) concrete silo; (D) concrete milk house; (E) wood and metal garage/shed

Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

Any obvious Additions/Alterations:

Barn Detail

Style: Gabled roof dairy

Wall materials: vertical wood board

Roof materials: metal

Foundation materials: fieldstone

Other distinguishing features: attached concrete milk house, addition to north side

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Property Group Date Range: L. 19th - E. 20th C.

Number of photos taken for this property*: three_____

* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date

circa 1892-1903



AL-28-3: 7507 Shields Road – Residence



AL-28-3: 7507 Shields Road – Barn, Shed



AL-28-3: 7507 Shields Road – Silo, Milk House

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-28-4 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 7704 Shields Road _____

Lat/Long: 42.4357606/-88.545616 _____

Primary Use: resid/agri. _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: six _____

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) garage (obscured); (E) wood-sided shed; (F) metal Quonset shed _____

Residence Detail

Style: Gabled El

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: porch

Any obvious Additions/Alterations:

Barn Detail

Style: Gabled roof dairy

Wall materials: vertical wood board

Roof materials: metal

Foundation materials: fieldstone

Other distinguishing features: attached concrete milk house and shed

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Property Group Date Range: L. 19th C.

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1910 assessor date

circa 1862-1872



AL-28-4: 7704 Shields Road – Barn, Silo



AL-28-4: 7704 Shields Road – Residence, Quonset, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-28-5 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 17715 Rt. 173_____

Lat/Long: 42.442894/-88.543639_____

Primary Use: agri. _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) shed/barn, obscured by foliage. Google satellite shows a silo further back from road_____

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Property Group Date Range: unknown

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.

circa 1941-1951

circa 1892-1903

Barn Detail

Style:

Wall materials:

Roof materials:


Foundation materials:

Other distinguishing features:



AL-28-5: 17715 Illinois Route 173 – Shed

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 29



Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-29-1 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 19033 Rt. 173 _____

Lat/Long: 42.437351/-88.567972 _____

Primary Use: resid/agri. _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) barn; (C) 2nd barn _____

Residence Detail

Style: Colonial Revival

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: one-story addition and attached garage on west side

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): 2nd barn: peaked roof, vertical board siding.

Property Group Date Range: L. 19th - E. 20th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date

before 1862



AL-29-1: 19033 Illinois Route 173 – Residence



AL-29-1: 19033 Illinois Route 173 – Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-29-2 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 18814 Altenberg Road _____

Lat/Long: 42.429472/-88.563975 _____

Primary Use: Res _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) garage _____

Residence Detail

Style: Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): garage, vinyl sided

Property Group Date Range: E. 20th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

circa 1892-1903



AL-29-2: 18125 Crowley Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 3/26/15_____ Survey Number: AL-29-3 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 18125 Crowley Road _____

Lat/Long: 42.443284/-88.567447 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: No style

Wall materials: vinyl

Roof materials: metal

Foundation materials: concrete

Other distinguishing features: stone chimney

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: one-story extension to south side. Appears to be a possible converted barn

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Late 19th C.

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.


circa 2003 assessor date

circa 1957-1988



AL-29-3: 18814 Altenberg Road – Residence

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 30





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-30-1 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 19916 Rt. 173 _____

Lat/Long: 42.428049/-88.586780 _____

Primary Use: res/agri _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) metal shed; (C) wood and concrete shed

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: diagonal corner windows, other Victorian trim.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: L.19th E. 20th C.

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

circa 1939-1988



AL-30-1: 19916 Illinois Route 173 – Sheds



AL-30-1: 19916 Illinois Route 173 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-30-2 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 19808 Rt. 173 _____

Lat/Long: 42.429036/-88.584161 _____

Primary Use: resid. _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) vinyl-covered shed

Residence Detail

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations: attached garage

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Mid - 20th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1950 assessor date

before 1862

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-30-2: 19808 Illinois Route 173 – Residence, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-30-3 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 19802 Rt. 173 _____

Lat/Long: 42.429126/-88.583658 _____

Primary Use: resid. _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Minimal Traditional

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations: attached garage

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Mid - 20th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1950 assessor date

before 1862



AL-30-3: 19802 Illinois Route 173 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-30-4 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: Roadhouse Name? _____

Address: 19622 Rt. 173 _____

Lat/Long: 42.430332/-88.579962 _____

Primary Use: resid/commercial _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) Roadhouse; (C) garage

Residence Detail

Style: Foursquare

Wall materials: wood clapboard

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features:

Any obvious Additions/Alterations: front porch enclosed

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: E. - 20th C.

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

A residential structure is shown is this location on 1908 plat.

circa 1920, 1950 assessor date

before 1862

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-30-4: 19622 Illinois Route 173 – Roadhouse



AL-30-4: 19622 Illinois Route 173 – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-30-5 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: Busy Bee Farm_____

Address: 19519 Rt. 173_____

Lat/Long: 42.429705/-88.579457_____

Primary Use: residential_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: two_____

List Observed Structures: (A) residence; (B) wood-sided garage

Residence Detail

Style: One story Gabled EI

Wall materials: vertical wood board

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: E. – Mid. 20th C.

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.

circa 1950 assessor date

before 1862

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-30-5: 19519 Illinois Route 173 – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-30-6 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 19416 Rt. 173 _____

Lat/Long: 42.430783/-88.575875 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) vinyl-sided garage

Residence Detail

Style: One story L-shaped Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Mid. 20th C.

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1988-2015

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-30-6: 19416 Illinois Route 173 – Residence



AL-30-6: 19416 Illinois Route 173 – Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-30-7 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 19420 (N-side) Rt. 173 _____

Lat/Long: 42.430903/-88.575216 _____

Primary Use: agriculture _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) fieldstone barn foundation

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: L.19th – E.20th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1910 assessor date

circa 1939-1988



AL-30-7: 19420 Illinois Route 173 – Barn Foundation

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-30-8 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 19448 (N-side) Rt. 173 _____

Lat/Long: 42.430852/-88.575467 _____

Primary Use: resid. _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: two _____

List Observed Structures: (A) residence; (B) small wood-sided shed

Residence Detail

Style: Upright and Wing

Wall materials: asphalt brick-face

Roof materials: asphalt

Foundation materials: concrete block visible

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: L.19th – E.20th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1910 assessor date

circa 1939-1988

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-30-8: 19448 Illinois Route 173 – Residence, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-30-9 Surveyor Name: M. Prchal, C. Flynn

Current Property or Structure Name: _____

Address: 19317 Rt. 173 _____

Lat/Long: 42.430852/-88.575467 _____

Primary Use: resid. _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence

Residence Detail

Style: Ranch

Wall materials: vertical wood board

Roof materials: metal

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations: attached garage

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: Mid. 20th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1979 assessor date

circa 1939-1988

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



AL-30-9: 19317 Illinois Route 173 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number:AL-30-10

Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 19219 Rt. 173_____

Lat/Long: 42.433385/-88.571750_____

Primary Use: resid. _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: (A) residence; (B) pole barn/garage

Residence Detail

Style: Cross Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone and concrete

Other distinguishing features:

Any obvious Additions/Alterations: bay window on front

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: L.19th – E. 20th C.

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.

circa 1930 assessor date

circa 1908-1939



AL-30-10: 19219 Illinois Route 173 – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/8/15_____ Survey Number: AL-30-11 Surveyor Name: M. Prchal, C. Flynn_____

Current Property or Structure Name: _____

Address: 19126 Rt. 173 _____

Lat/Long: 42.435813/-88.570655 _____

Primary Use: resid/agri. _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: three _____

List Observed Structures: (A) residence; (B) pole barn/garage; (C) wood sided shed _____

Residence Detail

Style: Two story Unknown

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: E. 20th C.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

before 1862

Barn Detail

Style: Gabled roof

Wall materials: vertical wood board

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: two shed extensions on E and W sides




AL-30-11: 19126 Illinois Route 173 – Barn



AL-30-11: 19126 Illinois Route 173 – Residence, Shed

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 31




Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/23/15 Survey Number: AL-31-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: Schultz Road

Lat/Long: 42.429273/-88.516399

Primary Use: shed

Is this a record of a single structure or group (give total number of structures):

Single: X Group: _____ Number Structures in Group: _____

List Observed Structures: shed

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

gabled shed/garage with board siding

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1935 assessor date

before 1862

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-31-1: Schultz Road – Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/23/15 Survey Number: AL-31-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 7001 Schultz Road

Lat/Long: 42.428177/-88.575491

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 4

List Observed Structures: (A) Res (B) Barn (C) silo (D) garage

Residence Detail

Style: Greek Revival

Wall materials: aluminum/vinyl/asbestos

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Frieze band windows; wide cornice
side entry

Any obvious Additions/Alterations
multiple phases of additions/building
multiple materials used

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - concrete stave silo with domed roof D - four bay modern garage/machine shed

Number of photos taken for this property*: 4

* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date

before 1862



AL-31-2: 7001 Schultz Road – Barn, Silo



AL-31-2: 7001 Schultz Road – Garage



AL-31-2: 7001 Schultz Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/23/15 Survey Number: AL-31-3 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 6817 Schultz Road

Lat/Long: 42.424979/-88.578176

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 4

List Observed Structures: (A) Res (B) Barn (C) shed (D) barn

Residence Detail

Style: Gabled

Wall materials: aluminum Roof

materials:

Foundation materials:

Other distinguishing features: possible side Gabled - obscured side entry

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - small gabled shed

D - Barn2 - Gabled Hay/Livestock with raised stone basement/foundation

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date

before 1862

Barn Detail

Style: Round roofed

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features banked



AL-31-3: 6817 Schultz Road – Residence



AL-31-3: 6817 Schultz Road – Barn, Shed



AL-31-3: 6817 Schultz Road – Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/23/15 Survey Number: AL-31-4 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 6414 Schultz Road

Lat/Long: 42.419738/-88.578866

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 4

List Observed Structures: (A) Res (B) Barn (C) shed (D) Res 2

Residence Detail

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features
aerial photos suggest it has been extended

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - small gabled shed

D - Residence 2 - probably original residence - basement gabled cottage (raised first floor)

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

circa 1900, 1940 assessor date

before 1862



AL-31-4: 6414 Schultz Road – Barn, Shed, Residence 2



AL-31-4: 6414 Schultz Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/23/15 Survey Number: AL-31-5 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 6306 Schultz Road

Lat/Long: 42.417582/-88.579038

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 6

List Observed Structures: (A) Res (B) Barn (C) pole building (D,E,F) grain silos

Residence Detail

Style: Cross Gabled

Wall materials: aluminum

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - metal pole building

D - E metal grain silos

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

circa 1910 assessor date

before 1862



AL-31-5: 6306 Schultz Road – Barn



AL-31-5: 6306 Schultz Road – Silos, Pole Building



AL-31-5: 6306 Schultz Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/23/15 Survey Number: AL-31-6 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 19619 East Brink Street

Lat/Long: 42.415102/-88.585126

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 4

List Observed Structures: (A) Res (B) Barn (C) shed (D) shed/barn

Residence Detail

Style: Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

side extension

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - small gabled timber shed

D - gabled machine shed/small barn

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

before 1862-1872

Barn Detail

Style: Gabled Hay/Livestock
Barn

Wall materials: board

Roof materials: fishscale

Foundation materials:

Other distinguishing features

attached concrete block

milkhouse with curved concrete roof



AL-31-6: 19619 East Brink Street – Barn, Sheds,
Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/23/15 Survey Number: AL-31-7 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 20012 East Brink Street

Lat/Long: 42.415105/-88.588293

Primary Use: Ag/Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 4

List Observed Structures: (A) Res (B) Barn (C) shed (D) silo

Residence Detail

Style: Ranch

Wall materials: horizontal and vertical board

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

Any obvious Additions/Alterations
newish bay window

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - Gabled barn/shed with board siding and asphalt roof

D - concrete stave silo with domed roof

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

circa 1955 assessor date

before 1862-1872



AL-31-7: 20012 East Brink Street – Residence, Barn, Silo



AL-31-7: 20012 East Brink Street – Shed

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 32



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/23/15 Survey Number: AL-32-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 18117 Altenberg Road

Lat/Long: 42.428735/-88.558322

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: X Group: _____ Number Structures in Group: _____

List Observed Structures: Residence _____

Residence Detail

Style: Ranch

Wall materials: aluminum/vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features
attached garage - may be newer addition

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1960 assessor date

circa 1957-1988

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-32-1: 18117 Altenberg Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/23/15 Survey Number: AL-32-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: Green Road

Lat/Long: 42.421376/-88.563762

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: X Group: _____ Number Structures in Group: _____

List Observed Structures: Residence

Residence Detail

Style: Cape Cod

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Obscured/far from road

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1960 assessor date

circa 1957-2015

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-32-2: Green Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/23/15 Survey Number: AL-32-3 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 18583 Green Road

Lat/Long: 42.421097/-88.560767

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: obscured

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

Obscured/far from road

Number of photos taken for this property*: 1

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date.

circa 1908-1939

Barn Detail


Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-32-3: 18583 Green Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/23/15 Survey Number: AL-32-4 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 18408 Green Road

Lat/Long: 42.422187/-88.556980

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 4

List Observed Structures: (A) Res (B) shed/garage (C) barn (D) greenhouse (E) silo

Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials:

Other distinguishing features

gabled dormers

side porch

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled shed/garage D - glass greenhouse E - brick silo with raised bands

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date

before 1862

Barn Detail

Style: Raised Gabled Barn

Wall materials: board

Roof materials: asphalt

Foundation materials: stone

Other distinguishing features




AL-32-4: 18408 Green Road – Residence, Shed



AL-32-4: 18408 Green Road – Silo, Barn, Greenhouse

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 33





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/23/15 Survey Number: AL-33-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 17210 Green Road

Lat/Long: 42.420714/-88.533221

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 5

List Observed Structures: (A) Res (B) machine shed (C) Barn (D) grain silo (E) silo

Residence Detail

Style: No style

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features
Gabled central dormer

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - frame machine shed/garage D - metal grain silo E - concrete stave silo

Number of photos taken for this property*: 4

* Attach Photo log, additional notes and map of resource location.

circa 1950 assessor date

before 1862

Barn Detail

Style: Gambrel roof

Wall materials: metal

Roof materials: metal

Foundation materials:

Other distinguishing features
attached side pole building



AL-33-1: 17210 Green Road – Silo, Shed



AL-33-1: 17210 Green Road - Silo



AL-33-1: 17210 Green Road - Barn



AL-33-1: 17210 Green Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/23/15 Survey Number: AL-33-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 17316 Green Road

Lat/Long: 42.422143/-88.535921

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 5

List Observed Structures: (A) Res (B) machine shed (C and D) silos (E) shed/milkhouse

Residence Detail

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features
attached rear garage

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - metal machine shed C and D - concrete stave silos E - concrete block shed/milkhouse with timber/asphalt roof

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

circa 1950 assessor date

before 1862

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-33-2: 17316 Green Road – Residence



AL-33-2: 17316 Green Road – Shed, Silos, Milk House

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/23/15 Survey Number: AL-33-3 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 17615 Altenberg Road

Lat/Long: 42.428742/-88.541352

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 6

List Observed Structures: (A) shed (B) barn (C) silo (D-F) sheds

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

A - low timber shed/long barn C - silo D-F - timber frame sheds

property also includes a fieldstone barn foundation

aerial indicates a residence at back of property, but this was not visible during survey

Number of photos taken for this property*: 4

* Attach Photo log, additional notes and map of resource location.

circa 2006 assessor date

circa 1908-1939

Barn Detail

Style: Gabled Hay Barn/ Three Bay

Wall materials: board

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features



AL-33-3: 17615 Altenberg Road – Shed



AL-33-3: 17615 Altenberg Road - Foundation




AL-33-3: 17615 Altenberg Road – Barn, Silo, Shed



AL-33-3: 17615 Altenberg Road - Sheds

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 34



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/23/15 Survey Number: AL-34-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: Clavey's Nursery Inc.

Address: 6223 Alden Road

Lat/Long: 42.417638/-88.511021

Primary Use: Commercial nursery

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 11

List Observed Structures: (A) Res (B) Barn (C) silo (D) shed (E) pavilion (F) pole building (G) grain silo (H - J) sheds (K) greenhouses

Residence Detail

Style: Gabled

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features
obscured - Gabled front or side gabled

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

C - formed concrete silo D - small shed E - metal pavilion F - pole building G - metal grain silo

H-J - sheds K - metal/plastic/glass greenhouses

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date

before 1862

Barn Detail

Style: Gabled

Wall materials: metal

Roof materials: metal

Foundation materials:

Other distinguishing features



AL-34-1: 6223 Alden Road – Barn, Silos, Shed, Pavilion, Pole Building



AL-34-1: 6223 Alden Road – Residence



AL-34-1: 6223 Alden Road – Sheds, Greenhouses

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/23/15 Survey Number: AL-34-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 6506 Alden Road

Lat/Long: 42.420598/-88.511912

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 2

List Observed Structures: (A) Res (B) garage

Residence Detail

Style: No style

Wall materials: vinyl and brick (facing?)

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features

Barn Detail

Style: Gabled

Wall materials: metal

Roof materials: metal

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

entire facade has been redone with new materials and windows

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - modern multi-bay garage

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

before 1862



AL-34-2: 6506 Alden Road – Residence



AL-34-2: 6506 Alden Road – Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/23/15 Survey Number: AL-34-3 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: Owl Farm

Address: 7015 Alden Road

Lat/Long: 42.420598/-88.511912

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 7

List Observed Structures: (A) Res (B) garage/shed (C) Barn (D) silo (E) long barn (F) shed/milkhouse (G) barn 2

Residence Detail

Style: Side Gabled/Massed Plan

Wall materials: vinyl

Roof materials: asphalt

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations

new windows

tall, wide chimney

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - gabled garage/shed D - concrete stave silo E - long timber barn F - pyramid roof shed/milkhouse

G - round roofed barn

Number of photos taken for this property*: 4

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

before 1862

Barn Detail

Style: Gambrel

Wall materials: board

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features



AL-34-3: 7015 Alden Road – Residence, Garage



AL-34-3: 7015 Alden Road – Barns, Silo, Milk House



AL-34-3: 7015 Alden Road – Barns, Milk House

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/23/15 Survey Number: AL-34-4 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: Owl Farm

Address: 17020 Altenberg Road

Lat/Long: 42.428728/-88.530392

Primary Use: Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 5

List Observed Structures: (A) Res (B) other outbuilding (C) shed (D) pole building (E) pole building

Residence Detail

Style: Bungalow

Wall materials: concrete block

Roof materials: asphalt

Foundation materials: concrete/block

Other distinguishing features

clipped gables

full front porch with decorative open brickwork

Any obvious Additions/Alterations

roof has been dormered

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - pyramid roofed outbuilding or other with concrete foundation C - small shed D and E - metal pole buildings

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

circa 1920 assessor date

circa 1908-1939



AL-34-4: 17020 Altenberg Road – Outbuilding, Pole Buildings, Shed



AL-34-4: 17020 Altenberg Road – Residence

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 35



Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

0 125 250 500 Meters

0 375 750 1,500 Feet

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/23/15 Survey Number: AL-35-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 15212 Thayer Road

Lat/Long: 42.414686/-88.494437

Primary Use: Res/Ag

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 5

List Observed Structures: (A) Res (B) Barn (CDE) silos (F) quonset

Residence Detail

Style: Cape Cod

Wall materials: aluminum

Roof materials: asphalt

Foundation materials:

Other distinguishing features

three gabled dormers

open to allow airflow

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

CDE - metal Harvestore silos F - metal quonset

property also includes numerous modern pole buildings and grain silos

Number of photos taken for this property*: 3

* Attach Photo log, additional notes and map of resource location.

circa 1950, 1985 assessor date

before 1862

Barn Detail

Style: Gambrel Dairy

Wall materials: open/removed

Roof materials: metal

Foundation materials:

Other distinguishing features spaces



AL-35-1: 15212 Thayer Road – Quonset




AL-35-1: 15212 Thayer Road - Residence



AL-35-1: 15212 Thayer Road – Barn, Silos

MCHENRY COUNTY
ALDEN TOWNSHIP
SECTION 36



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Structure
- - Structure Group
- AL-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/23/15 Survey Number: AL-36-1 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 6599 Manley Road

Lat/Long: 42.427874/-88.482444

Primary Use: Ag/Abandoned Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 5

List Observed Structures: (A) Res (B) pole building (CDE) silos (F) barn (G) silo base

Residence Detail

Style: Gabled EI

Wall materials: board

Roof materials: asphalt

Foundation materials:

Other distinguishing features
partially enclosed front porch
abandoned
section with raised

Barn Detail

Style: Gabled Hay Barn

Wall materials: board

Roof materials: metal

Foundation materials:

Other distinguishing features attached
concrete foundation

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - metal pole building CDE- 2 metal grain bins and a grain cage/bin G - brick silo base

property also includes numerous modern pole buildings and grain silos

Number of photos taken for this property*: 4

* Attach Photo log, additional notes and map of resource location.

circa 1900 assessor date

before 1862-1872



AL-36-1: 6599 Manley Road – Pole Building, Bins



AL-36-1: 6599 Manley Road – Barn, Silo Base



AL-36-1: 6599 Manley Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 4/23/15 Survey Number: AL-36-2 Surveyor Name: M Prchal/C Flynn

Current Property or Structure Name: _____

Address: 6508 Manley Road

Lat/Long: 42.420674/-88.480407

Primary Use: Ag/Abandoned Res

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X Number Structures in Group: 5

List Observed Structures: (A) Res (B) pole building (C) shed/barn (D) long barn/pole building

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features
obscured

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc)

B - metal pole building C - long wood shed/barn D - long barn/possible pole building

Number of photos taken for this property*: 2

* Attach Photo log, additional notes and map of resource location.

circa 1999 assessor date.

before 1862

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



AL-36-2: 6508 Manley Road – Pole Buildings, Barn



AL-36-2: 6508 Manley Road – Residence