

McHenry County



Illinois

Township Key

Chemung	Alden	Hebron	
Dunham	Hartland		
Marengo	Seneca		
Riley	Not Included in Survey		

Marengo Township

T44N, R5E

0 0.5 1 2 Miles

0 0.5 1 2 Kilometers



MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 1





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 1-1_____ Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 207 Menges Road _____

Lat/Long: 42.325856/-88.589051 _____

Primary Use: Residence /Ag _____

Is this a record of a single structure or group (give total number of structures): five visible

Single: _____ Group: _____ Number Structures in Group: five visible _____

List Observed Structures: Residence, Garage/outbuilding, old barn, concrete tile silo, wood-framed metal-clad shed. _____

Residence Detail

Style Unknown (Obscured)

Wall materials: wood

Roof materials: asphalt

Foundation materials

Other distinguishing features: none

Barn Detail

Style: Gabled

Wall materials: vertical wood boards

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: Round roof rear extension.

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): Garage: wood siding, asphalt roof

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-1-1: 207 Menges Road - Overview



MA-1-1: 207 Menges Road – Outbuilding



MA-1-1: 207 Menges Road - Residence



MA-1-1: 207 Menges Road - Barn



MA-1-1: 207 Menges Road – Barn, Silo, & Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 1-2_____ Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 609 N. Menges Road _____

Lat/Long: 42.320272/-88.591003 _____

Primary Use: Agriculture /Res _____

Is this a record of a single structure or group (give total number of structures): two

Single: _____ Group: X _____ Number Structures in Group: Two _____

List Observed Structures: Shed, residence. _____

Residence Detail

Style: Front Gabled

Wall materials: vinyl siding

Roof materials: asphalt

Foundation materials

Other distinguishing features: none

Barn Detail

Style

Wall materials:

Roof materials:

Foundation materials

Other distinguishing features:

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): Gambrel shed with drive through extensionsn

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1900



MA-1-2: 609 North Menges Road – Residence, Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 1-3_____ Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 20206 Kishwaukee Valley Rd. _____

Lat/Long: 42.313481/-88.591218 _____

Primary Use: Residential /Ag _____

Is this a record of a single structure or group (give total number of structures): six

Single: _____ Group: X _____ Number Structures in Group: six _____

List Observed Structures: Barn/garage, residence, dairy barn, concrete tile silo, smaller wood-framed shed, larger wood-framed shed behind residence. _____

Residence Detail

Style: Gabled EI

Wall materials: clapboard

Roof materials: asphalt

Foundation materials: covered

Other distinguishing features:

Barn Detail

Style Gabled

Wall materials: newer wood

Roof materials: metal

Foundation materials

Other distinguishing features: lean-to front attachment. - obscured by trees

Any obvious Additions/Alterations: addition to west side of house. Newer windows.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property*: six _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-1-3: 20206 Kishwaukee Valley Road - Silo



MA-1-3: 20206 Kishwaukee Valley Road –
Residence, Addition



MA-1-3: 20206 Kishwaukee Valley Road –
Barn, Silo, Shed



MA-1-3: 20206 Kishwaukee Valley Road -
Outbuilding

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 1-4_____ Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 20510 Kishwaukee Valley Rd. _____

Lat/Long: 42.31386/-88.596883 _____

Primary Use: Residential /Ag _____

Is this a record of a single structure or group (give total number of structures): nine

Single: _____ Group: X _____ Number Structures in Group: nine _____

List Observed Structures: residence, pole barn with wood plank foundation, dairy barn and milk or spring house with concrete foundations, small shed behind milk house, metal silo behind shed, large shed to NE, garage to E. All outbuildings metal-clad. All except pole barn have concrete foundations.

Residence Detail

Style: Upright and Wing

Wall materials: vinyl siding

Roof materials: asphalt

Foundation materials: obscured, concrete

Other distinguishing features: newer chimney on W end.

Barn Detail

Style: Gabled

Wall materials: vinyl/aluminum siding

Roof materials: metal

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations: original house may have been one-story side gabled west section.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property*: seven _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-1-4: 20510 Kishwaukee Valley Road – Barn, Garage



MA-1-4: 20510 Kishwaukee Valley Road – Milk House, Barn



MA-1-4: 20510 Kishwaukee Valley Road – Barn, Coops, Shed



MA-1-4: 20510 Kishwaukee Valley Road - Residence



MA-1-4: 20510 Kishwaukee Valley Road – Tool Shed



MA-1-4: 20510 Kishwaukee Valley Road – Pole Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 1-5_____ Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 20601 Kishwaukee Valley Rd. _____

Lat/Long: 42.313402/-88.599072 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures): nine

Single: _____ Group: Number Structures in Group: three _____

List Observed Structures: residence, wood-sided garage, small wooden tool shed. _____

Residence Detail

Style: Unknown (obscured)

Wall materials: vinyl siding

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: residence is mostly obscured.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property*: seven _____

* Attach Photo log, additional notes and map of resource location.

circa 1910



MA-1-5: 20601 Kishwaukee Valley Road – Residence



MA-1-5: 20601 Kishwaukee Valley Road – Garage,
Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 1-6_____ Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 906 Rt. 23 _____

Lat/Long: 42.31617/-88.607504 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures): four

Single: _____ Group: X _____ Number Structures in Group: four _____

List Observed Structures: center-bay vertical-board barn with concrete tile silo at SE corner, two-part connected metal-clad pole barn. Residential structure is totally obscured _____

Residence Detail

Style: Unknownn (obscured)

Wall materials:

Roof materials:

Foundation materials: Other

distinguishing features:

Barn Detail

Style: Gabled Center Bay

Wall materials: vertical board wood

Roof materials: asphalt

Foundation materials: obscured

Other distinguishing features:

Any obvious Additions/Alterations: residence is entirely obscured.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-1-6: 906 Route 23 – Barn



MA-1-6: 906 Route 23 – Barns

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 1-7_____ Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 202 Rt. 23 _____

Lat/Long: 42.325626/-88.607858 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures): four

Single: _____ Group: X _____ Number Structures in Group: four _____

List Observed Structures: newer vinyl-clad residence, metal-clad barn, metal-clad wood-framed shed, aluminum silo. _____

Residence Detail

Style: Minimal Traditional

Wall materials: vinyl siding Roof

materials: asphalt Foundation

materials: concrete

distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-1-7: 202 Route 23 - Residence




MA-1-7: 202 Route 23 – Barn, Shed, Silo



MA-1-7: 202 Route 23 - Shed

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 2





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 2-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 305 Rt. 23 _____

Lat/Long: 42.325301/-88.608956 _____

Primary Use: Residential/agricultural. _____

Is this a record of a single structure or group (give total number of structures): four

Single: _____ Group: X _____ Number Structures in Group: four _____

List Observed Structures: vinyl-clad residence, timber framed wood barn, concrete silo, metal-clad barn/garage with wood foundation. _____

Residence Detail

Style: Bungalow

Wall materials: vinyl siding

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style: Gabled

Wall materials: timber framed wood boards.

Roof materials: metal

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): concrete silo, metal-clad pole barn/garage with wood plank foundation.

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-2-1: 305 Route 23 - Residence



MA-2-1: 305 Route 23 – Shed, Silo



MA-2-1: 305 Route 23 – Barn, Wood Foundation

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 2-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 503 Rt. 23_____

Lat/Long: 42.321811/-88.608956_____

Primary Use: Residential/agricultural: _____

Is this a record of a single structure or group (give total number of structures): 10

Single: _____ Group: Number Structures in Group: 10_____

List Observed Structures: vinyl-clad residence, five metal-clad sheds/pole barns, alum. Bin, one concrete silo, one concrete tile silo, one vertical board barn.

Residence Detail

Style: Front Gabled

Wall materials: vinyl siding

Roof materials: asphalt

Foundation materials: field stone

Other distinguishing features:

Barn Detail

Style: Gabled

Wall materials: vertical wood boards.

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: central main bay

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): 2 silos described above, 5 metal-cad pole barns/sheds with concrete foundations, aluminum storage bin.

Number of photos taken for this property*: six_____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-2-2: 503 Route 23 – Residence, Silos



MA-2-2: 503 Route 23 – Silo, Barns, Shed



MA-2-2: 503 Route 23 - Outbuilding

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 2-3 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 710 Rt. 23_____

Lat/Long: 42.318384/-88.610759_____

Primary Use: Residential/agricultural_____

Is this a record of a single structure or group (give total number of structures): at least five

Single: _____ Group: Number Structures in Group: at least five barely visible _____

List Observed Structures: residence, larger barn (roof visible), two sheds, grain elevator/bins visible above trees.

Residence Detail

Style: Unknown - obscured

Wall materials: vinyl siding
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: set way back

Barn Detail

Style: Gambrel

Wall materials: unknown
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: cupola

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): sheds are metal-clad, barely visible. Grain elevator structure visible above tree tops.

Number of photos taken for this property*: three_____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-2-3: 710 Route 23 - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 2-4 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 21206 Kishwaukee Valley Road _____

Lat/Long: 42.31521/-88.609471 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures): one

Single: _____ Group: _____ Number Structures in Group: _____

List Observed Structures: residence _____

Residence Detail

Style: No style

Wall materials: vinyl siding

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

date unknown - the property does not appear on historic maps; it could be modern but may also be remodeled older home



MA-2-4: 21206 Kishwaukee Valley Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 2-5 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 21220 Kishwaukee Valley Road _____

Lat/Long: 42.313624/-88.610759 _____

Primary Use: Residential/Agriculture _____

Is this a record of a single structure or group (give total number of structures): four

Single: _____ Group: X _____ Number Structures in Group: four visible _____

List Observed Structures: residence, pole barn/shed, dairy barn, milk house, coop. _____

Residence Detail

Style: Gabled EI

Wall materials: vinyl siding
Roof materials: asphalt

Foundation materials: concrete-covered stone

Other distinguishing features:

Barn Detail

Style: Gabled Dairy

Wall materials: vertical boards
Roof materials: metal

Foundation materials: concrete/stone

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): wood and concrete milk house, wooden coop structure off east end of barn-concrete/stone foundation.

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.


circa 1872



MA-2-5: 21220 Kishwaukee Valley Road -
Residence



MA-2-5: 21220 Kishwaukee Valley Road– Barn,
Milk House



MA-2-5: 21220 Kishwaukee Valley Road –
Chicken Coop

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 2-6 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 311 S. Olbrich Rd. _____

Lat/Long: 42.313941/-88.612304 _____

Primary Use: Residential/Agriculture _____

Is this a record of a single structure or group (give total number of structures): possibly four

Single: _____ Group: X _____ Number Structures in Group: three visible _____

List Observed Structures: residence, barn, silo, possible shed/barn behind silo. _____

Residence Detail

Style: Cape Cod

Wall materials: vinyl siding
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: additions, gables

Barn Detail

Style: Gabled

Wall materials: vertical boards
Roof materials: asphalt

Foundation materials: concrete/stone

Other distinguishing features: one-story

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): concrete silo, possible pole barn/shed behind (N) of silo.

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.



MA-2-6: 311 South Olbrich - Residence



MA-2-6: 311 South Olbrich – Barn, Silo

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 2-7 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 21816 Kishwaukee Valley Road. _____

Lat/Long: 42.31337/-88.624628 _____

Primary Use: Residential/Agriculture _____

Is this a record of a single structure or group (give total number of structures): six-only four photographed

Single: _____ Group: X _____ Number Structures in Group: four photographed _____

List Observed Structures: barn with attached milk house, silo, metal-clad shed. Garage and residence new – not photographed

Residence Detail

Style: Unknown

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Barn Detail

Style: large dairy

Wall materials: vertical boards

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: see below

Any obvious Additions/Alterations: barn has shed extensions on north and west side, milk house attached east side

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): concrete tile silo, metal clad pole barn/shed, residence and garage are new – not photographed.

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-2-7: 21816 Kishwaukee Valley Road – Barn, Silos, Shed



MA-2-7: 21816 Kishwaukee Valley Road – Milk House, Garage

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 3



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 3-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 22402 Kishwaukee Valley Road. _____

Lat/Long: 42.313314/-88.633586 _____

Primary Use: Residential/Agriculture _____

Is this a record of a single structure or group (give total number of structures): six-only four photographed

Single: _____ Group: X _____ Number Structures in Group: 18, 10 photographed__

List Observed Structures: residence, small shed, smaller barn, dairy barn with attached milk house, 2 concrete silos, 2 attached sheds. Metal pole barn and five alum. Storage bins not visible, not photographed

Residence Detail

Style: Foursquare

Wall materials: clapboard

Roof materials: asphalt

Foundation materials: decorative concrete blocks

Other distinguishing features: rear extension

Barn Detail

Style: Gabled

Wall materials: vertical boards

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: timber framing

Any obvious Additions/Alterations: residence addition is wood siding with concrete foundation.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): small shed and barn, equipment barn, 2 attached sheds, dairy barn with attached milk house are wood siding, asphalt roofs, concrete foundations. 2 concrete silos NE corner of dairy barn. Not visible/not photographed: metal-clad pole barn and 5 aluminum storage bins.

Number of photos taken for this property*: eight _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-3-1: 22402 Kishwaukee Valley Road –
Residence, Rear Extension



MA-3-1: 22402 Kishwaukee Valley Road –
Shed, Smaller Barn



MA-3-1: 22402 Kishwaukee Valley Road –
Equipment Barn



MA-3-1: 22402 Kishwaukee Valley Road –
Dairy Barn, Milk House



MA-3-1: 22402 Kishwaukee Valley Road - Silos



MA-3-1: 22402 Kishwaukee Valley Road – Attached Sheds

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 3-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 22408 Kishwaukee Valley Road. _____

Lat/Long: 42.313257/-88.634536 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures): One

Single: _____ Group: _____ Number Structures in Group:

List Observed Structures: residence _____

Residence Detail

Style: Minimal Traditional

Wall materials: wood board

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: recessed front porch with overhang.

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1930-1950

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



MA-3-2: 22408 Kishwaukee Valley Road- Residence

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 4



Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 4-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 717 Root Road. _____

Lat/Long: 42.317495/-88.657565 _____

Primary Use: Residential/agriculture _____

Is this a record of a single structure or group (give total number of structures): three

Single: _____ Group: Number Structures in Group: three

List Observed Structures: residence, two newer pole barns _____

Residence Detail

Style: Cross Gabled

Wall materials: vinyl siding

Roof materials: asphalt

Foundation materials: decorative field stone

Other distinguishing features: newer wooden front steps

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: newer rear extension, wood plank siding, asphalt roof, foundation wood-covered.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): two metal clad pole barns – not photographed

Number of photos taken for this property*: three of residence _____


* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-4-1: 717 Root Road - Residence

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 5





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 5-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 24517 Tomlin Road. _____

Lat/Long: 42.327355/-88.676394 _____

Primary Use: Residential/agriculture _____

Is this a record of a single structure or group (give total number of structures): six

Single: _____ Group: Number Structures in Group: six

List Observed Structures: residence, metal-clad pole barn, tall crib with large roof structure, dairy barn with metal extension

Residence Detail

Style: Foursquare

Wall materials: vinyl siding

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Gambrel Dairy

Wall materials: vertical wood

Roof materials: metal

Foundation materials: concrete

Other distinguishing features: large attached extension/milk house etc.

Any obvious Additions/Alterations: replacement windows, large extension to west side of house. Tall wooden crib has large roof structure/cupola.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): property contains additional pole barn and a barn extension not visible from the road.

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-5-1: 24517 Tomlin Road - Residence



MA-5-1: 24517 Tomlin Road – Tall Crib, Metal Barn



MA-5-1: 4517 Tomlin Road – Dairy Barn, Extension

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 5-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 24303 Tomlin Road _____

Lat/Long: 42.327645/-88.670585 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures): One

Single: _____ Group: _____ Number Structures in Group:

List Observed Structures: residence with attached garage _____

Residence Detail

Style: Minimal Traditional

Wall materials: vinyl siding
Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1920-1930



MA-5-2: 24303 Tomlin Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 5-3 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 319 Noe Road. _____

Lat/Long: 42.323401/-88.667682 _____

Primary Use: Residential/agriculture _____

Is this a record of a single structure or group (give total number of structures): eight

Single: _____ Group: X _____ Number Structures in Group: eight

List Observed Structures: residence, metal-clad pole barn, wood garage, 2nd wood sided pole barn with four aluminum storage bins surrounding it, outhouse behind residence

Residence Detail

Style: Gabled EI

Wall materials: vinyl siding

Roof materials: asphalt

Foundation materials: concrete (visually)

Other distinguishing features: rear addition

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: residence has addition in rear – to west.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): 2nd pole barn, barely visible, four aluminum storage bins, wooden outhouse behind residence and garage.

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-5-3: 319 Noe Road – Garage, Outhouse



MA-5-3: 319 Noe Road – Residence, Pole Barns, Bins

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 5-4 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 803 Noe Road. _____

Lat/Long: 42.317598/-88.667468 _____

Primary Use: Residential/agriculture _____

Is this a record of a single structure or group (give total number of structures): four

Single: _____ Group: X _____ Number Structures in Group: four

List Observed Structures: residence, metal-clad pole barn, wood garage, 2nd wood sided pole barn with four aluminum storage bins surrounding it, outhouse behind residence

Residence Detail

Style: Bungalow

Wall materials: vinyl siding

Roof materials: asphalt

Foundation materials: decorative concrete block

Other distinguishing features: clipped gabled roof; front facing road altered

Barn Detail

Style: Gambrel

Wall materials: wood

Roof materials: metal

Foundation materials: concrete

Other distinguishing features: extensions on N (milk house) and on S.

Any obvious Additions/Alterations: wood porch on front of house.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): wood sided shed with metal roof, metal sided garage with metal roof

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

circa 1930



MA-5-4: 803 Noe Road - Residence



MA-5-4: 803 Noe Road – Shed, Garage



MA-5-4: 803 Noe Road – Dairy Barn,
Attachments

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 5-5 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: No # Kishwaukee Valley Road. _____

Lat/Long: 42.313378/-88.67361 _____

Primary Use: Abandoned farmstead _____

Is this a record of a single structure or group (give total number of structures): three

Single: _____ Group: X _____ Number Structures in Group: three

List Observed Structures: residence, old wooden crib, metal-clad pole barn _____

Residence Detail

Style: Foursquare

Wall materials: wood clapboard

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: empty-abandoned

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): post 1970 pole barn – not photographed ; partial corn crib

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-5-5: Kishwaukee Valley Road – Residence



MA-5-5: Kishwaukee Valley Road – Partial Crib

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 5-6 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: No # Oleson Road. _____

Lat/Long: 42.319851/-88.685106 _____

Primary Use: Residential/Agriculture _____

Is this a record of a single structure or group (give total number of structures): six

Single: _____ Group: Number Structures in Group: six

List Observed Structures: residence, tall concrete tile silo, long, low wood/concrete shed, old wooden crib, metal-clad pole barn

Residence

Style: No style

Wall materials: unknown

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: wrap-around front porch

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): vinyl-sided coop, tall concrete tile silo to S, half wood-half concrete sided shed N of silo. Outbuilding E of pole barn not visible- not photographed.

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-5-6: Oleson Road – Silo, Shed




MA-5-6: Oleson Road – Residence, Wire Storage Bins



MA-5-6: Oleson Road – Pole Barn, Chicken Coop

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 6



Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 6-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 25107 Tomlin Road _____

Lat/Long: 42.32757/-88.687541 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures): One

Single: _____ Group: _____ Number Structures in Group:

List Observed Structures: residence with attached garage _____

Residence Detail

Style: Gabled E1

Wall materials: vinyl siding

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: addition, attached garage

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: house is either a Front Gabled with two additions, or a Gabled E11 with an addition on E side.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-6-1: 25107 Tomlin Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 6-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 26084 Kishwaukee Valley Road _____

Lat/Long: 42.313402/-88.70533 _____

Primary Use: Residential/Agriculture _____

Is this a record of a single structure or group (give total number of structures): six

Single: _____ Group: X _____ Number Structures in Group: three

List Observed Structures: residence, garage, metal-clad pole barn _____

Residence Detail

Style: Upright and Wing

Wall materials: alum/vinyl siding

Roof materials: asphalt

Foundation materials: fieldstone/limestone

Other distinguishing features: enclosed front porch

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: front porch enclosed, newer concrete foundation; second floor addition to wing

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): garage: vinyl siding, asphalt roof, concrete foundation

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-6-2: 26084 Kishwaukee Valley Road - Residence



MA-6-2: 26084 Kishwaukee Valley Road – Garage,
Pole Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/8/14_____ Survey Number: MA 6-3 Surveyor Name: C. Flynn _____

Current Property or Structure Name: _____

Address: 11933 County Line Road _____

Lat/Long: 42.327597/-88.705316 _____

Primary Use: Residential/Agriculture _____

Is this a record of a single structure or group (give total number of structures): seven

Single: _____ Group: X _____ Number Structures in Group: seven

List Observed Structures: residence, crib with cupola, metal-clad barn, silo, metal-clad shed, wood garage, smaller wood outbuilding/shed _____

Residence Detail

Style: Upright and Wing

Wall materials: vinyl siding

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: enclosed front porch

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: front porch enclosed, one-story additions to rear (E)

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): wood garage, asphalt roof, wood shed, asphalt roof, larger metal clad barn, concrete foundation, metal clad shed, concrete tile silo on E side of metal clad barn.

Number of photos taken for this property*: five _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-6-3: 11933 County Line Road - Residence




MA-6-3: 11933 County Line Road - Crib



MA-6-3: 11933 County Line Road – Barn, Silo, Shed

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 7





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 7-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 1720 County Line Road _____

Lat/Long: 42.303726/-88.704853 _____

Primary Use: Residential/Agriculture _____

Is this a record of a single structure or group (give total number of structures): seven

Single: _____ Group: X _____ Number Structures in Group: four

List Observed Structures: residence with semi-attached garage, two pole barns, and storage bin complex _____

Residence Detail

Style: Upright and Wing

Wall materials: vinyl siding

Roof materials: asphalt

Foundation materials: concrete (visually)

Other distinguishing features: enclosed front porch

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: front porch enclosed, addition to N side and upper extension to wing

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): garage: vinyl, asphalt, concrete; metal clad pole barn with wood plank foundation; 2nd metal pole barn behind 1st (to E): concrete foundation; aluminum storage bin complex to S of driveway.

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-7-1: 1720 County Line Road– Barn, Bins, Garage



MA-7-1: 1720 County Line Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 7-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 1417 Olcott Road _____

Lat/Long: 42.307812/-88.691806 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures): One

Single: _____ Group: _____ Number Structures in Group:

List Observed Structures: garage/shed only _____

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): wood-sided garage/shed: unknown roof and foundation materials.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1908--1965



MA-7-2: 1417 Olcott Road - Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 7-3 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 1711 Olcott Road _____

Lat/Long: 42.303539/-88.694075 _____

Primary Use: Residential/Agriculture _____

Is this a record of a single structure or group (give total number of structures): three

Single: _____ Group: X _____ Number Structures in Group: three

List Observed Structures: residence, garage, aluminum storage bins (2) complex _____

Residence Detail

Style: Side Gabled

Wall materials: unknown

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: set way back

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): garage: wood siding, asphalt roof, foundation unknown. Complex of two aluminum storage bins (tops barely visible).

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-7-3: 1711 Olcott Road- Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 7-4 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 1614 Olcott Road _____

Lat/Long: 42.304706/-88.690889 _____

Primary Use: Residential/Agriculture _____

Is this a record of a single structure or group (give total number of structures): two

Single: _____ Group: Number Structures in Group: two

List Observed Structures: residence, large barn in state of collapse _____

Residence Detail

Style: Cross Gabled

Wall materials: vinyl, some wood trim
Roof materials: asphalt

Foundation materials: large field stones

Other distinguishing features: wood-framed front porch

Barn Detail

Style: No style

Wall materials: horizontal wood
Roof materials: missing

Foundation materials: unknown

Other distinguishing features: collapsing top down. Interior framing exposed.

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-7-4: 1614 Olcott Road - Residence



MA-7-4: 1614 Olcott Road - Barn

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 8





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 8-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 24319 Carmack Road _____

Lat/Long: 42.299103/-88.685246 _____

Primary Use: agriculture _____

Is this a record of a single structure or group (give total number of structures): One

Single: _____ Group: _____ Number Structures in Group:

List Observed Structures: garage/shed only _____

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): garage/shed: wood siding, some metal. Roof is asphalt over shake shingle. Foundation appears to be stone rubble.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1872-1892



MA-8-1: 24319 Carmack Road - Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 8-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 24314 Carmack Road _____

Lat/Long: 42.298865/-88.684734 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures): two

Single: _____ Group: x _____ Number Structures in Group: two

List Observed Structures: residence, small tool shed _____

Residence Detail

Style: Minimal Traditional

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: wood deck off SE corner

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: has been altered and added to.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): small wood tool shed - newer

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1920-1930



MA-8-2: 24314 Carmack Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 8-3 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 24208 Carmack Road _____

Lat/Long: 42.298865/-88.673294 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures): two

Single: _____ Group: x _____ Number Structures in Group: three

List Observed Structures: residence, garage, round roof barn _____

Residence Detail

Style: Gabled El

Wall materials: vinyl siding, stone face

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: wood framed front porch

Any obvious Additions/Alterations: covered rear patio

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): vinyl sided garage, asphalt roof

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style: Round Roofed

Wall materials: wood

Roof materials: asphalt.

Foundation materials: unknown

Other distinguishing features: window dormers in roof



MA-8-3: 24208 Carmack Road – Residence, Garage



MA-8-3: 24208 Carmack Road – Barn

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 9




Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 9-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 23612 Carmack Road _____

Lat/Long: 42.299151/-88.658817 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: x _____ Number Structures in Group: eight

List Observed Structures: residence, garage, large dairy barn, silo, smaller barn, 4 aluminum bins _____

Residence Detail

Style: Cross Gabled

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: enclosed front porch

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): garage/shed: vinyl sided, asphalt roof. Smaller barn: vinyl sided, asphalt roof. Silo is concrete tile

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style: Gabled dairy Barn

Wall materials: vinyl
Roof materials: metal

Foundation materials: unknown

Other distinguishing features:



MA-9-1: 23612 Carmack Road - Residence



MA-9-1: 23612 Carmack Road - Outbuildings



MA-9-1: 23612 Carmack Road – Barns, Silo

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 9-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 23215 Carmack Road _____

Lat/Long: 42.298961/-88.6568 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: x _____ Number Structures in Group: two

List Observed Structures: residence, garage, _____

Residence Detail

Style: Side Gabled

Wall materials: vinyl siding, wood board

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: possible corner front porch enclosed

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):Garage: wood siding, asphalt roof, concrete foundation.

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-9-2: 23215 Carmack Road– Residence, Garage

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 10




Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 10-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 23020 Carmack Road _____

Lat/Long: 42.303547/-88.646858 _____

Primary Use: Residential/Agriculture _____

Is this a record of a single structure or group (give total number of structures): two

Single: _____ Group: X _____ Number Structures in Group: two

List Observed Structures: residence, pole barn set way back, mostly obscured _____

Residence Detail

Style: unknown

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: Obscured

Barn Detail

Style: unknown

Wall materials: unknown
Roof materials: unknown

Foundation materials: unknown

Other distinguishing features:
Obscured

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-10-1: 23020 Carmack Road – Residence, Pole Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 10-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 22318 Carmack Road _____

Lat/Long: 42.299468/-88.633747 _____

Primary Use: Residential/Agriculture _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: seven

List Observed Structures: residence, four metal or vinyl-clad pole barns, one wood sided barn or shed

Residence Detail

Style: Upright and Wing

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style :

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: addition to west of residence

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): one pole barn to rear not visible

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1872-1892



MA-10-2: 23218 Carmack Road – Pole Barn Complex



MA-10-2: 23218 Carmack Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 10-3 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 1317 Hawthorn Road _____

Lat/Long: 42.299468/-88.633747 _____

Primary Use: Residential/Agriculture _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: eight

List Observed Structures: residence, three older wood-sided barns or sheds, one red low shed

Residence Detail

Style: unknown

Wall materials: vinyl

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features: mostly obscured by foliage

Barn Detail

Style: unknown

Wall materials: wood

Roof materials: metal

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations: addition to west of residence

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): S to N: low metal-clad red shed; vertical wood board-sided shed/garage, asphalt roof, concrete foundation; vertical wood board-sided barn or shed to N of main barn, shake shingle roof, concrete foundation.

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-10-3: 1317 Hawthorne Road - Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 10-4 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 22507 Kishwaukee Valley Road _____

Lat/Long: 42.312481/-88.636408 _____

Primary Use: Residential/Agriculture _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: ten plus

List Observed Structures: E to W: large asphalt and metal-clad pole barn; residence; smaller shed; large wood dairy barn with milk house and concrete silo, metal-clad pole barn; low and long wood-sided shed with asphalt roof; older barn with large cupola, shake shingle roof, vertical board siding, stone rubble and concrete foundation; two aluminum grain storage bins.

Residence Detail

Style: Front Gabled

Wall materials: wood shingle

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style: Gambrel

Wall materials: wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: has attached milk house and a silo

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): S to N: several structures not visible; possibly more storage bins

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-10-4: 22507 Kishwaukee Valley Road -
Residence



MA-10-4: 22507 Kishwaukee Valley Road –
Dairy Barn



MA-10-4: 22507 Kishwaukee Valley Road –
Barn, Silo, Sheds

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 10-5 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 22815 Kishwaukee Valley Road _____

Lat/Long: 42.312703/-88.639927 _____

Primary Use: Residential/Agriculture _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: ten plus (per google maps)

List Observed Structures: E to W: two large metal-clad pole barns; large dairy barn with large extension to the S and shed extension to the N; concrete tile silo on N side of barn; smaller wood and vinyl sided shed with asphalt roof; metal-clad pole barn S of shed; residence

Residence Detail

Style: Foursquare

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style: Gabled L Plan

Wall materials: vinyl/aluminum
Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: has large addition to S, shed extension to N, and concrete tile silo.

Any obvious Additions/Alterations: enclosed front porch with brick foundation

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): S to N: see observed structures

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-10-5: 22815 Kishwaukee Valley Road –
Barn, Silo




MA-10-5: 22815 Kishwaukee Valley Road -
Residence



MA-10-5: 22815 Kishwaukee Valley Road –
Outbuilding Complex

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 11





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 11-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 21703 Kishwaukee Valley Road _____

Lat/Long: 42.312545/-88.621109 _____

Primary Use: Residential/Agriculture _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: nine (per google maps)

List Observed Structures: E to W: residence; dairy barn with attached milk house; metal-clad pole barn; vinyl-clad garage with metal roof; metal-clad pole barn

Residence Detail

Style: Front Gabled

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Banked dairy barn

Wall materials: vinyl/aluminum
Roof materials: metal

Foundation materials: concrete

Other distinguishing features: attached milk house.

Any obvious Additions/Alterations: handicap wooden ramp to front door

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-11-1: 21703 Kishwaukee Valley Road -
Residence



MA-11-1: 21703 Kishwaukee Valley Road –
Barn, Milk House, Shed



MA-11-1: 21703 Kishwaukee Valley Road -
Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 11-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 1606 Hawthorn Road _____

Lat/Long: 42.305023/-88.626795 _____

Primary Use: Residential/Agriculture _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: two

List Observed Structures: residence; large barn

Residence Detail

Style: Upright and Wing

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: unknown, hidden by vinyl

Other distinguishing features: has been updated

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style: Gabled dairy barn

Wall materials: vinyl and wood
Roof materials: metal

Foundation materials: concrete

Other distinguishing features: has been updated



MA-11-2: 1606 Hawthorne Road– Residence



MA-11-2: 1606 Hawthorne Road – Barn, Outbuilding

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 11-3 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 1307 N. Rt.23_____

Lat/Long: 42.310768/-88.609285_____

Primary Use: Residential_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: Number Structures in Group: two

List Observed Structures: residence; garage

Residence Detail

Style: Minimal Traditional

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: hipped roof

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:



MA-11-3: 1307 North Route 23 – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 11-4 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 1501 N. Rt.23_____

Lat/Long: 42.30953/-88.609464_____

Primary Use: Residential_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: two

List Observed Structures: residence; garage

Residence Detail

Style: Ranch

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: hipped roof

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.

circa 1940-1960

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:



MA-11-4: 1501 North Route 23 – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 11-5 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 1513 N. Rt.23_____

Lat/Long: 42.30982/-88.609259_____

Primary Use: Residential_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: three

List Observed Structures: residence and garage, outbuilding _____

Residence Detail

Style: No style

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property*: one, of outbuilding only_____

* Attach Photo log, additional notes and map of resource location.

circa 1939-1965

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:



MA-11-5: 1513 North Route 23 – Outbuilding

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 11-6 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 1907 N. Rt.23_____

Lat/Long: 42.300992/-88.609092_____

Primary Use: Residential /Agriculture_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: seven (per google maps)

List Observed Structures: residence; concrete block smoke house; wood sided pump or spring house with asphalt roof and stone rubble/concrete foundation; small wood sided possible 2nd residence or guest cottage with asphalt roof and concrete foundation; wood-framed open sided pavilion building; barn with metal roof and siding and a metal water tank; garage with vinyl and wood siding, asphalt roof

Residence Detail

Style: Gabled EI

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: concrete-covered

Other distinguishing features: field stone front porch with wood columns

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*: five_____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style: Gabled

Wall materials: metal
Roof materials: metal

Foundation materials: unknown

Other distinguishing features:



MA-11-6: 1907 Route 23 - Residence




MA-11-6: 1907 Route 23 – Pump, Springhouse, Shed



MA-11-6: 1907 Route 23 - Barn

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 12





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 12-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: No # 2010 N. Rt.23 per google maps _____

Lat/Long: 42.299183/-88.607955 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: four (per google maps)

List Observed Structures: residence; collapsed wooden barn; garage or shed with metal roof and vinyl siding.

Residence Detail

Style: No style

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: large front porch and roof added

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): per google maps two large collapsing barns may be behind residence (to E) with shake shingle roofs – not observed.

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1908-1939

Barn Detail

Style:

Wall materials: wood
Roof materials: possibly shake shingle

Foundation materials: unknown

Other distinguishing features: collapsed



MA-12-1: Route 23 - Residence



MA-12-1: Route 23 - Barn



MA-12-1: Route 23 – Metal Vinyl Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 12-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 1750 N. Rt.23_____

Lat/Long: 42.304428/-88.608052_____

Primary Use: Residential_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three

List Observed Structures: residence; two small aluminum Quonset-style sheds

Residence Detail

Style: No style

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: unknown/concrete

Other distinguishing features:

Any obvious Additions/Alterations: garage added to front of house, raised porch to S

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.

circa 1965-1970

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:



MA-12-2: 1750 North Route 23 - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 12-3 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 1718 N. Rt.23_____

Lat/Long: 42.303123/-88.607927_____

Primary Use: Residential/agricultural_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: seven

List Observed Structures: residence; concrete barn foundation/slab; vinyl/metal-clad outhouse; vinyl/metal-clad shed or coop; brick and concrete smoke house; small metal-clad shed behind house; wood-sided milk house with asphalt roof and concrete foundation just S of barn slab; concrete tile silo just W of milk house.

Residence Detail

Style: No style

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: field stone

Other distinguishing features: Empty

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: addition to S side of house; originally may have been Gabled EI

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*: seven_____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-12-3: 1718 North Route 23 - Residence



MA-12-3: 1718 North Route 23 – Concrete Barn Pad



MA-12-3: 1718 North Route 23 – Outhouse, Shed



MA-12-3: 1718 North Route 23 - Smokehouse



MA-12-3: 1718 North Route 23 – Lean-to Shed



MA-12-3: 1718 North Route 23 – Silo, Milk or Spring House

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 12-4 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 1210 N. Rt.23_____

Lat/Long: 42.310962/-88.608006_____

Primary Use: Residential/agricultural_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: seven plus (per google maps)

List Observed Structures: residence; metal-clad barn to N; concrete block garage with asphalt roof; metal-clad lean-to style shed or barn.

Residence Detail

Style: Side Gabled

Wall materials: wood board

Roof materials: asphalt house, metal porch

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: wrap-around porch

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*: five_____

* Attach Photo log, additional notes and map of resource location.

circa 1908-1939

Barn Detail

Style: unknown

Wall materials: metal

Roof materials: metal

Foundation materials: unknown

Other distinguishing features:



MA-12-4: 1210 North Route 23 - Residence



MA-12-4: 1210 North Route 23 - Barn



MA-12-4: 1210 North Route 23 - Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 12-5 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 20917 Kishwaukee Valley Road. per google maps: 20777-21043 Kishwaukee Valley Road _____

Lat/Long: 42.312493/-88.605857 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: seven plus (per google maps)

List Observed Structures: multiple one-story structures including at least one residence and a four-car garage; attached five-sectioned and gabled chicken or poultry barn with numerous roof vents; an ivy-covered stone mushroom shaped structure. Per google maps a larger two-story residence is located in the SW corner of property out of sight.

Residence Detail

Style: No style

Wall materials: vertical wood board

Roof materials: asphalt shingles

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

circa 1872-1892

Barn Detail

Style: No style

Wall materials: asphalt and asbestos shingles over wood

Roof materials: asphalt over shake

Foundation materials: unknown

Other distinguishing features: five gabled sections



MA-12-5: 20917 Kishwaukee Valley Road –
Residence, Garage



MA-12-5: 20917 Kishwaukee Valley Road –
Coops, Barns



MA-12-5: 20917 Kishwaukee Valley Road –
Stone Structure, Log Outbuilding

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 12-6 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 1915 Deer Pass Road **Note: Deer Pass is correct. Deer Path is not correct** _____

Lat/Long: 42.300534/-88.589118 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group:

List Observed Structures: residence

Residence Detail

Style: Front Gabled

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: gable on S side of roof

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style:

Wall materials:
Roof materials:


Foundation materials:

Other distinguishing features:



MA-12-6: 1915 Deerpass Road - Residence

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 13





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 13-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 21022 Collins Road _____

Lat/Long: 42.298381/-88.607333 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: 11 plus

List Observed Structures: smaller residence; large dairy barn, collapsing; attached milk house; concrete tile silo; three smaller wooden sheds and one wood sided garage with asphalt roofs; metal-clad pole barn; one possible wood sided smoke house. Resident insisted main residence less than fifty years old. Allowed photos of barn.

Residence Detail

Style: Gabled EI

Wall materials: wood
Roof materials: asphalt

Foundation materials: concrete visible

Other distinguishing features: one story

Barn Detail

Style: Gabled Dairy

Wall materials: vertical wood
Roof materials: shake shingles

Foundation materials: high field stone

Other distinguishing features: wood peg construction.

Any obvious Additions/Alterations: enclosed porch, side porch, may not originally be EI shaped

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*: nine _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-13-1: 21022 Collins Road- Residence



MA-13-1: 21022 Collins Road – Dairy Barn



MA-13-1: 21022 Collins Road – Silo, Milk House

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 13-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 2213 Deer pass Road _____

Lat/Long: 42.296342/-88.589183 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group:

List Observed Structures: residence

Residence Detail

Style: Unknown

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: mostly obscured by foliage

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1908-1939

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:



MA-13-2: 2213 Deerpass Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 13-3 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 2406 Rt. 23, 2320 IL. RT. 23 per google _____

Lat/Long: 42.293812/-88.607207 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two

List Observed Structures: residence and garage

Residence Detail

Style: Bungalow

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: partly obscured by foliage; pyramid roof

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1930

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:



MA-13-3: 2406 Route 23 - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/9/14_____ Survey Number: MA 13-4 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 2804 IL. Rt.23; 2452-2608 IL. Rt.23 per google _____

Lat/Long: 42.288183/-88.608229 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: ten

List Observed Structures: residence; large dairy barn with two attached milk houses; concrete tile silo; wood-sided crib with metal roof; two wood sided coop buildings with metal roofs and concrete foundations; wood sided outhouse; metal frame windmill with pump; wood sided garage with asphalt roof; small metal shed.

Residence Detail

Style: Gabled E1

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: large fieldstones

Other distinguishing features:

Any obvious Additions/Alterations: front and back porches enclosed

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*: ten _____

* Attach Photo log, additional notes and map of resource location.

circa 1892-1908

Barn Detail

Style: Round roof Dairy

Wall materials: vertical wood
Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features



MA-13-4: 2804 Route 23 – Shed, Garages, Coop



MA-13-4: 2804 Route 23 - Outhouse



MA-13-4: 2804 Route 23 – Windmill, Pump, Crib, Silo




MA-13-4: 2804 Route 23 - Garage



MA-13-4: 2804 Route 23 - Residence

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 14



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/12/14_____ Survey Number: MA 14-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 2303 IL. Rt. 23_____

Lat/Long: 42.288183/-88.608229_____

Primary Use: Residential/Agriculture_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: four per google map

List Observed Structures: residence; garage; large barn; small wooded shed

Residence Detail

Style: Side Gabled

Wall materials: wood
Roof materials: asphalt

Foundation materials: stone

Other distinguishing features: partly obscured by foliage

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*: four_____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style: Gabled dairy barn

Wall materials: vertical wood boards
Roof materials: asphalt over shake
shingles

Foundation materials: concrete

Other distinguishing features:



MA-14-1: 2303 Route 23 – Dairy Barn



MA-14-1: 2303 Route 23 – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/12/14_____ Survey Number: MA 14-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name:_____

Address: 2521 IL. Rt. 23 (2913-2955 IL. 23 per google)_____

Lat/Long: 42.291427/-88.608754_____

Primary Use: Residential/Agriculture_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: Number Structures in Group: eight observed

List Observed Structures: residence; wooden shed with metal roof; wood-sided shed/barn, listing; three additional metal clad pole barns or sheds; two small wood-sided coops with concrete foundations, asphalt roofs.

Residence Detail

Style: Gabled EI

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

Any obvious Additions/Alterations: addition to rear

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*: five_____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style: Gabled Hay

Wall materials: red-painted wood boards
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: single bay



MA-14-2: 2521 Route 23 - Residence



MA-14-2: 2521 Route 23 - Sheds



MA-14-2: 2521 Route 23 - Barn



MA-14-2: 2521 Route 23 – Metal Sheds



MA-14-2: 2521 Route 23 - Coops

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/12/14_____ Survey Number: MA 14-3 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 2807 IL. Rt. 23 (2957-2975 IL. 23 per google) _____

Lat/Long: 42.287868/-88.608825 _____

Primary Use: Residential/Agriculture _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: five observed

List Observed Structures: residence; wood-sided garage; two aluminum storage bins; metal clad pole barn, mostly obscured.

Residence Detail

Style: Cape Cod

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features:

Any obvious Additions/Alterations: dormer

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1940-1960

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features: obscured



MA-14-3: 2807 Route 23 - Residence



MA-14-3: 2807 Route 23 – Bins, Garage, Pole Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/12/14_____ Survey Number: MA 14-4 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 2917 IL. Rt. 23 (2957-2975 IL. 23 per google) _____

Lat/Long: 42.285838/-88.609136 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: three observed

List Observed Structures: residence with attached garage; wood tree house; wooden shed.

Residence Detail

Style: No style

Wall materials: stone and wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: may be modern

Any obvious Additions/Alterations: remodeled? Unknown age

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1965

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:




MA-14-4: 2917 Route 23 - Residence



MA-14-4: 2917 Route 23 – Tree House, Shed

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 15





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/12/14_____ Survey Number: MA 15-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 2203 Hawthorn Road (2957-2975 IL. 23 per google)_____

Lat/Long: 42.296683/-88.628663_____

Primary Use: Residential/agricultural_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three

List Observed Structures: residence; pole barn; wood-sided shed/garage with asphalt roof.

Residence Detail

Style: Gabled EI

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: stone original; concrete addition

Other distinguishing features:

Any obvious Additions/Alterations: addition to front

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*: three_____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:



MA-15-1: 2203 Hawthorne Road - Residence



MA-15-1: 2203 Hawthorne Road - Barns

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/12/14_____ Survey Number: MA 15-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name:_____

Address: No # Carmack Road (22517 Carmack per google)_____

Lat/Long: 42.296627/-88.63742_____

Primary Use: Residential/agricultural_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group:

List Observed Structures: residence

Residence Detail

Style: No style

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: large addition to E side

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property*: one_____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:



MA-15-2: Carmack Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/12/14_____ Survey Number: MA 15-3 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 22919 Carmack Road (22517 Carmack per google) _____

Lat/Long: 42.296485/-88.639083 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: 16 per google map

List Observed Structures: wood sided barn; metal-clad pole barn; wood-sided crib

Residence Detail

Style: unknown

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features: obscured

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): wood-sided crib; many structures per google – not visible.

Number of photos taken for this property*: five _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style: unknown

Wall materials: red-painted wood

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: shed-angled roof line - obscured



MA-15-3: 22919 Carmack Road – Red Wood Barn



MA-15-3: 22919 Carmack Road – Pole Barn



MA-15-3: 22919 Carmack Road – Partial Crib

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/12/14_____ Survey Number: MA 15-4 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 22204 River Road _____

Lat/Long: 42.284415/-88.630333 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: five

List Observed Structures: residence; wood sided dairy barn; detached wood-sided milk house; wood-sided garage/shed; small well structure, wood on concrete pad

Residence Detail

Style: Colonial Revival

Wall materials: brick
Roof materials: asphalt

Foundation materials: limestone

Other distinguishing features:

Barn Detail

Style: Round roof

Wall materials: red-painted wood
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: addition to rear

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*: six _____

* Attach Photo log, additional notes and map of resource location.

circa 1920-1940



MA-15-4: 22204 River Road - Barn



MA-15-4B 22204 River Road – Residence, Well



MA-15-4: 22204 River Road - Shed



MA-15-4: 22204 River Road – Milk House

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/12/14_____ Survey Number: MA 15-5 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 22718 River Road _____

Lat/Long: 42.284405/-88.64066 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: five

List Observed Structures: residence with attached garage; numerous newer aluminum grain bins/silos etc. behind

Residence Detail

Style: Colonial Revival

Wall materials: brick
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: addition to rear, attached garage

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*: one _____

* Attach Photo log, additional notes and map of resource location.

circa 1920-1940

Barn Detail

Style:

Wall materials:
Roof materials:


Foundation materials:

Other distinguishing features



MA-15-5: 22718 River Road - Residence

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 16





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/12/14_____ Survey Number: MA 16-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 2544 Cox Road _____

Lat/Long: 42.291929/-88.654488 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: 14 per google

List Observed Structures: residence; two-part wood shed with metal roof; brick silo; large dairy barn with ramp; detached wood-sided milk house with asphalt roof; 2nd large wood-sided barn behind first, barely visible; two wood-sided garages; four aluminum bins

Residence Detail

Style: American Foursquare

Wall materials: wood and vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style: Gambrel dairy

Wall materials: vertical wood boards

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: ramp

Any obvious Additions/Alterations: enclosed porch with stone foundation walls

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*: nine _____

* Attach Photo log, additional notes and map of resource location.

circa 1892-1908



MA-16-1: 2544 Cox Road - Residence



MA-16-1: 2544 Cox Road – Silo, Dairy Barn, Milk House



MA-16-1: 2544 Cox Road – Shed, Bins



MA-16-1: 2544 Cox Road - Garages

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/12/14_____ Survey Number: MA 16-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 2403 Cox Road _____

Lat/Long: 42.284405/-88.64066 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three

List Observed Structures: residence; detached garage; new pole barn.

Residence Detail

Style: Cross Gabled

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: stone

Other distinguishing features:

Any obvious Additions/Alterations: addition to S side with concrete foundation

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*: two _____

* Attach Photo log, additional notes and map of resource location.

circa 1908-1939

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features



MA-16-2: 2403 Cox Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/12/14_____ Survey Number: MA 16-3 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 24013 Carmack Road _____

Lat/Long: 42.298343/-88.669779 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: 18 per google

List Observed Structures: residence; detached three-bay garage; E-W: metal pole barn; open front machine shed; large dairy barn with attached milk house and concrete tile silo; smaller wood-sided barn with metal roof to S of barn; wood-sided shed with asphalt roof; 2nd metal pole barn; numerous aluminum storage bins.

Residence Detail

Style: Bungalow

Wall materials: brick and vinyl

Roof materials: asphalt

Foundation materials: brick

Other distinguishing features: hipped and dormered roof

Barn Detail

Style: Gabled dairy

Wall materials: vertical wood boards

Roof materials: metal

Foundation materials: concrete

Other distinguishing features: shed extensions to E side and S side

Any obvious Additions/Alterations: enclosed porch with stone foundation walls

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*: eight _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-16-3: 24013 Carmack Road – Dairy Barn, Silo, Shed



MA-16-3: 24013 Carmack Road – Shed, Pole Barn, Bins




MA-16-3: 24013 Carmack Road – Garage, Bins



MA-16-3: 24013 Carmack Road - Residence

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 17





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/12/14_____ Survey Number: MA 17-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: No # Carmack Road _____

Lat/Long: 42.29818/-88.669626 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: 8 per google

List Observed Structures: residence; metal-clad pole barn with wood plank foundation attached to larger dairy barn; metal-clad shed; small wooden shed; two-bay wood sided garage.

Residence Detail

Style: Gabled EI

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: stone

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*: six _____

* Attach Photo log, additional notes and map of resource location.

circa 1892-1908

Barn Detail

Style: Round roof dairy

Wall materials: metal
Roof materials: metal

Foundation materials: concrete

Other distinguishing features:



MA-17-1: Carmack Road – Barn, Silo, Pole Barn



MA-17-1: Carmack Road – Wire Bin, Shed, Small Shed, Garage



MA-17-1: Carmack Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/12/14_____ Survey Number: MA 17-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 24319 Carmack Road _____

Lat/Long: 42.298306/-88.672709 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: 14 per google

List Observed Structures: residence; metal-clad barn; two attached concrete tile silos; wood sided cattle shed with metal roof; small wood shed; metal clad and concrete block cattle sheds; metal clad barn to S.

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete block visible

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*: five _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style: Gabled hay barn

Wall materials:

Roof materials: metal

Foundation materials: concrete

Other distinguishing features:



MA-17-2: 24319 Carmack Road - Residence



MA-17-2: 24319 Carmack Road – Barns, Silos, Sheds



MA-17-2: 24319 Carmack Road - Sheds



MA-17-2: 24319 Carmack Road - Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/12/14_____ Survey Number: MA 17-3 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 2906 Miller Road _____

Lat/Long: 42.286374/-88.686077 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: four

List Observed Structures: residence; small shed; detached garage; metal-clad pole barn with wood plank foundation.

Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



MA-17-3: 2906 Miller Road - Residence



MA-17-3: 2906 Miller Road – Pole Barn, Garage

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 18





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/12/14_____ Survey Number: MA 18-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 2717 Miller Road (1218 Miller per google) _____

Lat/Long: 42.288314/-88.686678 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: eight

List Observed Structures: residence; large dairy barn with attached concrete tile silo; attached concrete block milk house; metal clad shed extension to W side of barn; metal clad pole barn W of barn extension; small animal shed to N; small lean-to animal shed to W.

Residence Detail

Style: Italianate

Wall materials: vinyl with wood trim

Roof materials: asphalt

Foundation materials: limestone/fieldstone

Other distinguishing features: wrap-around porch

Any obvious Additions/Alterations: addition to rear (W)

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*: five _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style: Round roof Dairy

Wall materials: vinyl/metal

Roof materials: metal

Foundation materials: concrete

Other distinguishing features: attached milk house and silo



MA-18-1: 2717 Miller Road - Shed



MA-18-1: 2717 Miller Road – Barn, Silo, Milk House



MA-18-1: 2717 Miller Road - Residence



MA-18-1: 2717 Miller Road – Pole Barn, Shed Extension

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/12/14_____ Survey Number: MA 18-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 2410 County Line Road _____

Lat/Long: 42.289723/-88.704815 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: 12 per google maps

List Observed Structures: three metal clad outbuildings/pole barn; one metal clad barn with wood plank foundation; concrete block garage to S.

Residence Detail

Style: new – not photographed

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*: three _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style: Gambrel

Wall materials: vinyl/metal

Roof materials: metal

Foundation materials: wood plank

Other distinguishing features:



MA-18-2: 2410 County Line Road -
Outbuildings



MA-18-2: 2410 County Line Road – Barn, Pole
Barn



MA-18-2: 2410 County Line Road - Garage

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 19





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 19-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 3518 County Line Road _____

Lat/Long: 42.277333/-88.705257 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: 10 per google

List Observed Structures: residence; horse barn with a metal clad shed and a pole barn attached to N side; small horse hay shed; metal clad machine barn/shed; vinyl sided tack shop with metal roof; small metal Quonset hut; large wood sided horse barn with metal shed extension and metal roof; larger metal clad pole barn on E end of complex.

Residence Detail

Style: Queen Anne

Wall materials: vinyl with wood trim

Roof materials: asphalt

Foundation materials: limestone

Other distinguishing features: deck on E side

Any obvious Additions/Alterations: addition to rear (W)

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*: seven _____

* Attach Photo log, additional notes and map of resource location.

circa 1872-1892

Barn Detail

Style: Gabled livestock

Wall materials: vinyl/metal

Roof materials: metal

Foundation materials: limestone

Other distinguishing features: attached shed and pole barn



MA-19-1: 3518 County Line Road - Residence



MA-19-1: 3518 County Line Road – Horse Barn, Shed, Pole Barn



MA-19-1: 3518 County Line Road – Barn, Tack Shop, Small Horse, Barn, Pole Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 19-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 26006 River Road, Garden Prairie _____

Lat/Long: 42.276741/-88.704166 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two

List Observed Structures: residence; pole barn

Residence Detail

Style: Upright and Wing

Wall materials: limestone

Roof materials: asphalt

Foundation materials: limestone

Other distinguishing features: wood and stone trim, brick chimney

Any obvious Additions/Alterations: enclosed front porch; large addition to rear (S)

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*: four _____

* Attach Photo log, additional notes and map of resource location.

circa 1850-1850

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



MA-19-2: River Road - Residence



MA-19-2: River Road – Rear Extension, Pole Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 19-3 Surveyor Name: C. Flynn_____

Current Property or Structure Name: Sisson Farms_____

Address: 2570 River Road (25101 River Rd. per google)_____

Lat/Long: 42.277285/-88.698227_____

Primary Use: Residential/agricultural_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: Number Structures in Group: eight

List Observed Structures: residence; garage; barn with cupola; metal frame windmill; metal clad pole barn; three aluminum storage bins/silos.

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: brick face?

Other distinguishing features: has been added to and updated.

Barn Detail

Style: Gabled

Wall materials: asbestos shingle

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations: enclosed front porch; large addition to rear (S)

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* three_____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-19-3: 2570 River Road - Residence



MA-19-3: 2570 River Road – Barn, Windmill



MA-19-3: 2570 River Road – Garage, Bins, Pole Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 19-4 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 22512 River Road _____

Lat/Long: 42.277257/-88.695256 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: four

List Observed Structures: residence; garage; small shed; barn.

Residence Detail

Style: Cape Cod

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Round roof

Wall materials: wood
Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: rounded roof

Any obvious Additions/Alterations: enclosed front porch; small addition to rear (N)

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* three _____

* Attach Photo log, additional notes and map of resource location.

circa 1939-1965



MA-19-4: 22512 River Road - Residence



MA-19-4: 22512 River Road – Garage, Shed



MA-19-4: 22512 River Road – Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 19-5 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 25312 River Road _____

Lat/Long: 42.277227/-88.692474 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: seven

List Observed Structures: residence; barn with attached milk house and a metal extension; two concrete tile silos; 2nd wood sided barn to the E, metal shed in SE.

Residence Detail

Style: Upright and Wing

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: limestone

Other distinguishing features:

Barn Detail

Style: Gabled

Wall materials: asbestos shingle
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: enclosed front porch; small addition to rear (N)

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* five _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-19-5: 25312 River Road - Residence



MA-19-5: 25312 River Road – Barn, Silo, Milk House



MA-19-5: 25312 River Road - Barn



MA-19-5: 25312 River Road – Metal Shed, Barns

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 19-6 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 25208 River Road _____

Lat/Long: 42.280024/-88.688453 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: nine

List Observed Structures: residence; small residence (rt. In photo E); small metal clad shed (L in photo E); 2 metal clad sheds/barn to N (photo F); small Quonsett hut; concrete silo; concrete tile silo; large round barn.

Residence Detail

Style: Gabled EI

Wall materials: asphalt over wood clapboard

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*16 _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style: Round barn

Wall materials: asbestos shingle over wood

Roof materials: gone/collapsed

Foundation materials: large field stones

Other distinguishing features: collapsing



MA-19-6: 25208 River Road - Residence



MA-19-6: 25208 River Road – Small Residence, Shed



MA-19-6: 25208 River Road – Metal Clad Sheds



MA-19-6: 25208 River Road – Quonsett Shed, Silos



MA-19-6: 25208 River Road – Round Barn, Ramp, Milk House



MA-19-6: 25208 River Road –Pole Barn

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 20





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 20-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 24917 River Road _____

Lat/Long: 42.279754/-88.684391 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: five

List Observed Structures: residence; large dairy barn; wood sided crib with asphalt roof and large cupola; 2nd wood sided barn behind (to S); wood sided garage with asphalt roof.

Residence Detail

Style: Side Gabled

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: concrete visible

Other distinguishing features:

Barn Detail

Style: Gabled dairy

Wall materials: wood
Roof materials: metal

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations: screened porch to W

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*five _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-20-1: 24917 River Road – Dairy Barn



MA-20-1: 24917 River Road – Residence, Crib, Garage, Pole Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 20-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 24811 River Road _____

Lat/Long: 42.279992/-88.681773 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three

List Observed Structures: residence; vinyl and wood garage with metal roof; small apartment behind garage

Residence Detail

Style: Bungalow

Wall materials: vinyl
Roof materials: metal

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations: enclosed front porch

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*two _____

* Attach Photo log, additional notes and map of resource location.

circa 1930-1940

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:



MA-20-2: 24811 River Road – Residence



MA-20-2: 24811 River Road – Garage, Small
Apartment

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 20-3 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 225050 River Road (per google) _____

Lat/Long: 42.281008/-88.679413 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three

List Observed Structures: two aluminum silos; one concrete silo

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*one _____

* Attach Photo log, additional notes and map of resource location.

circa 1950-1970

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



MA-20-3: 225050 River Road - Bins

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 20-4 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 24605 River Road _____

Lat/Long: 42.280159/-88.677329 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two

List Observed Structures: residence; detached garage barely visible

Residence Detail

Style: Greek Revival

Wall materials: vinyl and wood
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: two-story main; one-story wings E and W. Carved front porch columns

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* five _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:



MA-20-4: 24605 River Road– Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 20-5 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 24414 River Road _____

Lat/Long: 42.280825/-88.6741 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group:

List Observed Structures: residence and attached garage

Residence Detail

Style: American Foursquare

Wall materials: vinyl and wood
Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: enclosed passage connecting house and garage. Rear porch.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* two _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-20-5: 24414 River Road– Residence, Garage

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 21





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 21-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 23918 River Road _____

Lat/Long: 42.281274/-88.664899 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: five

List Observed Structures: residence; pole barn #1 W of house; Pole barn #2 N of house; wooden shed with metal roof; concrete block smoke house. _____

Residence Detail

Style: Greek Revival

Wall materials: brick
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: brick detail

Any obvious Additions/Alterations: enclosed front porch

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*seven_____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-21-1: 23918 River Road – Pole Barn, Shed



MA-21-1: 23918 River Road – Residence, Pole Barn



MA-21-1: 23918 River Road – Smoke House

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 21-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name:_____

Address: 3808 Thorne Road_____

Lat/Long: 42.273732/-88.663638_____

Primary Use: Residential/agricultural_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group:_____ Number Structures in Group:

List Observed Structures: barn only – residence is new

Residence Detail

Style: new

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* one_____

* Attach Photo log, additional notes and map of resource location.

circa 1965-1978

Barn Detail

Style: Unknown

Wall materials: metal over wood
Roof materials: metal

Foundation materials: wood plank

Other distinguishing features: shed extensions N and S



MA-21-2: 3808 Thorne Road - Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 21-3 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 3608 Thorne Road _____

Lat/Long: 42.281274/-88.664899 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: five-including milk house

List Observed Structures: N-S: metal clad pole barn with wood plank foundation; residence; dairy barn with attached milk house and extension off SE corner; smaller metal clad barn with shed extension

Residence Detail

Style: American Foursquare

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: concrete
Other distinguishing features:

Barn Detail

Style: Gabled

Wall materials: vertical wood
Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: attached milk house and large extension on SE corner

Any obvious Additions/Alterations: addition to front, screened porch N side.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*seven _____

* Attach Photo log, additional notes and map of resource location.

circa 1872-1892



MA-21-3: 3608 Thorne Road –Barn, Shed



MA-21-3: 3608 Thorne Road –Barn



MA-21-3: 3608 Thorne Road – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 21-4 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 23816 River Road _____

Lat/Long: 42.281274/-88.664899 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: six per google

List Observed Structures: residence; 3 connected wood-sided outbuildings with metal roofs and concrete foundations; large dairy barn with connected concrete tile silo; small wood-sided shed in NE corner

Residence Detail

Style: Side Gabled

Wall materials: asbestos tile

Roof materials: asphalt

Foundation materials: limestone

Other distinguishing features:

Barn Detail

Style: Gabled dairy

Wall materials: metal, some wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: attached concrete tile silo.

Any obvious Additions/Alterations: additions to front and rear (N and S)

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*seven _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-21-4: 23816 River Road – Barn, Coop



MA-21-4: 23816 River Road – Dairy Barn, Silo



MA-21-4: 23816 River Road – Small Shed



MA-21-4: 23816 River Road – Residence,
Addition, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 21-5 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: No # River Road (23688 River Rd. per google) _____

Lat/Long: 42.281671/-88.659657 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: 3

List Observed Structures: residence with attached garage; small tool shed; concrete silo

Residence Detail

Style: Front Gabled

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features: attached garage

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* two _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:



MA-21-5: 23688 River Road – Residence, Silo

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 21-6 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 23308 River Road _____

Lat/Long: 42.282199/-88.652552 _____

Primary Use: Residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: 6 per google

List Observed Structures: residence; small metal clad shed/garage; metal pole barn; large dairy barn; detached wood sided milk house with concrete foundation; concrete tile silo

Residence Detail

Style: Upright and Wing

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: unknown Other
distinguishing features:

Barn Detail

Style: Gambrel L Plan

Wall materials: metal
Roof materials: metal

Foundation materials: unknown
Other distinguishing features:

Any obvious Additions/Alterations: addition or extension to W

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* six _____

* Attach Photo log, additional notes and map of resource location.

circa 1872-1892



MA-21-6: 23308 River Road – Residence



MA-21-6: 23308 River Road – Shed



MA-21-6: 23308 River Road – Pole Barn



MA-21-6: 23308 River Road – Dairy Barn, Silo, Milk House

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 22



Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 22-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name:_____

Address: 22905 River Road_____

Lat/Long: 42.283187/-88.643714_____

Primary Use: Residential_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group:

List Observed Structures: residence

Residence Detail

Style: No style

Wall materials: wood
Roof materials: asphalt

Foundation materials: stone

Other distinguishing features:

one story Gabled EI

Any obvious Additions/Alterations:

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* one_____

* Attach Photo log, additional notes and map of resource location.

circa 1908-1939



MA-22-1: 22905 River Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 22-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 22820 River Road _____

Lat/Long: 42.283941/-88.643395 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group:

List Observed Structures: residence

Residence Detail

Style: No style

Wall materials: vinyl and brick
Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: new or remodeled

Gabled EI style

Any obvious Additions/Alterations: **Note: red structure to extreme right unknown. May be foreshortening. Not shown on Google maps.**

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* one _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:



MA-22-2: 22820 River Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 22-3 Surveyor Name: C. Flynn_____

Current Property or Structure Name:_____

Address: 22509 River Road_____

Lat/Long: 42.283758/-88.636526_____

Primary Use: Residential/agricultural_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: 3

List Observed Structures: residence; two brick, ribbed silos, crumbling on E side

Residence Detail

Style: No style

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

single story gabled EI

Any obvious Additions/Alterations:

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* three_____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-22-3: 22509 River Road - Residence



MA-22-3: 22509 River Road – Brick Silos

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 23



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 23-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 22002 River Road _____

Lat/Long: 42.28381/-88.625904 _____

Primary Use: Residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: 1

List Observed Structures: residence; concrete pad and foundation wall to E; concrete pad N of house

Residence Detail

Style: Gabled EI

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: limestone

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* three _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:



MA-23-1: 22002 River Road - Residence



MA-23-1: 22002 River Road – Concrete Foundation

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 23-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 21804 River Rd. _____

Lat/Long: 42.283171/-88.622257 _____

Primary Use: residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group: 17 per google

List Observed Structures: main residence; metal clad pole barn; vinyl clad garage; vinyl shed with metal roof; several aluminum bins; concrete tile silo; brick silo; metal silo; dairy barn; open wood-sided animal shed with asphalt roof and concrete foundation. Aluminum storage bin and 2nd residence to E – possible converted barn?

Residence Detail

Style: Cross Gabled

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: limestone

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* five _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style: Gabled dairy

Wall materials: vertical wood board
Roof materials: metal

Foundation materials: poss. limestone

Other distinguishing features:



MA-23-2: 21804 River Road - Residence



MA-23-2: 21804 River Road – Pole Barn, Bins



MA-23-2: 21804 River Road – Dairy Barn, Shed, Silos



MA-23-2: 21804 River Road – Second Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 23-3 Surveyor Name: C. Flynn_____

Current Property or Structure Name:_____

Address: NE corner River Rd. and Elizabeth Rd._____

Lat/Long: 42.281536/-88.617804 **Note: coordinates are for residence just E of school**_____

Primary Use: Educational_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group:

List Observed Structures: Pringle School District # 139 school building

School Detail

Style: Front Gabled

Wall materials: limestone

Roof materials: shake shingle

Foundation materials: limestone

Other distinguishing features: wood and cut stone trim

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property* seven_____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



MA-23-3: Northeast Corner River Road & Elizabeth Road – Elizabeth Pringle School

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 23-4 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 21316 River Rd. _____

Lat/Long: 42.280514/-88.613612 _____

Primary Use: residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: six per google

List Observed Structures: residence; garage; wood-sided crib with cupola ; small wood-sided shed, both asphalt roofs; metal clad pole barn.

Residence Detail

Style: Gothic

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: lunknown

Other distinguishing features: center front gable

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* four _____

* Attach Photo log, additional notes and map of resource location.

circa 1850-1860

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:



MA-23-4: 21316 River Road – Barn,
Outbuilding



MA-23-4: 21316 River Road – Crib, Shed



MA-23-4: 21316 River Road – Residence,
Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14_____ Survey Number: MA 23-5 Surveyor Name: C. Flynn_____

Current Property or Structure Name: Prairie View Stock Farm_____

Address: 21118 River Rd._____

Lat/Long: 42.278797/-88.609924_____

Primary Use: residential/agricultural_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: Number Structures in Group: five

List Observed Structures: residence; dairy barn; attached wood sided milk house with asphalt roof and concrete foundation; concrete tile silo; metal clad garage residence.

Residence Detail

Style: Hall and Parlor

Wall materials: vinyl and wood
Roof materials: asphalt

Foundation materials: brick

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* five_____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style: Gabled dairy

Wall materials: wood
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:



MA-23-5: 21118 River Road - Residence




MA-23-5: 21118 River Road – Barn, Silos, Milk House



MA-23-5: 21118 River Road - Garage

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 24





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 24-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 21018 River Rd. _____

Lat/Long: 42.278265/-88.608156 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two

List Observed Structures: residence; vinyl sided garage with asphalt roof and concrete foundation.

Residence Detail

Style: American Foursquare

Wall materials: asbestos shingle
Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: enclosed front porch

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* one _____

* Attach Photo log, additional notes and map of resource location.

circa 1872-1892

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:



MA-24-1: 21018 River Road – Residence, Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 24-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 20916 River Rd. _____

Lat/Long: 42.277894/-88.606 _____

Primary Use: residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: seven

List Observed Structures: residence; dog kennel; two aluminum storage bins; two concrete tile silos; wood sided shed/possible early residence with shake shingle roof and a brick chimney; limestone and stone rubble probable barn foundation.

Residence Detail

Style: Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: enclosed front porch

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* three _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



MA-24-2: 20916 River Road – Residence, Dog Kennel



MA-24-2: 20916 River Road – Bins, Silos, Shed



MA-24-2: 20916 River Road – Limestone Foundation

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 24-3 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 20708 River Rd. _____

Lat/Long: 42.276858/-88.601601 _____

Primary Use: residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: seven

List Observed Structures: large dairy barn with attached milk house (barely visible); concrete tile silo; aluminum storage bin; metal clad pole barn to the NW; garage; newer looking residence; 2nd ivy covered concrete tile silo; Quonsett hut

Residence Detail

Style: Neo-Colonial

Wall materials: vinyl and brick

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: hipped roof

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* six _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style: Round Roof Dairy

Wall materials: wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: two metal roof vents/cupolas



MA-24-3: 20708 River Road – Shed, Barn, Silo, Bin



MA-24-3: 20708 River Road – Pole and Dairy Barns



MA-24-3: 20708 River Road - Residence



MA-24-3: 20708 River Road – Barns, Milk House, Shed, Silo

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 24-4 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 20708 River Rd. _____

Lat/Long: 42.276858/-88.601601 _____

Primary Use: residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: six per google

List Observed Structures: residence; garage; shed/2nd garage with asphalt roof and vinyl siding; metal clad pole barn; field stone smoke house E of pole barn

Residence Detail

Style: Upright and Wing

Wall materials: vinyl and wood
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: addition to W (left) side?

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* three _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:



MA-24-4: 20402 River Road - Residence



MA-24-4: 20402 River Road – Garage, Smokehouse,
Outbuildings

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 24-5 Surveyor Name: C. Flynn_____

Current Property or Structure Name: Deer Pass Farms_____

Address: NW corner River Rd. and Deer Pass Rd. _____

Lat/Long: 42.276102/-88.589984_____

Primary Use: agricultural_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group:

List Observed Structures: pole barn only

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property* one_____

* Attach Photo log, additional notes and map of resource location.

circa 1908-1939

Barn Detail


Style: pole barn

Wall materials: metal

Roof materials: metal


Foundation materials: unknown

Other distinguishing features: Sign: Deer Pass Farms



MA-24-5: Corner of River Road and Deepass at Deer Pass Farm – Pole Barn

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 25





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom




Township
Location

No Resources in Key Area





MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 26




Township
Location

No Resources in Key Area



MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 27



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 27-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name:_____

Address: 23104 West Railroad St. (23104 per google) _____

Lat/Long: 42.254927/-88.628037 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group:

List Observed Structures: residence only

Residence Detail

Style: Cape Cod

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property* one _____

* Attach Photo log, additional notes and map of resource location.

circa 1908-1939

Barn Detail

Style:

Wall materials:
Roof materials: l

Foundation materials:

Other distinguishing features:



MA-27-1: 23104 West Railroad Street - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 27-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name:_____

Address: N side West Railroad St. (22110 W Railroad per google) _____

Lat/Long: 42.254942/-88.628719 _____

Primary Use: residential_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: three per google

List Observed Structures: residence only

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations: addition to E side?

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property* one_____

* Attach Photo log, additional notes and map of resource location.

circa 1908-1939

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



MA-27-2: 22110 West Railroad Street - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 27-3 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 5010 Ritz Road _____

Lat/Long: 42.255445/-88.629348 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group

List Observed Structures: residence only

Residence Detail

Style: Cape Cod

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations: addition to front (W) and S sides

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property* one _____

* Attach Photo log, additional notes and map of resource location.

circa 1908-1939

Barn Detail

Style:

Wall materials:
Roof materials: I

Foundation materials:

Other distinguishing features:



MA-27-3: 5010 Ritz Road - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 27-4 Surveyor Name: C. Flynn_____

Current Property or Structure Name:_____

Address: 4501 Ritz Road _____

Lat/Long: 42.254875/-88.630099 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X _____ Number Structures in Group: five

List Observed Structures: residence; metal clad and wood shed; wooden coops with asphalt roof; dairy barn; concrete silo

Residence Detail

Style: Unknown - obscured

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* four _____

* Attach Photo log, additional notes and map of resource location.

circa 1908-1939

Barn Detail

Style: Gambrel dairy

Wall materials: vertical wood boards
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:



MA-27-4: 4501 Ritz Road - Residence



MA-27-4: 4501 Ritz Road – Shed, Coop, Barn, Silo

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 28



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 28-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name:_____

Address: 4609 Thorne Road _____

Lat/Long: 42.255445/-88.629348_____

Primary Use: residential_____

Is this a record of a single structure or group (give total number of structures):

Single: X _____ Group: _____ Number Structures in Group

List Observed Structures: concrete block storage building/garage. Asphalt, hipped roof.

Residence Detail

Barn Detail

Style: No residence observed

Style:

Wall materials:

Wall materials:

Roof materials:

Roof materials: I

Foundation materials:

Foundation materials:

Other distinguishing features:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property* one_____

* Attach Photo log, additional notes and map of resource location.

circa 1939-1965



MA-28-1: 4609 Thorne Road – Concrete Block Shed

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 29



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location


No Resources in Key Area

0 125 250 500 Meters

0 375 750 1,500 Feet



MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 30





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom




Township
Location

No Resources in Key Area



MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 31



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 31-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 25903 West Grant Highway _____

Lat/Long: 42.25156/-88.702401_____

Primary Use: residential/agricultural_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three standing

List Observed Structures: residence #1, S side; residence #2 S side; whitewashed concrete silo with asphalt roof; stone wall across front of residential property on N side of Grant Hwy; stone wall and part of stone foundation W, N, and E of concrete silo on N side of Grant Hwy.

Residence Detail

Style: Colonial Revival

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: set back

Barn Detail

Style: possible stone foundation only

Wall materials:
Roof materials:

Foundation materials: stone

Other distinguishing features:

Any obvious Additions/Alterations: Residence #2 appears to be similar in style to Residence #1

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* 11_____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-31-1: 25903 West Grant Highway - Residence



MA-31-1: 25903 West Grant Highway – Stone Wall, Iron Gates



MA-31-1: 25903 West Grant Highway – Second Residence



MA-31-1: 25903 West Grant Highway - Silo

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 31-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name:_____

Address: 25809 West Grant Highway _____

Lat/Long: 42.251883/-88.701105_____

Primary Use: residential/agricultural_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: two observed

List Observed Structures: residence N side of Grant Hwy.; vinyl clad garage

Residence Detail

Style: Cape Cod

Wall materials: wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* one_____

* Attach Photo log, additional notes and map of resource location.

circa 1908-1939

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



MA-31-2: 25809 West Grant Highway - Residence

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 32




Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 32-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name:_____

Address: 25013 West Grant Highway _____

Lat/Long: 42.251341/-88.685895_____

Primary Use: residential/agricultural_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: Number Structures in Group: four

List Observed Structures: residence; two aluminum storage bins; metal/vinyl clad pole barn;

Residence Detail

Style: I House

Wall materials: wood
Roof materials: asphalt

Foundation materials: stone

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* two_____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:



MA-32-1: 25013 West Grant Highway – Residence,
Pole Barn, Bins

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 32-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name:_____

Address: 15320 Burma Road _____

Lat/Long: 42.250924/-88.686297 _____

Primary Use: residential/agricultural_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: 2-3

List Observed Structures: residence; scale office; pole barn and bins shared with 25013 W. Grant Hwy (MA-32-1)

Residence Detail

Barn Detail

Style: Side gabled

Style:

Wall materials: vinyl
Roof materials: asphalt

Wall materials:
Roof materials:

Foundation materials: unknown

Foundation materials:

Other distinguishing features:

Other distinguishing features:

Any obvious Additions/Alterations: both residence and scale office may be less than 50 years old.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* two_____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-32-2: 15320 Burma Road – Residence, Pole Barn



MA-33-2: 15320 Burma Road – Office, Bins

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 32-3 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 25249 West Grant Highway _____

Lat/Long: 42.252104/-88.684468 _____

Primary Use: residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two

List Observed Structures: residence; large barn

Residence Detail

Style: Gabled EI

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* two _____

* Attach Photo log, additional notes and map of resource location.

circa 1908-1939

Barn Detail

Style: Gabled

Wall materials: wood
Roof materials: metal

Foundation materials: unknown

Other distinguishing features:



MA-32-3: 25249 West Grant Highway – Barn



MA-33-3: 25249 West Grant Highway – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 32-4 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 24817 West Grant Highway _____

Lat/Long: 42.250813/-88.682349 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two

List Observed Structures: residence; wood sided garage with asphalt roof

Residence Detail

Style: Bungalow

Wall materials: wood
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* two _____

* Attach Photo log, additional notes and map of resource location.

circa 1908-1939

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:



MA-32-4: 24817 West Grant Highway – Residence



MA-33-4: 24817 West Grant Highway – Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 32-5 Surveyor Name: C. Flynn_____

Current Property or Structure Name: was Shady Lane Farm, then Oak Steakhouse, now gone_____

Address: 24803 West Grant Highway _____

Lat/Long: 42.251143/-88.681083_____

Primary Use: commercial_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group:_____ Number Structures in Group:

List Observed Structures: concrete pads, rubble piles

Residence Detail

Barn Detail

Style:

Style:

Wall materials:

Wall materials:

Roof materials:

Roof materials:

Foundation materials:

Foundation materials:

Other distinguishing features:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* one_____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-32-5: East of 32-4 – Steakhouse Debris

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 32-6 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 24704 West Grant Highway _____

Lat/Long: 42.2511824/-88.679031_____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two

List Observed Structures: residence; trailer

Residence Detail

Style: Foursquare

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* one _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:



MA-32-6: 24704 West Grant Highway – Residence,
Trailer

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 32-7 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 24515 West Grant Highway _____

Lat/Long: 42.251004/-88.676432 _____

Primary Use: residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: 19 per google and observed

List Observed Structures: E-W: large wood sided corn crib with metal roof; eight small metal storage bins; large swine barn; small scale office (newer); residence; two concrete tile silos; metal and wood sided machine shop with metal roof and concrete foundation; grain bins/elevator complex; long and low asbestos shingle clad turkey coop building with asphalt roof and concrete foundation; semi-enclosed wood sided machinery shed; large wood sided swine farrowing barn with metal roof.

Residence Detail

Style: Front Gabled

Wall materials: wood
Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations: roof has been dormered

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* 12 _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style: gabled

Wall materials: wood
Roof materials: metal

Foundation materials: concrete

Other distinguishing features: adjacent to foundation of older barn.



MA-32-7: 24515 West Grant Highway -
Residence



MA-32-7: 24515 West Grant Highway – Bins,
Crib, Barn, Office



MA-32-7: 24515 West Grant Highway – Coops,
Silos



MA-32-7: 24515 West Grant Highway –
Machine Shop



MA-32-7: 24515 West Grant Highway – Swine Pens



MA-32-7: 24515 West Grant Highway – Farrowing Sheds

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 32-8 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 24516 West Grant Highway _____

Lat/Long: 42.251532/-88.676292 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two

List Observed Structures: residence; garage

Residence Detail

Style: Front Gabled

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

schoolhouse

Number of photos taken for this property* one _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:



MA-32-8: 24516 West Grant Highway - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 32-9 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 24577 West Grant Highway _____

Lat/Long: 42.250956/-88.674254 _____

Primary Use: residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: seven

List Observed Structures: residence; wood sided milk house standing adjacent to a barn and silo concrete pad/foundation; small metal clad shed; two metal grain bins; metal clad pole barn with wood plank foundation; older wood sided shed with asphalt roof; *limestone smoke house (*photo has to be re-taken)

Residence Detail

Style: No style

Wall materials: asbestos shingles

Roof materials: asphalt

Foundation materials: limestone

Other distinguishing features:

Barn Detail

Style: demolished

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations: may have been Italianate - roofline changed, front porch added

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* seven _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-32-9: East of 32-7 - Residence



MA-32-9: East of 32-7 – Barn and Silo Foundation, Milk House



MA-32-9: East of 32-7 – Shed, Bin, Pole Barn



MA-32-9: East of 32-7 – Other Shed and Bin

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 32-10 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 24406 West Grant Highway _____

Lat/Long: 42.250956/-88.674254 _____

Primary Use: residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: five

List Observed Structures: main residence; 2nd residence NE of 2st; small metal shed; metal/vinyl clad outbuilding attached to a limestone barn; 3rd vinyl clad residence with asphalt roof S of limestone barn close to road.

Residence Detail

Style: large Queen Anne

Wall materials: asbestos shingles

Roof materials: asphalt

Foundation materials: limestone

Other distinguishing features:

Barn Detail

Style: unknown

Wall materials: limestone and wood
lower, vinyl clad upper

Roof materials: asphalt

Foundation materials: limestone

Other distinguishing features

Any obvious Additions/Alterations: enclosed front porch; addition to E side

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* seven (smoke house needs to be re-taken _____)

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-32-10: 24406 West Grant Highway -
Outbuildings



MA-32-10: 24406 West Grant Highway -
Residence



MA-32-10: 24406 West Grant Highway –
Second Residence



MA-32-10: 24406 West Grant Highway –
Limestone Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 32-11 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 24308 West Grant Highway _____

Lat/Long: 42.251643/-88.671515 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: two

List Observed Structures: new residence; older garage with wood siding and asphalt roof (may not be old either)

Residence Detail

Style: Ranch

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* one _____

* Attach Photo log, additional notes and map of resource location.

circa 1939-1965

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



MA-32-11: 24308 West Grant Highway – Residence,
Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 32-12 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 24220 West Grant Highway _____

Lat/Long: 42.251643/-88.671515 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three

List Observed Structures: residence; newer garage; vinyl clad shed with asphalt roof

Residence Detail

Style: Foursquare

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations: 2-story front balcony and railings

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* one _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:



MA-32-12: 2403 West Grant Highway – Residence,
Garage, Shed

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 33





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/3/14_____ Survey Number: MA 33-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 5107 Thorne Road _____

Lat/Long: 42.254794/-88.664346 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: eight incl. milk house

List Observed Structures: residence; metal clad pole barn; wood sided garage; dairy barn with attached concrete block milk house; ivy-covered concrete silo; metal frame windmill over well/pump; small wooden animal shed

Residence Detail

Style: Cross Gabled

Wall materials: vinyl/aluminum
Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* three _____

* Attach Photo log, additional notes and map of resource location.

circa 1908-1939

Barn Detail

Style: Gabled dairy

Wall materials: vertical wood board
Roof materials: metal

Foundation materials: concrete block

Other distinguishing features:



MA-33-1: 5107 Thorne Road - Sheds



MA-33-1: 5107 Thorne Road – Milk House, Barn



MA-33-1: 5107 Thorne Road – Garage, Residence, Windmill, Pole Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/3/14_____ Survey Number: MA 33-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: NW corner Thorne Road and West Grant Highway _____

Lat/Long: 42.251312/-88.664984 _____

Primary Use: commercial/industrial _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: four

List Observed Structures: three newer metal clad pole barns; one older looking wood sided garage or shed with a metal roof. May be less than 50 years old

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* one _____

* Attach Photo log, additional notes and map of resource location.

circa 1960

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



MA-33-2: Northwest corner of Thorne Road and West Grant Highway - Sheds

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/3/14_____ Survey Number: MA 33-3 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: West Grant Highway S-side opposite Thorne Road _____

Lat/Long: 42.250404/-88.664002 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: eight

List Observed Structures: residence; wooden out house; low wooden shed with metal roof; concrete tile silo; metal framed windmill over concrete well pump; dairy barn; detached wood sided milk house with asphalt roof; low concrete block animal shed, open to south.

Residence Detail

Style: Side Gabled Greek Revival
Wall materials: brick and wood
Roof materials: asphalt
Foundation materials: limestone

Other distinguishing features: May be Hall and Parlor

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* four _____

* Attach Photo log, additional notes and map of resource location.

circa 1840-1860

Barn Detail

Style: Gambrel
Wall materials: vertical wood board
Roof materials: metal
Foundation materials: stone

Other distinguishing features:



MA-33-3: West Grant Highway- Residence



MA-33-3: West Grant Highway – Silo, Barn, Shed, Milk House, Windmill

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/3/14_____ Survey Number: MA 33-4 Surveyor Name: C. Flynn_____

Current Property or Structure Name:_____

Address: 23602 West Grant Highway _____

Lat/Long: 42.251103/-88.661378 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group:

List Observed Structures: residence

Residence Detail

Style: Dutch Colonial

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property* one _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:



MA-33-4: 23602 West Grant Highway - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/3/14_____ Survey Number: MA 33-5 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 24111 West Grant Highway _____

Lat/Long: 42.251103/-88.661378 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: four

List Observed Structures: residence; detached vinyl clad garage; metal clad pole barn; smaller wood sided shed with metal roof to SE of residence

Residence Detail

Style: Minimal Traditional

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations: addition to front

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property* one _____

* Attach Photo log, additional notes and map of resource location.

circa 1939-1965

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:



MA-33-5: 24111 West Grant Highway – Residence,
Garage, Shed, Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/3/14_____ Survey Number: MA 33-6 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 23711 West Grant Highway _____

Lat/Long: 42.250319/-88.660301_____

Primary Use: residential/agricultural_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: eight (per google)

List Observed Structures: residence; two new looking vinyl clad outbuildings with metal roofs; metal clad older barn; metal clad pole barn behind (S) of older barn; small shed detached vinyl clad garage.

Residence Detail

Style: Bungalow

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: cement covered limestone

Other distinguishing features: enclosed front porch

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property* three_____

* Attach Photo log, additional notes and map of resource location.

circa 1920

Barn Detail

Style: Gabled

Wall materials: vinyl/aluminum over vertical wood board

Roof materials: metal

Foundation materials: unknown

Other distinguishing features:



MA-33-6: 23711 West Grant Highway -
Residence



MA-33-6: 23711 West Grant Highway -
Outbuildings



MA-33-6: 23711 West Grant Highway – Sheds,
Barns

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/3/14_____ Survey Number: MA 33-7 Surveyor Name: C. Flynn_____

Current Property or Structure Name:_____

Address: No # N side of West Grant Highway _____

Lat/Long: 42.250875/-88.655846_____

Primary Use: residential_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group:

List Observed Structures: residence

Residence Detail

Style: Cape Cod
Wall materials: wood clapboard
Roof materials: asphalt
Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property* one_____

* Attach Photo log, additional notes and map of resource location.

circa 1920-1930

Barn Detail

Style:
Wall materials:
Roof materials:
Foundation materials:

Other distinguishing features:



MA-33-7: North side West Grant Highway - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/3/14_____ Survey Number: MA 33-8 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 23317 West Grant Highway _____

Lat/Long: 42.24995/-88.653239 _____

Primary Use: residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: ten (per google)

List Observed Structures: residence; W-E: wood sided barn with wood covered stone foundation; larger dairy barn; concrete tile silo; wood sided crib with stone foundation; rough wooden shed in SW corner; small wooden shed immediately S of residence

Residence Detail

Style: Greek Revival

Wall materials: wood
Roof materials: asphalt

Foundation materials: limestone

Other distinguishing features: intact details

Any obvious Additions/Alterations: nice collection of buildings

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* six _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style: Gambrel dairy

Wall materials: wood, vinyl on S side
Roof materials: asphalt

Foundation materials: limestone

Other distinguishing features:



MA-33-8: 23317 West Grant Highway-
Residence



MA-33-8: 23317 West Grant Highway – Barn
and Shed Complex, Silo



MA-33-8: 3317 West Grant Highway – Dairy
Barn, Low Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/3/14_____ Survey Number: MA 33-9 Surveyor Name: C. Flynn_____

Current Property or Structure Name:_____

Address: 23216 West Grant Highway _____

Lat/Long: 42.250535/-88.650838 _____

Primary Use: residential/agricultural_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: Number Structures in Group: three

List Observed Structures: residence; metal pole barn; metal covered garage

Residence Detail

Barn Detail

Style: Italianate

Style:

Wall materials: vinyl
Roof materials: asphalt

Wall materials:
Roof materials:

Foundation materials: limestone

Foundation materials:

Other distinguishing features:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* two_____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-33-9: 23216 West Grant Highway – Residence,
Pole Barns

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 34





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/3/14_____ Survey Number: MA 34-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 5017 Ritz Road _____

Lat/Long: 42.254875/-88.630072 _____

Primary Use: residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: eight per google

List Observed Structures: residence; metal clad older pole barn; wood sided barn/shed with asphalt roof and concrete foundation; newer metal pole barn with metal shed-type roof; dairy barn; concrete tile silo.

Residence Detail

Style: Queen Anne

Wall materials: wood clapboard

Roof materials: shake shingle

Foundation materials: brick or limestone, painted

Other distinguishing features: obscured by foliage

Barn Detail

Style: Gambrel dairy

Wall materials: vertical wood board

Roof materials: wood shake shingles

Foundation materials: stone

Other distinguishing features: metal cupolas/vents

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* four _____

* Attach Photo log, additional notes and map of resource location.

circa 1900



MA-34-1: 5017 Ritz Road - Residence



MA-34-1: 5017 Ritz Road – Shed, Pole Barn



MA-34-1: 5017 Ritz Road – Silo, Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/3/14_____ Survey Number: MA 34-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 22980 West Grant Highway _____

Lat/Long: 42.249459/-88.644932 _____

Primary Use: residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: X _____ Number Structures in Group: four

List Observed Structures: residence; collapsed wood sided barn with asphalt roof; two wooden sheds to SE with asphalt roofs and unknown foundations.

Residence Detail

Style: Unknown - obscured

Wall materials: wood clapboard
Roof materials: shake shingle

Foundation materials: brick or limestone, painted

Other distinguishing features: obscured by foliage

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property* four _____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-34-2: 22980 West Grant Highway - Residence



MA-34-2: 22980 West Grant Highway - Sheds

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/3/14_____ Survey Number: MA 34-3 Surveyor Name: C. Flynn_____

Current Property or Structure Name:_____

Address: No # N-side West Grant Highway (22818 per google)_____

Lat/Long: 42.251056/-88.643156_____

Primary Use: agricultural_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: three

List Observed Structures: two concrete silos; one wooden shed or small barn with wood shake shingle roof, unknown foundation – Note: abandoned and overgrown

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*three_____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style: Gabled

Wall materials: vertical wood board


Roof materials: wood shake shingles

Foundation materials: unknown

Other distinguishing features



MA-34-3: 22818 West Grant Highway - Silos



MA-34-3: 22818 West Grant Highway - Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/3/14_____ Survey Number: MA 34-4 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 22616 West Grant Highway _____

Lat/Long: 42.250093/-88.639184 _____

Primary Use: agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three

List Observed Structures: residence; garage; pole barn

Residence Detail

Style: Minimal Traditional

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*two _____

* Attach Photo log, additional notes and map of resource location.

circa 1939-1965

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features



MA-34-4: 22616 West Grant Highway - Residence



MA-34-4: 22616 West Grant Highway – Garage, Pole Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/3/14_____ Survey Number: MA 34-5 Surveyor Name: C. Flynn_____

Current Property or Structure Name: Full Moon Saloon_____

Address: 22418 West Grant Highway _____

Lat/Long: 42.24985/-88.635595_____

Primary Use: commercial_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group:

List Observed Structures: older building converted into the Full Moon Saloon

Residence Detail

Style: No style

Wall materials: wood
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property*two_____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features



MA-34-5: 22418 West Grant Highway– Full Moon Saloon

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/3/14_____ Survey Number: MA 34-6 Surveyor Name: C. Flynn_____

Current Property or Structure Name:_____

Address: 22394 West Grant Highway per google _____

Lat/Long: 42.24884/-88.635228_____

Primary Use: Ag _____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: two

List Observed Structures: new pole barn; concrete tile silo

Residence Detail

Barn Detail

Style:

Style:

Wall materials:

Wall materials:

Roof materials:

Roof materials:

Foundation materials:

Foundation materials:

Other distinguishing features:

Other distinguishing features

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property*one_____

* Attach Photo log, additional notes and map of resource location.

circa 1872



MA-34-6: 22394 West Grant Highway – Silo

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/3/14_____ Survey Number: MA 34-7 Surveyor Name: C. Flynn_____

Current Property or Structure Name:_____

Address: No # N-side West Grant Highway _____

Lat/Long: 42.249829/-88.633629_____

Primary Use: residential_____

Is this a record of a single structure or group (give total number of structures):

Single:X_____ Group:_____ Number Structures in Group:

List Observed Structures: residence

Residence Detail

Style: Side Gabled

Wall materials: asbestos tiles
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property*one_____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features



MA-34-7: North side West Grant Highway – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/3/14_____ Survey Number: MA 34-8 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: No # S-side West Grant Highway _____

Lat/Long: 42.249024/-88.631789 _____

Primary Use: residential _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: _____ Number Structures in Group:

List Observed Structures: residence

Residence Detail

Style: Greek Revival

Wall materials: wood
Roof materials: asphalt

Foundation materials: limestone

Other distinguishing features: single story

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Number of photos taken for this property*two _____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style:

Wall materials:
Roof materials:

Foundation materials:

Other distinguishing features



MA-34-8: South side West Grant Highway – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/3/14_____ Survey Number: MA 34-9 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 22216 West Grant Highway _____

Lat/Long: 42.249761/-88.631381_____

Primary Use: residential_____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: three

List Observed Structures: residence; barn; wood sided shed

Residence Detail

Style: Foursquare

Wall materials: vinyl
Roof materials: asphalt

Foundation materials: limestone

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*two_____

* Attach Photo log, additional notes and map of resource location.

circa 1872

Barn Detail

Style: Gabled

Wall materials: vertical wood
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features



MA-34-9: 22216 West Grant Highway – Residence,
Barn



MA-34-9: 22216 West Grant Highway - Sheds

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/3/14_____ Survey Number: MA 34-10 Surveyor Name: C. Flynn_____

Current Property or Structure Name: Sunset Motel_____

Address: 22116 West Grant Highway _____

Lat/Long: 42.249668/-88.629351_____

Primary Use: commercial_____

Is this a record of a single structure or group (give total number of structures):

Single:_____ Group: X_____ Number Structures in Group: three

List Observed Structures: two motel buildings; one garage

Residence Detail

Barn Detail

Style: No style

Style:

Wall materials: vinyl
Roof materials: asphalt

Wall materials:
Roof materials:

Foundation materials: concrete

Foundation materials:

Other distinguishing features:

Other distinguishing features

Any obvious Additions/Alterations: may not be over 50 years old

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*one_____


* Attach Photo log, additional notes and map of resource location.

circa 1950



MA-34-10: 22116 West Grant Highway – Sunset Motel

MCHENRY COUNTY
MARENGO TOWNSHIP
SECTION 35



Township
Location

Photo Location Key

- ← - Single Resource
- - Resource Group
- MA-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 35-1 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 21902 West Railroad Street _____

Lat/Long: 42.254903/-88.624123 _____

Primary Use: residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: seven per google

List Observed Structures: Residence; metal pole barn; wood and metal small shed

Residence Detail

Style: Bungalow

Wall materials: asbestos shingles

Roof materials: asphalt

Foundation materials: concrete blocks

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*one _____

* Attach Photo log, additional notes and map of resource location.

circa 1908-1939

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features



MA-35-1: 21902 West Railroad Street – Residence,
Shed, Pole Barn

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/29/14_____ Survey Number: MA 35-2 Surveyor Name: C. Flynn_____

Current Property or Structure Name: _____

Address: 22019 West Railroad Street _____

Lat/Long: 42.254857/-88.626961 _____

Primary Use: residential/agricultural _____

Is this a record of a single structure or group (give total number of structures):

Single: _____ Group: Number Structures in Group: seven per google

List Observed Structures: Residence; barn; 2nd collapsing wooden barn to right (W); garage; small shed

Residence Detail

Style: Front Gabled

Wall materials: wood
Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Gabled

Wall materials: wood
Roof materials: metal

Foundation materials: unknown

Other distinguishing features

Any obvious Additions/Alterations: all outbuildings obscured by foliage

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Number of photos taken for this property*one _____

* Attach Photo log, additional notes and map of resource location.

circa 1908-1939



MA-35-2: 22019 West Railroad Street -
Residence



MA-35-2: 22019 West Railroad Street – Barn,
Garage



MA-35-2: 22019 West Railroad Street – Small
Barn, Shed



MA-35-2: 22019 West Railroad Street –
Collapsing Barn, Shed

