

McHenry County



Township Key

Chemung	Alden	Hebron	
Dunham	Hartland		
Marengo	Seneca		
Riley	Not Included in Survey		

### Riley Township


T43N, R5E

0 0.5 1 2 Miles

0 0.5 1 2 Kilometers



MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 1





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number



# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/26/14\_\_\_\_\_ Survey Number: RI-1-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 6313 Maple Street \_\_\_\_\_

Lat/Long: 42.236891/-88.601599 \_\_\_\_\_

Primary Use: Residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: three \_\_\_\_\_

List Observed Structures: (A) Residence; (B) Barn; (C) garage \_\_\_\_\_

Residence Detail

Style: Front Gabled/Bungalow

Wall materials: vinyl

Roof materials: unknown

Foundation materials

Other distinguishing features:

Barn Detail

Style: Gambrel Roof

Wall materials: horizontal wood boards

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): Garage

No record per Twp. Assessor.

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-1-1: 6313 Maple Street – House, Barn,  
Garage, Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/26/14\_\_\_\_\_ Survey Number: RI-1-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 6371 Maple Street \_\_\_\_\_

Lat/Long: 42.236583/-88.600848 \_\_\_\_\_

Primary Use: Agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) Barn; (B) Barn; \_\_\_\_\_

### Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials

Other distinguishing features:

### Barn Detail

Style: Gambrel roof hay barn

Wall materials: vertical wood boards

Roof materials: asphalt over wood shingle

Foundation materials: limestone

Other distinguishing features: attached milk house

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): (B) 2<sup>nd</sup> barn has a round roof, asphalt roof, vertical wood siding, and concrete foundation

circa 1872

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-1-2: 6371 Maple Street – Barns

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/26/14\_\_\_\_\_ Survey Number: RI-1-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 6617 Maple Street \_\_\_\_\_

Lat/Long: 42.232084/-88.601314 \_\_\_\_\_

Primary Use: Residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) Residence; (B) Garage \_\_\_\_\_

Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: inknown

Other distinguishing features: none

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): Garage barely visible circa 1872

Number of photos taken for this property\*: one \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-1-3: 6617 Maple Street – Garage, Residence

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/26/14\_\_\_\_\_ Survey Number: RI-1-4\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 6720 Maple Street \_\_\_\_\_

Lat/Long: 42.231523/-88.600523 \_\_\_\_\_

Primary Use: Residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:  \_\_\_\_\_ Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: (A) Residence \_\_\_\_\_

Residence Detail

Style: ~Ranch

Wall materials: brick

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: none

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations: 1989 per Twp. Assessor

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): Garage: wood siding, asphalt roof circa 1989 per Twp. Assessor

Number of photos taken for this property\*: one \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-1-4: 6720 Maple Street – Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/26/14\_\_\_\_\_ Survey Number: RI-1-5\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 6917 Maple Street \_\_\_\_\_

Lat/Long: 42.227860/-88.601321 \_\_\_\_\_

Primary Use: Residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:  \_\_\_\_\_ Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: (A) Residence \_\_\_\_\_

---

### Residence Detail

Style: one- Ranch

Wall materials: vinyl/brick

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: none

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: attached garage

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

circa 1975 per Twp. Assessor

Number of photos taken for this property\*: one \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-1-5: 6917 Maple Street – Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/26/14\_\_\_\_\_ Survey Number: RI-1-6\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 7001 Maple Street \_\_\_\_\_

Lat/Long: 42.227382/-88.601286 \_\_\_\_\_

Primary Use: Residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) Residence; (B) vinyl clad 2-car garage \_\_\_\_\_

### Residence Detail

Style: Minimal Traditional

Wall materials: vinyl

Roof materials: asphalt

Foundation materials

Other distinguishing features: none

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): Garage: wood siding, asphalt roof circa 1968 per Twp. Assessor

Number of photos taken for this property\*: one \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-1-6: 7001 Maple Street – Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/26/14\_\_\_\_\_ Survey Number: RI-1-7\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 6212 Rt. 23\_\_\_\_\_

Lat/Long: 42.238491/-88.608180\_\_\_\_\_

Primary Use: Residence\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:  \_\_\_\_\_ Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: (A) Residence\_\_\_\_\_

### Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: front porch

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

circa 1980 per Twp. Assessor /circa 1940

Number of photos taken for this property\*: one\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-1-7: 6212 Illinois Route 23 – Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/26/14\_\_\_\_\_ Survey Number: RI-1-8\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 6302 Rt. 23\_\_\_\_\_

Lat/Long: 42.237733/-88.608240\_\_\_\_\_

Primary Use: Residence\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:  \_\_\_\_\_ Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: (A) Residence\_\_\_\_\_

### Residence Detail

Style: 1 1/2 story Cape

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: attached garage

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

circa 1972 per Twp. Assessor

Number of photos taken for this property\*: one \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-1-8: 6302 Illinois Route 23 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/26/14\_\_\_\_\_ Survey Number: RI-1-9\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 6216 Rt. 23\_\_\_\_\_

Lat/Long: 42.238181/-88.608266\_\_\_\_\_

Primary Use: Residence\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group: X \_\_\_\_\_ Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) Residence; (B) Barn \_\_\_\_\_

Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: faces sideways

Barn Detail

Style: Gambrel Roof

Wall materials: vinyl

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Circa 1987 per Twp. Assessor

Number of photos taken for this property\*: one \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-1-9: 6216 Illinois Route 23 – Residence, Barn

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/26/14\_\_\_\_\_ Survey Number: RI-1-10\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 6066 Rt. 23\_\_\_\_\_

Lat/Long: 42.238982/-88.607902\_\_\_\_\_

Primary Use: Residence\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:  \_\_\_\_\_ Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: (A) Residence\_\_\_\_\_

### Residence Detail

Style: Ranch

Wall materials: brick

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: none

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

circa 1963 per Twp. Assessor

Number of photos taken for this property\*: one \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-1-10: 6206 Illinois Route 23 – Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/26/14\_\_\_\_\_ Survey Number: RI-1-11\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 20916 Ratfield Road \_\_\_\_\_

Lat/Long: 42.231595/-88.606176 \_\_\_\_\_

Primary Use: Residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:  \_\_\_\_\_ Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: (A) Residence; \_\_\_\_\_

Residence Detail

Style: unknown/obscured

Wall materials:

Roof materials:

Foundation materials

Other distinguishing features: attached garage

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

circa 1977 per Twp. Assessor

Number of photos taken for this property\*: one \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-1-11: 20916 Ratfield – Residence, Barn

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/26/14\_\_\_\_\_ Survey Number: RI-1-12\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 6806 IL Rt. 23\_\_\_\_\_

Lat/Long: 42.229930/-88.608212\_\_\_\_\_

Primary Use: Residence/agri\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) Residence; (B) Barn\_\_\_\_\_

### Residence Detail

Style: Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features: none

### Barn Detail

Style: Gambrel roofed

Wall materials: vinyl

Roof materials: metal

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): pole barn-type garage attached to barns circa 1872

Number of photos taken for this property\*: two\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-1-12: 6808 Illinois Route 23 – Barn, Garage



RI-1-12: 6808 Illinois Route 23 - Residence

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/26/14\_\_\_\_\_ Survey Number: RI-1-13\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 6908 IL Rt. 23\_\_\_\_\_

Lat/Long: 42.228571/-88.608063\_\_\_\_\_

Primary Use: Residence/agri\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: four \_\_\_\_\_

List Observed Structures: (A) Residence; (B) Barn; (C) 3-car vinyl clad garage; (D) wood-sided shed with asphalt roof

Residence Detail

Style: Side Gabled

Wall materials: wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: centered front porch

Barn Detail

Style: unknown/obscured

Wall materials: wood

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

circa 1872

Number of photos taken for this property\*: two\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-1-13: 6908 Illinois Route 23 – Residence



RI-1-13: 6908 Illinois Route 23 – Outbuildings

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/26/14\_\_\_\_\_ Survey Number: RI-1-14\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 7106 IL Rt. 23\_\_\_\_\_

Lat/Long: 42.227348/-88.608250\_\_\_\_\_

Primary Use: Residence/agri\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: three\_\_\_\_\_

List Observed Structures: (A) Residence; (B) Barn; (C) shed\_\_\_\_\_

## Residence Detail

Style: Gabled EI

Wall materials: wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: stone front porch, stone wall

## Barn Detail

Style: unknown/obscured

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): shed.


circa 1872

Number of photos taken for this property\*: two\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.




RI-1-14: 7106 Illinois Route 23 – Residence



RI-1-14: 7106 Illinois Route 23 – Outbuildings

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 2





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number



## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/26/14\_\_\_\_\_ Survey Number: RI-2-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 6717 IL Rt.23\_\_\_\_\_

Lat/Long: 42.239513/-88.609000\_\_\_\_\_

Primary Use: Residence\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:  \_\_\_\_\_ Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: (A) Residence\_\_\_\_\_

### Residence Detail

Style: Unknown/obscured

Wall materials:

Roof materials:

Foundation materials

Other distinguishing features:

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

circa 1965-1978

Number of photos taken for this property\*: one\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-2-1: 6717 Illinois Route 23 – Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/26/14\_\_\_\_\_ Survey Number: RI-2-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 6311 IL Rt.23\_\_\_\_\_

Lat/Long: 42.236572/-88.609134\_\_\_\_\_

Primary Use: Residence\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:  \_\_\_\_\_ Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: (A) Residence\_\_\_\_\_

### Residence Detail

Style: Ranch

Wall materials: vertical wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

circa 1973 per Twp. Assessor

Number of photos taken for this property\*: one\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-2-2: 6311 Illinois Route 23 – Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/26/14\_\_\_\_\_ Survey Number: RI-2-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 6411 IL Rt.23\_\_\_\_\_

Lat/Long: 42.235578/-88.609320\_\_\_\_\_

Primary Use: Residence\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:  \_\_\_\_\_ Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: (A) Residence; (B) barn; (C) connected wood-sided sheds\_\_\_\_\_

### Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: enclosed front porch

### Barn Detail

Style: Banked Gabled

Wall materials: asbestos shingles

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features:

Any obvious Additions/Alterations: possible 2<sup>nd</sup> story addition to wing

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

circa 1872

Number of photos taken for this property\*: three\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-2-3: 6411 Illinois Route 23 – Residence, Barn,  
Outbuildings

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/26/14\_\_\_\_\_ Survey Number: RI-2-4\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 6503 IL Rt.23\_\_\_\_\_

Lat/Long: 42.234656/-88.609196\_\_\_\_\_

Primary Use: Residence\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:  \_\_\_\_\_ Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: (A) Residence; (B) concrete stave silo\_\_\_\_\_

### Residence Detail

Style: Side Gabled

Wall materials: unknown

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: obscured by foliage

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: one-story addition

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

circa 1872

Number of photos taken for this property\*: two\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-2-4: 6503 Illinois Route 23 – Residence



RI-2-4: 6503 Illinois Route 23 – Silo

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/26/14\_\_\_\_\_ Survey Number: RI-2-5\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 6805 IL Rt.23\_\_\_\_\_

Lat/Long: 42.230026/-88.609203\_\_\_\_\_

Primary Use: Resid/agri\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: four \_\_\_\_\_

List Observed Structures: (A) Residence; (B) barn; (C) crib/shed; (D) small shed or cottage \_\_\_\_\_

### Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

### Barn Detail

Style: Gabled roof/center bay

Wall materials: asbestos over vertical board

Roof materials: metal

Foundation materials: fieldstone

Other distinguishing features: ramp

Any obvious Additions/Alterations: addition to south

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

circa 1865 per Twp. Assessor

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-2-5: 6805 Illinois Route 23 - Barn



RI-2-5: 6805 Illinois Route 23 - Shed



RI-2-5: 6805 Illinois Route 23 - Residence

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/26/14\_\_\_\_\_ Survey Number: RI-2-6\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 6907 IL Rt.23\_\_\_\_\_

Lat/Long: 42.227035/-88.610015\_\_\_\_\_

Primary Use: Resid\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) Residence; (B) pole barn-type garage\_\_\_\_\_

Residence Detail

Style: Ranch

Wall materials: brick and vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: addition to south

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

circa 1940-1965

Number of photos taken for this property\*: three\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-2-6: 6907 Illinois Route 23 – Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/26/14\_\_\_\_\_ Survey Number: RI-2-7\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 7015 IL Rt.23\_\_\_\_\_

Lat/Long: 42.226496/-88.609777\_\_\_\_\_

Primary Use: Resid\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) Residence; (B) garage \_\_\_\_\_

### Residence Detail

Style: Ranch

Wall materials: brick and vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: walk-out basement.

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

circa 1982 per Twp. Assessor

Number of photos taken for this property\*: one \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.




RI-2-7: 7015 Illinois Route 23 – Residence



RI-2-7: 7015 Illinois Route 23 – Garage

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 3





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number



## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/27/14\_\_\_\_\_ Survey Number: RI-3-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 6113 Meyer Road \_\_\_\_\_

Lat/Long: 42.240286/-88.624314 \_\_\_\_\_

Primary Use: Resid \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:  \_\_\_\_\_ Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: (A) Residence \_\_\_\_\_

### Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete over fieldstone

Other distinguishing features:

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: one-story addition to south

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

circa 1955 per Twp. Assessor

Number of photos taken for this property\*: one \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-3-1: 6113 Meyer Road – Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/27/14\_\_\_\_\_ Survey Number: RI-3-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 6119 Meyer Road \_\_\_\_\_

Lat/Long: 42.239672/-88.629730 \_\_\_\_\_

Primary Use: Resid \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:  \_\_\_\_\_ Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: (A) Residence \_\_\_\_\_

### Residence Detail

Style: Ranch

Wall materials: brick

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

circa 1955 per Twp. Assessor

Number of photos taken for this property\*: one \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-3-2: 611X Meyer Road – Residence

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/27/14\_\_\_\_\_ Survey Number: RI-3-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 6119 Meyer Road \_\_\_\_\_

Lat/Long: 42.235464/-88.628360 \_\_\_\_\_

Primary Use: Resid \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: three \_\_\_\_\_

List Observed Structures: (A) Residence; (B) pole barn \_\_\_\_\_

Residence Detail

Style: Colonial Revival

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: less than 50 years old

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Property Group Date Range: 2000 per Twp. Assessor

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-3-3: 6408 Meyer Road – Barn



RI-3-3: 6408 Meyer Road – Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/27/14\_\_\_\_\_ Survey Number: RI-3-4\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 6520 Meyer Road \_\_\_\_\_

Lat/Long: 42.233559/-88.628781 \_\_\_\_\_

Primary Use: Resid \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: three \_\_\_\_\_

List Observed Structures: (A) Residence; (B) barn; (C) shed; (D) garage \_\_\_\_\_

---

### Residence Detail

Style: Foursquare

Wall materials: brick

Roof materials: asphalt

Foundation materials: concrete block or fieldstone

Other distinguishing features: dormer; nice brick work

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. Garage is brick, central bay, symmetrical windows, low hipped roof with flaring eaves.

circa 1872

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-3-4: 6520 Meyer Road – Barn, Shed



RI-3-4: 6520 Meyer Road - Garage



RI-3-4: 6520 Meyer Road - Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/27/14\_\_\_\_\_ Survey Number: RI-3-5\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 6715 Meyer Road \_\_\_\_\_

Lat/Long: 42.230592/-88.628611 \_\_\_\_\_

Primary Use: Resid/ Equestrian \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: three \_\_\_\_\_

List Observed Structures: (A) Residence; (B) barn; (C) barn; (D) long stables \_\_\_\_\_

---

### Residence Detail

Style: Colonial Revival

Wall materials: brick

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: center balcony over front door

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: large addition to south, connected by two-story open balconies

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1872

Number of photos taken for this property\*: five \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-3-5: 6715 Meyer Road - Stable



RI-3-5: 6715 Meyer Road - Barn



RI-3-5: 6715 Meyer Road - Residence



RI-3-5: 6715 Meyer Road - Barn

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/27/14\_\_\_\_\_ Survey Number: RI-3-6\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 22053 Pleasant Grove Road \_\_\_\_\_

Lat/Long: 42.228077/-88.634196 \_\_\_\_\_

Primary Use: Resid/Agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: four \_\_\_\_\_

List Observed Structures: (A) Residence; (B) barn with attached milk house; (C) Quonsett shed; (D) open metal/vinyl animal shed

---

### Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete-clad

Other distinguishing features:

### Barn Detail

Style: Round Roof

Wall materials: vinyl/metal

Roof materials: vinyl/metal

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1872

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-3-6: Pleasant Grove Road – Residence, Shed



RI-3-6: Pleasant Grove Road - Barn



RI-3-6: Pleasant Grove Road - Shed

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/27/14\_\_\_\_\_ Survey Number: RI-3-7\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 22508 Pleasant Grove Road \_\_\_\_\_

Lat/Long: 42.230551/-88.638088 \_\_\_\_\_

Primary Use: Resid/Agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: four \_\_\_\_\_

List Observed Structures: (A) Residence; (B) barn; (C) concrete stave silo; (D) concrete block milk house

---

### Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

### Barn Detail

Style: Gabled

Wall materials: vertical wood board

Roof materials: metal

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1830 per Twp. Assessor - actual date circa 1860

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-3-7: 22508 Pleasant Grove Road – Barn, Silo



RI-3-7: 22508 Pleasant Grove Road – Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/27/14\_\_\_\_\_ Survey Number: RI-3-8\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 22905 Pleasant Grove Road \_\_\_\_\_

Lat/Long: 42.232722/-88.644487 \_\_\_\_\_

Primary Use: Resid/Agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: four \_\_\_\_\_

List Observed Structures: (A) Residence; (B) barn; (C) wood-sided shed; (D) wood sided shed; (E) pole barn/garage

---

### Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete clad

Other distinguishing features: handicap ramp

### Barn Detail

Style: L Plan Round roof

Wall materials: wood board

Roof materials: asphalt over shake

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1940-1965 - actual date circa 1860-1890

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-3-8: 22905 Pleasant Grove Road – Barn, Sheds



RI-3-8: 22905 Pleasant Grove Road – Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/27/14\_\_\_\_\_ Survey Number: RI-3-9\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 22822 Pleasant Grove Road \_\_\_\_\_

Lat/Long: 42.232881/-88.643088 \_\_\_\_\_

Primary Use: Resid/Agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: eight \_\_\_\_\_

List Observed Structures: (A) Residence; (B) barn; (C-F) wood-sided sheds; (G) concrete stave silo; (H) metal pole barn

---

### Residence Detail

Style: Side Gabled

Wall materials: wood shingle

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: very weathered

### Barn Detail

Style: Gambrel roofed

Wall materials: vertical wood board

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features: weathered

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1880 per Twp. Assessor

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-3-9: 22822 Pleasant Grove Road – Barn, Sheds, Silo



RI-3-9: 22822 Pleasant Grove Road – Residence, Sheds

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/27/14\_\_\_\_\_ Survey Number: RI-3-10\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 23088 Pleasant Grove Road \_\_\_\_\_

Lat/Long: 42.234271/-88.6469438 \_\_\_\_\_

Primary Use: Resid \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) Residence; (B) barn

---

Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Gabled roof

Wall materials: unknown

Roof materials: metal

Foundation materials:

Other distinguishing features: obscured

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1872


Number of photos taken for this property\*: one \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-3-10: 23088 Pleasant Grove Road – Residence,  
Shed

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 4



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/27/14\_\_\_\_\_ Survey Number: RI-4-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 23207 Pleasant Grove Road \_\_\_\_\_

Lat/Long: 42.236091/-88.650276 \_\_\_\_\_

Primary Use: Resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) Residence; (B) barn

---

### Residence Detail

Style: Cross Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: enclosed front entry/porch

### Barn Detail

Style: Round roof Wall

materials: vinyl

Roof materials: metal

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1872

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-4-1: 23207 Pleasant Grove Road – Residence



RI-4-1: 23207 Pleasant Grove Road – Barn

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/27/14\_\_\_\_\_ Survey Number: RI-4-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 23213 Pleasant Grove Road \_\_\_\_\_

Lat/Long: 42.236472/-88.650692 \_\_\_\_\_

Primary Use: Resid \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) Residence; (B) metal shed

---

### Residence Detail

Style: Cape Cod

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete clad

Other distinguishing features: sits sideways to road

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1972 per Twp. Assessor

Number of photos taken for this property\*: one \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-4-2: 23213 Pleasant Grove Road – Residence, Shed

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/27/14\_\_\_\_\_ Survey Number: RI-4-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 23220 Pleasant Grove Road \_\_\_\_\_

Lat/Long: 42.237202/-88.650503 \_\_\_\_\_

Primary Use: Resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: four \_\_\_\_\_

List Observed Structures: (A) Residence; (B) barn; (C) concrete stave silo; (D) metal pole barn

---

## Residence Detail

Style: Foursquare

Wall materials: asphalt

Roof materials: asphalt Foundation

materials: concrete clad Other

distinguishing features:

## Barn Detail

Style: Salt Box

Wall materials: vertical wood boards

Roof materials: unknown

Foundation materials: part concrete

Other distinguishing features: rough exterior

Any obvious Additions/Alterations: Barn has Salt Box shape, or is a Peaked roof with shed extension on east side.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1872

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-4-3: 23220 Pleasant Grove Road – Barn, Sheds



RI-4-3: 23220 Pleasant Grove Road – Residence, Silo

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/27/14\_\_\_\_\_ Survey Number: RI-4-4\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 6216 Blissdale Road \_\_\_\_\_

Lat/Long: 42.237724/-88.657560 \_\_\_\_\_

Primary Use: Resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: seven \_\_\_\_\_

List Observed Structures: (A) Residence; (B) barn; (C) low shed or coop; (D) metal pole barn; (E-G) metal airplane hanger buildings not visible

---

### Residence Detail

Style: Tudor Revival

Wall materials: stucco/plaster and timbers, brick

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1920 per Twp. Assessor

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.

### Barn Detail

Style: Gambrel Roof dairy

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:



RI-4-4: 6216 Blissdale Road – Residence



RI-4-4: 6216 Blissdale Road – Barn, Sheds

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/27/14\_\_\_\_\_ Survey Number: RI-4-5\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 6307 Blissdale Road \_\_\_\_\_

Lat/Long: 42.236888/-88.657589 \_\_\_\_\_

Primary Use: Resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: four \_\_\_\_\_

List Observed Structures: (A) Residence; (B) vinyl-clad garage; (C) metal pole barn; (D) white metal pole barn

---

### Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete clad

Other distinguishing features:

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: Two-story extensions to rear of house.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1872-1892

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-4-5: 6307 Blissdale Road – Residence,  
Garage



RI-4-5: 6307 Blissdale Road - Barn



RI-4-5: 6307 Blissdale Road - Sheds

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 5



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

No Resources in Key Area

0 125 250 500 Meters

0 375 750 1,500 Feet



MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 6



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location


No Resources in Key Area

0 125 250 500 Meters

0 375 750 1,500 Feet



MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 7





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number



## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/28/14\_\_\_\_\_ Survey Number: RI-7-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 3997 County Line Road \_\_\_\_\_

Lat/Long: 42.211633/-88.704383 \_\_\_\_\_

Primary Use: Resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: three \_\_\_\_\_

List Observed Structures: (A) Residence; (B) pole barn; (C) aluminum shed

---

### Residence Detail

Style: Ranch

Wall materials: brick

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1940-1965

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



RI-7-1: 3997 County Line Road – Residence



RI-7-1: 3997 County Line Road – Sheds

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/28/14\_\_\_\_\_ Survey Number: RI-7-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 35903 Jackson Road \_\_\_\_\_

Lat/Long: 42.218271/-88.701550 \_\_\_\_\_

Primary Use: Residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) Residence; (B) pole barn; (C) aluminum shed

---

### Residence Detail

Style: Unknown/Obscured

Wall materials: vinyl

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1989 per Twp. Assessor

Number of photos taken for this property\*: one \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



RI-7-2: 25903 Jackson Road – Residence, Garage

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/28/14\_\_\_\_\_ Survey Number: RI-7-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 25709 Jackson Road \_\_\_\_\_

Lat/Long: 42.217772/-88.698634 \_\_\_\_\_

Primary Use: Resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: eight \_\_\_\_\_

List Observed Structures: (A) Residence; (B) barn; (C) concrete stave silo. (D) milk house; (E-G) sheds; (H) metal pole barn

---

### Residence Detail

Style: Side Gabled

Wall materials: wood/vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

### Barn Detail

Style: Gabled roof dairy and hay

Wall materials: vertical wood boards

Roof materials: asphalt/shake shingle

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): Milk house is metal roof, vertical board siding; high concrete foundation; Sheds are the same. Shed E has part metal roof. All have shake shingle under.

circa 1892

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-7-3: 25709 Jackson Road – Residence, Silo, Shed



RI-7-3: 25709 Jackson Road – Barns, Windmill,  
Outbuildings

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/28/14\_\_\_\_\_ Survey Number: RI-7-4\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 25619 Jackson Road \_\_\_\_\_

Lat/Long: 42.218398/-88.697671 \_\_\_\_\_

Primary Use: Residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: three \_\_\_\_\_

List Observed Structures: (A) Residence; (B) garage- asphalt, vinyl, concrete; (C) metal barn/shed

---

### Residence Detail

Style: Bungalow

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

### Barn Detail

Style: Shed type with three bays

Wall materials: metal

Roof materials: metal

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: addition to both sides of second floor near front, raising the roof line.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

circa 1930

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.




RI-7-4: 25619 Jackson Road – Residence



RI-7-4: 25619 Jackson Road – Shed, Garage

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 8



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/28/14\_\_\_\_\_ Survey Number: RI-8-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 24915 Jackson Road \_\_\_\_\_

Lat/Long: 42.218557/-88.683642 \_\_\_\_\_

Primary Use: Resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: four \_\_\_\_\_

List Observed Structures: (A) Residence; (B) barn; (C) garage; (D) metal shed

---

### Residence Detail

Style: Cross Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: wrap-around porch

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: one-story addition to west side

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): garage is asphalt, vinyl, concrete.

circa 1872

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-8-1: 24915 Jackson Road – Residence



RI-8-1: 24915 Jackson Road – Barn, Shed, Garage

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/28/14\_\_\_\_\_ Survey Number: RI-8-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 24511 Jackson Road \_\_\_\_\_

Lat/Long: 42.218205/-88.675654 \_\_\_\_\_

Primary Use: Resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: five \_\_\_\_\_

List Observed Structures: (A) Residence; (B) barn; (C) garage; (D) residence #2; (E) three metal grain bins

---

Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style: Gabled roof

Wall materials: metal sheets, wood trim

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: projecting roof peak

Any obvious Additions/Alterations: barn has along one-story extension to west

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): Residence #2 is a Ranch L.20<sup>th</sup> c.

circa 1872, 1961 per Twp. Assessor

Number of photos taken for this property\*: six \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-8-2: 24511 Jackson Road - Residence



RI-8-2: 24511 Jackson Road – Residence 2



RI-8-2: 24511 Jackson Road - Bins



RI-8-2: 24511 Jackson Road - Barn

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/28/14\_\_\_\_\_ Survey Number: RI-8-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 24511 Jackson Road \_\_\_\_\_

Lat/Long: 42.218205/-88.675654 \_\_\_\_\_

Primary Use: Resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: five \_\_\_\_\_

List Observed Structures: (A) Residence; (B) white wooden crib with shed extension; (C) grey metal/asbestos shed; (D) metal pole barn; (E) low metal shed

---

### Residence Detail

Style: Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: attached garage

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): Residence #2 is a Ranch L.20<sup>th</sup> c.

circa 1872

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



RI-8-3: 24213 Jackson Road – Barn, Sheds



RI-8-3: 24213 Jackson Road – Residence

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 9



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/28/14\_\_\_\_\_ Survey Number: RI-9-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 23810 Jackson Road \_\_\_\_\_

Lat/Long: 42.218884/-88.661863 \_\_\_\_\_

Primary Use: Resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: three \_\_\_\_\_

List Observed Structures: (A) Residence; (B) barn; (C) pole barn/shed/garage

---

### Residence Detail

Style: Cross Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

### Barn Detail

Style: Gambrel Roof

Wall materials: vinyl/metal

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: three large metal shed attachments

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

circa 1872-1892

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-9-1: 23810 Jackson Road – Barn, Sheds



RI-9-1: 23810 Jackson Road – Residence, Sheds

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/28/14\_\_\_\_\_ Survey Number: RI-9-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 7600 Blissdale Road \_\_\_\_\_

Lat/Long: 42.218371/-88.656655 \_\_\_\_\_

Primary Use: agriculture \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: four \_\_\_\_\_

List Observed Structures: (A) barn; (B) metal grain bins; (C) metal pole barn; (D) vinyl-clad shed, concrete found.

---

### Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

circa 1872

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.

### Barn Detail

Style: Gambrel Roof

Wall materials: wood board

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: T-shaped



RI-9-2: 7600 Blissdale Road – Barn, Bins, Sheds

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/28/14\_\_\_\_\_ Survey Number: RI-9-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 8015 Blissdale Road \_\_\_\_\_

Lat/Long: 42.211520/-88.657121 \_\_\_\_\_

Primary Use: residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) house; (B) metal pole barn

Residence Detail

Style: Front Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations: enclosed front porch

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

circa 1900 per Twp. Assessor

Number of photos taken for this property\*: one \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



RI-9-3: 8015 Blissdale Road – Residence, Sheds

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/28/14\_\_\_\_\_ Survey Number: RI-9-4\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 7320 Blissdale Road \_\_\_\_\_

Lat/Long: 42.221401/-88.656544 \_\_\_\_\_

Primary Use: residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group: X \_\_\_\_\_ Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) house; (B) residence

---

### Residence Detail

Style: Side Gabled

Wall materials:

Roof materials: asphalt

Foundation materials:

Other distinguishing features: may be

Minimal Traditional or older

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): property also includes Ranch house

Property Group Date Range: circa 1940-1965

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



RI-9-4: 7320 Blissdale Road – Residence



RI-9-4: 7320 Blissdale Road – Structure

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 10



Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

No Resources in Key Area

0 125 250 500 Meters

0 375 750 1,500 Feet



MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 11





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number



## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 8/28/14\_\_\_\_\_ Survey Number: RI-11-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 22006 Pleasant Grove Road \_\_\_\_\_

Lat/Long: 42.223422/-88.626587 \_\_\_\_\_

Primary Use: residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: four \_\_\_\_\_

List Observed Structures: (A) house; (B) barn; (C) shed; (D) concrete stave silo

---

### Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone?

Other distinguishing features:

### Barn Detail

Style: Unknown, top half demolished

Wall materials: wood board

Roof materials: N/A

Foundation materials: fieldstone

Other distinguishing features: mostly gone

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): shed has asphalt roof, vertical board siding.

circa 1872

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-11-1: 22006 Pleasant Grove Road –  
Residence



RI-11-1: 22006 Pleasant Grove Road – Silo,  
Shed



RI-11-1: 22006 Pleasant Grove Road - Shed

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/3/14\_\_\_\_\_ Survey Number: RI-11-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 22030 Pleasant Grove Road \_\_\_\_\_

Lat/Long: 42.224761/-88.628058 \_\_\_\_\_

Primary Use: residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) house; (B) vinyl-clad garage

---

### Residence Detail

Style: Front Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: possible schoolhouse

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

circa 1872

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-11-2: 22030 Pleasant Grove Road – Residence,  
Garage

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/3/14\_\_\_\_\_ Survey Number: RI-11-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 21805 Pleasant Grove Road \_\_\_\_\_

Lat/Long: 42.220106/-88.623375 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: four \_\_\_\_\_

List Observed Structures: (A) house; (B) garage/barn; (C) small shed; (D) concrete stave silo

---

Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

circa 1872

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style: small poss. horse barn

Wall materials: wood board

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:



RI-11-3: 21805 Pleasant Grove Road – Residence,  
Barn



RI-11-3: 21805 Pleasant Grove Road – Stable, Silo,  
Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/3/14\_\_\_\_\_ Survey Number: RI-11-4\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 21704 Pleasant Grove Road \_\_\_\_\_

Lat/Long: 42.219047/-88.620665 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: six \_\_\_\_\_

List Observed Structures: (A) house; (B) barn; (C-E) three wood-sided sheds; (F) metal pole barn; (G) metal grain bin

Residence Detail

Style: Minimal Traditional

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1948 per Twp. Assessor

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



RI-11-4: 21704 Pleasant Grove Road – Bin, Barn,  
Sheds



RI-11-4: 21704 Pleasant Grove Road – Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/3/14\_\_\_\_\_ Survey Number: RI-11-5\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 21704 Pleasant Grove Road \_\_\_\_\_

Lat/Long: 42.217858/-88.618456 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: three \_\_\_\_\_

List Observed Structures: (A) residence #1; (B) residence #2; (C) newer Gambrel-roof barn behind residence #2

---

### Residence #1 Detail

Style: No style

Wall materials: vertical wood upper, stone lower

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: Poss. converted barn

### Residence #2 Detail

Style: No style

Wall materials: wood board

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: poss.  
converted barn

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

1862 per Twp. Assessor

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-11-5: 21604 Pleasant Grove Road – Barn,  
Residence, Garage



RI-11-5: 21604 Pleasant Grove Road – Residence,  
Barn

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/3/14\_\_\_\_\_ Survey Number: RI-11-6\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 7905 IL 23\_\_\_\_\_

Lat/Long: 42.214239/-88.618634\_\_\_\_\_

Primary Use: residence\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) residence ; (B) vinyl/asphalt garage

---

### Residence Detail

Style: Cape Cod

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1940-1965

Number of photos taken for this property\*: one\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



RI-11-6: 7905 Illinois Route 23 – Residence, Garage

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/3/14\_\_\_\_\_ Survey Number: RI-11-7\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: King Residence\_\_\_\_\_

Address: 7708 IL 23\_\_\_\_\_

Lat/Long: 42.217042/-88.617839\_\_\_\_\_

Primary Use: resid/agri\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:\_\_\_\_\_ Group:  Number Structures in Group: five\_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) metal pole barn; (D) wood-sided crib; (E) metal-clad shed

---

### Residence Detail

Style: Side Gabled

Wall materials: alum/vinyl Roof

materials: asphalt Foundation

materials: unknown Other

distinguishing features:

### Barn Detail

Style: T Plan Gabled and Gambrel

Wall materials: vinyl

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: in two parts, T-shaped

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1860-1872. Local resident claims A. Lincoln stayed there.

Number of photos taken for this property\*: four\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-11-7: 7708 Illinois Route 23 – Barn, Shed



RI-11-7: 7708 Illinois Route 23 – Residence



RI-11-7: 7708 Illinois Route 23 – Shed, Barn

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/3/14\_\_\_\_\_ Survey Number: RI-11-8\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 21018 Coral Road \_\_\_\_\_

Lat/Long: 42.216134/-88.608902 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: nine \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) wood-sided crib; (D) wood-sided garage; (E) metal-clad shed; (F) small concrete block shed with wood/metal upper; (G) concrete stave silo; (H) small metal shed; (I) large concrete block shed with wood/metal upper

---

### Residence Detail

Style: Front Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete over fieldstone?

Other distinguishing features:

### Barn Detail

Style: Gabled roof

Wall materials: vertical wood board

Roof materials: asphalt over shake

Foundation materials: unknown

Other distinguishing features: shed extension to N

Any obvious Additions/Alterations: additions to E and W, enclosed front porch

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1872

Number of photos taken for this property\*: five \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-11-8: 21018 Coral Road – Residence, Barn



RI-11-8: 21018 Coral Road – Barns, Carport



RI-11-8: 21018 Coral Road – Silo, Sheds

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/3/14\_\_\_\_\_ Survey Number: RI-11-9\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 7211 IL 23 \_\_\_\_\_

Lat/Long: 42.224363/-88.609957 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: four \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) concrete block garage; (D) pole barn

---

### Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: extension to rear

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1872

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



RI-11-9: 7211 Illinois Route 23 – Residence,  
Shed




RI-11- 9: 7211 Illinois Route 23 – Garage, Shed



RI-11-9: 7211 Illinois Route 23 – Barn

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 12





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number



# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/3/14\_\_\_\_\_ Survey Number: RI-12-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 20904 Coral Road \_\_\_\_\_

Lat/Long: 42.215313/-88.602311 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: five \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) metal grain bins; (D) metal pole barn; (E) vinyl-clad garage

---

### Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1872

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.

### Barn Detail

Style: Banked Gabled roof

Wall materials: vertical wood board

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:



RI-12-1: 20904 Coral Road – Shed, Bin



RI-12- 1: 20904 Coral Road – Residence



RI-12-1: 20904 Coral Road – Barn, Garage

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/3/14\_\_\_\_\_ Survey Number: RI-12-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 7112 Maple Street \_\_\_\_\_

Lat/Long: 42.225202/-88.599813 \_\_\_\_\_

Primary Use: residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) residence; (B) metal pole barn/garage

---

### Residence Detail

Style: Front Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: roof is two-tiered

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1872-1892

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



RI-12-2: 7112 Maple Street – Residence, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/3/14\_\_\_\_\_ Survey Number: RI-12-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 7311 Maple Street \_\_\_\_\_

Lat/Long: 42.222447/-88.599465 \_\_\_\_\_

Primary Use: residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group: X \_\_\_\_\_ Number Structures in Group: three \_\_\_\_\_

List Observed Structures: (A) residence; (B) asphalt/vinyl garage; concrete silo

---

Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: two dormer windows on wing portion

Any obvious Additions/Alterations: wing portion raised. One story extension to rear.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1872

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



RI-12-3: 7311 Maple Street – Residence, Shed, Silo

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/3/14\_\_\_\_\_ Survey Number: RI-12-4\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 7602 Maple Street \_\_\_\_\_

Lat/Long: 42.219250/-88.598373 \_\_\_\_\_

Primary Use: Abandoned farmstead \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:  \_\_\_\_\_ Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: (A) shed or small barn

---

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Barn Detail

Style: Gabled roof

Wall materials: wood boards

Roof materials: shake shingles

Foundation materials: concrete

Other distinguishing features:  
deteriorating

Any obvious Additions/Alterations: barn/shed has a vertical board extension with a False front wall at the end

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

No date per Twp. Assessor

Number of photos taken for this property\*: one \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-12-4: 7602 Maple Street – Sheds

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/3/14\_\_\_\_\_ Survey Number: RI-12-5\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 20312 Coral Road \_\_\_\_\_

Lat/Long: 42.214587/-88.543630 \_\_\_\_\_

Primary Use: Resid/Agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: three \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo

---

## Residence Detail

Style: Unknown/obcured

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: obscured by foliage

## Barn Detail

Style: Gambrel-roofed dairy

Wall materials: vinyl/metal

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: attached milk house and silo

Any obvious Additions/Alterations: Two-story residence has high eaves and a low-pitched roof. Possibly originally Italianate.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1872

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-12-5: 20312 Coral Road – Barn, Silo



RI-12-5: 20312 Coral Road – Residence, Garage

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/3/14\_\_\_\_\_ Survey Number: RI-12-6\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 20120 Coral Road \_\_\_\_\_

Lat/Long: 42.214251/-88.591030 \_\_\_\_\_

Primary Use: Resid/Agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: five \_\_\_\_\_

List Observed Structures: (A) residence; (B) concrete stave silo; (C) shed; (D) small green house; (E) small gardening shed, obscured

---

### Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: outbuildings mostly obscured by foliage

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings


circa 1872

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.




RI-12-6: 20120 Coral Road – Shed, Residence



RI-12-6: 20120 Coral Road – Silo, Shed

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 13





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number



# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/3/14\_\_\_\_\_ Survey Number: RI-13-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 8703 Maple Street \_\_\_\_\_

Lat/Long: 42.201826/-88.599078 \_\_\_\_\_

Primary Use: Resid/Agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: four \_\_\_\_\_

List Observed Structures: (A) residence; (B) metal pole barn north of house; (C) metal pole barn south of house; (D) small vinyl-clad shed

---

### Residence Detail

Style: Poss. Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: obscured by foliage

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

distinguishing features:

Any obvious Additions/Alterations: two extensions to rear of house per google earth

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings


circa 1872

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-13-1: 8703 Maple Street – Sheds



RI-13-1: 8703 Maple Street – Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/3/14\_\_\_\_\_ Survey Number: RI-13-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 8202 Maple Street \_\_\_\_\_

Lat/Long: 42.209792/-88.598078 \_\_\_\_\_

Primary Use: Resid/Agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: five \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) garage; (D) metal pole barn #1; (E) metal pole barn #2

---

### Residence Detail

Style: Unknown/obscured

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: obscured by foliage

### Barn Detail

Style: Gambrel roof

Wall materials: vertical wood boards

Roof materials: metal

Foundation materials: high concrete

Other distinguishing features: tall

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1872-1892

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.




RI-13-2: 8202 Maple Street – Sheds, Barn



RI-13-2: 8202 Maple Street – Residence, Garage

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 14



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/4/14\_\_\_\_\_ Survey Number: RI-14-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 8303 IL 23\_\_\_\_\_

Lat/Long: 42.208155/-88.618901\_\_\_\_\_

Primary Use: Residence\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:  \_\_\_\_\_ Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: (A) residence

---

## Residence Detail

Style: Ranch

Wall materials: wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

## Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: google earth shows remnants of a demolished structure, prob. Barn.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1941-1951 per Twp. Assessor

Number of photos taken for this property\*: two\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-14-1: 8303 Illinois Route 23 – Residence

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/4/14\_\_\_\_\_ Survey Number: RI-14-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 8517 IL 23\_\_\_\_\_

Lat/Long: 42.204412/-88.618481\_\_\_\_\_

Primary Use: Residence\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: six\_\_\_\_\_

List Observed Structures: (A) residence; barn; (C) concrete stave silo; (D) detached milk-house; (E) concrete block garage; (F) wood sided shed with metal roof, concrete foundation

---

Residence Detail

Style: Front Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete over fieldstone

Other distinguishing features:

Barn Detail

Style: Gambrel roof

Wall materials: metal/vinyl

Roof materials: metal

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations: one-story extension to south of house

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1872

Number of photos taken for this property\*: four\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-14-2: 8517 Illinois Route 23 – Sheds, Barn, Silo



RI-14-2: 8517 Illinois Route 23 – Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/4/14\_\_\_\_\_ Survey Number: RI-14-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 8618 IL 23\_\_\_\_\_

Lat/Long: 42.202912/-88.617523\_\_\_\_\_

Primary Use: Residence\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: three\_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) metal pole barn

---

### Residence Detail

Style: Cube

Wall materials: wood boards

Roof materials: asphalt/tar paper

Foundation materials: unknown

Other distinguishing features: run-down

### Barn Detail

Style: Gabled roof

Wall materials: wood/vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: cupola

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1872

Number of photos taken for this property\*: two\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-14-3: 8618 Illinois Route 23 – Residence



RI-14-3: 8618 Illinois Route 23 – Barns

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/4/14\_\_\_\_\_ Survey Number: RI-14-4\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 8708 IL 23\_\_\_\_\_

Lat/Long: 42.202180/-88.617480\_\_\_\_\_

Primary Use: Residence\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) residence; (B) garage: asphalt, vertical wood board

---

### Residence Detail

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: attached garage

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1941-1951 per Twp. Assessor

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



RI-14-4: 8708 Illinois Route 23 – Residence, Garage

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/4/14\_\_\_\_\_ Survey Number: RI-14-5\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 8910 IL 23\_\_\_\_\_

Lat/Long: 42198169/-88.617704\_\_\_\_\_

Primary Use: agri/industr. \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: three \_\_\_\_\_

List Observed Structures: (A) large concrete block warehouse; (B) barn; (C) metal garage/office

---

### Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

### Barn Detail

Style: Round roofed

Wall materials: vertical wood board

Roof materials: shake shingles

Foundation materials: concrete

Other distinguishing features: metal cupola

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1872

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-14-5: 8910 Illinois Route 23 – Warehouse, Barn, Shed

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/4/14\_\_\_\_\_ Survey Number: RI-14-6\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 21708 Grange Road \_\_\_\_\_

Lat/Long: 42198164/-88.620692 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: seven \_\_\_\_\_

List Observed Structures: (A) residence; (B) pole barn; (C) metal grain bin; (D) concrete block shed; (E) metal-clad garage; (F) small wooden cube-shaped shed; (G) wood-sided coop with metal roof

---

### Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1872

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



RI-14-6: 21708 Grange Road – Residence, Garage,  
Shed



RI-14-6: 21708 Grange Road – Bin, Shed, Barn

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/4/14\_\_\_\_\_ Survey Number: RI-14-7\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 22008 Grange Road \_\_\_\_\_

Lat/Long: 42.198090/-88.626686 \_\_\_\_\_

Primary Use: residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) residence; (B) pole barn

---

### Residence Detail

Style: Neo-Tudor

Wall materials: brick, stucco, timbers, stone

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: attached garage

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1976 per Twp. Assessor

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



RI-14-7: 22008 Grange Road – Residence



RI-14-7: 22008 Grange Road – Garage

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/4/14\_\_\_\_\_ Survey Number: RI-14-8\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 21820 Grange Road \_\_\_\_\_

Lat/Long: 42.197206/-88.624873 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: eight \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C,D) two wood-sided sheds with metal roofs; (E) concrete stave silo; (F) detached wood-sided milk house; (G) Vinyl sided garage; (H) metal pole barn

---

### Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: decorative concrete block

Other distinguishing features:

### Barn Detail

Style: Gambrel roof

Wall materials: vertical wood board

Roof materials: asphalt/shake shingle

Foundation materials: poss. fieldstone

Other distinguishing features:

Any obvious Additions/Alterations: Wing portion roof raised; extension to rear, front porch

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1872-1892

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-14-8: 21820 Grange Road – Barn, Sheds



RI- 14-8: 21820 Grange Road – Silo



RI-14-8: 21820 Grange Road – Residence

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/4/14\_\_\_\_\_ Survey Number: RI-14-9\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 22022 Grange Road \_\_\_\_\_

Lat/Long: 42.197581/-88.627321 \_\_\_\_\_

Primary Use: residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:  \_\_\_\_\_ Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: (A) residence

---

### Residence Detail

Style: No style

Wall materials: wood, vinyl

Roof materials: asphalt, metal

Foundation materials: decorative concrete block

Other distinguishing features: attached 3-car garage

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: A barn converted to a residence. The barn is Gable-roofed with concrete block high foundation, wood board siding.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1940-1965

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-14-9: 22022 Grange Road – Residence

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 15



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/4/14\_\_\_\_\_ Survey Number: RI-15-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 22212 Grange Road \_\_\_\_\_

Lat/Long: 42.197849/-88.630755 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: eight \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) milk house; (D) garage; (E) metal pole barn #1; (F) metal pole barn #2; (G) silo (not visible); (H) metal pole barn #3 not visible)

---

### Residence Detail

Style: Gabled E1

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: brick, other

Other distinguishing features: front door turned to E side.

### Barn Detail

Style: Gabled roof

Wall materials: vertical wood board

Roof materials: metal

Foundation materials: concrete

Other distinguishing features: exterior staircase

Any obvious Additions/Alterations: Full length porch on E side (front entrance). Front porch enclosed, front door removed

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1872

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-15-1: 22212 Grange Road – Residence



RI-15-1: 22212 Grange Road – Barn, Sheds

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/4/14\_\_\_\_\_ Survey Number: RI-15-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 22414 Grange Road \_\_\_\_\_

Lat/Long: 42.198075/-88.632738 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: seven \_\_\_\_\_

List Observed Structures: (A) residence; (B) red metal pole barn; (C) metal grain bin; (D) small wooden shed with metal roof; (E) grey metal pole barn; (F) small wood sided tool shed; (G) large rambling wood sided garage/shed/barn with metal roof

---

### Residence Detail

Style: No style

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: dormer across front roof line

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1872

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

distinguishing features:



RI-15-2: 22414 Grange Road – Residence



RI- 15-2: 22414 Grange Road – Sheds



RI-15-2: 22414 Grange Road – Barn

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/4/14\_\_\_\_\_ Survey Number: RI-15-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 22620 Grange Road \_\_\_\_\_

Lat/Long: 42.200606/-88.639163 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: seven \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) concrete block garage/shed with asphalt roof; (D) small shed/garage; (E) smaller wood-sided lean-to type animal barn; (F) metal pole barn to rear; (G) white shed behind house, obscured.

---

### Residence Detail

Style: Side gabled

Wall materials: vinyl?

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features: obscured by foliage

### Barn Detail

Style: Gabled

Wall materials: vertical wood boards

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features: obscured by foliage

Any obvious Additions/Alterations: one-story rear extension to W

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1872

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-15-3: 22620 Grange Road – Residence



RI-15-3: 22620 Grange Road – Residence 2,  
Barn, Shed



RI-15-3: 22620 Grange Road – Barn, Sheds

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/4/14\_\_\_\_\_ Survey Number: RI-15-4\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 23017 Grange Road \_\_\_\_\_

Lat/Long: 42.201789/-88.606504 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group: X \_\_\_\_\_ Number Structures in Group: seven \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) garage; (D) detached milk or spring house with fieldstone foundation; (E) metal roofed machine shed; (F) metal pole barn; (G) red metal pole barn.

---

### Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete clad

Other distinguishing features:

### Barn Detail

Style: Gabled

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: front porch enclosed, front door removed, entrance now on E side.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1872

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-15-4: 23017 Grange Road – Barn, Sheds, Garage, Silo




RI-15-4: 23017 Grange Road – Residence



RI-15-4: 23017 Grange Road – Shed

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 16





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number



# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/4/14\_\_\_\_\_ Survey Number: RI-16-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 23103 Grange Road \_\_\_\_\_

Lat/Long: 42.201968/-88.647574 \_\_\_\_\_

Primary Use: resid/agri – abandoned farmstead \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: four \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) concrete block shed or smoke house; (D) peaked roof shed next to barn, obscured.

---

## Residence Detail

Style: Side Gabled

Wall materials: wood/vinyl

Roof materials: asphalt

Foundation materials: concrete clad

Other distinguishing features: obscured by foliage

## Barn Detail

Style: Gambrel roof

Wall materials: asbestos shingle

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features: obscured by foliage

Any obvious Additions/Alterations: some kind of addition or a garage next to house, obscured by foliage.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1872

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-16-1: 23103 Grange Road – Residence



RI-16-1: 23103 Grange Road – Barn, Sheds

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/4/14\_\_\_\_\_ Survey Number: RI-16-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: Keepsake Acres\_\_\_\_\_

Address: 23615 Grange Road\_\_\_\_\_

Lat/Long: 42.203556/-88.658229\_\_\_\_\_

Primary Use: resid/agri – abandoned farmstead\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:\_\_\_\_\_ Group:  Number Structures in Group: three\_\_\_\_\_

List Observed Structures: (A) residence; (B) concrete block shed or low barn; (C) concrete stave silo.

---

### Residence Detail

Style: Side Gabled

Wall materials: unknown

Roof materials: metal?

Foundation materials: unknown

Other distinguishing features: front porch.

Any obvious Additions/Alterations: house is obscured by foliage

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1872

Number of photos taken for this property\*: four\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.

### Barn Detail

Style: Gabled roof

Wall materials: concrete block, wood upper.

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features: obscured by foliage



RI-16-2: 23615 Grange Road – Residence



RI-16-2: 23615 Grange Road – Silo



RI-16-2: 23615 Grange Road – Stable

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/5/14\_\_\_\_\_ Survey Number: RI-16-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: ERC Farms\_\_\_\_\_

Address: 23615 Grange Road\_\_\_\_\_

Lat/Long: 42.203556/-88.658229\_\_\_\_\_

Primary Use: resid/Equestrian\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:\_\_\_\_\_ Group:  Number Structures in Group: three\_\_\_\_\_

List Observed Structures: (A) residence; (B) metal pole barn stables; (C) small horse or equipment barn; (D) small red shed with metal roof; (E) small red shed to west.

---

## Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: front porch.

## Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: extensions off wing portion.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1872

Number of photos taken for this property\*: four\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-16-3: 23803 Grange Road – Barn, Shed



RI-16-3: 23803 Grange Road – Residence



RI-16-3: 23803 Grange Road – Stable, Shed

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/5/14\_\_\_\_\_ Survey Number: RI-16-4\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 24002 Grange Road \_\_\_\_\_

Lat/Long: 42.204413/-88.664391 \_\_\_\_\_

Primary Use: abandoned farmstead \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: seven \_\_\_\_\_

List Observed Structures: (A) residence; (B) concrete stave silo; (C) small wooden shed, crumbling; (D) metal clad lean-to shed; (E) small wood sided shed/barn; (F) small wood sided garage or poss. apartment; (G) totally obscured outbuilding..

---

### Residence Detail

Style: Colonial Revival

Wall materials: limestone

Roof materials: asphalt

Foundation materials: limestone

Other distinguishing features: low-pitched hipped roof.

### Barn Detail

Style: demolished

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features: prob.  
Located near silo-gone now

Any obvious Additions/Alterations: house has modern additions in limestone.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1872

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-16-4: 24002 Grange Road – Silo, Shed



RI-16-4: 24002 Grange Road – Sheds



RI-16-4: 24002 Grange Road – Shed,  
Residence



RI-16-4: 24002 Grange Road - Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/5/14\_\_\_\_\_ Survey Number: RI-16-5\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 24019 Grange Road \_\_\_\_\_

Lat/Long: 42.203667/-88.665082 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: seven \_\_\_\_\_

List Observed Structures: (A) residence; (B) metal pole barn; (C) wood and concrete block stables; (D) garage; (E) small square concrete block shed; (F) 2<sup>nd</sup> Residence; (G) 2<sup>nd</sup> garage.

---

### Residence #1 Detail

Style: Cape Cod

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

### Residence #2 Detail

Style: One-story Cottage

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: Addition to W side of house

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1954-1956 per Twp. Assessor

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-16-5: 24019 Grange Road – Residence,  
Garage



RI-16-5: 24019 Grange Road – Barn, Stable,  
Shed



RI-16-5: 24019 Grange Road – Bin, Sheds

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/5/14\_\_\_\_\_ Survey Number: RI-16-6\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 24308 Grange Road \_\_\_\_\_

Lat/Long: 42.204685/-88.665795 \_\_\_\_\_

Primary Use: residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) residence; (B) metal pole barn; (C) garage

---

### Residence Detail

Style: Mansard

Wall materials: shingle, brick

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1951-1954 per Twp. Assessor

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



RI-16-6: 24308 Grange Road – Building




RI-16-6: 24308 Grange Road – Barn



RI-16-6: 24308 Grange Road – Outbuilding

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 17





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number



# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/5/14\_\_\_\_\_ Survey Number: RI-17-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 24017 Grange Road \_\_\_\_\_

Lat/Long: 42.203776/-88.666843 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: fifteen \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) detached milk house; (D-F) three concrete stave silos; (G) small wooden A-Frame; (H) wood-sided shed with metal roof; (I) wire corn bin; (J) metal grain bin; (K) white metal pole barn to rear; (L) red wood-sided equipment shed/crib; (M) small wood shed with metal roof; (N) open metal shed; (O) Quonsett barn wrapped in canvas/vinyl; (P) low Shed type wooden sided barn with metal roof and concrete foundation W of silos.

---

Residence Detail

Style: Side Gable

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

Barn Detail

Style: Gambrel Roof Dairy

Wall materials: vert. wood, vinyl

Roof materials: metal

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: three rear extensions including a garage

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1872

Number of photos taken for this property\*: six \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-17-1: 24017 Grange Road – A-Structure, Silo, Outbuildings



RI-17-1: 24017 Grange Road – Bins, Sheds



RI-17-1: 24017 Grange Road – Residence



RI-17-1: 24017 Grange Road – Barn, Sheds



RI-17-1: 24017 Grange Road – Barn, Silos

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/5/14\_\_\_\_\_ Survey Number: RI-17-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 24408 Grange Road \_\_\_\_\_

Lat/Long: 42.204401/-88.673019 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:  \_\_\_\_\_ Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: (A) residence

---

### Residence Detail

Style: Front Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: East wing of house could be an old Front Gabled

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1941-1951 per Twp. Assessor


Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-17-2: 24408 Grange Road – Residence

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 18





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number



## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/5/14\_\_\_\_\_ Survey Number: RI-18-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 25810 Grange Road \_\_\_\_\_

Lat/Long: 42.208170/-88.700701 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: eight \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) silo; (D) metal pole barn; (E) metal Gambrel roof barn; (F) grain elevator storage complex; (F) peaked-roof vinyl/metal barn; (G) pole barn equipment shed; (H) large pole barn; (I) small shed/office?

---

### Residence Detail

Style: Mansard

Wall materials: brick

Roof materials: shake single

Foundation materials: concrete

Other distinguishing features: Modern construction

### Barn Detail

Style: Modern Gambrel roofed

Wall materials: wood

Roof materials: asphalt

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1872 original farm date, but current buildings circa 1960

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-18-1: 25810 Grange Road – Barns, Silo, Bins, Shed



RI-18-1: 25810 Grange Road - Sheds



RI-18-1: 25810 Grange Road - Residence



RI-18-1: 25810 Grange Road - Barn

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/5/14\_\_\_\_\_ Survey Number: RI-18-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 3143 County Line Road \_\_\_\_\_

Lat/Long: 42.199272/-88.705216 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: six \_\_\_\_\_

List Observed Structures: (A) residence; (B) crib; (C) garage; (D) small wood/concrete/rubble structure; (E) Gambrel roof barn; (F) remains of concrete stave silo

---

### Residence Detail

Style: Cross Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: limestone

Other distinguishing features:

### Barn Detail

Style: (E) Gambrel-roof

Wall materials: vertical wood

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features: projecting peak

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings

circa 1872

Number of photos taken for this property\*: five \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-18-2: 3143 County Line Road – Residence



RI-18-2: 3143 County Line Road - Garage



RI-18-2: 3143 County Line Road – Barn, Shed



RI-18-2: 3143 County Line Road – Shed, Barn, Silo

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/5/14\_\_\_\_\_ Survey Number: RI-18-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 25306 Anthony Road \_\_\_\_\_

Lat/Long: 42.197321/-88.689965 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: fourteen \_\_\_\_\_

List Observed Structures: (A) residence #1; (B) residence #2; (C) residence #3; (D) red/green metal pole barn; (E) red/white pole barn; (F) wood shingle-sided shed with exposed roof rafter tails; (G) white two-bay garage; (H) grey/white pole barn; (I) residence #2 – modular; (J) Residence #3 ; (K) red/white metal pole barn; (L) small red/white pole barn/garage; (M) large wood-sided red barn with metal roof; (N) concrete stave silo

---

### Residence Detail

Style: Cape Cod

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: decorative concrete block

Other distinguishing features: covered front entryway

### Barn Detail

Style: (M) Gabled-roof

Wall materials: wood/vinyl

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: projecting peaks, metal cupola

Any obvious Additions/Alterations: Res #1 front and rear roof dormers.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings. Residence #3 is an Upright and Wing, asphalt roof, vinyl siding, limestone foundation.

circa 1872

Number of photos taken for this property\*: five \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-18-3: 25306 Anthony Road – Outbuildings



RI-18-3: 25306 Anthony Road – Shed, Garages



RI-18-3: 25306 Anthony Road – Residence



RI-18-3: 25306 Anthony Road – Sheds



RI-18-3: 25306 Anthony Road – Residence 2,  
Barn



RI-18-3: 25306 Anthony Road – Residence 3,  
Sheds



RI-18-3: 25306 Anthony Road – Silo, Barn

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 19





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number



## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/5/14\_\_\_\_\_ Survey Number: RI-19-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 25113 Anthony Road \_\_\_\_\_

Lat/Long: 42.196120/-88.687418 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: five \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) grain bins; (D) pole barn; (E) large pole barn equipment shed/garage

---

### Residence Detail

Style: No style

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: front remodeled

### Barn Detail

Style: Gabled-roof

Wall materials: vertical wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: shed added

Any obvious Additions/Alterations: front porch expanded, enclosed, given a peaked roof.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings.

circa 1872

Number of photos taken for this property\*: five \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-19-1: 25113 Anthony Road – Residence



RI-19-1: 25113 Anthony Road – Barn, Bins, Sheds



RI-19-1: 25113 Anthony Road – Shed

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/5/14\_\_\_\_\_ Survey Number: RI-19-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 25410 Harmony Road \_\_\_\_\_

Lat/Long: 42.182782/-88.693014 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: seven \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) 2 concrete stave silos; (D) small wood-sided shed; (E) low, long metal shed; (F) wood-sided crib with metal roof; (G) small wood-sided shed

---

### Residence Detail

Style: Neo-Colonial

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: wrap-around front porch

### Barn Detail

Style: Gambrel roof

Wall materials: vertical wood

Roof materials: unknown

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings.

circa 1872

Number of photos taken for this property\*: five \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-19-2: 25410 Harmony Road – Residence



RI-19-2: 25410 Harmony Road – Sheds



RI-19-2: 25410 Harmony Road – Barn, Silos

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/5/14\_\_\_\_\_ Survey Number: RI-19-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 25814 Harmony Road \_\_\_\_\_

Lat/Long: 42.183740/-88.701058 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: four \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) metal pole barn

---

### Residence Detail

Style: Queen Anne/Cross Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

### Barn Detail

Style: Gambrel roof

Wall materials: wood

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: in two sections - T-shaped

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings.

circa 1872

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-19-3: 25814 Harmony Road - Residence



RI-19-3: 25814 Harmony Road – Barn, Silo

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/5/14\_\_\_\_\_ Survey Number: RI-19-4\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 2293 Harmony Road \_\_\_\_\_

Lat/Long: 42.186604/-88.703419 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: four \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) metal pole barn; (D) metal pole barn

---

### Residence Detail

Style: Unknown - obscured

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

### Barn Detail

Style: Gabled roof

Wall materials: wood

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: two  
dormers

Any obvious Additions/Alterations: one-story addition to N

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings.

circa 1872

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-19-4: 2293 County Line Road – Residence, Barn,  
Sheds

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/5/14\_\_\_\_\_ Survey Number: RI-19-5\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 2301 County Line Road \_\_\_\_\_

Lat/Long: 42.192783/-88.704883 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: four \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) metal shed; (D) metal pole barn

---

Residence Detail

Style: Italianate

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: poss. fieldstone

Other distinguishing features: obscured

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed buildings.

circa 1872

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.




RI-19-5: 2301 County Line Road - Outbuildings



RI-19-5: 2301 County Line Road – Residence

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 20





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number



## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/17/14\_\_\_\_\_ Survey Number: RI-20-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 25010 Anthony Road \_\_\_\_\_

Lat/Long: 42.195870/-88.684543 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: four \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) shed/barn #1; (D) shed/barn #2; (E) milk or spring house

---

### Residence Detail

Style: Cross Gabled/Queen Anne

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: attached garage

### Barn Detail

Style: Gambrel Roof

Wall materials: vertical wood, vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): both shed/barns and milk/spring house are peaked asphalt roofed, wood board siding, concrete foundations

circa 1872

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-20-1: 25010 Anthony Road – Barn, Sheds



RI-20-1: 25010 Anthony Road – Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/17/14\_\_\_\_\_ Survey Number: RI-20-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 24810 Anthony Road \_\_\_\_\_

Lat/Long: 42.195592/-88.680691 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: four \_\_\_\_\_

List Observed Structures: (A) residence; (B) metal/vinyl shed/garage and connected wood-sided coop; (C) metal pole barn with shed overhang

---

### Residence Detail

Style: Upright and Wing

Wall materials: alum/vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: enclosed front porch with concrete foundation

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

circa 1872

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-20-2: 24810 Anthony Road – Residence,  
Shed



RI-20-2: 24810 Anthony Road – Garage, Shed



RI-20-2: 24810 Anthony Road – Shed

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/17/14\_\_\_\_\_ Survey Number: RI-20-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 24317 Anthony Road \_\_\_\_\_

Lat/Long: 42.194805/-88.671979 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) residence; (B) metal pole barn stable

---

### Residence Detail

Style: Minimal Traditional

Wall materials: vinyl/brick

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: attached garage

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

circa 1975 per Twp. Assessor

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-20-3: 24317 Anthony Road – Residence, Barn

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/17/14\_\_\_\_\_ Survey Number: RI-20-4\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 24040 Anthony Road \_\_\_\_\_

Lat/Long: 42.194137/-88.666706 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: minimum four \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) series of connected metal-clad sheds

---

## Residence Detail

Style: Unknown - obscured

Wall materials: limestone

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: obscured

## Barn Detail

Style: Gabled roof

Wall materials: alum/vinyl

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: projecting roof peaks

Any obvious Additions/Alterations: one-story vinyl-sided wing. Main house appears to constructed of limestone

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

circa 1941-1951 per Twp. Assessor

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-20-4: 24040 Anthony Road – Residence, Barn, Silo

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/17/14\_\_\_\_\_ Survey Number: RI-20-5\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 24102 Anthony Road \_\_\_\_\_

Lat/Long: 42.182813/-88.666823 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: minimum four \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) metal grain bin

---

Residence Detail

Style: No style

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: obscured

Barn Detail

Style: Round roofed

Wall materials: wood board

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

circa 1872

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-20-5: 24102 Harmony Road – Barn, Silo, Bins



RI-20-5: 24102 Harmony Road – Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/17/14\_\_\_\_\_ Survey Number: RI-20-6\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 24520 Harmony Road \_\_\_\_\_

Lat/Long: 42.182705/-88.675889 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: three \_\_\_\_\_

List Observed Structures: (A) residence; (B) connected vinyl/metal garage and equipment shed; (C) open lean-to animal shed

---

### Residence Detail

Style: Queen Anne

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: 2<sup>nd</sup> floor roof deck, front door faces E

### Barn Detail

Style: sheds

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

circa 1872

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.




RI-20-6: 24520 Harmony Road – Garage, Bins, Shed



RI-20-6: 24520 Harmony Road – Residence

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 21



Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/17/14\_\_\_\_\_ Survey Number: RI-21-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 23703 Harmony Road \_\_\_\_\_

Lat/Long: 42.194162/-88.659107 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn

---

### Residence Detail

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: Modern construction

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

circa 1960

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-21-1: 23703 Anthony Road – Residence



RI-21-1: 23703 Anthony Road – Barn

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/17/14\_\_\_\_\_ Survey Number: RI-21-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 23611 Anthony Road \_\_\_\_\_

Lat/Long: 42.193820/-88.658082 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) residence; (B) pole barn; (C) small tool shed

---

### Residence Detail

Style: No style

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: large, rambling modern construction or additions. Poss. originally a Gabled El or Upright and Wing, or all new

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

circa 1993 per Twp. Assessor - actual date circa 1900

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-21-2: 23611 Anthony Road – Residence



RI-21-2: 23611 Anthony Road – Barn, Shed

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/17/14\_\_\_\_\_ Survey Number: RI-21-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 23513 Anthony Road \_\_\_\_\_

Lat/Long: 42.193768/-88.656258 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) residence; (B) concrete stave silo

---

## Residence Detail

Style: Cape Cod

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: attached garage

## Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

circa 1872-1892

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-21-3: 23513 Anthony Road – Residence, Silo

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/17/14\_\_\_\_\_ Survey Number: RI-21-4\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 23315 Anthony Road \_\_\_\_\_

Lat/Long: 42.193641/-88.652841 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: five \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) concrete stove silo; (D) milk house with concrete foundation; (E) garage

---

## Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

## Barn Detail

Style: Gabled roof center bay

Wall materials: vertical wood board

Roof materials: shake shingles

Foundation materials: fieldstone

Other distinguishing features: side shed wings have concrete foundations

Any obvious Additions/Alterations: front porch enclosed and given a concrete block foundation. Extensions to rear.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

circa 1872

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-21-4: 23315 Anthony Road – Barn, Silo, Shed



RI-21-4: 23315 Anthony Road – Residence, Garage

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/17/14\_\_\_\_\_ Survey Number: RI-21-5\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: The Friendly Confines\_\_\_\_\_

Address: 23706 Harmony Road\_\_\_\_\_

Lat/Long: 42.182633/-88.659176\_\_\_\_\_

Primary Use: resid/agri\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:\_\_\_\_\_ Group: X\_\_\_\_\_ Number Structures in Group: ten\_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) barrel roof pole barn; (D) metal and frame equipment shed; (E) low coop or shed; (F) white metal pole barn/garage; (G) coop with metal roof and large cupola; (H) 3<sup>rd</sup> metal pole barn; (I) two plastic covered Quonsett sheds; (J) metal grain bins

---

### Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete clad

Other distinguishing features:

### Barn Detail

Style: Gambrel Roof

Wall materials: vertical wood board

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

Any obvious Additions/Alterations: front porch enclosed and given a concrete block foundation. Extensions to rear.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

circa 1872

Number of photos taken for this property\*: six\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-21-5: 23706 Harmony Road – Bin, Barns, Sheds



RI-21-5: 23706 Harmony Road – Residence



RI-21-5: 23706 Harmony Road – Barn



RI-21-5: 23706 Harmony Road – Barn, Sheds

MCHENRY COUNTY  
 RILEY TOWNSHIP  
 SECTION 22





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
 Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number



# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14\_\_\_\_\_ Survey Number: RI-22-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 22906 Harmony Road\_\_\_\_\_

Lat/Long: 42.183185/-88.643630\_\_\_\_\_

Primary Use: resid/agri\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:\_\_\_\_\_ Group:  Number Structures in Group: six\_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) concrete silo; (D) detached milk house or small shed; (E) wood-sided crib with metal roof; (F) metal pole barn

---

### Residence Detail

Style: Upright and Wing

Wall materials: vinyl and wood

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

### Barn Detail

Style: L-shaped Gabled roof dairy

Wall materials: vertical wood

board Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

No date per Twp. Assessor. Circa 1860s-1870s. A residence is shown just south of this location on 1872 and 1892 plats

Number of photos taken for this property\*: three\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-22-1: 22906 Harmony Road – Residence



RI-22-1: 23315 Anthony Road – Barn, Silo, Sheds

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14\_\_\_\_\_ Survey Number: RI-22-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 22506 Harmony Road\_\_\_\_\_

Lat/Long: 42.182725/-88.635863\_\_\_\_\_

Primary Use: residence\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:\_\_\_\_\_ Group: X\_\_\_\_\_ Number Structures in Group: three\_\_\_\_\_

List Observed Structures: (A) residence; (B) garage; (C) small wood-sided shed on concrete foundation

---

### Residence Detail

Style: Gabled EI

Wall materials: asbestos shingle?

Roof materials: asphalt

Foundation materials: fieldstone or limestone

Other distinguishing features:

### Barn Detail

Style

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: rear extension

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa 1872

Number of photos taken for this property\*: four\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-22-2: 22506 Harmony Road – Shed



RI-22-2: 22506 Anthony Road – Residence, Garage

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14\_\_\_\_\_ Survey Number: RI-22-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 23003 Anthony Road\_\_\_\_\_

Lat/Long: 42.192826/-88.645655\_\_\_\_\_

Primary Use: resid/agri\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:\_\_\_\_\_ Group: X\_\_\_\_\_ Number Structures in Group: five\_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) silo; (D) pole barn; (E) garage

---

## Residence Detail

Style: Side Gabled

Wall materials: alum/vinyl

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features:

## Barn Detail

Style: Gabled roof/raised Gambrel

Wall materials: wood

Roof materials: asphalt

Foundation materials: concrete?

Other distinguishing features: attached milk house

Any obvious Additions/Alterations: rear extension

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa 1872-1892

Number of photos taken for this property\*: five\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-22-3: 23003 Anthony Road – Barn, Silo



RI-22-3: 23003 Anthony Road – Shed



RI-22-3: 23003 Anthony Road – Residence



RI-22-3: 23003 Anthony Road – Garage

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14\_\_\_\_\_ Survey Number: RI-22-4\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 22613 Anthony Road\_\_\_\_\_

Lat/Long: 42.192074/-88.638570\_\_\_\_\_

Primary Use: resid/agri\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:\_\_\_\_\_ Group:  Number Structures in Group: five\_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) garage; (D) wood-sided equipment shed; (E) small wood-sided shed with center roof chimney.

---

## Residence Detail

Style: Upright and Wing

Wall materials: alum/vinyl

Roof materials: asphalt

Foundation materials: concrete covered

Other distinguishing features:

## Barn Detail

Style: Gabled roof, banked

Wall materials: vertical wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: shed extension

Any obvious Additions/Alterations: rear extension

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa 1872

Number of photos taken for this property\*: six\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-22-4: 22613 Anthony Road – Residence,  
Garage



RI-22-4: 22613 Anthony Road - Barn



RI-22-4: 22613 Anthony Road - Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14\_\_\_\_\_ Survey Number: RI-22-5\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: Riley Center Memorial Cemetery\_\_\_\_\_

Address: 9350 Riley Road\_\_\_\_\_

Lat/Long: 42.192998/-88.632792\_\_\_\_\_

Primary Use: Cemetery (1850 – 1939)\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: X\_\_\_\_\_ Group:\_\_\_\_\_ Number Structures in Group:\_\_\_\_\_

List Observed Structures:

\_\_\_\_\_

Residence Detail

Barn Detail

Style:

Style:

Wall materials:

Wall materials:

Roof materials:

Roof materials:

Foundation materials:

Foundation materials:

Other distinguishing features:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Before 1862 per Twp. Assessor. (circa 1850 – 1939)

Number of photos taken for this property\*: two\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-22-5: 9350 Riley Road – Cemetery, Gate

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14\_\_\_\_\_ Survey Number: RI-22-6\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: Riley Township Town Hall, built 1868\_\_\_\_\_

Address: 9312 Riley Road\_\_\_\_\_

Lat/Long: 42.193080/-88.632433\_\_\_\_\_

Primary Use: Municipal\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group: X \_\_\_\_\_ Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) Town Hall building; (B) Pole barn garage

---

### Residence Detail

Style: Front Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete clad

Other distinguishing features:

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

M.C.H.S. Plaque #7 says 1868

Number of photos taken for this property\*: two\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-22-6: 9312 Riley Road – Building



RI-22-6: 9312 Riley Road – Plaque

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14\_\_\_\_\_ Survey Number: RI-22-7\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: Riley United Methodist Church\_\_\_\_\_

Address: 9316 Riley Road\_\_\_\_\_

Lat/Long: 42.192778/-88.632438\_\_\_\_\_

Primary Use: Church\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:  \_\_\_\_\_ Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: (A) Church

---

### Residence Detail

Style: Gothic Revival

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

M.C.H.S. Plaque #35 says 1898.

Number of photos taken for this property\*: three\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-22-7: 9316 Riley Road – Riley United Methodist Church



RI-22-7: 9316 Riley Road – Plaque

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14\_\_\_\_\_ Survey Number: RI-22-8\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: Riley Elementary School\_\_\_\_\_

Address: 9320 Riley Road\_\_\_\_\_

Lat/Long: 42.192196/-88.632307\_\_\_\_\_

Primary Use: School\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:  \_\_\_\_\_ Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: (A) School

---

## Residence Detail

Style: M.20<sup>th</sup> c. Institutional

Wall materials: brick

Roof materials: asphalt/tar

Foundation materials: concrete

Other distinguishing features:

## Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

No record per Twp. Assessor. - circa 1940

Number of photos taken for this property\*: one\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-22-8: 9320 Riley Road – Riley Elementary School

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14\_\_\_\_\_ Survey Number: RI-22-9\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 22501 Anthony Road \_\_\_\_\_

Lat/Long: 42.191803/-88.633194 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: eight \_\_\_\_\_

List Observed Structures: (A) residence; (B) residence #2; (C) barn; (D) wood-sided crib (E) concrete stave silo; (F) Three-bay garage; (G) brick or concrete shed with metal roof; (H) vinyl sided shed with metal roof

---

### Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete clad

Other distinguishing features: newer large chimney

### Barn Detail

Style: Gambrel roof dairy

Wall materials: vertical wood

Roof materials: metal

Foundation materials: concrete

Other distinguishing features: metal cupola

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): Residence #2: One-story Side Gabled or Cape, asphalt, vinyl, concrete.

Circa 1872

Number of photos taken for this property\*: six \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-22-9: 22501 Anthony Road – Barn



RI-22-9: 22501 Anthony Road – Barn,  
Silo, Garage



RI-22-9: 22501 Anthony Road – Residence



RI-22-9: 22501 Anthony Road – Barns,  
Silo, Sheds, Outbuilding

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14\_\_\_\_\_ Survey Number: RI-22-10\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 9119 Riley Road \_\_\_\_\_

Lat/Long: 42.195493/-88.633689 \_\_\_\_\_

Primary Use: residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) residence; (B) garage

---

### Residence Detail

Style: Front Gabled

Wall materials: wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

circa 1872

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-22-10: 9119 Riley Road – Residence, Garage

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14\_\_\_\_\_ Survey Number: RI-22-11\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: Q 7 Ranch\_\_\_\_\_

Address: 22106 Anthony Road\_\_\_\_\_

Lat/Long: 42.191631/-88.628385\_\_\_\_\_

Primary Use: residence\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:\_\_\_\_\_ Group:  Number Structures in Group: four\_\_\_\_\_

List Observed Structures: (A) residence; (B) Pole barn #1; (C) Pole Barn #2; (D) Pole barn #3

---

## Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: wrap-around porch, front door faces E

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Circa 1872-1892

Number of photos taken for this property\*: five\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.

## Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials: Other

distinguishing features:



RI-22-11: 22106 Anthony Road – Residence



RI-22-11: 22106 Anthony Road – Barn



RI-22-11: 22106 Anthony Road – Shed



RI-22-11: 22106 Anthony Road – Shed

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 23



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14\_\_\_\_\_ Survey Number: RI-23-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 9512 IL 23\_\_\_\_\_

Lat/Long: 42.190397/-88.617869\_\_\_\_\_

Primary Use: residence\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:  \_\_\_\_\_ Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: (A) residence

---

### Residence Detail

Style: Bungalow

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: front porch

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Circa 1872

Number of photos taken for this property\*: one\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-23-1: 9512 Illinois Route 23 - Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14\_\_\_\_\_ Survey Number: RI-23-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 21313 Anthony Road \_\_\_\_\_

Lat/Long: 42.189430/-88.614053 \_\_\_\_\_

Primary Use: residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group: X \_\_\_\_\_ Number Structures in Group: five \_\_\_\_\_

List Observed Structures: (A) residence; (B) metal pole barn; (C) metal Quonset shed/garage

---

### Residence Detail

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: attached garage

### Barn Detail

Style:

Wall materials:

Roof materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

circa 1957 per Twp. Assessor.

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-23-2: 21313 Anthony Road - Residence



RI-23-2: 21313 Anthony Road - Shed



RI-23-2: 21313 Anthony Road - Outbuilding

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14\_\_\_\_\_ Survey Number: RI-23-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 21108 Anthony Road \_\_\_\_\_

Lat/Long: 42.190140/-88.609247 \_\_\_\_\_

Primary Use: residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: three \_\_\_\_\_

List Observed Structures: (A) residence; (B) concrete stave silo; (C) small wood-sided shed

---

### Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: front porch

### Barn Detail

Style:

Wall materials:

Roof materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc):

Circa 1872

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-23-3: 21108 Anthony Road – Silo, Shed



RI-23-3: 21108 Anthony Road - Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14\_\_\_\_\_ Survey Number: RI-23-4\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 9809 IL 23\_\_\_\_\_

Lat/Long: 42.185970/-88.618405\_\_\_\_\_

Primary Use: resid/agri\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: five \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) metal pole barn; (D) Quonsett shed; (E) small wooden shed, collapsing

---

### Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

### Barn Detail

Style: Gambrel roof

Wall materials: wood board

Roof materials: asphalt over shake

Other distinguishing features: wooden cupola

Any obvious Additions/Alterations: large addition to rear.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa 1872

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-23-4: 9809 Illinois Route 23 – Barn, Shed



RI-23-4: 9809 Illinois Route 23 - Residence



RI-23-4: 9809 Illinois Route 23 – Barn, Sheds

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14\_\_\_\_\_ Survey Number: RI-23-5\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: Harmony Oaks Stalls\_\_\_\_\_

Address: 21516 Harmony Road\_\_\_\_\_

Lat/Long: 42.182792/-88.617421\_\_\_\_\_

Primary Use: resid/Equestrian\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:\_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: five\_\_\_\_\_

List Observed Structures: (A) residence; (B) trailer home; (C) metal pole barn #1; (D) metal pole barn #2; (E) metal pole barn /stables

---

### Residence Detail

Style: Minimal Traditional

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: attached garage

### Barn Detail

Style:

Wall materials:

Roof materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

circa 1952 per Twp. Assessor.

Number of photos taken for this property\*: five\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-23-5: 21516 Harmony Road - Outbuildings



RI-23-5: 21516 Harmony Road - Residence



RI-23-5: 21516 Harmony Road - Stable



RI-23-5: 21516 Harmony Road - Stable

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/18/14\_\_\_\_\_ Survey Number: RI-23-6\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: Harmony Oaks Stalls\_\_\_\_\_

Address: 9314 IL 23\_\_\_\_\_

Lat/Long: 42.193035/-88.617491\_\_\_\_\_

Primary Use: residence\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:  \_\_\_\_\_ Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: (A) residence

---

### Residence Detail

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: attached garage

### Barn Detail

Style:

Wall materials:

Roof materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

circa 1960 per Twp. Assessor.


Number of photos taken for this property\*: one\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-23-6: 9314 Illinois Route 23 - Residence

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 24



Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

0 125 250 500 Meters

0 375 750 1,500 Feet

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number



# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/30/14\_\_\_\_\_ Survey Number: RI-24-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 1006 Maple Street \_\_\_\_\_

Lat/Long: 42.183729/-88.598192 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: five \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) trailer/mobile home; (D) garage; (E) metal pole barn

---

## Residence Detail

Style: Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

## Barn Detail

Style: Gambrel roof

Wall materials: metal/vinyl

Roof materials: metal

Other distinguishing features: one-story attachment

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa 1872

Number of photos taken for this property\*: six \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-24-1: 10006 Maple Street - Residence



RI-24-1: 10006 Maple Street - Barn



RI-24-1: 10006 Maple Street - Trailer



RI-24-1: 10006 Maple Street - Outbuildings

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/30/14\_\_\_\_\_ Survey Number: RI-24-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 20704 Anthony Road \_\_\_\_\_

Lat/Long: 42.190097/-88.601062 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: five \_\_\_\_\_

List Observed Structures: (A) residence; (B) shed/barn; (C) wood-sided shed/barn; (D) small wood-sided tool shed; (E) pole barn in back, obscured

---

## Residence Detail

Style: Upright and Wing

Wall materials: asbestos shingle

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features:

## Barn Detail

Style: Gabled

Wall materials: vertical wood

Roof materials: metal

Foundation materials: concrete visible

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa 1872

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-24-2: 20704 Anthony Road – Sheds



RI-24-2: 20704 Anthony Road - Shed



RI-24-2: 20704 Anthony Road – Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/30/14\_\_\_\_\_ Survey Number: RI-24-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 20806 Anthony Road \_\_\_\_\_

Lat/Long: 42.190125/-88.603708 \_\_\_\_\_

Primary Use: residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) residence; (B) vinyl clad garage

---

### Residence Detail

Style: Cape Cod

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa 1872

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-24-3: 20806 Anthony Road – Residence



RI-24-3: 20806 Anthony Road - Garage

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/30/14\_\_\_\_\_ Survey Number: RI-24-4\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 21010 Anthony Road \_\_\_\_\_

Lat/Long: 42.189940/-88.607162 \_\_\_\_\_

Primary Use: residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group: X \_\_\_\_\_ Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) residence; (B) large metal pole barn/possible plane hanger

Residence Detail

Style: Front Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

circa 1872

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-24-4: 21010 Anthony Road – Residence



RI-24-4: 21010 Anthony Road – Hangar

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/30/14\_\_\_\_\_ Survey Number: RI-24-5\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 20309 Beck Road \_\_\_\_\_

Lat/Long: 42.193712/-88.593939 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: four \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) Gambrel roof L-shaped garage

---

Residence Detail

Style: Foursquare

Wall materials: alum/vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: front door faces diagonally at NE corner

Barn Detail

Style: tall Gambrel roof

Wall materials: asbestos shingles

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: high foundation

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa 1872

Number of photos taken for this property\*: five \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-24-5: 20309 Beck Road – Barn, Silo



RI-24-5: 20309 Beck Road - Barn



RI-24-5: 20309 Beck Road – Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/30/14\_\_\_\_\_ Survey Number: RI-24-6\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 20216 Beck Road \_\_\_\_\_

Lat/Long: 42.195224/-88.891175 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: thirteen \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) wire grain bin; (E) garage (attached); (F) metal pole barn; (G) metal/wood pole barn; (H) small metal shed; (I) small wood-sided shed with asphalt roof; (J) fieldstone smoke house with wood upper, asphalt roof, probable stone foundation; (K) small tool shed or detached milk house; (L) metal garage; (M) small wood-sided barn/shed, asphalt roof, concrete foundation.

---

### Residence Detail

Style: Upright and Wing

Wall materials: alum/vinyl

Roof materials: asphalt

Foundation materials: concrete clad

Other distinguishing features:

### Barn Detail

Style: Gambreled

Wall materials:

Roof materials: metal

Foundation materials: concrete

Other distinguishing features: two metal vents

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

circa 1872

Number of photos taken for this property\*: eight \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-24-6: 20216 Beck Road – Bin, Outbuildings



RI-24-6: 20216 Beck Road – Barn, Silo, Outbuilding



RI-24-6: 20216 Beck Road - Outbuilding




RI-24-6: 20216 Beck Road - Residence



RI-24-6: 20216 Beck Road - Outbuildings

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 25



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/30/14\_\_\_\_\_ Survey Number: RI-25-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 20201 Harmony Road \_\_\_\_\_

Lat/Long: 42.177451/-88.591647 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: five \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) concrete stove silo; (D) small lean-to shed; (E) metal pole barn/garage

### Residence Detail

Style: Foursquare

Wall materials: alum/vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: extension to rear

### Barn Detail

Style: Round roofed

Wall materials: vertical wood board

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: attached milk house

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa 1872

Number of photos taken for this property\*: five \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-25-1: 20201 Harmony Road – Barn, Silo, Shed



RI-25-1: 20201 Harmony Road – Barn, Silo



RI-25-1: 20201 Harmony Road – Residence, Outbuilding

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/30/14\_\_\_\_\_ Survey Number: RI-25-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 10601 Getty Road \_\_\_\_\_

Lat/Long: 42.175069/-88.594082 \_\_\_\_\_

Primary Use: residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) residence; (B) small shed

Residence Detail

Style: Gabled EI

Wall materials: wood clapboard

Roof materials: asphalt

Foundation materials: concrete over stone

Other distinguishing features: enclosed front porch

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

No record per Twp. Assessor. (L. 19<sup>th</sup> c.) - circa 1900

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-25-2: 10601 Getty Road – Shed



RI-25-2: 10601 Getty Road – Residence

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 26





Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number



# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/30/14\_\_\_\_\_ Survey Number: RI-26-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 21303 Harmony Road \_\_\_\_\_

Lat/Long: 42.182186/-88.612410 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: six \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) metal pole barn; (E) wood-sided shed/garage with metal roof; (F) metal pole barn equipment garage

### Residence Detail

Style: No style

Wall materials: wood/vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: two-story wrap-around porches

### Barn Detail

Style: Gambrel roof

Wall materials: vertical board

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures

Circa 1941-1951 per Twp. Assessor. - actual circa 1900

Number of photos taken for this property\*: five \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-26-1: 21303 Harmony Road – Residence



RI-26-1: 21303 Harmony Road – Barn, Silo



RI-26-1: 21303 Harmony Road - Outbuildings



RI-26-1: 21303 Harmony Road - Outbuilding

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/30/14\_\_\_\_\_ Survey Number: RI-26-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 10610 Coon Creek Road \_\_\_\_\_

Lat/Long: 42.174517/-88.617109 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group: X \_\_\_\_\_ Number Structures in Group: five \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) barn #2; (D) concrete silo, lower portion only; (E) low shed or coop

### Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: Enclosed front porch, bay window on S

### Barn Detail

Style: Gambrel roof

Wall materials: wood/alum

Roof materials: unknown

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. Barn #2 is a large Gabled roof dairy and hay barn that is collapsing.

Circa 1872

Number of photos taken for this property\*: four\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-26-2: 10610 Coon Creek Road – Residence,  
Barn



RI-26-2: 10610 Coon Creek Road – Barn, Silo



RI-26-2: 10610 Coon Creek Road – Outbuilding

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/30/14\_\_\_\_\_ Survey Number: RI-26-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 10816 Coon Creek Road \_\_\_\_\_

Lat/Long: 42.171399/-88.627121 \_\_\_\_\_

Primary Use: resid/agri, abandoned \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group: X \_\_\_\_\_ Number Structures in Group: seven \_\_\_\_\_

List Observed Structures: (A) residence; (B) pole barn with extended roof; (C) concrete stave silo; (D) metal shed/equipment barn; (E) small, low possible 2<sup>nd</sup> residence; (F) three-bay garage; (G) unknown stone foundation on property

### Residence Detail

Style: Cross-Gabled

Wall materials: alum.vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: abandoned

### Barn Detail

Style: Gambrel roof

Wall materials: alum/vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: metal vent

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property\*: five \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-26-3: 10816 Carls Road – Residence, Silo,  
Barn, Shed



RI-26-3: 10816 Carls Road – Shed




RI-26-3: 10816 Carls Road – Shed, Garage



RI-26-3: 10816 Carls Road – Stone Foundation

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 27





Copyright: © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number



## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/30/14\_\_\_\_\_ Survey Number: RI-27-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 10409 Carls Road \_\_\_\_\_

Lat/Long: 42.177257/-88.628227 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: five \_\_\_\_\_

List Observed Structures: (A) residence; (B) metal pole barn; (C) garage; (D) larger metal pole barn; (E) small, wood sided shed with barn doors

### Residence Detail

Style: Cape Cod

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1939 per Twp. Assessor.

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-27-1: 10409 Carls Road – Barn, Shed, Garage



RI-27-1: 10409 Carls Road – Residence



RI-27-1: 10409 Carls Road – Shed

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/30/14\_\_\_\_\_ Survey Number: RI-27-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 10607 Carls Road \_\_\_\_\_

Lat/Long: 42.174374/-88.628740 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: three \_\_\_\_\_

List Observed Structures: (A) residence; (B) obscured outbuilding; (C) open sided lean-to shed

### Residence Detail

Style: Ranch

Wall materials: wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: attached garage

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1975 per Twp. Assessor.

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-27-2: 10607 Carls Road – Residence



RI-27-2: 10607 Carls Road – Outbuildings

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/30/14\_\_\_\_\_ Survey Number: RI-27-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 22314 Hartman Road \_\_\_\_\_

Lat/Long: 42.168438/-88.632813 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: three \_\_\_\_\_

List Observed Structures: (A) residence; (B) pole barn; (C) pole barn

### Residence Detail

Style: Ranch

Wall materials: brick/wood/vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: attached garage

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1960

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-27-3: 22314 Hartman Road – Barn, Shed



RI-27-3: 22314 Hartman Road – Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/30/14\_\_\_\_\_ Survey Number: RI-27-4\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 22704 Hartman Road \_\_\_\_\_

Lat/Long: 42.168126/-88.640127 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: six \_\_\_\_\_

List Observed Structures: (A) residence; (B) garage; (C) two-bay garage/shed with metal roof; (D) wood-sided out-house; (E) wood-sided milk house with shake shingle roof and concrete foundation; (F) concrete foundations from demolished barn

### Residence Detail

Style: Foursquare

Wall materials: brick/wood/vinyl

Roof materials: asphalt

Foundation materials: concrete clad

Other distinguishing features:

### Barn Detail

Style: demolished

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: one story addition

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-27-4: 22704 Hartman Road – Outbuildings



RI-27-4: 22704 Hartman Road – Residence, Garage

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/30/14\_\_\_\_\_ Survey Number: RI-27-5\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 22901 Harmony Road \_\_\_\_\_

Lat/Long: 42.182205/-88.642338 \_\_\_\_\_

Primary Use: agri, abandoned \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group: X \_\_\_\_\_ Number Structures in Group: three \_\_\_\_\_

List Observed Structures: (A) concrete stave silo; (B) small wood-sided shed with shake shingle roof; (C) metal pole barn

Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872-1892

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-27-5: 22901 Hartman Road – Silo, Shed



RI-27-5: 22901 Hartman Road – Shed

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 9/30/14\_\_\_\_\_ Survey Number: RI-27-6\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 22605 Harmony Road \_\_\_\_\_

Lat/Long: 42.182204/-88.637740 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: four \_\_\_\_\_

List Observed Structures: (A) residence; (B) garage; (C) small wood-sided shed with shake shingle roof; (D) obscured outbuilding

### Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: extension to west

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1848 per Twp. Assessor.

Number of photos taken for this property\*: five \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.




RI-27-6: 22605 Harmony Road – Residence,  
Outbuilding



RI-27-6: 22605 Harmony Road – Outbuildings

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 28



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/6/14\_\_\_\_\_ Survey Number: RI-28-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 10105 Payne Road \_\_\_\_\_

Lat/Long: 42.182137/-88.647479 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: three \_\_\_\_\_

List Observed Structures: (A) residence; (B) garage; (C) equipment barn/shed: asphalt, vinyl, concrete

### Residence Detail

Style: Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete clad

Other distinguishing features:

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1872

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-28-1: 10105 Payne Road – Shed



RI-28-1: 10105 Payne Road – Residence, Garage

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/6/14\_\_\_\_\_ Survey Number: RI-28-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: Dahlman Farms\_\_\_\_\_

Address: 10411 Payne Road\_\_\_\_\_

Lat/Long: 42.177153/-88.647440\_\_\_\_\_

Primary Use: resid/agri\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:\_\_\_\_\_ Group:  Number Structures in Group: six\_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) garage; (D) pole barn; (E) pole barn; (F) small wood-sided shed with concrete foundation

### Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: Limestone

Other distinguishing features:

### Barn Detail

Style: Gambrel roof

Wall materials: alum/vinyl/wood

Roof materials: metal

Foundation materials: concrete

Other distinguishing features: large roof cupola

Any obvious Additions/Alterations: additions to N side

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. Per resident: farm dates to 1870s. Dairy barn burned down 20 years ago.

circa 1872

Number of photos taken for this property\*: four\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-28-2: 10411 Payne Road – Garage, Outbuildings



RI-28-2: 10411 Payne Road – Residence



RI-28-2: 10411 Payne Road – Barn, Outbuilding

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/6/14\_\_\_\_\_ Survey Number: RI-28-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 10909 Payne Road \_\_\_\_\_

Lat/Long: 42.169952/-88.647375 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: seven \_\_\_\_\_

List Observed Structures: (A) residence; (B) garage; (C) concrete stave silo; (D) metal pole barn; (E) small garage/shed; (F) large metal pole barn; (G) two metal grain bins

### Residence Detail

Style: Foursquare

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete clad

Other distinguishing features: low pitched roof, flat

top; appears to have some Italiante characteristics

Any obvious Additions/Alterations: additions to N side

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1872

Number of photos taken for this property\*: five \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials: Other

distinguishing features:



RI-28-3: 10909 Payne Road – Residence



RI-28-3: 10909 Payne Road – Garage



RI-28-3: 10909 Payne Road – Silo, Outbuildings



RI-28-3: 10909 Payne Road – Bins

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/6/14\_\_\_\_\_ Survey Number: RI-28-4\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 23316 Hartman Road \_\_\_\_\_

Lat/Long: 42.168312/-88.652314 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) residence; (B) metal pole barn

### Residence Detail

Style: Ranch

Wall materials: brick

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1941-1951 per Twp. Assessor.

Number of photos taken for this property\*: two \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-28-4: 23316 Hartman Road – Residence, Shed

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/6/14\_\_\_\_\_ Survey Number: RI-28-5\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 23618 Hartman Road \_\_\_\_\_

Lat/Long: 42.168194/-88.658988 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: eight \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C-D) two concrete stave silos; (E) concrete block shed; (F) vinyl-clad shed with metal roof, chimney; (G) wood-sided crib; (H) wood-sided shed N of crib

### Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete clad

Other distinguishing features:

### Barn Detail

Style: Gabled roof

Wall materials: vertical wood board

Roof materials: shake shingle

Foundation materials: unknown

Other distinguishing features: most of exterior is gone.

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. (E) concrete block shed has shake shingle roof under metal, metal cupola, three doors closed off.

circa 1872

Number of photos taken for this property\*: five \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-28-5: 23618 Hartman Road – Barn, Silo, Shed



RI-28-5: 23618 Hartman Road – Stable



RI-28-5: 23618 Hartman Road – Sheds



RI-28-5: 23618 Hartman Road – Residence



RI-28-5: 23618 Hartman Road – Residence 2,  
Outbuilding

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/6/14\_\_\_\_\_ Survey Number: RI-28-6\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 10116 Burrows Road \_\_\_\_\_

Lat/Long: 42.181087/-88.665791 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: seven \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) masonry tile grain storage crib; (D) grain elevator/metal storage complex; (E) metal pole barn; (F) metal pole barn; (G) metal pole barn

### Residence Detail

Style: Side Gabled

Wall materials: aluminum

Roof materials: asphalt

Foundation materials:

Other distinguishing features:

### Barn Detail

Style: Gabled roof

Wall materials: vertical wood board

Roof materials: asphalt

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: rear/side extension

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1872

Number of photos taken for this property\*: six \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-28-6: 10116 Burrows Road – Bins, Sheds



RI-28-6: 10116 Burrows Road – Residence



RI-28-6: 10116 Burrows Road – Barn



RI-28-6: 10116 Burrows Road – Sheds

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/6/14\_\_\_\_\_ Survey Number: RI-28-7\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: Blizzard Ranch\_\_\_\_\_

Address: 23407 Harmony Road\_\_\_\_\_

Lat/Long: 42.182034/-88.653514\_\_\_\_\_

Primary Use: resid/agri\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:\_\_\_\_\_ Group:  Number Structures in Group: ten\_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C-E) metal-clad outbuildings/horse barns; (F-G) more metal clad outbuildings/horse barns; (H-J) more metal clad pole barn-type outbuildings/stables

### Residence Detail

Style: Italianate

Wall materials: vinyl

Roof materials: asphalt, metal

Foundation materials: concrete visible

Other distinguishing features: devoid of detail, wrap-around porch

### Barn Detail

Style: Gambrel roof

Wall materials: metal/vinyl

Roof materials: metal

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations: enclosed front porch with concrete foundation

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1872

Number of photos taken for this property\*: six\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-28-7: 23407 Harmony Road – Barn, Outbuildings



RI-28-7: 23407 Harmony Road – Outbuildings




RI-28-7: 23407 Harmony Road – Residence



RI-28-7: 23407 Harmony Road – Outbuildings

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 29



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/6/14\_\_\_\_\_ Survey Number: RI-29-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 10713 Harmony Road \_\_\_\_\_

Lat/Long: 42.172430/-88.667092 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: ten \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) grain elevator storage bin complex; (D) metal Quonsett-type barn; (E) large metal pole barn

### Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: awning

### Barn Detail

Style: Gambrel roof

Wall materials: metal/vinyl

Roof materials: metal

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1872

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-29-1: 10713 Burrows Road – Residence, Bins



RI-29-1: 10713 Burrows Road – Shed



RI-29-1: 10713 Burrows Road – Barn, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/6/14\_\_\_\_\_ Survey Number: RI-29-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: Black Beauty Farm\_\_\_\_\_

Address: 24707 Harmony Road\_\_\_\_\_

Lat/Long: 42.181624/-88.679535\_\_\_\_\_

Primary Use: resid/agri\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:\_\_\_\_\_ Group: X\_\_\_\_\_ Number Structures in Group: four\_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) large metal pole barn

Residence Detail

Style: Minimal Traditional

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Barn Detail

Style: Gabled roof

Wall materials: vertical board

Roof materials: metal

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1941-1951 per Twp. Assessor.

Number of photos taken for this property\*: five\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-29-2: 24707 Harmony Road – Barn



RI-29-2: 24707 Harmony Road – Outbuilding



RI-29-2: 24707 Harmony Road – Residence



RI-29-2: 24707 Harmony Road – Shed, Silo

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/6/14\_\_\_\_\_ Survey Number: RI-29-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 24305 Harmony Road \_\_\_\_\_

Lat/Long: 42.180874/-88.671153 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: six \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) grain bins; (D) 2<sup>nd</sup> barn: Gambrel roof, wood sided; (E-F) two concrete silos

### Residence Detail

Style: Side Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

### Barn Detail

Style: Gabled roof, obscured

Wall materials: vertical board?

Roof materials: metal

Foundation materials: unknown

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1941-1951 per Twp. Assessor.

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-29-3: 24305 Harmony Road – Bins, Sheds



RI-29-3: 24305 Harmony Road – Residence, Barn

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 30



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/6/14\_\_\_\_\_ Survey Number: RI-30-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: Diamond D Horse Farm (see photo #5)\_\_\_\_\_

Address: 25103 Harmony Road\_\_\_\_\_

Lat/Long: 42.181840/-88.686469\_\_\_\_\_

Primary Use: resid/agri\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group: X \_\_\_\_\_ Number Structures in Group: eight \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C-D) two concrete stave silos; (E) smaller wood-sided shed S of barn; (F) Quonsett style barn; (G) metal pole barn; (H) possible milk house near barn and silo

### Residence Detail

Style: Front Gabled

Wall materials: vinyl/wood

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

### Barn Detail

Style: Gambrel roof

Wall materials: vertical board?

Roof materials: metal

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1872

Number of photos taken for this property\*: five\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-30-1: 25103 Harmony Road – Barn, Silos, Stable, Outbuilding



RI-30-1: 25103 Harmony Road – Outbuilding



RI-30-1: 25103 Harmony Road – Residence



RI-30-1: 25103 Harmony Road – Outbuilding, Shed

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/6/14\_\_\_\_\_ Survey Number: RI-30-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 10817 Genoa Road \_\_\_\_\_

Lat/Long: 42.1171356/-88.697413 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: six \_\_\_\_\_

List Observed Structures: (A) residence; (B) metal garage; (C) double concrete silos with wire staves; (E) metal pole barn; (F) metal garage/shed

Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete block

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1872

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.




RI-30-2: 10817 Genoa Road – Silo, Sheds



RI-30-2: 10817 Genoa Road – Residence, Garage



MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 31



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location



**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number



## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/6/14\_\_\_\_\_ Survey Number: RI-31-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 101818 Genoa Road \_\_\_\_\_

Lat/Long: 42.156261/-88.694853 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: five \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) wood sided shed with metal roof; (D) two low connected shop sheds/garages; (E) wood-sided lean-to shed

### Residence Detail

Style: No style

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: modern

### Barn Detail

Style: Gabled roof

Wall materials: metal

Roof materials: metal

Foundation materials:

Other distinguishing features: shed extension to S

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1872 with modern residence (c. 1980)

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-31-1: 11818 Genoa Road – Residence



RI-31-1: 11818 Genoa Road – Barn, Outbuildings

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/6/14\_\_\_\_\_ Survey Number: RI-31-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 11318 Genoa Road \_\_\_\_\_

Lat/Long: 42.163759/-88.695220 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: six \_\_\_\_\_

List Observed Structures: (A) residence; (B) red metal pole barn; (C) grain elevator storage bins complex; (D) pole barn with wood plank foundation; (E) vinyl-clad smaller shed or office; (F) metal pole barn

### Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: 2-story addition to back of wing.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1941-1951 per Twp. Assessor.

Number of photos taken for this property\*: six \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-31-2: 11318 Genoa Road – Bins



RI-31-2: 11318 Genoa Road – Shed



RI-31-2: 11318 Genoa Road – Residence



RI-31-2: 11318 Genoa Road – Garage, Shed,  
Barn

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/6/14\_\_\_\_\_ Survey Number: RI-31-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 11319 Genoa Road \_\_\_\_\_

Lat/Long: 42.163345/-88.696065 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: eight \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) two metal grain bins; (D) peaked-roof wood-sided small barn; (E) concrete silo; (F) limestone/fieldstone barn foundation; (G) small lean-to structure; (H) low peaked roof shed/barn with metal roof, vertical board siding

### Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: wrap-around porch

### Barn Detail

Style: (B) Gabled roof

Wall materials: wood slats/vertical board

Roof materials: asphalt

Foundation materials: concrete visible

Other distinguishing features: large wooden cupola, extension w/shake roof

Any obvious Additions/Alterations: 2-story addition to back of wing.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. Original barn with stone foundation (F) demolished.

circa 1872

Number of photos taken for this property\*: six \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-31-3: 11319 Genoa Road – Bins, Barn



RI-31-3: 11319 Genoa Road – Barn, Silos, Shed



RI-31-3: 11319 Genoa Road – Residence



RI-31-3: 11319 Genoa Road – Shed

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 32



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/6/14\_\_\_\_\_ Survey Number: RI-32-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 24902 Poplar Road \_\_\_\_\_

Lat/Long: 42.153682/-88.682150 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: eight \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) low, wood/metal shed ; (D) peaked-roof wood-sided shed/garage, obscured; (E) small tool shed

### Residence Detail

Style: Side Gabled

Wall materials: clapboard

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: full-width front porch w/concrete fnd.

### Barn Detail

Style: Gabled roof

Wall materials: wood/metal

Roof materials: metal

Foundation materials: high concrete

Other distinguishing features:

Any obvious Additions/Alterations: 2-story addition to back of wing.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1872

Number of photos taken for this property\*: six \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-32-1: 24902 Poplar Road – Barn, Shed



RI-32-1: 24902 Poplar Road – Residence



RI-32-1: 24902 Poplar Road – Barn, Outhouse

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/6/14\_\_\_\_\_ Survey Number: RI-32-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 24606 Poplar Road \_\_\_\_\_

Lat/Long: 42.153880/-88.677454 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: eight \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) concrete stave silo; (D) stables/equipment barn; (E) small white outbuilding; (F) wood-sided garage/barn with metal roof; (G) wood-sided crib, asphalt roof, concrete found.; (H) metal pole barn

### Residence Detail

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

### Barn Detail

Style: Gabled roof

Wall materials: wood/metal

Roof materials: metal

Foundation materials: high concrete

Other distinguishing features:

Any obvious Additions/Alterations: 2-story addition to back of wing.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. Original barn with stone foundation (F) demolished.

circa 2012 per Twp. Assessor. - outbuildings circa 1900-1920

Number of photos taken for this property\*: seven \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-32-2: 24606 Poplar Road – Residence



RI-32-2: 24606 Poplar Road – Stable, Silo, Barn



RI-32-2: 24606 Poplar Road – Outbuildings



RI-32-2: 24606 Poplar Road – Outbuildings

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/6/14\_\_\_\_\_ Survey Number: RI-32-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 24110 Poplar Road \_\_\_\_\_

Lat/Long: 42.153721/-88.667355 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: five \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) stable/shed; (D) wood sided milk house; (E) residence #2, obscured

### Residence Detail

Style: Italianate

Wall materials: wood/vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

### Barn Detail

Style: Gambrel roof

Wall materials: wood Roof

materials: metal

Foundation materials: concrete

Other distinguishing features: cupola

Any obvious Additions/Alterations: large addition to west, front porch enclosed

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1872

Number of photos taken for this property\*: six \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-32-3: 24110 Poplar Road – Barn, Stable



RI-32-3: 24110 Poplar Road – Outbuilding, Windmill



RI-32-3: 24110 Poplar Road – Residence



RI-32-3: 24110 Poplar Road – Residence 2

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/6/14\_\_\_\_\_ Survey Number: RI-32-4\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 11213 Burrows Road \_\_\_\_\_

Lat/Long: 42.1165783/-88.666670 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: four \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) metal pole barn; (D) small wood sided shed/smoke house

### Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: fieldstone

Other distinguishing features: obscured

### Barn Detail

Style: distant and not visible

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1872-1892

Number of photos taken for this property\*: five \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-32-4: 11213 Burrows Road – Residence



RI-32-4: 11213 Burrows Road – Barn



RI-32-4: 11213 Burrows Road – Sheds

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/6/14\_\_\_\_\_ Survey Number: RI-32-5\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: Liberty School (1863)\_\_\_\_\_

Address: 11904 Burrows Road\_\_\_\_\_

Lat/Long: 42.156188/-88.666777\_\_\_\_\_

Primary Use: educ/resid\_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:\_\_\_\_\_ Group: X\_\_\_\_\_ Number Structures in Group: three\_\_\_\_\_

List Observed Structures: (A) Single room schoolhouse; (B) pole barn work shop; (C) garage

Residence Detail

Style: Greek Revival

Wall materials: wood

Roof materials: metal

Foundation materials: concrete clad

Other distinguishing features: school bell on roof

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. Schoolhouse plaque: “School District No.7 1863”. And over door: “Liberty School”

circa 1863

Number of photos taken for this property\*: five\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-32-5: 11904 Burrows Road – Shed




RI-32-5: 11904 Burrows Road – Outbuilding



RI-32-5: 11904 Burrows Road – School House

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 33





Copyright © 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number



## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/7/14\_\_\_\_\_ Survey Number: RI-33-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 23304 Hartman Road \_\_\_\_\_

Lat/Long: 42.167651/-88.653446 \_\_\_\_\_

Primary Use: residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) residence; (B) garage

### Residence Detail

Style: Ranch

Wall materials: vinyl

Roof materials: metal

Foundation materials: unknown

Other distinguishing features: modern

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1940-1965

Number of photos taken for this property\*: one \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-33-1: 23304 Hartman Road – Residence, Garage

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/7/14\_\_\_\_\_ Survey Number: RI-33-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 11119 Payne Road \_\_\_\_\_

Lat/Long: 42.166550/-88.647427 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:            Group: X            Number Structures in Group: ten

List Observed Structures: (A) residence; (B) barn; (C) milk house; (D) concrete block garage; (E) metal grain bin; (F) pole barn; (G) low, wood-sided coop; (H) wood-sided shed; (I) wood-sided crib; (J) wood-sided garage/shed with green metal roof

Residence Detail

Style: Cross-Gabled

Wall materials: vinyl

Roof materials: metal

Foundation materials: concrete over fieldstone

Other distinguishing features:

Barn Detail

Style: Gambrel Roof

Wall materials: vertical wood board

Roof materials: asphalt

Foundation materials: cc. over fieldstone

Other distinguishing features: attached milk house

Any obvious Additions/Alterations: addition to rear.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1901 per Twp. Assessor.

Number of photos taken for this property\*: seven\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-33-2: 11119 Payne Road - Shed



RI-33-2: 11119 Payne Road – Barn, Milk House



RI-33-2: 11119 Payne Road – Bin, Garage, Shed



RI-33-2: 11119 Payne Road - Sheds



RI-33-2: 11119 Payne Road – Residence

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/7/14\_\_\_\_\_ Survey Number: RI-33-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 11615 Payne Road \_\_\_\_\_

Lat/Long: 42.159777/-88.647320 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group: X \_\_\_\_\_ Number Structures in Group: eight \_\_\_\_\_

List Observed Structures: (A) residence #1; (B) residence #2: modern Ranch; (C) garage; (D) garage; (E) wood-sided barn/crib; (F) metal-clad barn; (G) small shed; (H) metal clad garage

### Residence Detail

Style: (A) Cape Cod

Wall materials: vinyl

Roof materials: metal

Foundation materials: unknown

Other distinguishing features:

### Barn Detail

Style: (E) Gambrel Roof

Wall materials: wood

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features: cupola

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1930-1940

Number of photos taken for this property\*: five \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-33-3: 11615 Payne Road – Residence 2, Garage



RI-33-3: 11615 Payne Road – Residence 1



RI-33-3: 11615 Payne Road – Garage, Corn Crib, Sheds



RI-33-3: 11615 Payne Road - Shed

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/7/14\_\_\_\_\_ Survey Number: RI-33-4\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 23104 Poplar Road \_\_\_\_\_

Lat/Long: 42.153703/-88.647311 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group: X \_\_\_\_\_ Number Structures in Group: seven \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn/crib; (C) garage; (D) gmetal pole barn; (E) small office bldg. on concrete foundation; (F) wood-sided shed with metal roof; (G) wood-sided shed with metal roof

## Residence Detail

Style: Front Gabled

Wall materials: vinyl

Roof materials: metal

Foundation materials: concrete block

Other distinguishing features:

## Barn Detail

Style: Gabled roof barn/crib

Wall materials: wood Roof

materials: metal

Foundation materials: concrete

Other distinguishing features: large cupola

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1872

Number of photos taken for this property\*: five \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-33-4: 23104 Poplar Road – Residence



RI-33-4: 23104 Poplar Road – Barn, Garage



RI-33-4: 23104 Poplar Road – Outbuilding, Sheds



RI-33-4: 23104 Poplar Road – Residence 2

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/7/14\_\_\_\_\_ Survey Number: RI-33-5\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 24108 Poplar Road \_\_\_\_\_

Lat/Long: 42.153686/-88.666098 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: two \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn/shed

### Residence Detail

Style: Upright and Wing

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete clad O

Other distinguishing features: Greek Revival cornice

returns

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1872

Number of photos taken for this property\*: three \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:



RI-33-5: 24108 Poplar Road – Residence



RI-33-5: 24108 Poplar Road – Shed

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 34



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/7/14\_\_\_\_\_ Survey Number: RI-34-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 22211 Hartman Road \_\_\_\_\_

Lat/Long: 42.167695/-88.630631 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group: X \_\_\_\_\_ Number Structures in Group: three \_\_\_\_\_

List Observed Structures: (A) residence; (B) small 2<sup>nd</sup> residence; (C) obscured shed

Residence Detail

Style: Cross Gabled

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. 2<sup>nd</sup> residence (B) is a one-story cottage, vinyl siding, asphalt roof, concrete foundation.

circa 1872

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-34-1: 22211 Hartman Road - Residence



RI-34-1: 22211 Hartman Road – Residence 2



RI-34-1: 22211 Hartman Road – Shed

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/7/14\_\_\_\_\_ Survey Number: RI-34-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 11657 IL 23 \_\_\_\_\_

Lat/Long: 42.159878/-88.637629 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: three \_\_\_\_\_

List Observed Structures: (A) residence; (B) grain bins; (C) concrete stave silo; (D) vinyl-clad shed/garage; (E) pole barn near silo; (F) metal pole barn; (G) octagonal possible 2<sup>nd</sup> residence on concrete foundation

### Residence Detail

Style: Ranch

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1872-1892

Number of photos taken for this property\*: five \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-34-2: 11657 Illinois Route 23 – Silo, Shed,  
Residence



RI-34-2: 11657 Illinois Route 23 – Outbuilding

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/7/14\_\_\_\_\_ Survey Number: RI-34-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 16000 Poplar Road \_\_\_\_\_

Lat/Long: 42.153602/-88.645591 \_\_\_\_\_

Primary Use: abandoned farmstead \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: three \_\_\_\_\_

List Observed Structures: (A) possible residence concrete block foundation; (B) corrugated metal shed; (C) small cabin/shed with metal roof, wood and asphalt siding

### Residence Detail

Style: see (A)

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1941-1951 per Twp. Assessor.

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-34-3: 16000 Poplar Road - Foundation



RI-34-3: 16000 Poplar Road – Shed



RI-34-3: 16000 Poplar Road – Shed

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/7/14\_\_\_\_\_ Survey Number: RI-34-4\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 16000 Poplar Road \_\_\_\_\_

Lat/Long: 42.153602/-88.645591 \_\_\_\_\_

Primary Use: residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:  \_\_\_\_\_ Group: \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: (A) residence

### Residence Detail

Style: Ranch

Wall materials: brick

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features: attached garage

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1956 per Twp. Assessor.

Number of photos taken for this property\*: one \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-34-4: 16220 Poplar Road – Residence

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/7/14\_\_\_\_\_ Survey Number: RI-34-5\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 11512 IL 23 \_\_\_\_\_

Lat/Long: 42.161068/-88.633082 \_\_\_\_\_

Primary Use: residence \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: \_\_\_\_\_

List Observed Structures: (A) residence; (B) greenhouse; (C) wood-sided lean-to shed on concrete; (D) vertical wood-sided shed/garage on concrete over poss. fieldstone

### Residence Detail

Style: Gabled EI

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: poss. fieldstone

Other distinguishing features: attached garage

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1872

Number of photos taken for this property\*: one \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-34-5: 11512 Illinois Route 23 – Glass House,  
Shed




RI-34-5: 11512 Illinois Route 23 – Shed



RI-34-5: 11512 Illinois Route 23 – Residence

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 35



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/7/14\_\_\_\_\_ Survey Number: RI-35-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 11204 Carls Road \_\_\_\_\_

Lat/Long: 42.166422/-88.627352 \_\_\_\_\_

Primary Use: residence/agriculture \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single:            Group: X            Number Structures in Group: nine

List Observed Structures: (A) residence; (B) barn; (C) (E) small wood-sided shed; (F) metal Quonset structure; (G) wood-sided storage barn/garage with shed attachment; (H) wood-sided milk house with metal roof on concrete; (I) concrete stave silo

### Residence Detail

Style: Foursquare

Wall materials: vinyl

Roof materials: metal

Foundation materials: concrete visible

Other distinguishing features: Victorian trim at front entrance

### Barn Detail

Style: Gabledb roof

Wall materials: vertical wood

boards Roof materials: metal

Foundation materials: unknown

Other distinguishing features: poss. covered shed extension to south ; Salt Box profile

Any obvious Additions/Alterations: addition to S.

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

circa 1872

Number of photos taken for this property\*: eight\_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-35-1: 11204 Carls Road - Outbuildings



RI-35-1: 11204 Carls Road – Residence, Shed



RI-35-1: 11204 Carls Road - Outbuildings



RI-35-1: 11204 Carls Road - Shed



RI-35-1: 11204 Carls Road – Barn, Outbuilding, Silo

# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/7/14\_\_\_\_\_ Survey Number: RI-35-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 11310 Carls Road \_\_\_\_\_

Lat/Long: 42.161267/-88.627384 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: unknown \_\_\_\_\_

List Observed Structures: No observed structures. Farmstead at end of long drive, completely obscured by foliage.

### Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials: u

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property\*: one \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-35-2: 11310 Carls Road – Farmstead

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/7/14\_\_\_\_\_ Survey Number: RI-35-3\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 11506 Coon Creek Road \_\_\_\_\_

Lat/Long: 42.161690/-88.617564 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: ten \_\_\_\_\_

List Observed Structures: (A) residence; (B) smaller pole barn garage; (C) metal grain bin(s); (D) metal pole barn with shed extension; (E) metal pole barn; (F) metal pole barn; (G) metal-clad pole barn with wood foundation; (H) low wood-sided shed/barn; (I,J) two concrete stave silos

### Residence Detail

Style: Front Gable

Wall materials: asbestos shingle

Roof materials: asphalt

Foundation materials: concrete under front porch

Other distinguishing features: center peak

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872

Number of photos taken for this property\*: five \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-35-3: 11506 Coon Creek Road - Residence



RI-35-3: 11506 Coon Creek Road – Sheds



RI-35-3: 11506 Coon Creek Road – Shed, Silos



RI-35-3: 11506 Coon Creek Road - Sheds

## McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/7/14\_\_\_\_\_ Survey Number: RI-35-4\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 12016 Coon Creek Road \_\_\_\_\_

Lat/Long: 42.153788/-88.613765 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: unknown \_\_\_\_\_

List Observed Structures: (A) one garage-like structure visible at end of a long drive and all else obscured by foliage

### Residence Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

### Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations:

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1872


Number of photos taken for this property\*: one \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-35-4: 12016 Coon Creek Road – Unknown

MCHENRY COUNTY  
RILEY TOWNSHIP  
SECTION 36



Copyright:© 2013 Esri, DeLorme, NAVTEQ, TomTom



Township  
Location

**Photo Location Key**

- ← - Single Resource
- - Resource Group
- RI-1-1 - Survey Number

0 125 250 500 Meters

0 375 750 1,500 Feet



# McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/7/14\_\_\_\_\_ Survey Number: RI-36-1\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 11905 Getty Road \_\_\_\_\_

Lat/Long: 42.155948/-88.593991 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  Number Structures in Group: six \_\_\_\_\_

List Observed Structures: (A) residence; (B) barn; (C) residence #2; (D) 2 metal grain bins; (E) metal pole barn on concrete; (F) small shed with metal roof;

### Residence Detail

Style: Minimal Traditional

Wall materials: vinyl

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

### Barn Detail

Style: Gabled roof

Wall materials: wood boards

Roof materials: asphalt

Foundation materials: concrete

Other distinguishing features:

Any obvious Additions/Alterations: additions to rear include attached garage. Addition to north

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures. Residence #2 is a modern ranch

Circa 1941-1951 per Twp. Assessor.

Number of photos taken for this property\*: six \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-36-1: 11905 Getty Road – Residence, Sheds,  
Barn



RI-36-1: 11905 Getty Road – Bins, Sheds



RI-36-1: 11905 Getty Road – Residence 2

McHenry County Intensive Rural Structures Field Survey Form

Survey Date: 10/7/14\_\_\_\_\_ Survey Number: RI-36-2\_\_\_\_\_ Surveyor Name: J. Davis\_\_\_\_\_

Current Property or Structure Name: \_\_\_\_\_

Address: 11109 Getty Road \_\_\_\_\_

Lat/Long: 42.167143/-88.594096 \_\_\_\_\_

Primary Use: resid/agri \_\_\_\_\_

Is this a record of a single structure or group (give total number of structures):

Single: \_\_\_\_\_ Group:  \_\_\_\_\_ Number Structures in Group: five \_\_\_\_\_

List Observed Structures: (A) residence; (B) garage; (C) small tool shed; (D) metal pole barn/garage/shed; (E) concrete silo

Residence Detail

Style: Minimal Traditional

Wall materials: brick/stoneface

Roof materials: asphalt

Foundation materials: unknown

Other distinguishing features:

Barn Detail

Style:

Wall materials:

Roof materials:

Foundation materials:

Other distinguishing features:

Any obvious Additions/Alterations: additions to rear include attached garage. Addition to north

Other structures on property – list type/function, materials, and other characteristics for each (includes buildings and other structures such as windmills, silos, carports, etc): see observed structures.

Circa 1941-1951 per Twp. Assessor.

Number of photos taken for this property\*: four \_\_\_\_\_

\* Attach Photo log, additional notes and map of resource location.



RI-36-2: 11109 Getty Road – Sheds, Silo



RI-36-2: 11109 Getty Road – Residence



RI-36-2: 11109 Getty Road – Garage, Shed